J17-8
NOV

Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO # WG203154

Status
Printed 03/17/2026 8:51:24 AM

SERVICE ORDER
CUSTOMER COPY

User C403 **Page** 1

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home **Bus** (780) 453-6996
Cell **Today**
Email

Type
Term Cash

Advisor	Bruce Kobylnyk	**Promised**	03/16/2026 5:30 PM	**Tag#**	4217
Shop	S1	**Opened**	03/16/2026 11:19 AM	**Location**	
Priority	4	**Cashiered**		**PO #**	WS189

License	**Odom In**	**Odom Out**	**In Service Date**	**Stock No**
CFD9001	208777	208777	02/05/2020	C4184217
Year	**Make**	**Model**	**Model Number**	**Colour**
2020	CHEVROLET	SILVERADO 3500HD	CK30743	
Vehicle ID No		**Selling Dealer**	**Extended Warranty**	**Delivery Date**
1GC4YTEY5LF184217		01		02/05/2020
Engine	DURAMAX 6.6L TURBO-DIESEL V8,		WS189	

Request **Description**
DRIVE inspect and report ses light on

Job	**CSR**	**Status**
1	C403	Original

Labour **Description**
DRIVE inspect and report ses light on
DRIVE inspect and report ses light on

Type	**Amount**
CMAP	70.00
CMAP	308.00

Part	**Description**	**Shp**	**SL**	**Bin**	**Type**	**Retail**	**Price**	**Amount**
87821864 STK	TANK	1		300121	CG13R	1,975.22	1,343.15	1,343.15
19433253 STK	FLUID	1		320101	CG13R		34.61	34.61

Technician C185 -
C8256 -

Cause P10D9, P10F3, P143C and P20B9. Heater 1, 2 and 3 circuits. Commanded reductant heaters on with scan tool. None functioning at this time. All related fuses ok. Raised vehicle on hoist and inspected for damaged chassis or reductant tank harness. No issues found. Checked continuity between the reductant control module and heaters - continuity ok. All related terminals clean and tight. Requires replacement of reductant tank assembly. Heaters are not serviceable.

Correction Replaced Reductant fluid tank following SI procedure.
Torqued everything to spec.
Filled the tank with 1 jug of DEF.
Tried to perform a temper bay test - test failed setting up a P249C.
Performed a reductant fluid tank level reset - fluid tank level is at 34%.
Performed a reductant system leak test.
Performed a reductant system leak test - pressure was 500 kPa.
After performing all those procedures cleared up DTC and service DEF system message went away.
No DTCs currently present.

Parts Total	1,377.76
Labour Total	378.00
Request Sub-total	**1,755.76**

Request **Description**
DFUELFILT DIESEL FUEL FILTER

Job	**CSR**	**Status**
2	C403	Approved

Labour **Description**
DFUELFILT DIESEL FUEL FILTER

Type	**Amount**
CS	120.61

Part	**Description**	**Shp**	**SL**	**Bin**	**Type**	**Retail**	**Price**	**Amount**
13539108	FILTER KI	1		290207	CQS		78.84	78.84
ENVIRO	HNDL CHG	10			CQS		0.05	0.50

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S (EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE CHARGED ON OVERDUE ACCOUNTS

CUSTOMER SIGNATURE: _____ DATE:

Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | **Fax:** (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO # WG203154

Status
Printed 03/17/2026 8:51:24 AM

SERVICE ORDER
CUSTOMER COPY

User C403 **Page** 2

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home
Bus (780) 453-6996
Cell **Today**
Email

Type
Term Cash

Advisor	Bruce Kobylnyk	**Promised**	03/16/2026 5:30 PM	**Tag#**	4217
Shop	S1	**Opened**	03/16/2026 11:19 AM	**Location**	
Priority	4	**Cashiered**		**PO #**	WS189

License	**Odom In**	**Odom Out**	**In Service Date**	**Stock No**
CFD9001	208777	208777	02/05/2020	C4184217
Year	**Make**	**Model**	**Model Number**	**Colour**
2020	CHEVROLET	SILVERADO 3500HD	CK30743	
Vehicle ID No		**Selling Dealer**	**Extended Warranty**	**Delivery Date**
1GC4YTEY5LF184217		01		02/05/2020
Engine	DURAMAX 6.6L TURBO-DIESEL V8,		WS189	

Technician	C8256 -
Cause	DIESEL FUEL FILTER
Correction	Replaced diesel fuel filter. Reset diesel fuel filter life (was at 0%)

Parts Total	79.34
Labour Total	120.61
Request Sub-total	**199.95**

Labour	498.61
Parts	1,457.10
Supplies	49.86
Sub-Total	**2,005.57**
GST	100.28
Total Invoice	**2,105.85**

POSTED

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S (EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE CHARGED ON OVERDUE ACCOUNTS

CUSTOMER SIGNATURE:

DATE:

Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | **Fax:** (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO # WG198156

Status
Printed 11/07/2025 7:29:57 AM

SERVICE ORDER
CUSTOMER COPY

User C403 **Page** 1

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home **Bus** (780) 453-6996
Cell **Today**
Email

Type
Term Cash

Advisor	Bruce Kobylnyk	**Promised**	10/24/2025 5:30 PM	**Tag#**	4217
Shop	S1	**Opened**	10/24/2025 1:07 PM	**Location**	
Priority	4	**Cashiered**		**PO #**	WS189

License	**Odom In**	**Odom Out**	**In Service Date**	**Stock No**
CFD9001	193790	193790	02/05/2020	C4184217
Year	**Make**	**Model**	**Model Number**	**Colour**
2020	CHEVROLET	SILVERADO 3500HD	CK30743	
Vehicle ID No		**Selling Dealer**	**Extended Warranty**	**Delivery Date**
1GC4YTEY5LF184217		01		02/05/2020
Engine	DURAMAX 6.6L TURBO-DIESEL V8,		WS189	

Request	**Description**	**Job**	**CSR**	**Status**
TRANS	inspect and report transmission would not shift stuck 1st gear dtc p0700-p0747 stuck # valve note see special pol # n242454441 valve body replacement	1	C403	Original

Labour	**Description**	**Type**	**Amount**
TRANS	inspect and report transmission would not shift stuck 1st gear dtc p0700-p0747 stuck # valve note see special pol # n242454441 valve body replacement	CHS	0.00

Part	**Description**	**Shp**	**SL**	**Bin**	**Type**	**Retail**	**Price**	**Amount**
24298004	FILTER KI	1		240101	W			
24066238	VALVE	1			W			
EDM...SPAC # G00790662								
CORE CHARGE	CORE CHARGE|24066238	1			W			
19352620	DEXRON ULV ATF	12		400302	W			
C-24066238	CORE - VALVE	-1			W			

Technician C8261 -

Cause inspect and report transmission would not shift stuck 1st gear dtc p0700-p0747 stuck # valve note see special pol # n242454441 valve body replacement
verified check engine light is on and dtc p0747 is set. following the special policy determined that truck requires valve body replacement. ordered valve body and fluid

Correction following SI procedure removed and replaced the control valve body, refilled the transmission fluid
reprogrammed the tcm with new valve body information claim code: 18YN302876997
completed the fluid level check
completed service fast learn procedure

Request	**Description**	**Job**	**CSR**	**Status**
MENU/TPMS	Replace one TPMS sensor with a Schrader EZ sensor and relearn sensor locations - Replace one TPMS sensor with a Schrader EZ sensor and relearn sensor locations note left front	2	C403	Approved

Labour	**Description**	**Type**	**Amount**
MENU/TPMS	Replace one TPMS sensor with a Schrader EZ sensor and relearn sensor locations - Replace one TPMS sensor with a Schrader EZ sensor and relearn sensor locations note left front	CMAP	

Part	**Description**	**Shp**	**SL**	**Bin**	**Type**	**Retail**	**Price**	**Amount**
33500	DUAL BAND TPMS	1		290912	CG13R			

Technician C8261 -

Cause replace tpms sensor

Request Sub-total **109.95**

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED PARTS AFTER 90 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S (EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE:

Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | **Fax:** (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO # WG198156

Status
Printed 11/07/2025 7:29:58 AM

SERVICE ORDER
CUSTOMER COPY

User C403 **Page** 2

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home **Bus** (780) 453-6996
Cell **Today**
Email

Type
Term Cash

Advisor	Bruce Kobylnyk	**Promised**	10/24/2025 5:30 PM	**Tag#**	4217
Shop	S1	**Opened**	10/24/2025 1:07 PM	**Location**	
Priority	4	**Cashiered**		**PO #**	WS189

License	**Odom In**	**Odom Out**	**In Service Date**	**Stock No**
CFD9001	193790	193790	02/05/2020	C4184217
Year	**Make**	**Model**	**Model Number**	**Colour**
2020	CHEVROLET	SILVERADO 3500HD	CK30743	
Vehicle ID No		**Selling Dealer**	**Extended Warranty**	**Delivery Date**
1GC4YTEY5LF184217		01		02/05/2020
Engine	DURAMAX 6.6L TURBO-DIESEL V8,		WS189	

Correction
removed wheel, removed old non functioning tpms sensor
installed new tpms sensor
installed tire onto vehicle torqued to spec
inflated tire to spec
relearned tpms sensors
verified sensors work

Labour	59.95
Parts	50.00
Supplies	0.00
Sub-Total	**109.95**
GST	5.50
Total Invoice	**115.45**

RECEIVED
NOV 07 2025

POSTED

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S (EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____ DATE:

CITY COLLISION

GST/HST #: 861863033
Printed Date: 01/30/2025 9:22:24 AM

CITY COLLISION

4507 55 Ave NW
Edmonton, AB T6B 3S8
(780) 438-2879, (780) 435-2875 Fax

INVOICE

RO# 16410

Est: Pino Sanginiti

P o/# WS189

MAP WATER AND SEWER SERVICES LTD 14303 116 AVE EDMONTON, AB T5M 4G2 Home: Cell:	20 Chevrolet 3500HD Silverado Color: Blue Metallic Type: TK 4 Door Crew Cab 160" VIN: 1GC4YTEY5LF184217 Prod Date: Plate: AB CFD-9001 Odometer: Engine:	MAP WATER & SEWER Adjustor: ATTN FRANK CHIARELLO Phone: Claim #: WS 189 Deductible: 0 Loss Type: Other

P = Who Pays? (I = Insurance, C = Customer)

Qty	Type	Description	Part #	Amount	Sup #	Labor	Op	Labor Units	Paint Units	P
	Parts Existing	R Pickup Bed Side Panel				Body	Rpr	9.0		C
	Parts Existing	R Bed Outer Side Panel					Refn		3.3	C
	Parts Existing	R Bed Rail Protector				Body	R&I	0.4		C
	Parts Existing	R Bed Wheel Opening Moulding				Body	R&I	0.3		C
		Tailgate Complete					Refn		2.4	C
	Parts New	Tailgate Shell (Alum/Steel)				Body	Repl	1.7		C
		Tailgate Outside					Refn			C
		Tailgate Inside					Refn			C
	Parts New	Upr Tailgate Moulding				Body	Repl			C
	Parts New	R Rear Combination Lamp Assembly				Body	Repl	0.3		C
1	Pnt/Mat	Paint/Materials		388.24			Addl			C
1	Haz	Hazardous Waste Disposal		5.00			Addl			C
1	Bdy/Sup	Shop Materials		264.00			Addl			C
		Clear Coat					Addl		1.8	C
		Mask For Overspray					Addl		0.5	C
		Feather, Prime & Block					Addl		1.0	C
	Parts Existing	BOX RACK				Body	R&I	1.0		C
	Parts Existing	TOOL BOX				Body	R&I	0.8		C
	Parts Existing	TWO TONE					Addl		1.3	C
	Parts Existing	RT INNER PILLAR				Body	Rpr	3.0		C

Note: UNIT # WS 189

Parts	0.00
Labor	2,144.00
Additional Costs	657.24
SubTotal	2,801.24
PST	0.00
GST/HST	140.06
Grand Total	2,941.30

POSTED

Due from Insurance		Due from Customer	
SubTotal	0.00	SubTotal	2,801.24
Tax	0.00	Tax	0.00
GST/HST Tax	0.00	GST/HST Tax	140.06
Grand Total	0.00	Grand Total	2,941.30

Total Amount 2,941.30

Warranty on Labour and Paint for as long as you own the vehicle.

WOLFE CHEVROLET EDMONTON

Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | **Fax:** (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO# WG181307

Status
Printed 08/02/2024 1:42:21 PM

SERVICE ORDER
CUSTOMER COPY

User C86 **Page** 1

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home
Bus (780) 453-6996
Cell **Today**
Email

Type
Term Cash

Advisor	Amica Allenbach	**Promised**	08/01/2024 5:30 PM	**Tag#**	4217
Shop	S1	**Opened**	08/01/2024 11:19 AM	**Location**	
Priority	4	**Cashiered**		**PO #**	

License	**Odom In**	**Odom Out**	**In Service Date**	**Stock No**
CFD9001	142069	142069	02/05/2020	C4184217
Year	**Make**	**Model**	**Model Number**	**Colour**
2020	CHEVROLET	SILVERADO 3500HD	CK30743	
Vehicle ID No		**Selling Dealer**	**Extended Warranty**	**Delivery Date**
1GC4YTEY5LF184217		01	GM	02/05/2020
Engine	DURAMAX 6.6L TURBO-DIESEL V8,		WS189	

Request CHECKENG **Description** Diagnose and report on Check Engine Light
Labour CHECKENG **Description**

Job	**CSR**	**Status**
1	C86	Original

Type	**Amount**
CMAP	140.25

Part	**Description**	**Shp**	**SL**	**Bin**	**Type**	**Retail**	**Price**	**Amount**
12708005	SENSOR	1		270210	CG13R	388.25	264.01	264.01

Technician C185 -

Cause: Scanned for related codes. P22F9 was the last code to trigger the SES lamp. NOx Sensor 1 Performance - Slow Response Low to High. Checked for related bulletins or software updates. None present. No other current codes set. Checked for any obvious issues with induction or exhaust system. None found. Ran engine under conditions to set P22F9. Code ran and passed. Inspected for any obvious damage to NOx sensor 1. No issues found. All related terminals clean and tight. Condition is not current at this time, however likely cause is an intermittently faulty NOx sensor 1. Customer authorized based on possible cause.

Correction: Removed and replaced NOx sensor 1. Performed relearn procedure. Cleared codes and tested. NOx sensor operation now ok.

Parts Total	264.01
Labour Total	140.25
Request Sub-total	**404.26**

Request FORMMPVI **Description** Certified Service - Mulitpoint Vehicle Health Inspection
Labour MPVI **Description**

Job	**CSR**	**Status**
2	C86	Original

Type	**Amount**
CS	89.95

Technician C8075 -

POSTED

Cause: Multipoint Vehicle Health Check

Correction: Performed a comprehensive assessment of vehicle including, Tires Rotation and Inspection, Brake Inspection, Systems, Fluids & Visible Leak Inspection, Visible & Functional Inspections including: exhaust, driveline, steering and suspension components, belts and hoses, Lubrication of Chassis, Weatherstriping, Door Hinges, Lock Cylinders. Brakes are good with 8mm of life left front and rear, No issues found with vehicle.

Labour Total	89.95
Request Sub-total	**89.95**

RECEIVED
AUG 0 8 2024
M.A.P.

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S (EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____ DATE: _____

G.S.T # 750585713RT0001

Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | **Fax:** (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO# WG181307

Status
Printed 08/02/2024 1:42:21 PM

SERVICE ORDER
CUSTOMER COPY

User C86 **Page** 2

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home
Bus (780) 453-6996
Cell
Today
Email

Type
Term Cash

Advisor	Amica Allenbach	**Promised**	08/01/2024 5:30 PM	**Tag#**	4217
Shop	S1	**Opened**	08/01/2024 11:19 AM	**Location**	
Priority	4	**Cashiered**		**PO #**	

License	**Odom In**	**Odom Out**	**In Service Date**	**Stock No**
CFD9001	142069	142069	02/05/2020	C4184217
Year	**Make**	**Model**	**Model Number**	**Colour**
2020	CHEVROLET	SILVERADO 3500HD	CK30743	
Vehicle ID No		**Selling Dealer**	**Extended Warranty**	**Delivery Date**
1GC4YTEY5LF184217		01	GM	02/05/2020
Engine	DURAMAX 6.6L TURBO-DIESEL V8,		WS189	

Labour	230.20
Parts	264.01
Supplies	21.04
Sub-Total	**515.25**
GST	25.76
Total Invoice	**541.01**

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S (EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____ DATE: _____

G.S.T # 750585713RT0001

WOLFE CHEVROLET

Certified Service

Multipoint Vehicle Health Inspection

Name: M.A.P. Water And Sewer Services Ltd. Year/Model: 2020 SILVERADO 3500HD Date 08/01/2024 11:43: AM

RO # : WG181307 VIN (last 8 digits) : 1GC4YTEY5LF18 4217 Odometer: 142069 Tag# : Lic. Plate # : CFD9001

Service Consultant : Amica Allenbach Technician : Mitchell Zwaneveld

G CHECKED AND OK Y FUTURE ATTENTION REQUIRED R IMMEDIATE MAINTENANCE/REPAIR REQUIRED

X FLUID LEVEL INSPECTION

OK	FILLED	REQUIRES ATTENTION
X	Windshield Washer	R
X	Inspect brake fluid level	R
X	Transmission (if equipped with dipstick)	R
X	Coolant recovery reservoir	R
X	Power steering	R
X	Engine oil	R
X	Diesel exhaust fluid (DEF) (if required)	R

X VISIBLE LEAK INSPECTION

X Y R Fuel System (also including gas cap seating)
X Y R Engine
X Y R Transmission
X Y R Drive axel
X Y R Transfer case
X Y R Engine cooling system
X Y R Shocks and struts - also check operation

X VISUAL AND FUNCTIONAL INSPECTIONS

X Y R Belts: engine, accessory, serpentine, and/or V-drive
X Y R Engine air cleaner filter
X Y R Gas struts on hood or hatch for wear and hold open ability
X Y R Suspension components
X Y R Steering components and steering linkage
X Y R CV drive axel boots or driveshafts and U-joints
X Y R Exhaust system components and nearby heat shield
X Y R Passenger compartment air filters
X Y R Starter switch operation
X Y R Ignition control operation
X Y R Automatic transmission park mechanism holding ability
X Y R Automatic transmission shift lock control functions
X Y R Accelerator pedal damage, high effort or binding
X Y R Safety belt reminder lights
X Y R Safety belts, buckles, latches, plates & anchors

X TIRE INSPECTION

G 6/32 or Greater Y 5/32 to 4/32 R 3/32 or Less

LF
G Y R Set to 60 PSI
Tread Depth: 7 /32

RF
G Y R Set to 60 PSI
Tread Depth: 7 /32

LR
G Y R Set to 70 PSI
Tread Depth: 9 /32

RR
G Y R Set to 70 PSI
Tread Depth: 9 /32

Tires Rotated
Balance Needed
Alignment Needed
X Wheel Lug Nut Check

X BRAKE INSPECTION

G 6mm or Greater Y 5mm – 4 mm R 3mm or Less

LF
X Y R Pad
Actual 8 mm
X Y R Rotor

RF
X Y R Pad
Actual 8 mm
X Y R Rotor

LR
X Y R Pad
Actual 8 mm
X Y R Rotor

RR
X Y R Pad
Actual 8 mm
X Y R Rotor

Caliper Service Needed
X Y R Brake system (Including lines and hoses
X Y R Parking Brake

X BATTERY INSPECTION

X Y R Battery condition Measured ____ CCA
X Y R Battery cables & connections Spec ____ CCA

☐ Malfunction Indicator Lamp

Check Engine Lamp Warning Message Other

Additional Notes or Comments: