



J17-9
NOV

Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320

reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO # WG201969

Status

Printed 02/17/2026 2:12:51 PM

SERVICE ORDER CUSTOMER COPY



User C403 Page 1

Customer No	
M.A.P. Water And Sewer Services Ltd. 14303 - 116 Avenue NW Edmonton, AB T5M 4G2	
Home	Bus (780) 453-6996
Cell	Today
Email	
Type	
Term	Cash

Advisor	Bruce Kobylnyk	Promised	02/06/2026 5:30 PM	Tag#	7128
Shop	S1	Opened	02/06/2026 1:06 PM	Location	
Priority	4	Cashiered		PO #	WS193

License	Odom In	Odom Out	In Service Date	Stock No
TBA	248871	248874	05/03/2022	CU507128
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 1500	CK10543	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET	WS193	05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6			

Request	Description
DRIVE	inspect and report ses light on
Labour	Description
DRIVE	inspect and report ses light on
DRIVE	inspect and report ses light on

Part	Description
87867197	TANK
DEALER	
19433253	FLUID

STK	
Technician	C185 - C8218 -

Cause P20B9 - reductant heater control circuit. Commanded heat 1 on with scan tool - no current flow present. Raised vehicle on hoist and removed reductant tank shield. Disconnected reservoir connector and inspected. Found signs of overheating at reductant reservoir and connector. Requires reductant tank replacement. No serviceable parts.

Correction replaced DEF tank following si procedure, refilled tank, primed system, performed NOx catalyst reductant loading reset and reductant tank fluid level reset. cleared DTCs and went on road test to confirm proper operation and no dtc set again after repair.

Job	CSR	Status
1	C403	Original
	Type	Amount
	CMAP	70.00
	CMAP	350.00
	Price	Amount
	1,337.46	1,337.46
	34.61	69.22
Parts Total		1,406.68
Labour Total		420.00
Request Sub-total		1,826.68

Labour	420.00
Parts	1,406.68
Supplies	42.00
Sub-Total	1,868.68
GST	93.43
Total Invoice	1,962.11

POSTED

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 90 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____



Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320

reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO # WG200961

**SERVICE ORDER
CUSTOMER COPY**



Status
Printed 01/12/2026 1:30:50 PM

User C403 Page 2

Customer No
M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home **Bus** (780) 453-6996
Cell **Today**
Email

Type
Term Cash

Advisor	Bruce Kobylnyk	Promised	01/12/2026 5:30 PM	Tag#	7128
Shop	S1	Opened	01/12/2026 10:32 AM	Location	
Priority	14	Cashiered		PO #	WS193

License	Odom In	Odom Out	In Service Date	Stock No
TBA	244804	244805	05/03/2022	CU507128
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 1500	CK10543	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET	WS193	05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6			

- Replace Both Engine and Cabin Filters

Part	Description	Shp	SL	Bin	Type	Price	Amount
84121219	ELEMENT	1		240202	CQS		
19363960	FILTER	1		250203	CQS		
Technician	C8279 -						
Cause	Replace engine air filter. Replace cabin air filter.						
Correction	Removed old engine air filter. Replaced with new engine air filter. Removed old cabin air filter. Replaced cabin air filter.						
Request Sub-total							149.95

403

dtc p0421 cat/conv
p24da
history

POSTED

Labour	112.40
Parts	270.73
Supplies	5.49
Sub-Total	388.62
GST	19.43
Total Invoice	408.05

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THE INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE:



Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320

reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO # WG197889

Status

Printed 11/11/2025 12:00:06 PM

SERVICE ORDER CUSTOMER COPY



User C403 Page 1

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home Bus (780) 453-6996
Cell Today
Email
Type
Term Cash

Advisor Bruce Kobyluk Promised 10/20/2025 5:30 PM Tag# 7128
Shop S1 Opened 10/20/2025 12:11 PM Location
Priority 4 Cashiered PO # WS193

License Odom In Odom Out In Service Date Stock No
TBA 235181 235185 05/03/2022 CU507128
Year Make Model Model Number Colour
2022 CHEVROLET SILVERADO 1500 CK10543
Vehicle ID No Selling Dealer Extended Warranty Delivery Date
3GCUDEET5NG507128 WOLFE CHEVROLET
Engine DURAMAX 3.0L TURBO-DIESEL I6 WS193

Request	Description							Job	CSR	Status
DRIVE	INSPECT AND REPORT SES LIGHT ON							1	C403	Original
Labour	Description								Type	Amount
DRIVE	INSPECT AND REPORT SES LIGHT ON								C403	132.92
GENERAL	GENERAL MECHANICAL REPAIRS								CMAP	5,040.00
Part	Description	Shp	SL	Bin	Type	Retail	Price	CMAP	Amount	
55515943	CHAIN	1			CG13R	41.21	28.02		28.02	
EDM										
55489211	CHAIN	1			CG13R	41.36	28.12		28.12	
EDM										
55493234	BELT	1		290714	CG13R	32.81	22.31		22.31	
STK										
55489220	TENSIONER	1			CG13R	39.83	27.08		27.08	
EDM										
55496367	BOLT	2		291036	CG13R	5.33	3.62		7.24	
STK										
40009454	COVER	1		250402	CG13R	163.89	111.45		111.45	
STK										
55489219	GUIDE	1			CG13R	21.17	14.40		14.40	
EDM										
55489221	GUIDE	1			CG13R	18.49	12.57		12.57	
EDM										
55489213	GUIDE	1			CG13R	12.46	8.47		8.47	
EDM										
55489216	GUIDE	1			CG13R	6.26	4.26		4.26	
EDM										
13579646	SEAL	1		290353	CG13R	34.83	23.68		23.68	
STK										
13579648	SEAL	1		290350	CG13R	34.30	23.32		23.32	
STK										
13579649	SEAL	1		290352	CG13R	24.74	16.82		16.82	
STK										
11548684	BOLT	8		260310	CG13R	5.06	3.44		27.52	
STK										

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 90 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXCEPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS

CUSTOMER SIGNATURE:



Wolfe Chevrolet Edmonton

10145 178th Street NW | Edmonton, AB T5S 1E4

Phone: (780) 483-3320 | Fax: (780) 483-8068

Toll Free: 1-877-483-3320

reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO # WG197889

Status

Printed 11/11/2025 12:00:06 PM

SERVICE ORDER CUSTOMER COPY



User C403 Page 2

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home Bus (780) 453-6996
Cell Today
Email
Type
Term Cash

Advisor	Bruce Kobylnyk	Promised	10/20/2025 5:30 PM	Tag#	7128
Shop	S1	Opened	10/20/2025 12:11 PM	Location	
Priority	4	Cashiered		PO #	WS193

License	Odom In	Odom Out	In Service Date	Stock No
TBA	235181	235185	05/03/2022	CU507128
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 1500	CK10543	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET		05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6	WS193		

40009281	INSULATOR	1		CG13R	73.49	49.97	49.97
EDM							
55502647	GASKET KI	1	280110	CG13R	93.12	63.32	63.32
STK							
55503171	CLAMP	1	270506	CG13R	65.51	44.55	44.55
STK							
55494570	GASKET	1	260510	CG13R	4.47	3.04	3.04
STK							
55509254	SEAL	1	271006	CG13R	34.33	23.34	23.34
STK							
12626252	SEALS	1		CG13R	5.71	3.88	3.88
EDM							
55506825	CLAMP	1	290939	CG13R	28.03	19.06	19.06
STK							
55497083	GASKET	2	280306	CG13R	5.97	4.06	8.12
STK							
55496593	SEAL	1	290240	CG13R	7.66	5.21	5.21
STK							
55508537	GASKET	1		CG13R	5.64	3.84	3.84
EDM							
55496936	GASKET	1	280313	CG13R	3.77	2.56	2.56
STK							
55490621	GASKET	1	291035	CG13R	13.86	9.42	9.42
STK							
55496995	GASKET	1	270307	CG13R	8.34	5.67	5.67
STK							
55514599	GASKET	1	270509	CG13R	7.14	4.86	4.86
STK							
55496729	BOLT	6	271105	CG13R	7.76	5.28	31.68
EDM							
55503136	SEAL KIT	1		CG13R	90.52	61.55	61.55
EDM							
55514861	PIPE	3	280708	CG13R	44.90	30.53	91.59
STK							

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXCEPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE:

DATE:

SALES REPRESENTATIVE:



Wolfe Chevrolet Edmonton

10145 178th Street NW | Edmonton, AB T5S 1E4

Phone: (780) 483-3320 | Fax: (780) 483-8068

Toll Free: 1-877-483-3320

reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO # WG197889

Status

Printed 11/11/2025 12:00:08 PM

SERVICE ORDER CUSTOMER COPY



User C403 Page 3

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home Cell Email
Bus Today (780) 453-6996
Type Term Cash

Advisor	Bruce Kobylnyk	Promised	10/20/2025 5:30 PM	Tag#	7128
Shop	S1	Opened	10/20/2025 12:11 PM	Location	
Priority	4	Cashiered		PO #	WS193

License	Odom In	Odom Out	In Service Date	Stock No
TBA	235181	235185	05/03/2022	CU507128
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 1500	CK10543	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET		05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6		WS193	

55514860	PIPE	3	290908	CG13R	44.90	30.53	91.59
STK							
55514859	PIPE	1	240105	CG13R	107.56	73.14	73.14
STK							
55514858	PIPE	1	220305	CG13R	86.75	58.99	58.99
STK							
85628205	SEAL	1	280907	CG13R	8.81	5.99	5.99
STK							
85628209	SEAL	1	290245	CG13R	8.52	5.79	5.79
STK							
55496956	GASKET	1	260711	CG13R	5.24	3.56	3.56
STK							
55512949	GASKET	1	260106	CG13R	5.02	3.41	3.41
STK							
11588835	NUT	3	290244	CG13R	6.66	4.53	13.59
STK							
40009034	GASKET	2		CG13R	5.52	3.75	7.50
EDM							
12735608	PF66 FILTER	1	400205	CG13R	15.50	10.54	10.54
STK							
55506321	BOLT	1	#227998	CG13R	6.41	4.36	4.36
DEALER							
NPN	DEALER PURCHASE	1	#5550632	CG13R	0.38	0.38	0.38
RON HOD INV# 565859							
40009159	GASKET	1	280705	CG13R	46.45	31.59	31.59
STK							
ENVIRO	HNDL CHG	10		CG13R	0.05	0.05	0.50
19370139	OW20 DEXOS D	7	400402	CG13R	23.02	18.00	126.00
STK							
ENVIRO	HNDL CHG	14		CG13R	0.05	0.05	0.70
19369832	SEALANT	1	280406	CG13R		38.00	38.00
55494714	GASKET	1	290345	CG13R	35.59	24.20	24.20
STK							
55490656	GASKET	1	290360	CG13R	18.71	12.72	12.72

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____



Wolfe Chevrolet Edmonton

10145 178th Street NW | Edmonton, AB T5S 1E4

Phone: (780) 483-3320 | Fax: (780) 483-8068

Toll Free: 1-877-483-3320

reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO # WG197889

Status

Printed 11/11/2025 12:00:08 PM

SERVICE ORDER CUSTOMER COPY



User C403 Page 4

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home Cell Email
Bus Today (780) 453-6996
Type Term Cash

Advisor	Bruce Koblynky	Promised	10/20/2025 5:30 PM	Tag#	7128
Shop	S1	Opened	10/20/2025 12:11 PM	Location	
Priority	4	Cashiered		PO #	WS193

License	Odom In	Odom Out	In Service Date	Stock No
TBA	235181	235185	05/03/2022	CU507128
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 1500	CK10543	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET		05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6		WS193	

STK	10953464	COOLANT	1	330101	CG13R	30.13	30.13
STK	55515929	PIPE	1		CG13R	142.82	97.12
Technician	C8256 -				CG13R	142.82	97.12
Cause	No SES lamp at this time. Scanned for related codes. History P0016 - Crankshaft Position Sensor and Intake/Single Camshaft Position Sensor Correlation					Parts Total	1,426.72
Correction	Replaced primary and secondary timing chains as per previous diagnose following SI Document ID: 5743634.					Labour Total	5,172.92
	Replaced oil pump belt.					Request Sub-total	6,599.64
	Cleaned all the disassembled components.						
	Replaced all necessary components, gaskets and covers following SI Document ID: 5743634.						
	Torqued everything to spec.						
	Filled engine with new engine oil and installed new engine oil filter.						
	Filled and bled the cooling system with new coolant.						
	Started the engine - engine sounded and worked properly.						
	Cleared all the codes and went on an extensive test drive.						
	Everything was working properly on a test drive and there are no codes present after test drive.						

Request	Description	Job	CSR	Status
GENERAL	INSPECT AND REPORT SQUEAK FROM UNDER VEHICLE GET BY STEPPING ONTO RUNNING BOARDS	2	C403	Original
Labour	Description	Type	Amount	
GENERAL	INSPECT AND REPORT SQUEAK FROM UNDER VEHICLE GET BY STEPPING ONTO RUNNING BOARDS	C403	70.00	
Technician	C8256 -			
Cause	INSPECT AND REPORT SQUEAK FROM UNDER VEHICLE GET BY STEPPING ONTO RUNNING BOARDS	Labour Total	70.00	
Correction	Verified a squeak from under the vehicle.	Request Sub-total	70.00	
	Squeak is coming from the front left side of the vehicle.			
	The reason for squeak is aftermarket left front upper control arm.			
	Also during inspection found both rear left and right leaf spring bushings to be tom, needs new leaf springs since bushings are integrated in them.			

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THE INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____



SO # WG197889

Status

Printed: 11/11/2025 12:00:09 PM

Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SERVICE ORDER CUSTOMER COPY



User C403 Page 5

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home **Bus** (780) 453-6996
Cell **Today**
Email

Type
Term Cash

Advisor	Bruce Kobyluk	Promised	10/20/2025 5:30 PM	Tag#	7128
Shop	S1	Opened	10/20/2025 12:11 PM	Location	
Priority	4	Cashiered		PO #	WS193

License	Odom In	Odom Out	In Service Date	Stock No
TBA	235181	235185	05/03/2022	CU507128
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 1500	CK10543	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET	WS193	05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6			

Labour	5,242.92
Parts	1,426.72
Supplies	100.00
Sub-Total	6,769.64
GST	338.48
Total Invoice	7,108.12

POSTED

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED -
PARTS AFTER 90 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

.20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____

G.S.T # 750585713RT0001



Farleys Truck & Auto Addictions
14735 119 Avenue Northwest
Edmonton, AB T5L 2N9
(780) 488-3883
www.farleystruckandauto.com
GST# 835247057RT0001

Invoice #14459

Created: 09/15/2025 at 10:36AM
Invoiced: 09/26/2025 at 4:19PM
Payment Term: On Receipt
Payment Due: 09/26/2025
Service Writer: Steve Villeneuve

M.A.P Water & Sewer
14303 116 Ave
Edmonton, AB T5M 4G2

2022 Chevrolet Silverado 1500 RST (#WS-193)
VIN: 3GCUDEET5NG507128
License Plate: CLH-5513
Mileage In: 230,081 km
Mileage Out: 230,081 km

Front Suspension Noise When Turing hard right / Tire shop told them something was worn out or missing.

Description	Price	QTY	HRS	Subtotal
Labor: Install Stabilizer Relocation Brackets			1	\$135.00
Part: Stabilizer relocation brackets		1		\$0.00
Shop Supplies (10%): \$13.50			Total: \$155.93	

Check Engine Light

Description	HRS	Subtotal
Labor: Scan Engine Codes - P0016 - Crankshaft/Camshaft Correlation + P2C7A - Nitrogen Oxides Catalytic Converter Below Threshold History Codes - Cleared and have not returned	1	\$135.00
Shop Supplies (10%): \$13.50		Total: \$155.93

Service + Air Filter + Check Cabin Air Filter

Description	Price	QTY	HRS	Subtotal
Labor: Oil Change + replace Air & Cabin Air Filter			1	\$135.00
Part: OIL FILTER Part #: PZF-8-WL10351 OIL FILTER	\$12.41	1		\$12.41
Part: AIR FILTER / 19-20 Chevrolet Silverado/GMC Sierra 1500 / 2020 Silverado/Sierra 2500/35 AIR FILTER / 19-20 Chevrolet Silverado/GMC Sierra 1500 / 2020 Silverado/Sierra 2500/35	\$75.21	1		\$75.21
Part: WIX-24211 Cabin Air Filter	\$51.65	1		\$51.65
Part: S020227X1M BULK Synthetic 0W20 Motor Oil Per Litre S020227X1M BULK Synthetic 0W20 Motor Oil Per Litre	\$10.00	7		\$70.00
Shop Supplies (10%): \$13.50			Total: \$375.66	

POSTED



Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320

reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO# WG193036

Status
Printed 06/16/2025 12:51:03 PM

SERVICE ORDER CUSTOMER COPY



User C403 Page 1

Customer No	
M.A.P. Water And Sewer Services Ltd.	
14303 - 116 Avenue NW	
Edmonton, AB T5M 4G2	
Home	Bus (780) 453-6996
Cell	Today
Email	
Type	
Term	Cash

Advisor	Bruce Kobylnyk	Promised	06/03/2025 5:30 PM	Tag#	7128
Shop	S1	Opened	06/03/2025 2:45 PM	Location	
Priority	4	Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
TBA	201559	201559	05/03/2022	CU507128
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 1500	CK10543	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET	WS193	05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6			

Request	Description	Shp	SL	Bin	Type	Retail	Price	Amount
GENERAL	service transmission warning light on	1			CG13R	688.75	468.35	468.35
Labour	Description							
GENERAL	GENERAL MECHANICAL REPAIRS							
Part	Description							
86540772	CONTROL							
EDM								
Technician	C105 -							
Cause	Preformed system check - found P07B4 Transmission Park Position Switch 1 Circuit High. Checked for software updates to ECM and gear shift control module. None available. Requires replacement of gear shift control module.							
Correction	Removed components to access & replace gear shift control. Reassembled fully. Programmed new module. Tested operation - op ok.							

Labour	318.75
Parts	468.35
Supplies	31.87
Sub-Total	818.97
GST	40.95
Total Invoice	859.92

POSTED

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 90 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____



Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320

reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO# WG190333

Status

Printed 04/03/2025 2:56:20 PM

SERVICE ORDER CUSTOMER COPY



User C403 Page 1

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home Bus (780) 453-6996
Cell Today
Email
Type
Term Cash

Advisor	Bruce Kobyluk	Promised	03/31/2025 5:30 PM	Tag#	7128
Shop	S1	Opened	03/31/2025 10:46 AM	Location	
Priority	4	Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
TBA	188344	188359	05/03/2022	CU507128
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 1500	CK10543	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET		05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6	WS193		

Request	Description						Job	CSR	Status
GENERAL	inspect and report noise from engine area						1	C403	Original
Labour	Description						Type	Amount	
GENERAL	inspect and report noise from engine area						CMAP	1,413.50	
Part	Description	Shp	SL	Bin	Type	Retail	Price	Amount	
13579649	SEAL	1		290352	CG13R	24.43	16.61	16.61	
STK									
13579648	SEAL	1		290350	CG13R	32.87	22.35	22.35	
STK									
85628208	SEAL	2		270111	CG13R	7.04	4.79	9.58	
STK									
40009584	PUMP KIT	1			CG13R	189.18	128.64	128.64	
EDM NO DLRS									
10953464	COOLANT	1		330101	CG13R		29.28	29.28	
10953456	COOLANT	1		320101	CG13R	18.48	12.57	12.57	
Technician	C8075 -				Parts Total			219.03	
Cause	inspect and report noise from engine area				Labour Total			1,413.50	
					Request Sub-total			1,632.53	

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____

G.S.T # 750585713RT0001



Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320

reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO# WG190333

Status

Printed 04/03/2025 2:56:20 PM

SERVICE ORDER CUSTOMER COPY



User C403 Page 2

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home Bus (780) 453-6996
Cell Today
Email
Type
Term Cash

Advisor	Bruce Kobylnyk	Promised	03/31/2025 5:30 PM	Tag#	7128
Shop	S1	Opened	03/31/2025 10:46 AM	Location	
Priority	4	Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
TBA	188344	188359	05/03/2022	CU507128
Year Make	Model		Model Number	Colour
2022 CHEVROLET	SILVERADO 1500		CK10543	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET		05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6	WS193		

Correction

Brought into shop and can hear loud noise coming from engine bay and gets louder when vehicle is revved up, no current DTCs or warnings, sound is coming from passenger side and sounds like turbo area, removed heat shields and disassembled to remove intake tubing from back of turbo and use boroscope to inspect turbo, no signs of damage or concerns found with turbo assembly, ran vehicle and used stethoscope to listen for noise and is louder towards the front and lower down, watched drive belt and pulleys and noticed water pump pulley is moving in and out, disassembled as needed to remove drive belt and can feel excessive play in water pump pulley and rough spinning, lifted vehicle and removed skid plated and can see water pump leaking at bottom, suspect failed water pump is cause of noise, got auth and recovered AC, drained coolant, removed front wheels and liners, disconnected battery, removed intake baffle, manifold cover, grill assembly, front bumper assembly, lower baffles, trans cooler, lower rad mounts and rad, air box assembly, fuse block, ac condenser lines, exc then removed Condenser, Fan, and Radiator Assembly as a whole unit, unbolted and removed old water pump, cleaned gasket surface and installed new pump and gasket and torqued bolts to spec, installed drive belt and washed off old leaking fluid, reassembled all removed components and replaced needed gaskets and seals, torqued all bolts to spec and vac and filled cooling system, recharged AC and verified proper transmission fluid level, ran vehicle and noise is now gone, road tested and verified no current concerns or leaks present. (11 hrs)

POSTED

Labour	1,413.50
Parts	219.03
Supplies	0.00
Sub-Total	1,632.53
GST	81.63
Total Invoice	1,714.16

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____

G.S.T # 750585713RT0001



Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO# WG186697

Status
Printed 02/13/2025 7:13:45 AM

SERVICE ORDER CUSTOMER COPY



User C403 Page 1

Customer No
M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home **Bus** (780) 453-6996
Cell **Today**
Email

Type
Term Cash

Advisor	Bruce Kobylnyk	Promised	01/17/2025 5:30 PM	Tag#	7128
Shop	S1	Opened	12/20/2024 7:24 AM	Location	
Priority	14	Cashiered		PO #	WS193

License	Odom In	Odom Out	In Service Date	Stock No
TBA	180473	180473	05/03/2022	CU507128
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 1500	CK10543	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET		05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6		WS193	

Request	Description	Job	CSR	Status				
DRIVE	inspect and report ses light on note vehicle was towed in . driver said lost brake assist	1	C403	Original				
Labour	Description		Type	Amount				
DRIVE	inspect and report ses light on note vehicle was towed in . driver said lost brake assist		CMAP	127.50				
GENERAL	GENERAL MECHANICAL REPAIRS		CMAP	382.50				
Part	Description	Shp	SL	Bin	Type	Retail	Price	Amount
85051994	MODULE KI	1			CG13R	656.08	446.13	446.13
SPAC...NO DEALERS - SPAC # G09032949								
Technician	C185 - C8185 -	Parts Total						446.13
Cause	P0606 set in the brake system control module.	Labour Total						510.00
Correction	removed LF wheel and wheel liner prepared module for removal with scanner disconnected battery disconnected and removed module	Request Sub-total						956.13
installed new module with new bolts-tightened down in sequence reconnected battery programmed module and set up performed necessary tests as per document cleared codes and road tested- brakes are good and no warnings or codes came up.								

Request	Description	Job	CSR	Status				
LOF/WOLFE	Wolfe Pack Advantage LOF	2	C403	Original				
Change engine oil and filter, lube chassis, top up fluids and perform complimentary 15 point visual health inspection								
Labour	Description		Type	Amount				
LOF/WOLFE	Wolfe Pack Advantage LOF		IWPA					
Change engine oil and filter, lube chassis, top up fluids and perform complimentary 15 point visual health inspection								
Part	Description	Shp	SL	Bin	Type	Retail	Price	Amount
19370139	0W20 DEXOS D	7		400402	IQS			
ENVIRO	HNDL CHG	14			IQS			
12735608	PF66 FILTER	1		400205	IQS			

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

TERMS
NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXCEPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

DEBTS ARE HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS AN ARRANGEMENT IS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____

G.S.T# 756395713RT0001



Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO# WG186697

Status
Printed 02/13/2025 7:13:45 AM

SERVICE ORDER CUSTOMER COPY



User C403 Page 2

Customer No M.A.P. Water And Sewer Services Ltd. 14303 - 116 Avenue NW Edmonton, AB T5M 4G2 Home Cell Email Bus (780) 453-6996 Today Type Term Cash	Advisor Bruce Kobylnyk Shop S1 Priority 14 Promised 01/17/2025 5:30 PM Opened 12/20/2024 7:24 AM Cashiered Tag# 7128 Location PO # WS193 License TBA Year 2022 Make CHEVROLET Vehicle ID No 3GCUDEET5NG507128 Engine DURAMAX 3.0L TURBO-DIESEL I6 Odom In 180473 Odom Out 180473 Model SILVERADO 1500 Selling Dealer WOLFE CHEVROLET In Service Date 05/03/2022 Model Number CK10543 Extended Warranty WS193 Stock No CU507128 Colour Delivery Date 05/03/2022
---	---

ENVIRO HNDL CHG
Technician C8185 -
Cause DEXOS OIL CHANGE
Correction Changed 0w20 engine oil and filter, lube chassis, top up fluids and perform 15 point inspection - includes up to 6L. reset oil life

Request	Description	Job	CSR	Status
FORMMPVI	Certified Service - Multipoint Vehicle Health Inspection	3	C403	Original
Labour	Description		Type	Amount
MPVI	Multipoint Vehicle Health Check as required by your Owners Manual every 12,000 km - a comprehensive assessment of your vehicle including: Tires Rotation and Inspection; Brake Inspection; Systems, Fluids & Visible Leak Inspection; Battery Condition and voltage test; Visible & Functional Inspections including: exhaust, driveline, steering and suspension components, belts and hoses; Lubrication of Chassis, Weatherstripping, Door Hinges, Lock Cylinders.		CS	89.95
Technician	C8185 -			
Cause	Certified Service - Multipoint Vehicle Health Inspection	Labour Total		89.95
Correction	inspection:	Request Sub-total		89.95
	front crank seal is leaking-replace and re-seal transmission fluid exchange due.			
	tires: front: 10/32nds rear: 10.5-11/32nds brakes: front: 8mm LR: 8mm RR 6-8mm			

Request	Description	Job	CSR	Status				
DRIVE	inspect and report no air flow from vents note cabin air filter installed wg184532 10/28/2024	6	C403	Approved				
Labour	Description		Type	Amount				
DRIVE	inspect and report no air flow from vents note cabin air filter installed wg184532 10/28/2024		CMAP	49.95				
Part	Description	Shp	SL	Bin	Type	Retail	Price	Amount
19363960	FILTER	1		250203	CG13R	34.45	23.43	23.43
Technician	C185 -							
Correction	replace cabin air filter							
					Parts Total			23.43
					Labour Total			49.95
					Request Sub-total			73.38

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXCEPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS

INDEBTNESS I HEREBY ACKNOWLEDGE IN THE SUM OF MONEY BEING ALL OR THE BALANCE DUE FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: 5% CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAY BE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____

G.S.T# 750585713RTCC00



Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO# WG186697

Status
Printed 02/13/2025 7:13:45 AM

SERVICE ORDER CUSTOMER COPY



User C403 Page 3

Customer No

M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue NW
Edmonton, AB T5M 4G2

Home **Bus** (780) 453-6996
Cell **Today**
Email

Type
Term Cash

Advisor	Bruce Kobylnyk	Promised	01/17/2025 5:30 PM	Tag#	7128
Shop	S1	Opened	12/20/2024 7:24 AM	Location	
Priority	14	Cashiered		PO #	WS193

License	Odom In	Odom Out	In Service Date	Stock No
TBA	180473	180473	05/03/2022	CU507128
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 1500	CK10543	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET		05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6			

Labour	649.90
Parts	469.56
Supplies	64.99
Sub-Total	1,184.45
GST	59.22
Total Invoice	1,243.67

POSTED

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

TERMS

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXCEPTING MAINTENANCE AND WEAR AND TEAR ITEMS) INQUIRE FOR FURTHER
DETAILS

DEBTNESS: I HEREBY ACKNOWLEDGE IN THE SUM OF MONEY BEING ALL OR THE BALANCE DUE FOR REPAIRS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH IN PERS.
CHARGED ON OVERDUE ACCOUNTS

CUSTOMER SIGNATURE: _____

DATE: _____

G.S.T # 750595713RT000



Wolfe Chevrolet Edmonton
10145 178th Street NW | Edmonton, AB T5S 1E4
Phone: (780) 483-3320 | Fax: (780) 483-8068
Toll Free: 1-877-483-3320
reception-tcf@wolfeautomotive.com | www.wolfechevrolet.com

SO# WG173358

Status Comeback
Printed 05/21/2024 11:46:05 AM

SERVICE ORDER CUSTOMER COPY



User C403 Page 1

Customer No
M.A.P. Water And Sewer Services Ltd.
14303 - 116 Avenue
Edmonton, AB T5M 4G2

Home **Bus** 453-6996
Cell **Today**
Email

Term Cash

Advisor	Bruce Kobylnyk	Promised	01/09/2024 5:30 PM	Tag#	7128
Shop	S1	Opened	01/09/2024 8:54 AM	Location	
Priority	14	Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
TBA	106952	106953	05/03/2022	CU507128
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 1500	CK10543	NORTHSKY
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3GCUDEET5NG507128	WOLFE CHEVROLET GM		05/03/2022	
Engine	DURAMAX 3.0L TURBO-DIESEL I6			

Request	Description	Job	CSR	Status			
DRIVE	inspect and report ses light on	1	C403	Original			
Labour	Description		Type	Amount			
DRIVE	inspect and report ses light on		W				
DRIVE	inspect and report ses light on		W				
Part	Description	Shp	SL	Bin	Type	Price	Amount
24001355	VALVE	1		SEE	W		
10953464	COOLANT	1		320201	W		
Technician	C185 - C8075 -						
Cause	P1098 - Engine Coolant Control Valve Position Sensor Minimum Stop Performance. Coolant flow control valve replaced on previous RO. Vehicle has most recent ECM software updates. TAC contacted by 316. Was told that this code is handled internally of the valve. No external source can cause this code. Told to order new valve and install, as per TAC.						
Correction	Used SI procedure and performed coolant flow control valve replacement, disconnected battery, drained coolant, removed wheel liner, intermediate shaft, oil level tube, hoses at flow control, valve, connectors, master cylinder connector, unbolted and removed old flow control valve, cleaned surface and installed new assembly and torqued bolts to spec, reassembled all removed components and bled cooling system, washed off old leaking fluid and installed wheel liner, performed coolant control valve learn and road tested vehicle, verified no coolant leaks or DTCs set. (8075)						
	Engine Coolant Flow Control Valve Replacement LABOR CODE: 4033320 LM2 LABOR TIME: 3.4						

Tac case 9-11676275019 01/11/24

Labour	0.00
Parts	0.00
Supplies	0.00
Sub-Total	0.00
GST	0.00
Total Invoice	0.00

Westgate Chevrolet (2018) Ltd. has the ability to contact you via Mobile Texting in regards to vehicle servicing or information requests. Please be advised that standard charges may apply.

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON STOCKED
PARTS AFTER 30 DAYS OR SPECIAL ORDERS.

TERMS
NO REFUNDS OR EXCHANGE ON ELECTRICAL ITEMS OR
SPECIAL ORDERS.

20% HANDLING CHARGE ON ALL
ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE

ALL GENUINE PARTS & ACCESSORIES ARE WARRANTED FOR 12 MONTHS UNLIMITED KM'S
(EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS). INQUIRE FOR FURTHER
DETAILS.

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF MONEY BEING ALL OR THE BALANCE OWING FOR PEPA RS, PARTS &
ACCESSORIES DESCRIBED IN THIS INVOICE. TERMS: STR CTLY CASH UNLESS ARRANGEMENTS MADE 2% PER MONTH MAX FEE
CHARGED ON OVERDUE ACCOUNTS.

CUSTOMER SIGNATURE: _____

DATE: _____

G.S.T # 75059573R10001