

04057823

INSPECTION CERTIFICATE

Manitoba

X03-1

Box 45064 Regent Postal Out
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba
C050703Date
Inspection
Started310
DAY111
MO.215
YR.Date
Inspection
Completed011
DAY112
MO.215
YR.Inspection
Expiry
Date311
DAY112
MO.215
YR.Station
Number

A5131411

5496633 Manitoba

Station Name

City

Mechanic
Number

M7171712

Mechanic Signature

Station Phone Number

204 999-3179

Vehicle Owner

FGK Transport INC.

Address

City

Province

Postal Code

Phone

- ☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☒ Fail/Hazardous

Licence
Number

T1418161210

Prov. MB

NSC #

Odometer
ReadingOdom.
Type km ☐ mi ☐Vehicle Identification
Number

11U1YMS13151317616171212141112

Make

Utility

Model

Healer

Year

2006

Unit #

FGK303

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck

GVWR

KGS

Truck Tractor

Trailer

Semi-Trailer

Bus

School Bus

Coach Bus

List of options: Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	XX	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 13A) Both Gladhand Seals Broken 15(C) 3th AXLE Both Brake Shoes 2/32 15(E) 3th AXLE Both Brake Drum 16630 16(D) LRA Slack adjuster not working 15(F) LRA wheel Seal Leaking
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) 1(A) Right Side All marker lights not working
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X	X	Section 9 - Tire & Wheel: Defects (if any) 4(A) All Tire Air Pressure Lower than Recommended 1(B) RRA inner tire tread 2/32"
X		Section 10 - Coupling Devices: Defects (if any)

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	5/8	5/8	16560	16558	1 1/2	1 1/2
2	5/8	5/8	16535	16560	1 1/2	1 1/2
3	7/8	7/8	16500	16500	1 1/2	1 1/2
4						
5						
Final Measurement						

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	11	10	11	11	90	90	85	90
2	11	11	11	10	90	80	80	85
3	11	11	09	12	85	90	90	90
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
 This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: All Repair Done by Goldshine Truck and Trailer Repair Ltd