

04103190

INSPECTION CERTIFICATE

Manitoba



X03-2

Box 45064 Regent Postal Centre
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba



C091961

Date Inspection Started 3P 04 26 DAY MO YR	Station Number A16H54	Station Name NEON FREIGHT	City Winnipeg
Date Inspection Completed 3P 04 26 DAY MO YR	Mechanic Number M10P52	Mechanic Signature Satindehal	Station Phone Number 431-373-1673
Inspection Expiry Date 3P 04 27 DAY MO YR	Vehicle Owner Bugsy's TRANSPORT LTD.		
Address City Province Postal Code Phone			
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number TJ16H8P	Prov. MB	Nsc #
Vehicle Identification Number LUVV6PFBHPPPPR7	Make Ford	Model F100	Year 1988
☒ Confirmed legible Vehicle Identification Number on vehicle		Odometer Reading	Odom. Type km mi
Unit #		306 RT	

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 Truck GVWR 36000 KGS Truck Tractor X Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	X	Section 3 - Brake Systems: <u>3H 3A</u> Defects (if any) <u>Circle Brake Type</u> <u>1413 Axle 1 Left, 2 Right Brake</u> <u>Chamber Springs Broken</u> <u>15 All axle Brake Drum Limit</u> <u>Exceeds</u>
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) <u>1414 Right Side Middle Signal Inoperative</u>
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	10	7	9	8	100	100	100	100
2	7	10	10	9	100	100	100	100
3	15	15	9	6	100	100	100	100
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and