

X03-3



Commercial Vehicle Inspection Report

Decal Number: PY12642
Decal Expiry Date: 2026-Apr-30
Inspection Number: 21523054

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: Sluggett, Ryan / 202690
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual

INSP. START: 2025-Oct-06 08:00 AM MST
INSP. COMPLETE: 2025-Oct-06 08:45 AM MST

VEHICLE JUR: British Columbia
PLATE #: 80211U
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2005
MAKE: LOADLINE
MODEL: GED17

REGI: 12113599
UNIT/FLEET#: PT8
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2D9ED172751012338
OWNER/LESSEE NAME: H.F NODES CONSTRUCTION LT. .
ADDRESS: PO BOX 373
Pouce Coupe, British Columbia
V0C2C0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) Number two right Slack adjuster indicator pin, bushing missing
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	35	39
2	Clamp	30	Automatic	33	32
3	Clamp	30	Automatic	36	34

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
12	11	11	11	
14	15	11	9	
11	9	8	9	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	81	79
2	71	77
3	75	84

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	13	13
Lining (Shoe)	14	14
Lining (Shoe)	14	13

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: Sluggett, Ryan

Signature: 

This Inspection Report was submitted to CVSE on 2025-Oct-06 02:25 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE014

10/6/2025 2:25:04 PM MST