



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A318804

Station #: 71709

Station Name: Redhead Equipment

Technician #: 87734

Technician Name: Cale Boehm

Signing Officer #: 92422

Signing Officer Name: Kassey Kohl

Customer Details:

Name: Hillsvale Farming Co.Ltd

Address: P.O. Box 518, Cut Knife, Saskatchewan, S0M 0N0

Inspection Completed Date: 31Dec2025

Inspection Expiry Date: 31Dec2026

Vehicle Details:

VIN: 2A9LB3525NS037087

Hubometer Reading:

Year: 1992

Vehicle Make/Model: TRAILER/TRAILER

Plate:

Jurisdiction:

Unit: 7-357

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71709

Station Name: Redhead Equipment

Technician #: 87734

Technician Name: Cale Boehm

Signing Officer #: 92422

Signing Officer Name: Kassey Kohl

Customer Details:

Name: Hillsvale Farming Co.Ltd

Address: P.O. Box 518, Cut Knife, Saskatchewan, S0M 0N0

Vehicle Details:

VIN: 2A9LB3525NS037087

Hubometer Reading:

Year: 1992

Vehicle Make/Model: TRAILER TRAILER

Inspection Details:

| Pass | Rejected | Corrected | Req Attn | DRIVERS COMPARTMENT | Comments |
|------|----------|-----------|----------|------------------------------|----------|
| x | | | | Vehicle Identification (5) | |
| x | | | | Fire Extinguisher (5) | |
| x | | | | Auxiliary Controls/Equip (5) | |

| Pass | Rejected | Corrected | Req Attn | BODY EXTERIOR | Comments |
|------|----------|-----------|----------|-------------------------------|----------|
| x | | | | Lamps (6) | |
| x | | | | Reflex Reflectors (6) | |
| x | | | | Retro Reflective Markings (6) | |
| x | | | | Trailer Hitch (10) | |
| x | | | | Attached Equipment (8) | |
| x | | | | Cargo Bodies/Vessels (8) | |
| x | | | | Mud Flaps/Fenders (8) | |
| x | | | | Landing Gear (8) | |
| x | | | | Rear Impact Guard (8) | |
| x | | | | Trailer Power Cord (7) | |

| Pass | Rejected | Corrected | Req Attn | ENGINE COMPARTMENT | Comments |
|------|----------|-----------|----------|------------------------------|----------|
| x | | | | Fuel System (1) | |
| x | | | | Battery/Wiring Condition (7) | |

| Pass | Rejected | Corrected | Req Attn | CHASSIS | Comments |
|------|----------|-----------|----------|---|--|
| x | | | | Hyd Brake System/Components (3.1) | |
| | | x | | Air Brake System/Components (3.2) | MULTIPLE AIR LEAKS, AIR TANK HAS BEEN REMOVED AND NOT REPLACED, LF BRAKE CHAMBER PLUG CORRODED AND MISSING |
| x | | | | Elec Brake System/Components (3.1) | |
| x | | | | Wheel Bearings (9) | |
| | | x | | Tires/Wheels (9) | RF INSIDE AND OUTSIDE, LR INSIDE, RR TIRES WEATHER DEGREDATION BEYOND 3MM OF DEPTH |
| x | | | | Self-Steering Axle (2&4) | |
| x | | | | Frame/Crossmembers/Mounts (8) | |
| | | x | | Suspension/Axles (2) | AIRBAG TOP PLATES RUST JACKED BETWEEN PLATE AND FRAME AS WELL AS BETWEEN AIRBAG TOP MOUNT AND PLATE |
| x | | | | Exhaust/Emission System (1) | |
| x | | | | Sliding Axle Assembly (if equipped) (8) | |

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 14 mm

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 19 mm • Brake Drum/Rotor: 16.505 in • Brake Stroke: 41 mm

Wheel3-Off : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 19 mm • Brake Drum/Rotor: 16.504 in • Brake Stroke: 40 mm

Wheel4 : Tire Tread Depth: 14 mm

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 14 mm

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 19 mm • Brake Drum/Rotor: 16.504 in • Brake Stroke: 41 mm

Wheel3-Off : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 19 mm • Brake Drum/Rotor: 16.506 in • Brake Stroke: 40 mm

Wheel4 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

| | | |
|----------------------------------|-----------------|--------------------------------------|
| PASS - vehicle passes inspection | Decal # A318804 | Inspection Completed Date: 31Dec2025 |
|----------------------------------|-----------------|--------------------------------------|

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.