



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

03 - MELBOURNE

Date

28/08/2024

Time

13:52:58 (O)

Page

1

Account No.

9100015

Phone No.

136135

Rev/Quote No. 04

005380

Ship Via

EP

ABN

Purchase Order

WORK ORDER

ACN

Salesperson

TR4

ESTIMATE EXPIRY DATE: 25/09/2024

SERVICE ESTIMATE

1DW844KXTCD642583

**THE BELOW PARTS WILL INCUR FREIGHT CHARGES, TOTAL MAY EXCEED \$2,000.

**PARTS SUBJECT TO AVAILABILITY - IN ACCEPTING REPAIRS, THERE MAY BE WAITING TIMES FOR PARTS ASSOCIATED.

**LABOUR SUBJECT TO BEST ESTIMATE.

***** Segment 01 *****

Stock #: C000321 844K 4WD LOADER

MS #: 1DW844KXTCD642583

Make: JD Model: 844K

Is to have the following work done

STEER CYLINDER LEAKING

NOTES:_____

**STEER CYLINDER PINS AND BUSHES NOTE PARTS ONLY

**This is a rough estimate, pins could be rusted or tight leading to requirements for more labour.

Part#	Description	Qty	Price	Amount
AT467984	Pin	2	683.70	1367.40
H180084	BUSHING	4	162.38	649.52
T157275	SEAL	8	26.66	213.28
T209869	Bushing	1	318.95	318.95
AT202860	Pin	1	1385.96	1385.96

Parts: 3935.11

Labour: 1750.00

Subtotal: 5685.11

Authorization: _____

Name: RDO Equipment Pty Ltd

BSB: 014-657

Acc: 7754 77613

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

03 - MELBOURNE

Date

28/08/2024

Time

13:52:58 (O)

Page

2

Account No.

9100015

Phone No.

136135

Rev/Quote No. 04

005380

Ship Via

EP

ABN

Purchase Order

WORK ORDER

ACN

Salesperson

TR4

ESTIMATE EXPIRY DATE: 25/09/2024

SERVICE ESTIMATE

***** Segment 02 *****

STEP LADDER BROKEN - REPLACE

NOTES:_____

**STEP LADDER BROKEN - REPLACE

**Please see comments in email.

Part#	Description	Qty	Price	Amount
AT372070	Step	1	6368.22	6368.22

Parts:	6368.22
Labour:	525.00
Subtotal:	6893.22

Authorization: _____

***** Segment 03 *****

REAR LHS MUD GUARD REPLACEMENT

NOTES:_____

**REAR LHS MUD GUARD REPLACEMENT

**REAR LHS WHEEL GUARD REPLACEMENT

Part#	Description	Qty	Price	Amount
T330633	SPLASH GUARDS	1	297.29	297.29
T354149	Fender	1	939.19	939.19
AT449009	Bracket	1	934.24	934.24
AT321097	Hinge	1	2149.14	2149.14
AT321095	Support	1	2709.47	2709.47

Name: RDO Equipment Pty Ltd

BSB: 014-657

Acc: 7754 77613

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

03 - MELBOURNE

Date

28/08/2024

Time

13:52:58 (O)

Page

3

Account No.

9100015

Phone No.

136135

Rev/Quote No. 04

005380

Ship Via

EP

Purchase Order

WORK ORDER

ABN

ACN

Salesperson

TR4

ESTIMATE EXPIRY DATE: 25/09/2024

SERVICE ESTIMATE

Parts: 7029.33
Labour: 525.00
Subtotal: 7554.33

Authorization: _____

***** Segment 04 *****

CLEANING UP WIRING HARNESS

NOTES:_____

**CLEANING UP WIRING HARNESS

**Active EGR code needs to be investigated + calibration.

Labour: 612.50
Subtotal: 612.50

Authorization: _____

***** Segment 05 *****

REAR FAN COVER PANEL

NOTES:_____

**PRICE TO REPLACE.

**Please see email comments.

Part#	Description	Qty	Price	Amount
AT371147	Guard	1	4088.27	4088.27

Parts: 4088.27
Labour: 350.00
Subtotal: 4438.27

Authorization: _____

Name: RDO Equipment Pty Ltd

BSB: 014-657

Acc: 7754 77613

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

03 - MELBOURNE

Date

28/08/2024

Time

13:52:58 (O)

Page

4

Account No.

9100015

Phone No.

136135

Rev/Quote No. 04

005380

Ship Via

- EP

Purchase Order

WORK ORDER

ABN

ACN

Salesperson

TR4

ESTIMATE EXPIRY DATE: 25/09/2024

SERVICE ESTIMATE

***** Segment 06 *****

ROCKER ARM COVER GASKET W TIER 2 OR 3, R&R

NOTES:_____

*****ROCKER ARM COVER GASKET W TIER 2 OR 3, R&R (10-020-111)

**The O-ring is the rocker cover has been replaced
before and has a silicone on it

*REMOVE OLD GASKET AND INSTALL NEW GASKET

*VALVE ADJUSTMENTS AND CLEAN

Part#	Description	Qty	Price	Amount
DZ120103	Gasket Kit	1	379.35	379.35

Parts: 379.35

Labour: 700.00

Authorization: _____

Subtotal: 1079.35

***** Segment 07 *****

BUCKET PINS, R&R

NOTES:_____

*****BUCKET PINS, R&R (10-220-090).

**CAN ATTACH IMAGES IF REQUIRED ALSO.

Part#	Description	Qty	Price	Amount
T224915	WASHER	4	29.91	119.64
T223721	SHIM	12	34.44	413.28
AT415857	RING	4	70.36	281.44
AT341093	SEAL	4	338.08	1352.32

Name: RDO Equipment Pty Ltd

BSB: 014-657

Acc: 7754 77613

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

03 - MELBOURNE

Date

28/08/2024

Time

13:52:58 (O)

Page

5

Account No.

9100015

Phone No.

136135

Rev/Quote No. 04

005380

Ship Via

EP

Purchase Order

WORK ORDER

ABN

ACN

Salesperson

TR4

ESTIMATE EXPIRY DATE: 25/09/2024

SERVICE ESTIMATE

Part#	Description	Qty	Price	Amount
AT467524	Pin	2	1673.88	3347.76
AT469983	Pin	2	1929.35	3858.70
AT469983	Pin	2	1929.35	3858.70

Parts: 13231.84
Labour: 1750.00
Subtotal: 14981.84

Authorization: _____

***** Segment 08 *****

LHS JOYSTICK NOT OPERATIONAL - REPLACE

NOTES: _____

**LHS JOYSTICK NOT OPERATIONAL - REPLACE

**NO LABOUR - FULL DISCOUNT

Part#	Description	Qty	Price	Amount
AT365217	Electrohydrauli	1	5471.76	5471.76
	Electrohydraulic Controller			

Parts: 5471.76
Subtotal: 5471.76

Authorization: _____

***** Segment 09 *****

TRANSMISSION RECALIBRATION

NOTES: _____

**COMPLETE A TRANSMISSION RECALIBRATION.

**SEE IF ANY FAULT CODES COME UP ON THE MACHINE & WHETHER

Name: RDO Equipment Pty Ltd

BSB: 014-657

Acc: 7754 77613

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

03 - MELBOURNE

Date

28/08/2024

Time

13:52:58 (O)

Page

6

Account No.

9100015

Phone No.

136135

Rev/Quote No. 04

005380

Ship Via

- EP

Purchase Order

WORK ORDER

ABN

ACN

Salesperson

TR4

ESTIMATE EXPIRY DATE: 25/09/2024

SERVICE ESTIMATE

WE WILL NEED TO LOOK INTO THIS FURTHER.

Authorization: _____

Labour: 350.00
Subtotal: 350.00

Parts: 40503.88
Labour: 6562.50
Tax: 4706.64
TOTAL: 51773.02

Name: RDO Equipment Pty Ltd

BSB: 014-657

Acc: 7754 77613

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

03 - MELBOURNE

Date

15/10/2024

Time

11:43:05 (O)

Page

1

Account No.

9100015

Phone No.

136135

Rev/Quote No. 03

005613

Ship Via

EP

Purchase Order

WN1523

ABN

ACN

Salesperson

TBF

ESTIMATE EXPIRY DATE: 06/11/2024

SERVICE ESTIMATE

SOME PARTS SUBJECT TO AVAILABILITY EX USA, PLEASE NOTE WHEN
ACCEPTING QUOTE.

Stock #: X150600 LOADER

MS #: 1DW844KXECD642581

Make: JD Model: 844KII F

Is to have the following work done

CYLINDER, STEERING - R&I AND RECONDITION

NOTES:_____

Relieve hydraulic system pressure.

Disconnect hydraulic lines (cap & plug).

Remove pins from cylinder.

Remove cylinder from machine.

Disassemble cylinder.

Remove and replace worn parts.

Assemble in reverse order.

Check fluid level.

Test operations and check for leaks.

Part#	Description	Qty	Price	Amount
AT325850	Pin	2	502.39	1004.78
T444874	Shim	10	19.68	196.80
T215504	BUSHING	4	114.73	458.92
R521349	GASKET	1	4.49	4.49
A811045	O-Ring	1	5.86	5.86
R524335	V-Ring Seal	1	93.89	93.89
R524334	V-Ring Seal	1	145.45	145.45
RE527102	Seal	1	131.47	131.47
T157275	SEAL	4	26.91	107.64
H180084	BUSHING	2	163.93	327.86

Parts: 2477.16
Labour: 1750.00
Tax: 422.72

Name: RDO Equipment Pty Ltd

BSB: 014-657

Acc: 7754 77613

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

03 - MELBOURNE

Date

15/10/2024

Time

11:43:05 (O)

Page

2

Account No.

9100015

Phone No.

136135

Rev/Quote No. 03

005613

Ship Via

EP

ABN

Purchase Order

WN1523

ACN

Salesperson

TBF

ESTIMATE EXPIRY DATE: 06/11/2024

SERVICE ESTIMATE

Authorization: _____

TOTAL: 4649.88

Name: RDO Equipment Pty Ltd

BSB: 014-657

Acc: 7754 77613

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

28/08/24

Account No.

9100015

Ship Via

EP

ABN

Time

00:05:20 (B)

Phone No.

136135

Purchase Order

ACN

Page

01

Invoice No.

WN0794

Salesperson

LM8

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

SEGMENT# 1 C SP803 NA 10/05/24 14/05/24

Replace VCU

CORRECTION:_____

traveled to site waited to be escort me to machine
Checked parts that were supplied found that parts were not
right for job description
Talk to Simon that was looking after job
After talking to him decided to take a second look and
fault with machine
While looking at machine found found that machine will not
go in reverse when steering wheel tilted forward
Removed plastic trim to steering wheel column checked
wiring loom through steering column found loose connection
cleaned connections put column back together
test forward and revers while tilting column
did not fault
arm rest still faulting
16/5 date
-isolated battery
-unplugged vcu connections
-unbolted vcu
-installed new vcu
-programed vcu
armrest stil faulting this time i can see reading to
joystick steering on the ADU
checked powr from vcu to the joy stick found 24vpower and
earth the new vcu fixed the issue with power to the joy
stick
followed the diagnostic steo to the fault code 002129.09

CONTINUED ON PAGE 02

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
 415 Fitzgerald Road
 Derrimut VIC 3026
 Ph 03 8851 6200
 ABN: 58 060 286 759
 ACN: 060 286 759

Branch

MELBOURNE

Date

28/08/24

Account No.

9100015

Ship Via

EP

ABN

Time

00:05:20 (B)

Phone No.

136135

Purchase Order

ACN

Page

02

Invoice No.

WN0794

Salesperson

LM8

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321 844K 4WD LOADER		X 1DW844KXTCD642583		
844K		E RG6135L026651		
found the need to replace rhs joy stick				
AT393842	VEHICLE CONTROL	1 N	5400.97	5400.97
Vehicle Controller				
CRAT393842	Vehicle Control		412.00	412.00
FREIGHT	FREIGHT	2	39.06	78.12
19M9384	SCREW	2 N	3.82	7.64
			PARTS	5898.73
			LABOUR	1788.50
10401099	SEGMENT TOTAL==>			7687.23

SEGMENT# 2 C SP803 NA	10/05/24 10/05/24		
Replace motion controller			
CONDITION:_____			
motion controller not working when steering wheel tilted back			
CAUSE:_____			
loose connections			
CORRECTION:_____			
checked wiring through steering wheel column			
found loose connections cleaned and reconnected			
			LABOUR
			154.00
10401099	SEGMENT TOTAL==>		
			154.00

SEGMENT# 3 C SP803 STT-100	10/05/24 14/05/24		
TRAVEL, ROUND TRIP			
			LABOUR
			1114.75
10401099	SEGMENT TOTAL==>		
			1114.75

SEGMENT# 4 C SP803 NA	10/05/24 31/05/24		
BEACON NOT WORKING			

CONTINUED ON PAGE 03

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
 Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

28/08/24

Account No.

9100015

Ship Via

EP

ABN

Time

00:05:20 (B)

Phone No.

136135

Purchase Order

Page

03

Invoice No.

WN0794

Salesperson

LM8

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

CAUSE:_____

not selected on function enabled

CORRECTION:_____

activated beacon through monitor

NOTES:_____

Customer has supplied his own parts for the beacon - will
drop off to replace

10401099	LABOUR	3.50
	SEGMENT TOTAL==>	3.50

***** WORK ORDER TOTALS *****

PARTS	5898.73
LABOUR	3060.75
Consumables	114.86
SUB TOTAL==>	9074.34
GST	907.43
ON ACCOUNT	9981.77

Please remit to:

BSB: 014-657

Account: 7754 77613

Name: RDO Equipment Pty Ltd

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

02/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

01

Invoice No.

WN1772

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

SEGMENT# 1 C RG503 NA 29/08/24 29/08/24 06/09/24

STEER CYLINDER LEAKING

CONDITION:_____

Excessive movement in steering cylinder front pins

CAUSE:_____

general wear over time

CORRECTION:_____

Steering cylinder pins and bushes excess play (front)

removed old worn pin with pry bar

used oxy and wet rag to expand cylinder and shrink bush

used copper hammer and socket to hit out old bush

used power pack to press in new bush

slid new pin into position

shimmed excess gap

repeated on opposite side

NOTES:_____

*****STEER CYLINDER PINS AND BUSHES NOTE PARTS ONLY

**This is a rough estimate, pins could be rusted or tight
leading to requirements for more labour.

AT202860	Pin	1 N	1385.96	1385.96
AT467984	Pin	2 N	683.70	1367.40
FREIGHT	FREIGHT	5	46.32	231.58
H180084	BUSHING	2 N	162.38	324.76
T157275	SEAL	4 N	26.66	106.64
T209869	Bushing	1 N	318.95	318.95
	PARTS			3735.29
	LABOUR			1750.00

CONTINUED ON PAGE 02

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

02/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

02

Invoice No.


WN1772

Salesperson

TBF

Ship to: SAME AS BELOW

Invoice to:



WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		
10301003		SEGMENT TOTAL==>		5485.29

SEGMENT# 2 C RG503 NA 29/08/24 18/09/24 06/09/24
CLEANING UP WIRING HARNESS

**CLEANING UP WIRING HARNESS
**Active EGR code needs to be investigated + calibration.

	LABOUR	1050.00
10301003	SEGMENT TOTAL==>	1050.00

SEGMENT# 3 C RG503 10-020-111 29/08/24 29/08/24 06/09/24

ROCKER ARM COVER GASKET W TIER 2 OR 3, R&R
CONDITION:_____

**ROCKER ARM COVER GASKET W TIER 2 OR 3, R&R (10-020-111)
**The O-ring is the rocker cover has been replaced
before and has a silicone on it
*REMOVE OLD GASKET AND INSTALL NEW GASKET
*VALVE ADJUSTMENTS AND CLEAN

CAUSE:_____
rocket cover gasket worn
valve lash and injector preload needs attention
CORRECTION:_____

Remove engine top cover with crane
Remove coolant hose
Remove EGR cooling pipe covering engine
Remove air cleaner and intake hose
Remove muffler and exhaust pipe to turbo

CONTINUED ON PAGE 03

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

02/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

03

Invoice No.

WN1772

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

Remove muffler engine mounts
Remove rocker cover isolators and bolts
Remove loom covering rocker cover
Remove rocker cover
Book out Deere special tooling and parts
* Follow procedure for valve clearance and injector preload
as per service advisor including turning engine over to 6
different locations to set valve clearance and injector
preload*
*Clean old gasket material from block and rocker cover
gasket*
Clean rocker cover gasket in parts washer
Follow DTAC solution for updated gasket and isolators
Bolt and torque rocker cover in place
Re-attach all removed items

NOTES:_____

**ROCKER ARM COVER GASKET W TIER 2 OR 3, R&R (10-020-111)
**The O-ring is the rocker cover has been replaced
before and has a silicone on it
*REMOVE OLD GASKET AND INSTALL NEW GASKET
*VALVE ADJUSTMENTS AND CLEAN

DZ120103	Gasket Kit	1	379.35	379.35
JDG1333	FEELER GAUGE	1	.01	.01
JDG820	TURNING TOOL	1	.02	.02
	PARTS			379.38
	LABOUR			1400.00
10301003	SEGMENT TOTAL==>			1779.38

CONTINUED ON PAGE 04

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

02/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

04

Invoice No.

WN1772

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet HRS PIN/EIN WARRANTY DATE HRS
C000321 844K 4WD LOADER X 1DW844KXTCD642583

844K E RG6135L026651

SEGMENT# 4 C RG503 10-220-090 29/08/24 29/08/24 06/09/24

BUCKET PINS, R&R

CONDITION:_____

Bucket pins and bushed to be replaced

CAUSE:_____

Customer request

CORRECTION:_____

Removed bucket

Cleaned all mating surfaces on bucket and loader arms with
needler and wire wheel

inserted old pins into bucket separately

Measured free play

Inserted old pins into loader

measured free play

Free play insignificant and recommended to customer to not
proceed

Measured bucket mating area and loader mating area

Ordered shims as per needed to make up for excess lateral
movement

Reinstalled old pins and added shims

NOTES:_____

**BUCKET PINS, R&R (10-220-090).

**CAN ATTACH IMAGES IF REQUIRED ALSO.

AT341093	SEAL	4 N	338.08	1352.32
AT415857	RING	4 N	70.36	281.44
AT467524	Pin	2 N	1673.88	3347.76
AT469983	Pin	4 N	1929.35	7717.40
FREIGHT	FREIGHT	3	859.70	2579.11

CONTINUED ON PAGE 05

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

02/10/24

Account No.

9100015

Ship Via

- EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

05

Invoice No.

WN1772

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER		X 1DW844KXTCD642583		
	844K		E RG6135L026651		
T223721	SHIM	11	N	34.44	378.84
T224915	WASHER	4	N	29.91	119.64
				PARTS	15776.51
				LABOUR	1750.00
10301003			SEGMENT TOTAL==>		17526.51

SEGMENT# 5 C RG503 NA 29/08/24 29/08/24 06/09/24

LHS JOYSTICK NOT OPERATIONAL - REPLACE

CONDITION:_____

*LHS Joystick Not Operational.

CAUSE:_____

*Communication Fault.

CORRECTION:_____

*Left hand joystick replaced and still not working.

*Connected machine to service advisor via EDL.

*Searched fault codes on service advisor for further details of the problem.

*Ran through joystick steering fault diagnostic procedure.

*Power, ground, can H/can L to joystick all ok.

*Power. ground, can H/can L to controller all ok.

*VCU is having communication errors.

NOTES:_____

**LHS JOYSTICK NOT OPERATIONAL - REPLACE

CONTINUED ON PAGE 06

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

02/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

06

Invoice No.

WN1772

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		
**NO LABOUR - FULL DISCOUNT				

AT467524	Pin	2-	1690.14	3380.28-
CP6938	ISO 68 HYD 20L	1	152.35	152.35
FREIGHT	FREIGHT	2	31.42	62.84
OIL707.82	EP GREASE	2	11.22	22.44
SHIM110-180-3	110-180-3MM	14 N	18.90	264.60
SHIM60-105-1	60-105-1MM SHIM	5 N	5.71	28.55
SHIM60-105-1.6	60-105-1.6MM	4 N	7.14	28.56
SHIM60-105-1B	ID 60 1MM	20 N	4.29	85.80
SHIM60-105-3	ID 60 3MM SHIM	5 N	10.00	50.00
SHIM90-160-1.6	SHIM90-160-1.6	2	9.29	18.58
SHIM90-160-3	90MM ID x 3MM	2	11.50	23.00
T209869	Bushing	1-	321.99	321.99-
T223725	Shim	6 N	53.85	323.10
T224839	SHIM	8 N	84.46	675.68
T352828	SEAL	4	46.97	187.88
			PARTS	1778.89-
			LABOUR	1750.00
10301003		SEGMENT TOTAL==>		28.89-

SEGMENT# 6 C RG503 NA 29/08/24 16/09/24 06/09/24

TRANSMISSION RECALIBRATION

CONDITION:_____

Transmission extremely lagging and rough

CAUSE:_____

Transmission service and recalibration needed

CORRECTION:_____

Transmission warm up procedure followed as per service
advisor

CONTINUED ON PAGE 07

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

02/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

07

Invoice No.

WN1772

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

Engine Rpm raised

Recalibration procedure followed as per service advisor

NOTES:_____

*****Please note 9 hours from this segment needs to be moved to 1772-07*****

**COMPLETE A TRANSMISSION RECALIBRATION.

**SEE IF ANY FAULT CODES COME UP ON THE MACHINE & WHETHER WE WILL NEED TO LOOK INTO THIS FURTHER.

10301003	LABOUR	700.00
	SEGMENT TOTAL==>	700.00

SEGMENT# 7 C RG503 NA 29/08/24 03/09/24 06/09/24

CENTRE HITCH FAULT DIAGNOSIS

CAUSE:_____

Transmission slipping

Bad leak around transmission housing

CORRECTION:_____

CENTRE HITCH FAULT DIAGNOSIS / TESTING

Hydraulic system warm up procedure followed to achieve system operating temperature

belly plates removed for better visibility

Machine operated while inspection camera was inside machine

Hydraulic pump leaking near swash plate piston housing

Vacuum attached to hydraulic reservoir

Piston housing plate removed

O-Rings replaced

Belly plates washed and reinstalled

Hydraulic system no longer leaking

CONTINUED ON PAGE 08

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

02/10/24

Account No.

9100015

Ship Via

EP

ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

08

Invoice No.

WN1772

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet HRS PIN/EIN WARRANTY DATE HRS
C000321 844K 4WD LOADER X 1DW844KXTCD642583
844K E RG6135L026651

Hydraulic reservoir cleaned and inspected for leak

NOTES:_____

*Auto level fault

*Centre hitch

10301003 LABOUR 2100.00
SEGMENT TOTAL==> 2100.00

SEGMENT# 9 C RG503 NA 29/08/24 03/09/24 06/09/24

TRANSMISSION SLIPPING / CLUTCH RECALIBRATION

CORRECTION:_____

Diagnosis procedure for slipping transmission followed as
per service advisor

Transmission system pressure checked and in spec

Torque converter in pressure checked and in spec

Clutch plates K1,K2,K3,KV and KR checked and in spec

Clutch cut off and spin control features checked

Clutch cut off switch checked and found not in spec

Clutch cut off stuck 30% engaged at all times and causing
transmission to feel as if its slipping

Clutch cut off switch voltage adjusted

Transmission no longer slipping

10301003 LABOUR 1050.00
SEGMENT TOTAL==> 1050.00

SEGMENT#10 C RG503 NA 29/08/24 03/09/24 06/09/24

WASH MACHINE

*WASH MACHINE SO THAT LEAKS CAN BE CHECKED FOR.

*RUN UP AND GENERAL CHECK OVER

10301003 LABOUR 1750.00
SEGMENT TOTAL==> 1750.00

CONTINUED ON PAGE 09

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

02/10/24

Account No.

9100015

Ship Via

- EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

09

Invoice No.

WN1772

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

***** WORK ORDER TOTALS *****

PARTS	18112.29
LABOUR	13300.00
SUB TOTAL==>	31412.29
GST	3141.23
CREDIT CARD	34553.52

Please remit to:
BSB: 014-657
Account: 7754 77613
Name: RDO Equipment Pty Ltd

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

04/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

01

Invoice No.

WN2097

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

SEGMENT# 1 C RG503 NA 04/10/24 29/08/24 06/09/24

STEER CYLINDER LEAKING

CONDITION:_____

Excessive movement in steering cylinder front pins

CAUSE:_____

general wear over time

CORRECTION:_____

Steering cylinder pins and bushes excess play (front)

removed old worn pin with pry bar

used oxy and wet rag to expand cylinder and shrink bush

used copper hammer and socket to hit out old bush

used power pack to press in new bush

slid new pin into position

shimmed excess gap

repeated on opposite side

NOTES:_____

*****STEER CYLINDER PINS AND BUSHES NOTE PARTS ONLY

**This is a rough estimate, pins could be rusted or tight
leading to requirements for more labour.

AT202860	Pin	1 N	1399.41	1399.41
AT467984	Pin	2 N	690.21	1380.42
FREIGHT	FREIGHT	5	46.32	231.58
H180084	BUSHING	2 N	163.93	327.86
T157275	SEAL	4 N	26.91	107.64
T209869	Bushing	1 N	321.99	321.99
	PARTS			3768.90
	LABOUR			1750.00

CONTINUED ON PAGE 02

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

04/10/24

Account No.

9100015

Ship Via

- EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

02

Invoice No.

WN2097

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER		X 1DW844KXTCD642583		
	844K		E RG6135L026651		
10401099			SEGMENT TOTAL==>		5518.90

SEGMENT# 2 C RG503 NA 04/10/24 18/09/24 06/09/24
CLEANING UP WIRING HARNESS

**CLEANING UP WIRING HARNESS

**Active EGR code needs to be investigated + calibration.

	LABOUR	1050.00
10401099	SEGMENT TOTAL==>	1050.00

SEGMENT# 3 C RG503 10-020-111 04/10/24 29/08/24 06/09/24

ROCKER ARM COVER GASKET W TIER 2 OR 3, R&R

CONDITION:_____

**ROCKER ARM COVER GASKET W TIER 2 OR 3, R&R (10-020-111)

**The O-ring is the rocker cover has been replaced
before and has a silicone on it

*REMOVE OLD GASKET AND INSTALL NEW GASKET

*VALVE ADJUSTMENTS AND CLEAN

CAUSE:_____

rocket cover gasket worn

valve lash and injector preload needs attention

CORRECTION:_____

Remove engine top cover with crane

Remove coolant hose

Remove EGR cooling pipe covering engine

Remove air cleaner and intake hose

Remove muffler and exhaust pipe to turbo

CONTINUED ON PAGE 03

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

04/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

03

Invoice No.

WN2097

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

Remove muffler engine mounts

Remove rocker cover isolators and bolts

Remove loom covering rocker cover

Remove rocker cover

Book out Deere special tooling and parts

* Follow procedure for valve clearance and injector preload
as per service advisor including turning engine over to 6
different locations to set valve clearance and injector
preload*

*Clean old gasket material from block and rocker cover
gasket*

Clean rocker cover gasket in parts washer

Follow DTAC solution for updated gasket and isolators

Bolt and torque rocker cover in place

Re-attach all removed items

NOTES:_____

**ROCKER ARM COVER GASKET W TIER 2 OR 3, R&R (10-020-111)

**The O-ring is the rocker cover has been replaced
before and has a silicone on it

*REMOVE OLD GASKET AND INSTALL NEW GASKET

*VALVE ADJUSTMENTS AND CLEAN

DZ120103	Gasket Kit	1	382.97	382.97
JDG1333	FEELER GAUGE	1	.01	.01
JDG820	TURNING TOOL	1	.02	.02
	PARTS			383.00
	LABOUR			1400.00
10401099	SEGMENT TOTAL==>			1783.00

CONTINUED ON PAGE 04

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

04/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

04

Invoice No.

WN2097

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet HRS PIN/EIN WARRANTY DATE HRS
C000321 844K 4WD LOADER X 1DW844KXTCD642583

844K E RG6135L026651

SEGMENT# 4 C RG503 10-220-090 04/10/24 29/08/24 06/09/24

BUCKET PINS, R&R

CONDITION:_____

Bucket pins and bushed to be replaced

CAUSE:_____

Customer request

CORRECTION:_____

Removed bucket

Cleaned all mating surfaces on bucket and loader arms with
needler and wire wheel

inserted old pins into bucket separately

Measured free play

Inserted old pins into loader

measured free play

Free play insignificant and recommended to customer to not
proceed

Measured bucket mating area and loader mating area

Ordered shims as per needed to make up for excess lateral
movement

Reinstalled old pins and added shims

NOTES:_____

**BUCKET PINS, R&R (10-220-090).

**CAN ATTACH IMAGES IF REQUIRED ALSO.

AT341093	SEAL	4 N	341.30	1365.20
AT415857	RING	4 N	71.03	284.12
AT467524	Pin	2 N	1690.14	3380.28
AT469983	Pin	4 N	1948.09	7792.36
FREIGHT	FREIGHT	3	859.70	2579.11

CONTINUED ON PAGE 05

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

04/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

05

Invoice No.

WN2097

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER		X 1DW844KXTCD642583		
	844K		E RG6135L026651		
T223721	SHIM	11	N	34.77	382.47
T224915	WASHER	4	N	30.20	120.80
				PARTS	15904.34
				LABOUR	1750.00
10401099			SEGMENT TOTAL==>		17654.34

SEGMENT# 5 C RG503 NA 04/10/24 29/08/24 06/09/24

LHS JOYSTICK NOT OPERATIONAL - REPLACE

CONDITION:_____

*LHS Joystick Not Operational.

CAUSE:_____

*Communication Fault.

CORRECTION:_____

*Left hand joystick replaced and still not working.

*Connected machine to service advisor via EDL.

*Searched fault codes on service advisor for further details of the problem.

*Ran through joystick steering fault diagnostic procedure.

*Power, ground, can H/can L to joystick all ok.

*Power, ground, can H/can L to controller all ok.

*VCU is having communication errors.

NOTES:_____

**LHS JOYSTICK NOT OPERATIONAL - REPLACE

CONTINUED ON PAGE 06

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

04/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

06

Invoice No.

WN2097

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER		X 1DW844KXTCD642583		
	844K		E RG6135L026651		
**NO LABOUR - FULL DISCOUNT					

AT467524	Pin	2-	1690.14		3380.28-
CP6938	ISO 68 HYD 20L	1	152.35		152.35
FREIGHT	FREIGHT	2	31.42		62.84
OIL707.82	EP GREASE	2	11.22		22.44
SHIM110-180-3	110-180-3MM	14 N	18.90		264.60
SHIM60-105-1	60-105-1MM SHIM	5 N	5.71		28.55
SHIM60-105-1.6	60-105-1.6MM	4 N	7.14		28.56
SHIM60-105-1B	ID 60 1MM	20 N	4.29		85.80
SHIM60-105-3	ID 60 3MM SHIM	5 N	10.00		50.00
SHIM90-160-1.6	SHIM90-160-1.6	2	9.29		18.58
SHIM90-160-3	90MM ID x 3MM	2	11.50		23.00
T209869	Bushing	1-	321.99		321.99-
T223725	Shim	6 N	53.85		323.10
T224839	SHIM	8 N	84.46		675.68
T352828	SEAL	4	46.97		187.88
			PARTS		1778.89-
			LABOUR		1750.00
10401099			SEGMENT TOTAL==>		28.89-

SEGMENT# 6 C RG503 NA 04/10/24 16/09/24 06/09/24

TRANSMISSION RECALIBRATION

CONDITION:_____

Transmission extremely lagging and rough

CAUSE:_____

Transmission service and recalibration needed

CORRECTION:_____

Transmission warm up procedure followed as per service
advisor

CONTINUED ON PAGE 07

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

04/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

07

Invoice No.

WN2097

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

Engine Rpm raised

Recalibration procedure followed as per service advisor

NOTES:_____

*****Please note 9 hours from this segment needs to be moved to 1772-07*****

**COMPLETE A TRANSMISSION RECALIBRATION.

**SEE IF ANY FAULT CODES COME UP ON THE MACHINE & WHETHER WE WILL NEED TO LOOK INTO THIS FURTHER.

10401099	LABOUR	700.00
	SEGMENT TOTAL==>	700.00

SEGMENT# 7 C RG503 NA 04/10/24 03/09/24 06/09/24

CENTRE HITCH FAULT DIAGNOSIS

CAUSE:_____

Transmission slipping

Bad leak around transmission housing

CORRECTION:_____

CENTRE HITCH FAULT DIAGNOSIS / TESTING

Hydraulic system warm up procedure followed to achieve system operating temperature

belly plates removed for better visibility

Machine operated while inspection camera was inside machine

Hydraulic pump leaking near swash plate piston housing

Vacuum attached to hydraulic reservoir

Piston housing plate removed

O-Rings replaced

Belly plates washed and reinstalled

Hydraulic system no longer leaking

CONTINUED ON PAGE 08

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

04/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

08

Invoice No.

WN2097

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet HRS PIN/EIN WARRANTY DATE HRS
C000321 844K 4WD LOADER X 1DW844KXTCD642583
844K E RG6135L026651

Hydraulic reservoir cleaned and inspected for leak

NOTES:_____

- *Auto level fault
- *Centre hitch

10401099 LABOUR 2100.00
SEGMENT TOTAL==> 2100.00

SEGMENT# 8 C PEND DELETED 04/10/24 29/08/24 06/09/24
WELDING - QUOTE

SEGMENT# 9 C RG503 NA 04/10/24 03/09/24 06/09/24

TRANSMISSION SLIPPING / CLUTCH RECALIBRATION

CORRECTION:_____

Diagnosis procedure for slipping transmission followed as
per service advisor

Transmission system pressure checked and in spec

Torque converter in pressure checked and in spec

Clutch plates K1,K2,K3,KV and KR checked and in spec

Clutch cut off and spin control features checked

Clutch cut off switch checked and found not in spec

Clutch cut off stuck 30% engaged at all times and causing
transmission to feel as if its slipping

Clutch cut off switch voltage adjusted

Transmission no longer slipping

10401099 LABOUR 1050.00
SEGMENT TOTAL==> 1050.00

SEGMENT#10 C RG503 NA 04/10/24 03/09/24 06/09/24

WASH MACHINE

*WASH MACHINE SO THAT LEAKS CAN BE CHECKED FOR.

CONTINUED ON PAGE 09

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

04/10/24

Account No.

9100015

Ship Via

EP

ABN

Time

00:05:18 (B)

Phone No.

136135

Purchase Order

101970

ACN

Page

09

Invoice No.

WN2097

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet

C000321 844K 4WD LOADER
844K

HRS PIN/EIN

X 1DW844KXTCD642583
E RG6135L026651

WARRANTY DATE

HRS

*RUN UP AND GENERAL CHECK OVER

LABOUR

1750.00

10401099

SEGMENT TOTAL==>

1750.00

***** WORK ORDER TOTALS *****

PARTS

18277.35

LABOUR

13300.00

SUB TOTAL==>

31577.35

GST

3157.74

ON ACCOUNT

34735.09

Please remit to:

BSB: 014-657

Account: 7754 77613

Name: RDO Equipment Pty Ltd

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

15/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:23 (B)

Phone No.

136135

Purchase Order

PO# 101970

ACN

Page

01

Invoice No.

WN2104

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

SEGMENT# 1 C RG503 NA 07/10/24 29/08/24 06/09/24

STEER CYLINDER LEAKING

CONDITION:_____

Excessive movement in steering cylinder front pins

CAUSE:_____

general wear over time

CORRECTION:_____

Steering cylinder pins and bushes excess play (front)

removed old worn pin with pry bar

used oxy and wet rag to expand cylinder and shrink bush

used copper hammer and socket to hit out old bush

used power pack to press in new bush

slid new pin into position

shimmed excess gap

repeated on opposite side

NOTES:_____

*****STEER CYLINDER PINS AND BUSHES NOTE PARTS ONLY

**This is a rough estimate, pins could be rusted or tight
leading to requirements for more labour.

AT467984	Pin	2 N	690.21	1380.42
FREIGHT	FREIGHT	6	44.76	268.58
H180084	BUSHING	2 N	163.93	327.86
T157275	SEAL	4 N	26.91	107.64
	PARTS			2084.50
	LABOUR			1750.00
10401099	SEGMENT TOTAL==>			3834.50

CONTINUED ON PAGE 02

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

15/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:23 (B)

Phone No.

136135

Purchase Order

PO# 101970

ACN

Page

02

Invoice No.


WN2104

Salesperson

TBF

Ship to: SAME AS BELOW

Invoice to:



WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321 844K 4WD LOADER		X 1DW844KXTCD642583		
844K		E RG6135L026651		
SEGMENT# 2 C RG503 NA	07/10/24	18/09/24	06/09/24	
CLEANING UP WIRING HARNESS				

**CLEANING UP WIRING HARNESS				
**Active EGR code needs to be investigated + calibration.				

10401099		LABOUR		1050.00
		SEGMENT TOTAL==>		1050.00

SEGMENT# 3 C RG503 10-020-111 07/10/24 29/08/24 06/09/24
ROCKER ARM COVER GASKET W TIER 2 OR 3, R&R
CONDITION:_____

**ROCKER ARM COVER GASKET W TIER 2 OR 3, R&R (10-020-111)
**The O-ring is the rocker cover has been replaced
before and has a silicone on it
*REMOVE OLD GASKET AND INSTALL NEW GASKET
*VALVE ADJUSTMENTS AND CLEAN

CAUSE:_____
rocket cover gasket worn
valve lash and injector preload needs attention
CORRECTION:_____

Remove engine top cover with crane
Remove coolant hose
Remove EGR cooling pipe covering engine
Remove air cleaner and intake hose
Remove muffler and exhaust pipe to turbo
Remove muffler engine mounts
Remove rocker cover isolators and bolts

CONTINUED ON PAGE 03

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

15/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:23 (B)

Phone No.

136135

Purchase Order

PO# 101970

ACN

Page

03

Invoice No.

WN2104

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

Remove loom covering rocker cover

Remove rocker cover

Book out Deere special tooling and parts

* Follow procedure for valve clearance and injector preload
as per service advisor including turning engine over to 6
different locations to set valve clearance and injector
preload*

*Clean old gasket material from block and rocker cover
gasket*

Clean rocker cover gasket in parts washer

Follow DTAC solution for updated gasket and isolators

Bolt and torque rocker cover in place

Re-attach all removed items

NOTES:_____

**ROCKER ARM COVER GASKET W TIER 2 OR 3, R&R (10-020-111)

**The O-ring is the rocker cover has been replaced
before and has a silicone on it

*REMOVE OLD GASKET AND INSTALL NEW GASKET

*VALVE ADJUSTMENTS AND CLEAN

DZ120103	Gasket Kit	1	382.97	382.97
JDG1333	FEELEER GAUGE	1	.01	.01
JDG820	TURNING TOOL	1	.02	.02
	PARTS			383.00
	LABOUR			1400.00
10401099	SEGMENT TOTAL==>			1783.00

SEGMENT# 4 C RG503 10-220-090 07/10/24 29/08/24 06/09/24

BUCKET PINS, R&R

CONTINUED ON PAGE 04

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

15/10/24

Account No.

9100015

Ship Via

- EP
ABN

Time

00:05:23 (B)

Phone No.

136135

Purchase Order

PO# 101970

ACN

Page

04

Invoice No.

WN2104

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

CONDITION:_____

Bucket pins and bushed to be replaced

CAUSE:_____

Customer request

CORRECTION:_____

Removed bucket

Cleaned all mating surfaces on bucket and loader arms with
needler and wire wheel

inserted old pins into bucket separately

Measured free play

Inserted old pins into loader

measured free play

Free play insignificant and recommended to customer to not
proceed

Measured bucket mating area and loader mating area

Ordered shims as per needed to make up for excess lateral
movement

Reinstalled old pins and added shims

NOTES:_____

**BUCKET PINS, R&R (10-220-090).

**CAN ATTACH IMAGES IF REQUIRED ALSO.

AT341093	SEAL	4 N	341.30	1365.20
AT415857	RING	4 N	71.03	284.12
T223721	SHIM	11 N	34.77	382.47
T224915	WASHER	4 N	30.20	120.80
	PARTS			2152.59
	LABOUR			1750.00
10401099	SEGMENT TOTAL==>			3902.59

CONTINUED ON PAGE 05

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

15/10/24

Account No.

9100015

Ship Via

- EP
ABN

Time

00:05:23 (B)

Phone No.

136135

Purchase Order

PO# 101970

ACN

Page

05

Invoice No.

WN2104

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

SEGMENT# 5 C RG503 NA 07/10/24 29/08/24 06/09/24

LHS JOYSTICK NOT OPERATIONAL - REPLACE

CONDITION:_____

*LHS Joystick Not Operational.

CAUSE:_____

*Communication Fault.

CORRECTION:_____

*Left hand joystick replaced and still not working.

*Connected machine to service advisor via EDL.

*Searched fault codes on service advisor for further details of the problem.

*Ran through joystick steering fault diagnostic procedure.

*Power, ground, can H/can L to joystick all ok.

*Power, ground, can H/can L to controller all ok.

*VCU is having communication errors.

NOTES:_____

**LHS JOYSTICK NOT OPERATIONAL - REPLACE

**NO LABOUR - FULL DISCOUNT

CP6938	ISO 68 HYD 20L	1	152.35	152.35
FREIGHT	FREIGHT	2	31.42	62.84
OIL707.82	EP GREASE	2	11.22	22.44

CONTINUED ON PAGE 06

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

15/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:23 (B)

Phone No.

136135

Purchase Order

PO# 101970

ACN

Page

06

Invoice No.

WN2104

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321 844K 4WD LOADER		X 1DW844KXTCD642583		
844K		E RG6135L026651		
SHIM110-180-3	110-180-3MM	14 N	18.90	264.60
SHIM60-105-1	60-105-1MM SHIM	5 N	5.71	28.55
SHIM60-105-1.6	60-105-1.6MM	4 N	7.14	28.56
SHIM60-105-1B	ID 60 1MM	20 N	4.29	85.80
SHIM60-105-3	ID 60 3MM SHIM	5 N	10.00	50.00
SHIM90-160-1.6	SHIM90-160-1.6	2	9.29	18.58
SHIM90-160-3	90MM ID x 3MM	2	11.50	23.00
T223725	Shim	6 N	53.85	323.10
T224839	SHIM	8 N	84.46	675.68
T352828	SEAL	4	46.97	187.88
			PARTS	1923.38
			LABOUR	1750.00
10401099		SEGMENT TOTAL==>		3673.38

SEGMENT# 6 C RG503 NA 07/10/24 16/09/24 06/09/24

TRANSMISSION RECALIBRATION

CONDITION:_____

Transmission extremely lagging and rough

CAUSE:_____

Transmission service and recalibration needed

CORRECTION:_____

Transmission warm up procedure followed as per service advisor

Engine Rpm raised

Recalibration procedure followed as per service advisor

NOTES:_____

*****Please note 9 hours from this segment needs to be moved to 1772-07*****

**COMPLETE A TRANSMISSION RECALIBRATION.

CONTINUED ON PAGE 07

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

15/10/24

Account No.

9100015

Ship Via

- EP
ABN

Time

00:05:23 (B)

Phone No.

136135

Purchase Order

PO# 101970

ACN

Page

07

Invoice No.

WN2104

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet	HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	X 1DW844KXTCD642583		
	844K	E RG6135L026651		

**SEE IF ANY FAULT CODES COME UP ON THE MACHINE & WHETHER
WE WILL NEED TO LOOK INTO THIS FURTHER.

10401099	LABOUR	700.00
	SEGMENT TOTAL==>	700.00

SEGMENT# 7 C RG503 NA 07/10/24 03/09/24 06/09/24

CENTRE HITCH FAULT DIAGNOSIS

CAUSE:_____

Transmission slipping

Bad leak around transmission housing

CORRECTION:_____

CENTRE HITCH FAULT DIAGNOSIS / TESTING

Hydraulic system warm up procedure followed to achieve
system operating temperature

belly plates removed for better visibility

Machine operated while inspection camera was inside machine

Hydraulic pump leaking near swash plate piston housing

Vacuum attached to hydraulic reservoir

Piston housing plate removed

O-Rings replaced

Belly plates washed and reinstalled

Hydraulic system no longer leaking

Hydraulic reservoir cleaned and inspected for leak

NOTES:_____

*Auto level fault

*Centre hitch

10401099	LABOUR	2100.00
	SEGMENT TOTAL==>	2100.00

CONTINUED ON PAGE 08

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

15/10/24

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:23 (B)

Phone No.

136135

Purchase Order

PO# 101970

ACN

Page

08

Invoice No.

WN2104

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet HRS PIN/EIN WARRANTY DATE HRS

C000321 844K 4WD LOADER X 1DW844KXTCD642583
844K E RG6135L026651

SEGMENT# 9 C RG503 NA 07/10/24 03/09/24 06/09/24

TRANSMISSION SLIPPING / CLUTCH RECALIBRATION

CORRECTION:_____

Diagnosis procedure for slipping transmission followed as
per service advisor

Transmission system pressure checked and in spec

Torque converter in pressure checked and in spec

Clutch plates K1,K2,K3,KV and KR checked and in spec

Clutch cut off and spin control features checked

Clutch cut off switch checked and found not in spec

Clutch cut off stuck 30% engaged at all times and causing
transmission to feel as if its slipping

Clutch cut off switch voltage adjusted

Transmission no longer slipping

LABOUR

1050.00

10401099

SEGMENT TOTAL==>

1050.00

SEGMENT#10 C RG503 NA 07/10/24 03/09/24 06/09/24

WASH MACHINE

*WASH MACHINE SO THAT LEAKS CAN BE CHECKED FOR.

*RUN UP AND GENERAL CHECK OVER

LABOUR

1750.00

10401099

SEGMENT TOTAL==>

1750.00

***** WORK ORDER TOTALS *****

PARTS 6543.47

LABOUR 13300.00

SUB TOTAL==> 19843.47

CONTINUED ON PAGE 09

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

15/10/24

Account No.

9100015

Ship Via

- EP

ABN

Time

00:05:23 (B)

Phone No.

136135

Purchase Order

PO# 101970

ACN

Page

09

Invoice No.

WN2104

Salesperson

TBF

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet

C000321 844K 4WD LOADER
844K

HRS PIN/EIN

X 1DW844KXTCD642583
E RG6135L026651

WARRANTY DATE

HRS

GST

1984.35

ON ACCOUNT

21827.82

Please remit to:

BSB: 014-657

Account: 7754 77613

Name: RDO Equipment Pty Ltd

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

29/04/25

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:34 (B)

Phone No.

136135

Purchase Order

106703

ACN

Page

01

Invoice No.


WN3263

Salesperson

KO2 / KO2

Ship to: SAME AS BELOW

Invoice to:



Attention: Darren Varcoe

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		

SEGMENT# 1 C SP803 10-030-090 12/02/25 21/02/25 20/02/25

AFTERCOOLERINTERCOOLER, R&R

CONDITION:_____

Intercooler has a crack top right hand side need replacing.

all intake hoses need to be checked for boost leaks

DIAGNOSTICS:_____

- removed top right hand side panel
- removed aftercooler intakes hoses
- unbolted aftercooler and removed
- installed new aftercooler
- reinstalled side panel

REPAIR:_____

Loosen top rail and slide cooler out right-hand side.

Remove hood and side panels.

Drain coolant.

Remove air inlet duct back to the air cleaner canister.

Detach oil cooler from radiator aftercooler.

Disconnect upper and lower radiator hoses.

Remove two bolts from bottom of front support.

Remove radiator.

Install in reverse order.

Refill system with recommended coolant.

NOTES:_____

intercooler has too many cracks to be repaired

FREIGHT	FREIGHT	5	51.00	255.00
SUBLET-CE	INTERCOOLER REP	1	6550.00	6550.00
	PARTS			255.00
	LABOUR			1137.50
	SUBLET			6550.00

CONTINUED ON PAGE 02

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Ship to: SAME AS BELOW

Date

29/04/25

Time

00:05:34 (B)

Page

02

Account No.

9100015

Phone No.

136135

Invoice No.

WN3263

Ship Via

EP

Purchase Order

106703

ABN

ACN

Invoice to:



Salesperson

KO2 / KO2

Attention: Darren Varcoe

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		
10301003			SEGMENT TOTAL==>		7942.50

SEGMENT# 2 C SP803 10-090-042 12/02/25 21/02/25 20/02/25

WIPER, R&R

CONDITION:_____

Front wiper blade damaged, all wipers need checking front one replaced.

DIAGNOSTICS:_____

-installed new front and rear wiper blades

-lubricated all door catches

-installed new gromets on door catch release handle

REPAIR:_____

R&R component.

AT173192	WASHER BOTTLE P	2	176.06	352.12
----------	-----------------	---	--------	--------

AT324681	WIPER BLADE	1	87.05	87.05
----------	-------------	---	-------	-------

AT478409	WIPER BLADE	1 N	34.00	34.00
----------	-------------	-----	-------	-------

PARTS	473.17
-------	--------

LABOUR	175.00
--------	--------

10301003	SEGMENT TOTAL==>	648.17
----------	------------------	--------

SEGMENT# 3 C SP803 NA 12/02/25 25/02/25 20/02/25

MUFFLER CRACKED REQUIRES WELDING

CONDITION:_____

Muffler cracked need welding.

DIAGNOSTICS:_____

-cleaned cracked area and welded crack

-reinstalled muffler with new mounting bolts

REPAIR:_____

Welded crack

LABOUR	700.00
--------	--------

CONTINUED ON PAGE 03

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

29/04/25

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:34 (B)

Phone No.

136135

Purchase Order

106703

ACN

Page

03

Invoice No.

WN3263

Salesperson

KO2 / KO2

Ship to: SAME AS BELOW

Invoice to:

Attention: Darren Varcoe

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		
10301003			SEGMENT TOTAL==>		700.00

SEGMENT# 4 C SP803 NA 12/02/25 26/02/25 20/02/25

MUFFLER BRACKET BOLTS REQUIRE REPLACEMENT

DIAGNOSTICS:_____

- removed top engine cover
- unbolted and removed muffler
- reinstalled muffler and new bolts

LABOUR

525.00

10301003

SEGMENT TOTAL==>

525.00

SEGMENT# 5 C SP803 NA 12/02/25 19/02/25 20/02/25

RESEAL EGR COOLANT PIPE

DIAGNOSTICS:_____

- checked codes
- ran an EGR clean test through service advisor rear EGR valve not working removed EGR vale found stuck open
- removed EGR valve
- cleaned gasket surface
- installed new EGR valve
- Completed EGR valve learn on service advisor
- drained coolant from radiator
- removed coolant pipes to EGR cooler
- installed new o rings
- reinstalled coolant pips
-

REPAIR:_____

EGR coolant pipe is weeping needs to be resealed.

EGR valve notworking

Removed EGR cooler pipes.

CONTINUED ON PAGE 04

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

29/04/25

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:34 (B)

Phone No.

136135

Purchase Order

106703

ACN

Page

04

Invoice No.

WN3263

Salesperson

KO2 / KO2

Ship to: SAME AS BELOW

Invoice to:

Attention: Darren Varcoe

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		
Cleaned up pipes and resealed.					
Oil return line on turbo had to be removed, gasket was in poor condition.					
replaced gasket and o ring for sump.					
CP8277	COOL-GARD 20L	1	133.40		133.40
DZ10556	CLAMP	1 N	130.18		130.18
DZ123152	Exhaust Gas Rec	1	927.18		927.18
	Exhaust Gas Recycling Valve				
FREIGHT	FREIGHT	2	10.50		21.00
RE572220	Clamp	2 N	25.74		51.48
R183409	O-RING	1	2.55		2.55
R28782	O'RING	2	3.00		6.00
R519398	GASKET	1	9.46		9.46
			PARTS		1281.25
			LABOUR		1050.00
10301003			SEGMENT TOTAL==>		2331.25

SEGMENT# 6 C SP803 NA	12/02/25 19/02/25 20/02/25	
WASH AND DETAIL		
DIAGNOSTICS:_____		
washed machine down		
clean dust out of cab		
cleaned windows		
	LABOUR	1400.00
10301003	SEGMENT TOTAL==>	1400.00

SEGMENT# 7 C SP803 10-070-310	12/02/25 25/02/25 20/02/25	
HYDRAULIC SYSTEM CLEANUP		
CONDITION:_____		
Replace all leaking and faulty hydraulic hoses and		

CONTINUED ON PAGE 05

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

29/04/25

Account No.

9100015

Ship Via

- EP
ABN

Time

00:05:34 (B)

Phone No.

136135

Purchase Order

106703

Page

05

Invoice No.

WN3263

Salesperson

KO2 / KO2

Ship to: SAME AS BELOW

Invoice to:



Attention: Darren Varcoe

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		

hydraulic pumps

DIAGNOSTICS:_____

- drained hydraulic oil
- disconnected all hydraulic hose to cab
- disconnected all electrical connections
- unbolted cab and removed
- disconnected all hoses to steer pump, secondary steer pump and main hydraulic pump
- removed all hydraulic pumps
- drained over full transmission oil
- picked up pumps from finer hydraulics
- installed new hydraulic main pump and reconnected

hydraulic hoses

- installed new steering pump and hydraulic hoses
- replaced damaged drain valve to transmission
- reinstalled operators station
- filled hydraulic tank with oil
- changed hydraulic filters
- cleaned all battery connection and reconnected battery
- replaced perished heater core hose joiners
- filled machine with coolant
- installed secondary steer pump
- filled transmission with oil
- reinstalled bucket
- warmed machine to operating temp
- calibrated transmission
- performed operational check out
- after testing machine checked all over for hydraulic leaks
- toped up hydraulic oil and transmission oil
- reinstalled belly plate and all guards

CONTINUED ON PAGE 06

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
 415 Fitzgerald Road
 Derrimut VIC 3026
 Ph 03 8851 6200
 ABN: 58 060 286 759
 ACN: 060 286 759

Branch

MELBOURNE

Date

29/04/25

Account No.

9100015

Ship Via

- EP
 ABN

Time

00:05:34 (B)

Phone No.

136135

Purchase Order

106703

Page

06

Invoice No.

WN3263

Salesperson


KO2 / KO2

Ship to: SAME AS BELOW

Invoice to:



Attention:



WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		
-removed dash column on steering wheel removed wiring loom to forward and revers lever repaired broken wire and reinstalled -replaced washer motors x2 for wiper blades					
REPAIR:_____					
Perform complete hydraulic system cleanup.					
AT307331	OIL FILTER	1	N	599.02	599.02
AT375802	Hydraulic Pump	RETAIL		29983.15	
		2	N	26209.04	52418.08
AT395348	ELBOW FITTING	1	N	14.19	14.19
AT396144	ELEC-HYD PROPOR	1	N	5676.87	5676.87
	Elec-Hyd Proportional Valve				
CPM287301	Sealant	1		29.41	29.41
CP1566	HY-Gard 20L	4		157.75	631.00
CP8239	HYDRAU 20L	5		187.05	935.25
CP8240	HYDRAU 205L	1		1747.73	1747.73
FREIGHT	FREIGHT	3		948.33	2845.00
L169406	GROMMET	3	N	8.51	25.53
R183412	O-RING	1	N	3.87	3.87
R519643	GASKET	2		19.31	38.62
R521349	GASKET	1		4.49	4.49
R548117	O-RING	1		7.58	7.58
R72328	O RING	1		3.34	3.34
SUBLET-CE	MAKE HOSES	1		4988.15	4988.15
SUBLET-CE	PARKER PUMP	1		1720.00	1720.00
SUBLET-CE	STRIPAND ASSESS	1		1380.00	1380.00
TY26632AU	Cleaning Solven	1		16.13	16.13
	ELECTRONIC CONTACT CLEANER				
T107883	O-RING	2		9.07	18.14
T160492	Fitting	2	N	32.60	65.20

CONTINUED ON PAGE 07

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
 Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
 415 Fitzgerald Road
 Derrimut VIC 3026
 Ph 03 8851 6200
 ABN: 58 060 286 759
 ACN: 060 286 759

Ship to: SAME AS BELOW

Branch
 MELBOURNE

Date	29/04/25	Time	00:05:34 (B)	Page	07
Account No.	9100015	Phone No.	136135	Invoice No.	WN3263
Ship Via	EP	Purchase Order	106703		
ABN		ACN			

Invoice to:



Salesperson
 KO2 / KO2

Attention:

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		
T174107	O-RING		1	29.91	29.91
T177737	O-RING		1 N	25.45	25.45
T76938	O RING		3	4.49	13.47
T77613	O RING		3	3.00	9.00
T77858	O RING		1	3.50	3.50
U12547	O RING		3	3.96	11.88
U13639	O RING		2 N	7.02	14.04
19M7789	SCREW		3	2.92	8.76
24M7180	WASHER		6 N	3.71	22.26
24M7338	WASHER		4	4.03	16.12
51M7067	O-RING		2 N	4.37	8.74
				PARTS	65242.58
				LABOUR	17500.00
				SUBLET	8088.15
10301003			SEGMENT TOTAL==>		90830.73

SEGMENT# 8 C SP803 NA 12/02/25 19/02/25 20/02/25

INSPECTION OF MACHINE

CONDITION:_____

-000977.05 Reversing Fan Solenoid Open or Short

-002033.09

Controller Area Network (CAN) Communication Lost For
 Vehicle Control Unit (VCU) -

-002378.05

Marker/Tail Lights Open CircuitVCUActive0

522411.05

1st FNR Open CircuitTCUStored4

523837.01

Brake Pressure LowRearVCUStored76

523840.01

CONTINUED ON PAGE 08

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
 Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

29/04/25

Account No.

9100015

Ship Via

- EP
ABN

Time

00:05:34 (B)

Phone No.

136135

Purchase Order

106703

ACN

Page

08

Invoice No.

WN3263

Salesperson

KO2 / KO2

Ship to: SAME AS BELOW

Invoice to:

Attention:

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		

Brake Pressure LowFrontVCUStored91
ECU 000641.13

VGT Actuator Learn ErrorECUStored

-engine misfire
-transmission wrong oil and filter needs changing
-park break not working
-JOYSTICK STEERING
needs new controller

DIAGNOSTICS:_____

-washed grease and oil off transmission area
-brake accumulators front and rear need replacing does not
hold gas
-leaking hoses under cab need repairing
-axle pump oring to aux drive on engine leaking needs
replacing
-hydraulic thermostat housing leaking need replacing
-ride control vale leaking needs new o rings
-all earth connections need cleaning when cab is removed
need to repair all fault with wiring
-can bus fault needs diagnosing
-turbocharger vgt solenoid noisy checked turbine found some
some play on bearing slightly grabs when turning buy hand
with side load-steering pressure sensor
-tail light marker not working needs replacing
-steering pressure sensor has oil inside plug
cleaned fault has not reappeared
-fan reversing solenoid not plugged in found wiring
connection full off dirt and rubbing on intake hose revers
solenoid full of dirt has been unplugged for a long time
PARK BRAKE NOT HOLDING

CONTINUED ON PAGE 09

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

29/04/25

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:34 (B)

Phone No.

136135

Purchase Order

106703

ACN

Page

09

Invoice No.

WN3263

Salesperson

KO2 / KO2

Ship to: SAME AS BELOW

Invoice to:

Attention:

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		

checked oil pressure oil pressure in spec
checked oil level no oil in park brake park brake smells
burnt
need disassembling further diagnose

REPAIR:_____

- washed oil and dirt off cab and transmission area 3hr
- Removed bucket from machine 1hr

	LABOUR	1750.00
10301003	SEGMENT TOTAL==>	1750.00

SEGMENT# 9 C AMJ03 NA 12/02/25 20/02/25 20/02/25

Degas AC

REPAIR:_____

machine de gassed as requested
mollies car also de gassed and re gassed. on this work
order.

- machine re gassed with 2.3kg of R134a as pec spec.
- machine vent temp. checked and found at 7 degrees.
- machine A/C system working as intended.

	LABOUR	525.00
10301003	SEGMENT TOTAL==>	525.00

SEGMENT#10 C SP803 NA 12/02/25 14/03/25 20/02/25

Remove belly plate

CONDITION:_____

remove belly plate

DIAGNOSTICS:_____

-removed belly plate
and reinstalled belly plate

	LABOUR	87.50
CONTINUED ON PAGE 10		

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

29/04/25

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:34 (B)

Phone No.

136135

Purchase Order

106703

ACN

Page

10

Invoice No.

WN3263

Salesperson

KO2 / KO2

Ship to: SAME AS BELOW

Invoice to:

Attention:

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		
10301003			SEGMENT TOTAL==>		87.50

SEGMENT#11 C SP803 NA	12/02/25	25/03/25	25/03/25		
Fit brake accumulators					
CONDITION:_____					
install new brake accumulators					
DIAGNOSTICS:_____					
-gassed both accumulators 375psi					
-removed old brake accumulators					
-installed new accumulators					
AT380265	Accumulator Kit	2 N	3842.50		7685.00
			PARTS		7685.00
			LABOUR		700.00
10301003			SEGMENT TOTAL==>		8385.00

SEGMENT#12 C SP803 NA	12/02/25	26/03/25	20/02/25		
Weld filter housing					
CONDITION:_____					
filter housing has fallen inside hydraulic tank the					
canister has cracks					
DIAGNOSTICS:_____					
-removed damaged canister from hydraulic tank					
-welded up all cracks					
-reinstalled canister					
REPAIR:_____					
welded cracks on housing					
NOTES:_____					
this is a temporary fix and filter housing must be replaced					
when canister falls in hydraulic tank there is no					
filtration causing damage to pumps and hydraulic system					

CONTINUED ON PAGE 11

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

29/04/25

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:34 (B)

Phone No.

136135

Purchase Order

106703

ACN

Page

11

Invoice No.

WN3263

Salesperson

KO2 / KO2

Ship to: SAME AS BELOW

Invoice to:



Attention:



WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS	
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583			
	844K		RG6135L026651			
				LABOUR		175.00
10301003				SEGMENT TOTAL==>		175.00
SEGMENT#13	C SP803 NA	12/02/25	27/03/25	28/03/25		
	Straighten battery box					
	DIAGNOSTICS:_____					
	-straighten battery box cover					
				LABOUR		175.00
10301003				SEGMENT TOTAL==>		175.00
SEGMENT#14	C SP803 NA	12/02/25	04/04/25	28/03/25		
	Transmission issue					
	CONDITION:_____					
	Drain and refill transmission flush contaminated oil out of system					
	DIAGNOSTICS:_____					
	removed hydraulic hose off trans cooler flushed					
	contaminated oil from torque convertor					
	changed oil filters					
	toped up trans oil					
	calibrated transmission					
AT335977	FILTER ELEMENT	2		372.15		744.30
AT400292	PLUG	1	N	139.22		139.22
AT468647	TRANSMISSION OI	2		128.43		256.86
A4730R	O-RING	2		3.84		7.68
				PARTS		1148.06
				LABOUR		350.00
10301003				SEGMENT TOTAL==>		1498.06
SEGMENT#15	C SP803 NA	12/02/25	16/04/25	22/04/25		

CONTINUED ON PAGE 12

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

29/04/25

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:34 (B)

Phone No.

136135

Purchase Order

106703

ACN

Page

12

Invoice No.

WN3263

Ship to: SAME AS BELOW

Invoice to:

Salesperson

KO2 / KO2

Attention:

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		

Park brake R/R

CONDITION:_____

park brake not holding needs replacing

DIAGNOSTICS:_____

-removed drive shaft to front axle and front of transmission

-removed hydraulic lines to park brake

-unbolted park brake and removed

-removed all fittings and drive shaft yokes from park brake and installed on new park brakes

-filled new park brake with oil

-installed park brake on machine

-reinstalled drive shafts with new bolts

-transmission

after machine sitting for the weekend found oil on ground coming from transmission suction screen cover and sump plug there has been a repair to the suction screen cover in the past found the cover has been glued in with RTV silicone and failed after removing cover to replace o ring found suction filter missing

the sump plug has been rounded off and needed to heat sump plug and remove with cold chisel

installed new trans drain plug

installed new trans suction filter and seal

-tested park brake

-rechecked for oil leaks

REPAIR:_____

replace park brake

AT330289	Brake	1 N	15134.78	15134.78
FREIGHT	FREIGHT	3	429.00	1287.00

CONTINUED ON PAGE 13

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

29/04/25

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:34 (B)

Phone No.

136135

Purchase Order

106703

ACN

Page

13

Invoice No.

WN3263

Salesperson

KO2 / KO2

Ship to: SAME AS BELOW

Invoice to:

Attention:

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	18500	1DW844KXTCD642583		
	844K		RG6135L026651		
N209756	Screw	4	N	16.41	65.64
OIL707.82	EP GREASE	2		11.22	22.44
RE507950	DRAIN VALVE	1		159.61	159.61
RE529871	ELBOW FITTING	1	N	20.15	20.15
R114105	SCREW	8	N	17.94	143.52
19M7789	SCREW	8	N	2.92	23.36
19M7790	SCREW, 12X35MM	6	N	4.62	27.72
				PARTS	16884.22
				LABOUR	2975.00
10301003				SEGMENT TOTAL==>	19859.22

***** WORK ORDER TOTALS *****

PARTS	92969.28
LABOUR	29225.00
SUBLET	14638.15
Consumables	500.00
Environmental	100.00
SUB TOTAL==>	137432.43
GST	13743.24
CREDIT CARD	151175.67

Please remit to:
BSB: 014-657
Account: 7754 77613
Name: RDO Equipment Pty Ltd

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Ship to: SAME AS BELOW

Date

15/08/25

Time

00:05:19 (B)

Page

01

Account No.

9100015

Phone No.

136135

Invoice No.

WN4198

Ship Via

- EP

ABN

Purchase Order

PO#

ACN

Invoice to:



Salesperson

TBF / TBF

Attention:



WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	19066	1DW844KXTCD642583		
	844K		RG6135L026651		

SEGMENT# 1 C AMJ03 N/A 04/06/25 05/06/25 12/06/25

Check ride accumulators

CONDITION:_____

- ride control not working

DIAGNOSTICS:_____

- machine inspected and fault confirmed ride control is not working.

- accumulator pressures checked and R/H found at 500psi in spec. L/H found at 350psi slightly below spec, L/H psi adjusted to spec.

- machine retested and ride control still not working.

- solenoids checked for power and earth and found to be working as intended.

- on/off 1 solenoid removed and inspected and found ok.

- on/off solenoid 2 removed and found to be bent and externally damaged, suspect solenoid is sticking restriction accumulator flow.

- recommend re charging accumulators and replacing solenoid.

- returned to site

- de gassed accumulators

- replaced solenoid

- re gassed accumulators to spec at 500psi

- tested machine and ride control is now working as intended

REPAIR:_____

- replace on off solenoid #2.

NOTES:_____

Please contact Paul Berry on 0429 864 845 for Workshop

CONTINUED ON PAGE 02

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd
415 Fitzgerald Road
Derrimut VIC 3026
Ph 03 8851 6200
ABN: 58 060 286 759
ACN: 060 286 759

Branch

MELBOURNE

Date

15/08/25

Account No.

9100015

Ship Via

EP
ABN

Time

00:05:19 (B)

Phone No.

136135

Purchase Order

PO#

ACN

Page

02

Invoice No.

WN4198

Salesperson


TBF / TBF

Ship to: SAME AS BELOW

Invoice to:



Attention:



WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
C000321	844K 4WD LOADER	19066	1DW844KXTCD642583		
	844K		RG6135L026651		
Operations, or Mario Tenaglia on 0439 332 936 for Workshop Management enquiries.					
AT429043	Flow Control Hy		1 N		
	Flow Control Hyd. Valve				
			PARTS		1041.49
			LABOUR		875.00
10401099			SEGMENT TOTAL==>		1916.49

***** WORK ORDER TOTALS *****

PARTS	1041.49
LABOUR	875.00
SUB TOTAL==>	1916.49
GST	191.65
ON ACCOUNT	2108.14

1

Please remit to:
BSB: 014-657
Account: 7754 77613
Name: RDO Equipment Pty Ltd

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard