

## Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number: GH34084 2025-Aug-31 21225904 Inspection Result:

SURREY INSPECTION & REPAIR / S4168 2025-Jan-25 12:00 PM PST INSP. START: INSP. TYPE: Complete FACILITY: INSP. COMPLETE: 2025-Feb-01 04:34 PM PST INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSPECTOR: SANGHA, NIRBHAI SINGH / 200739 WORK ORDER #: INSP. REASON: Semi-annual 2HSCEAPRX2C033471 VIN: 00850373 VEHICLE JUR: British Columbia REGI: MALHI GURNAM SINGH, MALHI UNIT/FLEET#: 788 OWNER/LESSEE NAME: PLATE #: RF6268 **GURNAM SINGH** ADDRESS: 11700 90 AVE BODY STYLE: Truck Tractor LICENCED GVW(kg): 47000 Delta, British Columbia 564260 KM ODOMETER: VEHICLE YEAR: V4C3H6, Canada HUB ODOMETER: INTERNATNA MAKE: BRAKE TYPE: Air MODEL: FUEL TYPE: Diesel

Passed Vehicle Identification (VIN) Passed Section 1 - Power Train Passed Section 2 - Suspension Passed Section 3 - Brake System Passed Section 3A - Air Brakes Section 3H - Hydraulic Brakes Not Applicable Passed Section 4 - Steering Section 5 - Instruments and Auxiliary Passed Equipment Passed Section 6 - Lamps Passed Section 7 - Electrical System Section 8 - Frame and Body Passed Section 9A - Tires Passed Section 9B - Wheels Passed Passed Section 10 - Coupling Devices Section 11 - Other Vehicle Components Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Air Brake Chamber Type, Size and Push Rod Stroke (mm)					fire fread Deptil (film)					
Axles	Туре	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	32	32	9			12	
2	Clamp	30L	Automatic	32	35	19	18	19	18	
3	Clamp	30L	Automatic	35	35	17	16	15	16	
Comment: D	UST COVERS	REMOVED				Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	85	85	Lining (Shoe)	13	13	Drum			
2	70	70	Lining (Shoe)	14	14	Drum			
3	50	40	Lining (Shoe)	16	17	Drum			
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor			

Inspection Comments:

Has this Vehicle been road tested?

Inspector: SANGHA, NIRBHAI SINGH

Road Test Date: Signature: Road Tester:

Thickness or Drum Diameter not measured.

This Inspection Report was submitted to CVSE on 2025-Feb-01 04:34 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement CVSE0014

2/1/2025 4:34:59 PM PST