

TRIM(WOHH.WOWH_MODEL)	WOWH_DESC	WOWH_ORDER_N	WOWH_INVOICE_DATE	WOWH_METER	Comments	Full Rep Code
P27-N-024	CATERPILLAR PS150C MULTIROLLER	253876	13/10/2025 0:00	5716	PREPARED FOR AUCTION., Completed by:Rory.Lyne@porterplant.com.auon:Oct 13, 2025, Completed by:Rory.Lyne@porterplant.com.auon:Oct 23, 2025	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C MULTIROLLER	247340	01/08/2025 0:00	5716	COMPLETED PLANT INSPECTION. LISTED REPAIRS REQUIRED., Completed by:Ronald.galdiano@porterplant.com.auon:Jun 05, 2025	PI - PLANT INSPECTION
P27-N-024	CATERPILLAR PS150C MULTIROLLER	232929	06/06/2024 0:00	5716	COMPLETED PREDELIVERY INSPECTION, Completed by: shaun.scanlan@porterplant.com.au on: Jun 07, 2024	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C MULTIROLLER	229900	01/04/2024 0:00	5676	REPLACED LOOSE HOSE CLAMPS TO A/C COOLER., RED FLUID WAS LEAKING FROM UNDER A/C. INSPECTED & FOUND HOSE CLAMP LOOSE ON A/C COOLER. REMOVED COVERS, & REPLACED HOSE CLAMPS. PRESSURE TESTED, OK. RAN UP & CHECKED AT HIGH IDLE, OK., Completed by:darcey.hales@porterplant.com.auon:Mar 28, 2024	MR - MECHANICAL REPAIR
P27-N-024	CATERPILLAR PS150C MULTIROLLER	229631	21/03/2024 0:00	5701	COMPLETED 5,700hr SERVICE. REPLACED ENGINE OIL & FILTER., REPLACED FIRE EXTINGUISHER. REPLACED BLOWN FUSE TO HORN., Completed by:darcey.hales@porterplant.com.auon:Mar 21, 2024	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C MULTIROLLER	223927	17/10/2023 0:00	5676	REPLACED SHROUD & RADIATOR., NB: PART OF OFF SEASON REPAIRS. SEE WO#218766 FOR ADDITIONAL PARTS & LABOUR.	MR - MECHANICAL REPAIR
P27-N-024	CATERPILLAR PS150C MULTIROLLER	218766	02/10/2023 0:00	5500	COMPLETED END OF SEASON REPAIRS., REPLACED FAULTY BATTERY ISOLATION SWITCH. REPLACED LEAKING RADIATOR & RADIATOR MOUNTS INCLUDING RUBBERS., REPLACED FAN HUB, FAN BELTS & WORN PULLIES. REPLACED FORWARD/REVERSE CABLE & ADJUSTED. REPAIRED DRIVERS, SEAT & REPLACED FAULTY ARM REST. REPLACED HOOD LINING WITH MARINE CARPET. RAN UP & TESTED, ALL OK. WASHED, INSIDE & OUT., Completed by:rick.havlicek@porterplant.com.auon:Oct 04, 2023, REPLACED DAMAGED (THROUGH WEAR & TEAR) ON ROLLER. TRAVELLED TO YARD & REPLACED HOSES. REMOVED HOSES, & MADE NEW & RESEALED FITTINGS. FITTED HOSES., PO#187568, RESEALED CAT ROLLER CYLINDER. DISMANTLED CYLINDER & FOUND FOR WAS BADLY DAMAGED (WORN). MACHINED NEW, ROD & ORDERED IN SEALS. CUT CLEVIS OFF & WELDED ONTO NEW ONE. CLEANED COMPONENTS & FITTED NEW SEALS., REASSEMBLED & TESTED, ALL OK., PO#188946	MR - MECHANICAL REPAIR
P27-N-024	CATERPILLAR PS150C MULTIROLLER	223404	02/10/2023 0:00	5676	COMPLETED 5,500hr SERVICE. REPLACED ENGINE OIL & FILTER., REPLACED FUEL, HYDRAULIC & TRANS & AIR FILTERS. REPLACED HYDRAULIC OIL. REPLACED COOLANT.	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C MULTIROLLER	223437	01/10/2023 0:00	5676	REPAIRED AIRCON, CHECK A/C, INSERT GAS & DYE & TEST., PO 190333 - WAL'S AUTO ELECTRICS	AC - AIR-CONDITION REPAIR
P27-N-024	CATERPILLAR PS150C MULTIROLLER	219527	30/08/2023 0:00	5676	REPLACED 2 DRIVE TYRES, 2 X 7.50R15 XLC TT MICHELIN, 2 X 7.00/7.50R15 TR75 (CTN-15) PREM TUBE, PO 186770 - BEAUREPAIRES WODONGA	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C MULTIROLLER	221830	25/08/2023 0:00	5676	REPAIRED & REINFORCED A/C MOUNTED BRACKETS, PO 189338 - WARNOCK WELDING	AC - AIR-CONDITION REPAIR
P27-N-024	CATERPILLAR PS150C MULTIROLLER	221594	16/08/2023 0:00	5676	S & F 2 X CUSTOM CUT 1/2 WINDSCREENS, PO 189058 - BEST FIT WINDSCREENS	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C MULTIROLLER	218015	01/06/2023 0:00	5676	REPLACED FLAT FRONT TYRE - POS 1, FITTED REPLACEMENT TYRE, PO 185381 - MIDLAND MACHINERY, REPLACED FLAT WORN TYRE - POS 1, 1 X 7.50R15 XLC TT MICHELIN & 1 X 7.00/7.50R15 TR75 (CTN-15) PREM TUBE, PO 185447 - BEAUREPAIRES WODONGA	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C MULTIROLLER	217603	20/05/2023 0:00	5500	REPLACED WORN TYRE WITH SPARE AT WORKSHOP., REPLACED STEER TYRE. REMOVED AXLE HOUSING TO REMOVE TYRE.	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C MULTIROLLER	216503	12/05/2023 0:00	5500	REPLACED 1X WORN TYRE, 1 X TYRE & 1 X 7.00/7.50R15 TR75 (CTN-15) PREM TUBE, PO 184674 - BEAUREPAIRES WODONGA	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C MULTIROLLER	216122	01/04/2023 0:00	5500	COMPLETED PREDELIVERY INSPECTION., PART MEANT TO BE ADDED TO WO#209618 AS PART OF NEW ROOF COVERINGS. ADDED TO WO#209628 IN ERROR.	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C MULTIROLLER	211132	09/03/2023 0:00	5392	WORK ORDER CANCELLED. NO LONGER IN AREA., MACHINE IS NO LONGER IN MECHANICS AREA. PART NO#119-7017 SOLENOID GIVEN TO MELBOURNE WORKSHOP	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C MULTIROLLER	213901	08/03/2023 0:00	5500	COMPLETED 500hr SERVICE. REPLACED ENGINE OIL & FILTER., REPLACED HYDRAULIC, FUEL & AIR FILTERS., REPAIRED DRIVERS DOOR LATCH. SWAPPED 2x REAR TYRES WITH SPARES.	PS - PLANNED SERVICE

P27-N-024	CATERPILLAR PS150C MULTIROLLER	211106	01/12/2022 0:00	5392 REPLACED 3x WORN TYRES., TRAVELLED TO SITE. CHECKED FLAT TYRE. FOUND RH INNER TYRE WAS FLAT DUE TO EXCESSIVE WEAR. ALSO, FOUND LH REAR INNER & CENTRE FRONT TYRES READY TO FAIL. ROTATED OUT REAR TYRES TO CENTRE, TO KEEP MACHINE WORKING., TRAVELLED TO SITE. REMOVED WHEELS FOR TYRE FITTER & REFITTED TO MACHINE WHEN TYRES REPLACED. ADJUSTED, SQUEALING FAN BELTS., REPLACED 3x TYRES & TUBES., PO#178188	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C MULTIROLLER	209618	21/10/2022 0:00	5392 COMPLETED PRE-DELIVERY INSPECTION. GREEN TAGGED., FITTED NEW FRONT WHEEL NUT INDICATORS. CUT OUT NEW ROOF COVERINGS. GLUED INTERIOR ROOF, MATERIAL & GLUED IN RH WINDOW SEAL BEHIND DOOR.	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C MULTIROLLER	208220	15/09/2022 0:00	5389 FITTED NEW SAFETY STICKERS AS PER CUSTOMER REQUIREMENTS., FITTED HYDRANT, E STOP & ISOLATOR STICKERS., POUND RD, DANDENONG STH, RIKKI 0439 698 739	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C MULTIROLLER	207934	09/09/2022 0:00	5389 COMPLETED PRE-DELIVERY INSPECTION. GREEN TAGGED., COMPLETED GENERAL INSPECTION. CLEANED OPERATORS STATION. GREASED UNIT., REPAIRED WIRING TO REAR BEACON LIGHT HANGING DOWN. REFITTED REAR WINDOW GLASS DUE TO SEAL, POPPED OUT & WINDOW LOOSE IN BODY WORK. REPLACED INNER & OUTER AIR FILTER., NB: ORGANISED NEW RH TYRE & RIM DUE TO DAMAGE.	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C MULTIROLLER	203599	21/06/2022 0:00	5303 Pre delivery,	-
P27-N-024	CATERPILLAR PS150C MULTIROLLER	204278	15/06/2022 0:00	5318 REPAIRED FAULTY REVERSE CAMERA & LOOSE WINDOW., RECEIVED A CALL FROM CUSTOMER & HAD ISSUES WITH LH LARGE WINDOW TRYING TO FALL OUT & ISSUES WITH REVERSE CAMERA., TRAVELLED TO SITE & LOCATED MACHINE. OPERATOR COMPLAINED THAT BUTTONS ON CAMERA NOT WORKING & VOLUME STUCK, ON HIGH CAUSING HORRIFIC NOISE WHILE OPERATING ROLLER. ATTEMPTED TO TURN DOWN BUT COULDN'T. THIS UNIT, SEEMED TO BE BRAND NEW. REMOVED MONITOR & PULLED APART. DISABLED SPEAKER & REMOUNTED MONITOR & TESTED, TO FIND ALL WORKING WELL & QUIET. SPOKE TO SUPERVISOR ABOUT DISABLING SPEAKER & THEY WERE MORE THAN HAPPY, AS THEY ARE ALWAYS ON MUTE ANYWAY., INSPECTED LHS WINDOW TO FIND FRONT HALF OF WINDOW HANGING OUT. REFITTED SEAL & WINDOW TO CAB. FOUND THAT, WINDOW SEAL WAS INCORRECT & TOO SMALL. UNSURE IF ITS POSSIBLE TO GET CORRECT ONE. CUSTOMER WILL REPORT, IF WINDOW BECOMES LOOSE AGAIN.	ER - ELECTRICAL REPAIR
P27-N-024	CATERPILLAR PS150C MULTIROLLER	202295	01/06/2022 0:00	5291 COMPLETED REPAIRS TO DAMAGED CABIN., CHECKED DAMAGED CABIN. CARRIED OUT REMOVAL & REPLACEMENT OF CABIN. CARRIED OUT REPAIR & MODIFICATIONS, TO NEW CABIN TO SUIT MACHINE & NEW MIN SPEC. CARRIED OUT REPAIR TO BROKEN BOLTS & DAMAGED CABIN MOUNTS., CARRIED OUT DEGAS & REGASSED A/C SYSTEM. REMOVED ALL GLASS & DOORS & REFITTED AFTER CABIN SWAP., REPLACED UHF & AM/FM RADIO. FITTED REVIEW CAMERA & SCREEN. CARRIED OUT REPAIR TO SEAT & SEAT PIVOT., CARRIED OUT REMOVAL & REPLACEMENT OF PK STICKERS & SAFETY LABELS. FITTED WHEEL NUT INDICATORS, FIRE, EXTINGUISHER. GENERAL INSPECTION AS TO MIN SPEC., GREEN TAGGED & COMPLETED PREDELIVERY INSPECTION. CLEANED UNIT. FITTED SIDE BEACON LAMPS SO MACHINE NOW, MEETS MIN SPECS., CUT 3x GLASS & FITTED TO MULTI ROLLER., PO#169660, NB: CUSTOMER HAS BEEN CHARGED FOR DAMAGE AS PART OF OFF HIRE CHARGES.	MJ - MAJOR REPAIR
P27-N-024	CATERPILLAR PS150C MULTIROLLER	202677	04/05/2022 0:00	5297 VACUUMED DOWN & REGASSED A/C SYSTEM.	AC - AIR-CONDITION REPAIR
P27-N-024	CATERPILLAR PS150C MULTIROLLER	201891	11/04/2022 0:00	5291 REPAIR DAMAGE TO MULTI (ROLLED) CAB, SEAT, WINDOWS, REPAIR DAMAGE TO MULTI (ROLLER), SUPPLY CAB / ACCESSORIES, \$71,500+, SUPPLY SEAT, \$2,500+, SUPPLY REPLACEMENT WINDOWS, \$4,000+, LABOUR X 120 @ \$95 PER HR, \$11,400+	CD - CUSTOMER DAMAGE
P27-N-024	CATERPILLAR PS150C MULTIROLLER	199413	08/02/2022 0:00	5291 COMPLETED PRE-DELIVERY INSPECTION., FITTED LOUVRE ASSEMBLY. SUPPLIED FIRST AID KIT	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C MULTIROLLER	196799	01/12/2021 0:00	5240 COMPLETED 'B' SERVICE. REPLACED ENGINE OIL & FILTER, REPLACED FUEL FILTER. GREASED. CHECKED ALL LIGHTS & FUNCTIONS.	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C MULTIROLLER	195859	26/10/2021 0:00	5240 REPLACED FAULTY UHF & ANTENNA.	ER - ELECTRICAL REPAIR
P27-N-024	CATERPILLAR PS150C MULTIROLLER	195257	24/10/2021 0:00	5240 REPLACED LEAKING FUEL HOSE & FAILED TAILLIGHT ASSY., TRAVELLED TO SITE. COMPLETED A PRESTART ON MACHINE. BELIEVE FUEL LEAKING FROM HEAD. CLEANED AROUND, AREA & FOUND RETURN LINES WEEPING. HAVE ORDERED. OPERATOR ALSO MENTIONED CREAKING FROM REAR OF, MACHINE WHEN OPERATING. TESTED & BELIEVE IT WAS JUST THE PIVOTS. PIVOTS THAT ARE NON GREASEABLE., REPLACED INJECTOR RETURN LINES AS SUSPECTED WEEPING. ORIGINAL LINES WERE VERY BRITTLE. REPLACED, FAILED TAILLIGHT ASSEMBLY.	MR - MECHANICAL REPAIR

P27-N-024	CATERPILLAR PS150C PHEUNMATIC	194497	17/09/2021 0:00	5132	REPLACED LOOSE LHS PIVOT PIN ON DRIVE BOLT., LHS PIVOT PIN ON DRIVE HAD LOST BOLT & WORKED ITS WAY OUT PARTIALLY. REMOVED BROOM & GUIDES AS WELL, AS OUTER TYRES. CLEANED OUT CAVITY. PLACED PIN BACK IN PLACE. REPLACED BOLT. REASSEMBLED.	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	193020	10/08/2021 0:00	5132	REPLACED ENGINE BREATHER TUBE PARTS., NB: PARTS ORDERED ON WORK ORDER 187583, CLOSED FOR EOFY	MR - MECHANICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	190781	08/06/2021 0:00	5025	REFITTED LOOSE COAX CABLE TO UHF., UHF WAS NOT TRANSMISSING, FOUND COAX CABLE HAD FALLEN OUT. GREASED MACHINE.	ER - ELECTRICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	187583	01/06/2021 0:00	5055	REPLACED FAULTY UHF ANTENNA. WASHED DOWN ENGINE., TRAVELLED TO SITE. FITTED NEW ANTENNA. FOUND ENGINE VERY DIRTY. CLEANED ENGINE DOWN. LOCATED CAUSE, FROM PIN HOLE IN BREATHER TUBE. ORDERED A NEW ONE.	ER - ELECTRICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	186022	10/03/2021 0:00	5025	COMPLETED 5,000hr SERVICE. REPLACED ENGINE OIL & FILTER., REPLACED FUEL/WATER SEPARATOR FILTER. REPLACED AIR FILTERS. GREASED ALL GREASE POINTS. REPLACED FR PARKER, GLOBE. CHECKED ALL LIGHTS. TIGHTENED RIGHT WIPER ARM AS IT WAS SLIPPING. REAR WIPER SWITCH WAS LOOSE, TIGHTENED, ALSO. TIGHTENED ALTERNATOR BELT. FITTED NEW AIR & HYDRAULIC FILTERS. REPLACED RHS PARK LENS. TOPPED UP COOLANT.	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	180643	16/09/2020 0:00	4844	REPLACED FLAT TYRE ON ROLLER WITH SPARE FROM YARD., PICKED UP SPARE TYRE FROM YARD & TRAVELLED TO KOROIT &, CHANGED OVER WITH FLAT ON FRONT OF ROLLER.	TP - PUNCTURE REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	176801	01/06/2020 0:00	4753	REVERSAL OF INCORRECT WO 174156 - CLOSED TO WRONG PLANT, NUMBER. SHOULD BE P27-N-034 AS PER WO 172103., NOW PROCESSED UNDER CORRECT WO 176802.	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	174156	01/06/2020 0:00	4746.6	REPLACED REAR WINDSCREEN, REFER TO WO 172103 FOR LABOUR	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	174461	18/05/2020 0:00	4753	CALLED OUT TO SITE & REPAIRED PUNCTURE ., PO 140764 - WARRNAMBOOL TYRE MART, TRAVELED TO WARRNAMBOOL. HAD TUBE FITTED TO SPARE., TRAVELLED TO KOROIT & FITTED SPARE TO FRONT AFTER REMOVING, AXLE.	TP - PUNCTURE REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	173714	04/05/2020 0:00	4745	COMPLETED 'B' SERVICE. REPLACED ENGINE OIL & FILTER, REPLACED FUEL/WATER SEPARATOR FILTER. BLED MACHINE., CHECKED OVER. TEST DROVE MACHINE TO GET HOT. TESTED FOR, LEAKS AROUND FINAL DRIVE CAPS. RECENTLY WORKED ON., GREASE. REPLACED BONNET STRUTS.	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	174015	01/05/2020 0:00	4746.6	, CLEAN INTERIOR, CS - INTERIOR DETAIL., JC#06347	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	173035	29/04/2020 0:00	4745	REPAIRED DRIVE MOTOR , MANIFOLD & REAR AXLE, DIFF BUSHES SUPPLIED & FITTED, DRIVE MOUNTS BROKEN AWAY, PO 139386 - EVANS MAINTENANCE & WELDING, JOB COMPLETED WITH ASSISTANCE. REFITTED REPAIRED, DRIVE MOTOR & FITTED NEW PINS. PICKED UP WHEELS FROM, SUPPLIER & FITTED. PULLED OTHER SIDE APART SO CRACK COULD, BE WELDED. NEW PARTS FITTED SHIMS, BOLTS, CAPS & 4 NEW, PINS., REFITTED BROOM TO REAR & REWELDED ON STOPS., REIFTTED IDLE UP SOLENOID THAT WAS REMOVED TO TEST ON, ANOTHER ROLLER & STARTED UP. FOUND EXHAUST MANIFOLD LEAK., REMOVED MANIFOLD & ORDERED PARTS., PARTS ARRIVED & REFITTED MANIFOLD, NEW GASKETS & BOLTS., ALL OK., REPAIRED REAR AXLE, BROKEN RETAINING BOLT HOLDING, OSCILLATION PIN, A PREVIOUS REPAIR TO WELD THE, OSCILLATION PIN IN & BOUND UP, BREAKING THE TRUNNION OFF THE, CHASSIS. TRAVEL TO SITE, INSPECTED & JACKED UP MACHINE &, REMOVE WHEELS, FOUND TRUNNION SNAPPED OFF CHASSIS, REMOVED, AXLE ASSEMBLY & INSPECTED, REMOVED BROKEN PIN, INFORMED CUST, WHO WILL ORGANISE TRUNNION WELD REPAIR, ORDERED PARTS., PO 139978 - WILLIAM ADAMS CAT, CK - ASSIST NICK IN FITTING UP RH FINAL DRIVE & REMOVED LH, FINAL DRIVE., JC#56312	MR - MECHANICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	173232	20/04/2020 0:00	4745	3 LOOSE TYRES - REPLACED 2 TYRES & 1 PUNCTURE REPAIRED, 2 X 7.50R15 MICHELIN XLC & 1 X 7.50-15 TUBE TR75A, PO 139548 - TRANSPORT TYRES	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	173153	20/04/2020 0:00	4745	WELDED ON MOTOR MOUNT BRACKET ON FRONT OF ROLLER., JC#54111	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	171045	03/03/2020 0:00	4745	ATTENDED BREAKDOWN. ORGANISED PICK UP FOR REPAIRS, CHECKED BROKEN DOWN ROLLER & FOUND PIVOT PINS HAD FALLEN, OUT OF AXLE & POSSIBLY BENT FRAME ON LHS. FOUND ANOTHER, BOLT SNAPPED ON RHS & NOT FAR FROM FALLING OUT AS WELL., ROLLER TO BE PICKED UP & TAKEN BACK TO YARD.	BM - BREAKDOWN - MECHANICAL

P27-N-024	CATERPILLAR PS150C PHEUNMATIC	169129	29/01/2020 0:00	6042	TOWED TO WORKSHOP TO REPLACE BLOWN HYD HOSE, TRAVEL TO SITE & ASSESS LEAK ON ROLLER, TRACE LINE THAT HAS, LEAK & FIND IT GOES TO BOTTOM OF OIL TANK SO OIL WILL HAVE, TO BE REMOVED BEFORE THE HOSE IS TAKEN OFF. CONTACT PP &, ARRANGE FOR FLOAT TO BRING TO WORKSHOP. TOP UP TANK WITH OIL, AS IT WAS LOW & THEN MOVE. AT WORKSHOP DRAIN TANK INTO CLEAN, DRUMS USING TRANSFER PUMP, REMOVE HOSE & REPLACE ORFS, O-RING, REINSTALL HOSE, FILL TANK BACK UP, DEGREASE &, PRESSURE WASH OIL AREAS, TEST MACHINE, GOOD PERFORMANCE &, NO LEAKS., PO 135805 - WARRNAMBOOL HYDRAULICS	BH - BREAKDOWN - HYDRAULIC
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	169186	16/01/2020 0:00	6042	TRAVELLED TO SITE. REPAIRED PUNCTURED TYRE., REMOVED INSIDE RIGHT REAR WHEEL. FITTED NEW TUBE., REASSEMBLED & BOLTED BACK ON., 1 X TUBE 7.00/7.50R15 TR75A, PO 135844 - WESTVIC TYRES MORTLAKE	TP - PUNCTURE REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	167837	01/01/2020 0:00	6042	PUNCTURE REPAIRED - BACK RIGHT, CALLED TO PURNIM, REMOVED BACK RIGHT 750X15 WHEEL, FITTED, NEW TUBE & BOLTED BACK ON + TRAVEL., 1 X TUBE 7.00/7.50R15 TR75A, PO 167837 - WESTVIC TYRES	TP - PUNCTURE REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	165771	01/01/2020 0:00	6042	CALLED OUT TO SITE. REPAIRED PUNCTURED TYRE., NB: COST INCLUDES 3 HOURS LABOUR & TRAVEL CHARGES., PO 132387 - GRAMPIANS TYRE SERVICE	TP - PUNCTURE REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	161072	31/07/2019 0:00	6042	R#BUS011421598	RE - REGISTRATION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	160801	15/07/2019 0:00	6042	FIT INNER & OUTER AIR FILTERS, FIT FUEL/WATER SEPARATOR., BLOW OUT RADIATOR, FIND LEAK, HEATER NOT GETTING HOT, HEATER, ISSUES STILL UNRESOLVED, HELICOIL IN FRONT RH WHEEL, BLOW, OUT AC UNIT ON ROOF, REMOVE LEAKING RADIATOR, BLOW OUT, HEATER CORE, FIT NEW RADIATOR, GREASE, PUMP TYRES UP TO, RIGHT PRESSURE., JC#51622	MR - MECHANICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	159564	01/07/2019 0:00	6042	GELLIBRAND 17/01/19 NEEDS NEW BONNET STRUTS *, CARRY OUT SERVICE, REPLACED ENGINE OIL & FILTER., JC#01337	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	159072	27/06/2019 0:00	6042	REPAIRED R/H/R WORK LIGHT MOUNT, CHECKED A/C (HAS NO GAS), CHECKED MISSING SHAFT IN R/H WIPER MECHANISM., ADJUSTED ENGINE COVER MOUNTS DUE TO HITTING ON RADIATOR, & JAMMING WHEN OPENED. CHECKED ED HORN (WORKING FINE)., LABOUR ON W/O #155760. CLOSED FOR EOFY	MR - MECHANICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	157140	26/06/2019 0:00	6042	CARRY OUT PRE/DEL, 28/5/19 - ATTEMPT TO START MACHINE WITH BRAKE CLEANER., REMOVE BOTH TAIL SHAFTS & TOW ROLLER INTO WORKSHOP, REMOVE, FAN & RADIATOR SHROUD, DRAIN COOLANT, REMOVE WATER PUMP &, FRONT COVER, REMOVE ALL FUEL LINES & FUEL PUMP, CLEAN UP, PARTS & ORDER ADDITIONAL PARTS., 29/5/19 - FIT NEW FUEL PUMP & TIMES, FIT FRONT COVER WITH, NEW SEAL, REFIT FAN ASSEMBLY & NEW BELTS, PLUMB UP FUEL, PUMP, FIT FAN SHROUD & HOSES, FILL WITH COOLANT, RUN UP &, TEST, ALL OK, REFIT BOTH DRIVE SHAFTS., 30/5/19 - REMOVE BOOST PIPE & INJECTOR LIGHT COVER, REMOVE, ROCKER COVER & CLEAN UP, REFIT WITH NEW SEALS., PO 125367 - ON TRACK DIESELS, CARRY OUT PRE/DEL, REPLACE ENGINE MOUNTS X 2, REPLACE HORN., REPLACE REAR LIGHTS X 2, REPAIR WIPER WASHERS, FIT FIRE EXTI, NGUISHER, REPLACE RADIO SPEAKERS, REPLACE UHF HAND PIECE., REPLACE REAR BEACON, GREASE, REPLACE L/H WIPER ASSY, CHECK, ALL FLUIDS ECT. JC#52890	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	156319	03/06/2019 0:00	6042	ENGINE STOPPED, CHECKED FOR ENGINE NO START. COMPLETED TESTS ON, FUEL SYSTEM, FUEL FILTER OK, PRIMING PUMP OK, SUSPECT, INJECTOR PUMP FAULT AS FUEL NOT SQUIRT ENOUGH THROUGH, INJECTOR PIPES., HAD ANOTHER LOOK AT INJECTOR PUMP REMOVED, TIMING DEVICE FROM BOTTOM OF PUMP AND FOUND TRACES OF WATER, CONTAMINATION AND FINE METAL , PUMP HAS HAD INTERNAL FAILURE, AND REQUIRES REPLACEMENT., WAITED WITH ROLLER FOR TRANSPORT TO GET ENGINE RUNNING, & DRIVABLE ONTO FLOAT THEN FOLLOWED TO YARD, & REMOVED OFF FLOAT, CHECKED PUMP NUMBER WITH SLOANE DIESEL & GOT PRICE FOR, REPLACEMENT. AWAITING APPROVAL., PUMP TO BE FITTED BY WORKSHOP, NICK HETHERINGTON: Completed by:, nick.hetherington@porterplant.com.au, on:, 03 Jun, 2019	MR - MECHANICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	155760	01/06/2019 0:00	6042	REPAIRED R/H/R WORK LIGHT MOUNT, CHECKED A/C (HAS NO GAS), CHECKED MISSING SHAFT IN R/H WIPER MECHANISM, ADJUSTED, ENGINE COVER MOUNTS DUE TO HITTING ON RADIATOR &, JAMMING WHEN OPENED, CHECKED ED HORN (WORKING FINE), CLOSING W/O FOR EOFY. NEW W/O #159072 FOR COMPLETED REPAIRS.	MR - MECHANICAL REPAIR

P27-N-024	CATERPILLAR PS150C PHEUNMATIC	155761	01/05/2019 0:00	6042	REPAIRED R/H/R WORK LIGHT MOUNT, CHECKED A/C (HAS NO GAS), , CHECKED MISSING SHAFT IN R/H WIPER MECHANISM,, ADJUSTED, ENGINE COVER MOUNTS DUE TO HITTING ON RADIATOR AND, JAMMING, WHEN OPENED, CHECKED ED HORN (WORKING FINE), BRECK CORBETT: DOUBLE UP WO# WITH WO#155760 PLEASE CLOSE, BRECK CORBETT: Completed by:, breck@porterplant.com.au, on:, 07 May, 2019	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	151430	01/03/2019 0:00	6042	S & F NEW CONDENSOR FANS AND REGAS AIRCON, TRAVEL TO GELLIBRAND DEPOT, INSPECT A/C, FOUND LOW GAS & 2 X, CONDENSOR FANS NOT WORKING, CHECK FANS, HAVE POWER TO MOTOR, BUT NOT RUNNING, FANS ARE UNSERVICEABLE, REMOVE FAN FOR, SAMPLE. S & F 2 X NEW CONDENSOR FANS, EVACUATE SYSTEM, ADD, OIL & UV DYE, CLEAN CAB FILTER SCREEN, CLEAN CONDENSOR,, CHARGE SYSTEM WITH UV DYE GAS, CHECK OPERATION, SYSTEM, OPRATING TO FULL POTENTIAL,, PO 121166 - I.C. COLD - DAVE 0418550427, AIRCON NOT WORKING. FOUND NO GAS IN SYSTEM. REFITTED SPRINGS, TO SEAT MECHANISM,, JC #53525, **RECOMMENDATION LOGGED INTO TEXADA**, GELLIBRAND 17/01/19 A/CON NEEDS REGASSING *	AC - AIR-CONDITION REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	147296	01/11/2018 0:00	6042	CHECKED A/CON - NO GAS. VAC DOWN & CHECKED FOR LEAKS. FOUND, FITTING LOOSE AT REAR OF COMPRESSOR. REPLACED O'RING &, FILLED WITH A/CON GAS. WORKING AT 6c. ALL OK., JC #49256	AC - AIR-CONDITION REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	146544	17/10/2018 0:00	4297	7.50R15 XLC MICHELIN ROLLER TY X 1 + 7.50-15 TUBES X 1, REPLACED BEACON GLOBE. FITTED TYRE FROM SPARE ROLLER AS REAR, INSIDE WAS FLAT. TOPPED UP HYDRAULIC OIL. CLEANED CAB, JC #50056, TYRE REPAIR - PO 115291 - TRANSPORT TYRES	ER - ELECTRICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	143175	08/08/2018 0:00	4297	0	RE - REGISTRATION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	135783	01/06/2018 0:00	4057	D/UP CLOSE AT ZERO. REFER TO W/O #132443, TRAVELLED TO SITE & CHECKED OVER SYSTEM. REMOVED AC UNIT., CHECKED HOSES & FOUND NO LEAK. RETURNED TO WORKSHOP WITH, UNIT. STRIPPED OUT & REPLACED TX VALVE & DRYER & THERMO, SWITCH. RETURNED WITH UNIT TO SITE. REMOVED CARPET & INNER, FLOOR CHECKED HOSES UNDER FLOOR. ALL OK. REFITTED UNIT, & FILLED WITH GAS. HAD TO LOCATE A SUITABLE HOSE WHICH TOOK, 2 HOURS. RETURNED & FITTED NEW HOSE AS NEEDED & PROTECT, FROM RUBBING. REGASSED SYSTEM & CHECKED. ALL OK. REFITTED, & SECURED ALL PARTS THAT GOT REMOVED., P/O #106225 - G & R MAINTENANCE	AC - AIR-CONDITION REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	139720	01/06/2018 0:00	4297	CHECKED OUT ALTERNATOR, ONLY OUTPUT IS 24.9 -25.2V, PUT AC, ON, DROPPED DOWN TO 23.9 THEN TO 22.5 V., PO#102711 - JUNGLES TRUCKS AND EQUIPMENT	ER - ELECTRICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	138224	01/06/2018 0:00	4297	SUPPLY 1 MISSING WHEEL NUT INDICATOR,	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	138183	01/06/2018 0:00	4297	CUSTOMER DAMAGE FRONT SCREEN REPLACED BY BALL, AUTO GLASS P/O#108147	CD - CUSTOMER DAMAGE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	138184	08/05/2018 0:00	4297	REPLACE CRACKED FRONT WINDSCREEN AND 2 X REAR WORKLIGHTS	CD - CUSTOMER DAMAGE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	132335	01/05/2018 0:00	4057	COMPLETED 2000 HR SERVICE. ADJUSTED TAPPETS IN ENGINE, MOE 25/10/17 NEEDS UHF MIC PART NO: (MK089), MOE 18/01/18 OVERDUE BY 2000 HOURS FOR SERVICE	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	136725	01/04/2018 0:00	4238	FITTED 2 NEW TYRES SUPPLIED BY TYREPOWER SALE, 7.50-15 TR177A, P/O #105954	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	135363	16/03/2018 0:00	4057	REPLACED 2 TYRES - 7.50R15 XLC MICHELIN ROLLER, TRANSPORT TYRES P/O 105836	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	132443	01/02/2018 0:00	4057	ONGOING ISSUES WITH AIR CON, G & R MAINTENANCE TO ATTEND (ANTHONY) PO # 103369, PLEASE SEE ATTACHED INVOICE FOR DETAILS OF WORK	AC - AIR-CONDITION REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	132139	17/01/2018 0:00	4057	CHECKED OUT FAULTY A/CON. BLOWS OUT COLD AT 10 DEGREES &, REQUIRES REGASSING. OVERDUE 2000 HRS FOR SERVICE. REAR, LIGHT SMASHED OFF., JC #39234, **RECOMMENDATIONS LOGGED INTO TEXADA**	AC - AIR-CONDITION REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	132244	09/01/2018 0:00	4057	CUSTOMER RANG TO SAY STILL HAVING ELECTRICAL ISSUES. FITTED, ANOTHER ALTERNATOR AS SUGGESTED BY ELECTRICIAN. CHARGING, 27.2 VOLTS, JC #39485, PARTS LISTED ON W/ORDER #131512	ER - ELECTRICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	131512	05/01/2018 0:00	4057	ALTERNATOR NOT CHARGING. REMOVED & FITTED NEW ALTERNATOR, TESTED @ 26.6 VOLTS, PO 102711 - JUNGLES, JC #39485	BE - BREAKDOWN - ELECTRICAL
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	131490	04/01/2018 0:00	4044	FOUND AIR/CON SYSTEM SHORT OF GAS & LEAKING DISCHARGE, FITTING. REMOVED & REPLACED FITTING & CONDENSOR COVER., INSPECTED FOR LEAKS.EVACUATE SYSTEM & RECHARGED WITH GAS., MOE 20/12/17 A/CON NEEDS REGASSING, PO # 102694	AC - AIR-CONDITION REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	129453	18/12/2017 0:00	4044	ATTEND AND CHECK AIR CON, PO # 101074 MAT 0427 029 729, CHECKED OUT A/CON NOT WORKING. FOUND TO BE LOOSE PLUG, IN UNIT IN CABLING., NEEDS REGASSING., JC #39223, **RECOMMENDATION LOGGED INTO TEXADA 20/12/17**	AC - AIR-CONDITION REPAIR

P27-N-024	CATERPILLAR PS150C PHEUNMATIC	130835	14/12/2017 0:00	4022	CHECKED OUT LOW VOLTAGE. JUMP STARTED. FOUND TO HAVE, DEAD BATTERY ON LHS. REPAIRED BOTH BATTERIES. CHECKED CHARGE, RATE. CHARGING AT 27.5 VOLTS., JC #39217, **RECOMMENDATION LOGGED INTO TEXADA. DUE FOR 3000 HR SERVICE	ER - ELECTRICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	128210	19/10/2017 0:00	3884	CHECKED OUT ALL ISSUES & FOUND BROKEN VENT STUCK IN, THE FAN MOTOR., NEEDS UHF MIC PART NO: (MK089), JC #36684	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	127761	17/10/2017 0:00	3731	DOOR LOCKED JAM COULD NOT OPEN IT. GOT DOOR OPEN & ADJUSTED, DOOR CAN NOW BE OPENED EASIER., JUNGLES P/O 99513	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	127733	12/10/2017 0:00	3731	COMPLETE P/DELIVERY. CHECKED FRONT DRIVE SHAFT, BRAKES, HAND, FOOT STEERING OK. DRIVES OK. STOP OK, START OK. SMALL AMOUNT, OF MOVEMENT IN IT. DOOR & LOCKS WORKING WELL. SMALL OIL LEAK, AROUND ENGINE FILTER. FIXED UP. ALL TYRES OK GOOD CONDITION., JUNGLES P/O 99479	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	126768	01/10/2017 0:00	3731	PRE/DEL AND REPAIRS, CHECK TYRE PRESSURE, REPAIR REVERSE BEEPER, REMOVE, AND REPAIR SEAT SUSPENSION, SWAP SEAT OUT OF P27-N-016, GREASE AND CHECK EVERYTHING OPERATIONAL, JC# 40159	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	125135	28/08/2017 0:00	3391	PRE/DEL, ADJUST DRIVE BELT, CLEAN AND CHECKLIST, REPAIR SUSPENSION, ON SEAT, ADJUST WINDOW WASHERS, GREASED AND WASHED., , JC# 40054 LOUIS,KAILE	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	122730	15/06/2017 0:00	3391	SUBLET TO AUTOGLASS, REPLACED DAMAGED GLASS RETURNED YARD FROM SLD, CHARGE OUT IS ON W/O122679	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	122679	13/06/2017 0:00	3391	REPLACED CRACKED LHS QUARTER SECTION OF FRONT WINDSCREEN, , , (EMAILED RICHARD 13/06 FOR P/O), QUOTED COST \$88 INC - BALLARAT AUTO GLASS FITTED, CHARGE OUT PRICE \$100 + GST),	CD - CUSTOMER DAMAGE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	122399	06/06/2017 0:00	3391	OIL LEAK ? FROM TRAVEL PUMP AREA, CONTACT ON SITE DALE 0417 312 358, HWY DUPLICATION - FULHAM, (OUR REF: P/O #94753) UNION HYDRAULICS, PO # 94753	BH - BREAKDOWN - HYDRAULIC
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	120249	11/04/2017 0:00	3391	NAMBROK 2/12/16 DRAG BROOM WILL NOT COME DOWN, REPLACE X 2 RIGHT REAR TYRES, , SUB CONTRACTOR WAS SUPPOSED TO TAKE PICTURES AT CUSTOMERS, REQUEST BUT DID NOT HAPPEN	TC - TYRE CHANGE/REPLACMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	119593	27/03/2017 0:00	3391	REPLACED ROLLER TYRES AND TUBE., (OUR REF: PO#92579) RE-TYRE LATROBE VALLEY	TC - TYRE CHANGE/REPLACMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	118115	16/02/2017 0:00	3391	REPLACED LEAKING HYDRAULIC PLUGS ON HYDRAULIC PUMP., TESTED & WASHED., JC#35737	HR - HYDRAULIC REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	117608	03/02/2017 0:00	3364	REPAIRED HYD OIL LEAK AT HYDRAULIC PUMP. RESEALED PLUGS., JC#35716	HR - HYDRAULIC REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	117327	27/01/2017 0:00	3364	CARRIED OUT 250hr SERVICE. REPLACED ENGINE OIL & FILTER., JC#35705	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	114865	29/11/2016 0:00	3099	REMOVED & REFITTED GLASS FROM WINDOW FRAME & RESEALED., WINDSCREEN ABOUT TO FALL OUT - REQUIRED RESEALING., PO# 88787	GR - GENERAL REPAIRS
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	114527	10/11/2016 0:00	3099	PERFORMED 1000hr SERVICE. REPLACED ENGINE OIL & FILTER., REPLACED FUEL, HYDRALIC & AIR FILTERS., CHECKED OVER MACHINE & GREASED., JC#35670	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	114056	02/11/2016 0:00	3033	REPLACED FAULTY FUEL LIFT PUMP., ENGINE RANDOMLY CUTTING OUT AND THEN HARD TO START. BLOWING, SMOKE AS WELL., TESTED. CHECKED OVER MACHINE., JC#35655	BM - BREAKDOWN - MECHANICAL
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	113707	20/10/2016 0:00	2951.5	FITTED NEW CB ANTENNA. TOPPED UP GAS IN A/C. NO LEAKS FOUND, CB WORKING OK. CHECKED RADIATOR FOUND NO LEAKS., PO#87947	BH - BREAKDOWN - HYDRAULIC
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	112763	26/09/2016 0:00	2951.5	CALLED OUT SATURDAY MORNING BY STEVE P FOR FUEL LEAK, RETURN FULL TAP WAS OFF AND THE REURN FUL LINE BLOW OFF, UNDER PRESSURE - RUN UP AND ALL OK, P/O 87252	BM - BREAKDOWN - MECHANICAL
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	112997	23/09/2016 0:00	2951.5	CALLED OUT TO INSPECT BLOWING SMOKE, CHECK FILTERS ALL OK., TEST DROVE ALL OK, REPAIRED BROOM GUIDE AND TESTED ALL OK	MR - MECHANICAL REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	112338	13/09/2016 0:00	2951.5	PRE HIRE GREEN TAG, CUSTOMER SLD HIRE, REQUIREMENTS, UHF, ROOF BEACONS, REVERSE ALARM, FIRST AID KIT, FIRE EXTINGUISHER	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	112541	12/09/2016 0:00	2951.5	GREEN TAGGED AND PREPARED FOR HIRE., REPLACED BLOWN BEACON AND HEADLIGHT GLOBES., JC#23434	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	111615	25/08/2016 0:00	2951.5	0	RE - REGISTRATION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	108368	28/06/2016 0:00	2767	REPLACE LEFT CORNER GLASS #9791 CONTRACT, , REPLACE DAMAGED CORNER SECTION OF FRONT WINDSCREEN, \$115.00 PLUS GST, , SUBLET	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	108213	04/06/2016 0:00	2767	GREEN TAG PRE HIRE, RE STAMP F/E, REPAIR WIRING FAULT IN BEACON, TOP UP ENG OIL, REPASIR HUB OIL LEAK, ROTATE TYRES, DETAIL, UPDATE ALL DOCUMENTS	PD - PRE-DELIVERY INSPECTION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	107088	09/05/2016 0:00	2876	COMPLETED 250hr SERVICE. REPLACED OIL FILTER. CHECKED OVER, GREASED. ALL OK., JC# 18207	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	106233	06/04/2016 0:00	40779.1	REPLACED LEAKING ORING ON RHS HUB SEAL. WASHED DOWN., JC 21582	Other

P27-N-024	CATERPILLAR PS150C PHEUNMATIC	105632	04/04/2016 0:00	40779.1	REPLACED RADIATOR & REFILLED COOLANT. RAN, INSPECTED WATER LEAK AROUND RADIATOR., TOPPED UP RADIATOR & TESTED IT. WATER LEAKING OUT OF, RADIATOR AT FRONT, WILL NOT HOLD WATER., P/O 81656 - INSPECT RADIATOR, WAITING ON DAVE J/C JC 26364	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	105336	23/03/2016 0:00	40779.1	REPLACE ONE WORN TYRE, P/O 81415	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	105201	18/03/2016 0:00	40779.1	REPLACED BLOWN POWER STEERING HOSE., P/O 81269	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	104261	19/02/2016 0:00	40779.1	REPLACED BOLTS IN PIVOT PIN. CLEANED OUT BEACON LENSE., CHECKED OUT PIVOT PIN ADRIFT. JACKED UP & REMOVED PIN., CLEANED OUT HOLES. ADJUSTED FAN BOLTS., JC 25479, WILL NEED TO BE RE-FURBISHED AT THE END OF SEASON.	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	104732	15/02/2016 0:00	40779.1	REPAIRED A/C PARTS JAMMING UP MOTOR., FOUND CABIN FAN NOT TO BE WORKING. REMOVED FAN ASSEMBLY &, FOUND BROKEN AIR VENT PLASTIC'S TO BE JAMMING UP MOTOR., CLEANED OUT DAMAGED PARTS & REASSEMBLED & CHECKED., P/O	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	103028	03/02/2016 0:00	2285	REPAIRED AIR CON SYSTEM, PRESSURE TESTED SYSTEM & FOUND LEAKING FITTINGS ON THE, DISCHARGE HOSE. REMOVED HOSE TO RECRIMP FITTING. REFITTED, HOSE & PRESSURE TESTED. REGASED WITH R134A. FITTED SUPPLIED, ALTERNATOR BELTS., PO 79867 - TRARALGON AUTO AND AIR	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	104124	02/02/2016 0:00	25081.1	REPAIRED WIRING ON ENGINE., CHECKED CHARGE RATE ON BATTERIES. ALL OK., JC 26335	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	103246	22/01/2016 0:00	2285	REPLACED WORN TYRE., PO 79923	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	102584	22/01/2016 0:00	25081.1	COMPLETED 500HR SERVICE., JC 26317	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	104057	18/01/2016 0:00	17983	INSPECTED ROLLER, JC 104057, NOTE: AUTO ELECTRIAN TO REPAIR A/C	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	100005	01/01/2016 0:00	2173	JOB NOT COMPLETED, UNABLE TO COMPLETE ON SITE, REPAIR CRACKED RADIATOR MOUNTS	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	99127	01/12/2015 0:00	2173	REMOVED FLAT TYRE, HAD IT REPAIRED & REFITTED TO ROLLER., P/O 77050, JC# 27175	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	99593	13/11/2015 0:00	2285	REPLACED FAILED ALTERNATOR, CHECKED CHARGE - OK, INSPECT ELECTRICAL FAULT- FOUND ALTERNATOR NOT CHARGING., CHARGED UP BATTERY TO ALLOW ROLLER TO BE LOADED TO TRAILER., P/O 99593, RETURNED FOR NO POWER FAULT, CHECKED WIRING HARNEDD FOR, RUBBED THROUGH HOSES. OPERATED FOR AN HOUR & WATCHED WORK, ON JOB. JC# 27196 & 27108	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	101126	30/10/2015 0:00	2270	REPLACED FAILED BATTERIES. CHECKED CHARGE RATE - OK, JC# 27183	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	97569	11/09/2015 0:00	2170	PRESEASON AIRCON SERVICE	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	96941	26/08/2015 0:00	2170	12 MONTHS REGISTRATION PAID BY EFRS - EXPIRY 26/08/2016	RE - REGISTRATION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	96031	12/08/2015 0:00	2170	GT WIRE IN BRAKE LIGHTS BON STRUTS DETAIL AND GREASE, CARRY OUT GREEN TAG	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	96036	05/08/2015 0:00	2170	DAMAGE FRONM CONTRACT 7114 REPLACE SMASHED WINDSCREEN, , REPLACED SMASHED CENTER SECTION, OUR REF PO (74643 ) BALLARAT AUTOGLASS, TOTAL COST \$467.50 INCLUDING GST	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	93684	01/06/2015 0:00	2138	REPLACED 1x WORN TYRE., P/O 72584	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	93795	01/06/2015 0:00	2138	REPAIRED PUNCTURED TYRE, P/O 72682	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	93273	04/05/2015 0:00	2138	REPLACED FLAT FRONT TYRE., NOTE: WHEEL TAKEN OFF ROLLER AT BALLARAT YARD., JC# 33536	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	91878	30/03/2015 0:00	2018	REPLACED 1x TYRE, COMPLETED ON SITE ELPHINSTONE, P/O 71358	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	91877	30/03/2015 0:00	2018	REPLACED 1x TYRE, DONE AT CASTLEMAINE, P/O 71357	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	91876	30/03/2015 0:00	2018	REPLACED 1x TYRE, ON SITE AT STRATHDALE, P/O 71356	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	91768	30/03/2015 0:00	2018	REPAIRED PUNCTURED TYRE, P/O 71274	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	91818	28/03/2015 0:00	2018	COMPLETED 2000HR SERVICE - CHECKED OVER ALL OK, BENDIGO 11/3 2000hr SERVICE OVERDUE, BENDIGO 29/10 BALLAST TANK STILL LEAKING, JC 20532	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	90181	05/01/2015 0:00	1865	REPLACED ONE TYRE., DONE ON SITE AT COROP, P/O 70059	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	88554	05/12/2014 0:00	1780	FITTED NEW UHF RADIO AND REPLACED WORN TYRE WITH SPARE, JC 32107	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	88450	03/12/2014 0:00	1780	COMPLETED 250HR SERVICE (1750HR) AND CHECK OVER, DRAG BROOM TO BE REPLACED BY BORAL, BENDIGO 29/10 BROOM WORN OUT, NEED NEW ONE, JC 19549	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	86824	27/10/2014 0:00	1715	REPLACED RADIO AERIAL. REPLACED 4 INSIDE REAR TYRES., ROTATED USED TYRES FROM REAR TO FRONT., P/O 67561 &	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	86755	15/10/2014 0:00	1445	SERVICED & TESTED A/C - ALL OK., REPAIR / REGAS A/C SYSTEM, P/O 67531, INSPECTED A/C NEEDS TO BE TESTED / REGASED. JC# 19451	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	86383	09/10/2014 0:00	1445	CARRY OUT GREEN TAG AS REQUIRED, CARRY OUT GREEN TAG	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	84922	27/08/2014 0:00	1445	12 MONTHS REGISTRATION PAID BY EFRS - EXPIRY 27/08/2015	RE - REGISTRATION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	84882	26/08/2014 0:00	1445	REPAIRED PUNCTURED TYRE, P/O 66052, LOCATIONS: ARTHURS LANE, MOUNT MERCER	TC - TYRE CHANGE/REPLACEMENT
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	83940	31/07/2014 0:00	1445	REPAIRED PUNCTURED REAR TYRE ON SITE AT MEREDITH DEPOT, P/O 65202	TC - TYRE CHANGE/REPLACEMENT



P27-N-024	CATERPILLAR PS150C PHEUNMATIC	83672	24/07/2014 0:00	1445	REPAIRED TWO TYRE PUNCTURES ON REAR., P/O 64986	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	82996	01/07/2014 0:00	1445	COMPLETED GREEN TAG, JOB CARD #22333	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	81576	20/05/2014 0:00	1445	COMPLETED 500 HOUR SERVICE, REPLACED ENGINE OIL & FILTERS, DID NOT COMPLETE GREEN TAG., JOB CARD #33225	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	80677	14/04/2014 0:00	1445	COMPLETED PRE DELIVERY CHECK & REPLACED RADIO AERIAL, JOB CARD #20925, BENDIGO 26/3 AM/FM RADIO AERIAL BROKEN	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	79971	03/04/2014 0:00	1436	REPAIRED PUNCTURED TYRE., CHANGED FLAT TYRE, JOB CARD #21054, P/O 62266, (NO CHARGE PUNCTURE REPAIR)	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	79947	01/04/2014 0:00	1428	CHANGED FLAT TYRE & CHECKED OVER, JOB CARD #05800	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	79861	27/03/2014 0:00	1399	COULDNT LOCATE CHECKLIST BOOK, NOTE: NEEDS FRONT TYRES & SOME REAR TYRES, JOB CARD #17744	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	79232	11/03/2014 0:00	1366	COMPLETED 250HR SERVICE, NOTE: NEEDS FRONT TYRES SOON, ENGINE DRIVE BELTS (CHANGING, NEXT SERVICE), JOB CARD #0686	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	77204	17/01/2014 0:00	1789	REPLACED BLOWN BEACON FUSE & REASSEMBLED, REMOVED ACCESS PLATE TO OVERHEAD CONSOLE, JOB CARD #15878	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	76522	20/12/2013 0:00	1147	TIGHTENED ENGINE DRIVE BELTS AND WELDED BROOM ALL THREAD, IN PLACE., JC# 15851	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	76496	17/12/2013 0:00	1147	ADJUSTED A/C BELT, JOB CARD #16116	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	76525	13/12/2013 0:00	1147	REPLACED PUNCTURE TYRE, 2ND FROM L/H/S FRONT, TYRES ON FRONT ARE GETTING LOW., JC# 15825	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	76181	03/12/2013 0:00	1092	REMOVED FRONT WHEEL DISMANTLED & FITTED NEW TUBE, JOB CARD #16043	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	74444	04/11/2013 0:00	1010	COMPLETED 1000hr SERVICE, JOB CARD #0656	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	73727	09/10/2013 0:00	8560	REPAIRED PUNCTURED TYRE, BORAL DO NOT PAY FOR THESE DUE TO, CONTRACTUAL AGREEMENT.	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	73725	09/10/2013 0:00	8560	CREDIT FOR W/O 68046, INV 46422 DUE TO BORAL BEING CHARGED, FOR PUNCTURE REPAIR, DUE TO CONTRACTUAL AGREEMENT BORAL DO, NOT PAY FOR THIS. INTERNAL W/O 73727 OPENED TO RECOVER COSTS	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	73402	26/09/2013 0:00	8560	REPLACED NUMBER PLATE GLOBE, & GREEN TAGGED, JOB CARD #27608	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	73079	13/09/2013 0:00	8560	REPAIRED PUNCTURE. POSITION NO: 9, JOB CARD #33670	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	72437	02/09/2013 0:00	806	FITTED REVERSING CAMERA, OUR REF PO(56823) BOWTIE, NOTE# THIS JOB WAS DONE 28/9/12 BUT WAS FORGOTTEN ABOUT	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	72222	27/08/2013 0:00	806	REGISTRATION PAID BY ERFS 27/8	RE - REGISTRATION
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	72300	26/08/2013 0:00	806	FITTED RUNOUT TO POSITION NO 9 & FIXED PUNCTURE IN TUBE., JOB CARD #33640	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	72097	22/08/2013 0:00	806	COMPLETED GREEN TAG, UPDATED REGO LABEL, REMOVED & REPLACED, BROOM FOR TYRE REPAIR. CLEANED INTERIOR & WINDOWS, JOB CARD #33582	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	70776	24/07/2013 0:00	801	UNBLOCKED WIPER WASHERS & CLEANED WINDOWS. REMOVED REAR, SWEEPER AND REMOVED L/H INNER WHEEL. CLEANED INTERIOR, JOB CARD #33547	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	71085	23/07/2013 0:00	801	PUNCTURE REPAIRED ON POSITION 8, JC - 32585	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	71256	19/07/2013 0:00	801	D.D.# 7807, PICK UP ROLLER AT BORAL BENDIGO., HELD UP WAITING FOR TRUCK TO BE FITTED WITH NEW WINDSCREEN	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	71023	18/07/2013 0:00	800	COMPLETED 750HR (A) SERVICE 800KM, GENERAL CHECK OVER, JC-0731	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	69607	05/06/2013 0:00	642	OPENED ACCESS DOOR & ADJUSTED DOOR STRIKER. TESTED - OK, DOOR WOULD NOT OPEN., JC# 30210	UR - UNPLANNED REPAIR
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	69420	30/05/2013 0:00	642	REPLACED FRONT WIPER MOTOR AND AM/FM RADIO, NO JC SENT	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	68977	30/05/2013 0:00	632	REPLACED BROKEN WINDSCREEN & SIDE WINDOW., HAD BEEN CHARGED TO BORAL ON W/O 67049 BUT HAD TO BE, CREDITED DUE TO CONTRACT CONDITIONS.	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	68970	30/05/2013 0:00	632	REVERSAL OF INVOICE 45765, REQUESTED BY: JOHN DALGLEISH, APPROVED: DEAN S.	-
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	69159	21/05/2013 0:00	642	TRACED AND REPAIRED WIRING FAULT., HAD NO BEACONS, RADIO IR REVERSE CAMERA. FOUND BROKEN WIRE, IN WIRING LOOM. CONNECTED POWER TO AUXILIARY SOURCE. OK., JC# 4838	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	68338	13/05/2013 0:00	635	REPLACED 4x REAR TYRES., REPLACE REAR TYRES, P/O 53694, JC# 14364	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	68292	09/05/2013 0:00	550	FITTED SPARE TYRE TO R/H REAR 2nd FROM OUTSIDE., NOTE: NEEDS NEW REAR TYRES., P/O 53648, JC# 5999	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	68046	03/05/2013 0:00	550	REPAIRED PUNCTURED TYRE. CHANGED FLAT TYRE WITH SPARE., JC# 10811, P/O 53172	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	67049	05/04/2013 0:00	354.6	REPLACED BROKEN WINDSCREEN AND SIDE WINDOW, P/O 52625	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	67289	02/04/2013 0:00	513	COMPLETED 500hr SERVICE., SJ# 0050	PS - PLANNED SERVICE
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	65424	16/02/2013 0:00	134	REPLACED BATTERIES & ALTERNATOR. REPLACED CD PLAYER FUSE., TIGHTENED LOOSE HEATER HOSE. CHECKED FOR CAUSE OF WIPER NOT, WORKING, FOUND WIPER MOTOR BURNT OUT - NEEDS REPLACING., JC# 4744	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	65941	15/02/2013 0:00	354.6	CHECKED BATTERIES - ONE DEAD, TO BE REPLACED AT DEPOT.	Other



P27-N-024	CATERPILLAR PS150C PHEUNMATIC	65938	13/02/2013 0:00	346 SWAPPED OVER FRONT WHEEL & REPLACED DAMAGED WHEEL BOLT., REPAIRED PUNCTURE.	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	65266	08/02/2013 0:00	FITTED SPARE TYRE TO ROLLER AFTER PUNCTURE., TRAVELLED TO ROLLER TO CHANGE TYRE, NO 134 SPARE COULD NOT DO IT, OBTAINED SPARE FROM BENALLA, WENT BACK TO ROLLER & CHANGED, TOOK PUNCTURED TYRE FOR REPAIR. REPAIRED WHEEL STUD THREADS., JC # 5911	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	62634	09/11/2012 0:00	48.8 FITTED STEERING WHEEL EZY TURN KNOB., JOB CARD # 13964	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	62565	08/11/2012 0:00	48.8 REPLACED DAMAGED WINDOW GLASS., OUR REF: P/O 48965	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	62768	05/11/2012 0:00	72 FITTED ALLTHREAD TO BROOM ON REAR OF ROLLER TO MAKE IT, ADJUSTABLE & STOP LEVEL WHEN PUT DOWN., JOB CARD # 9954, NOTE: PARTS ON W/O 61730	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	60916	26/10/2012 0:00	0 REPAIRED FOR HIRE/FITTED BRUSH & MUD GUARDS, (OUR REF: P/O # 47659) GRECH ENGINEERING, PO# 48251	Other
P27-N-024	CATERPILLAR PS150C PHEUNMATIC	61730	15/10/2012 0:00	0 FITTED FLASHING LIGHT & BRACKET., OUR REF: P/O 48280	Other