

TRIM(WOHH.WOWH_MODEL)	WOWH_DESC	WOWH_ORDER_N	WOWH_INVOICE_DATE	WOWH_METER	Comments	Full Rep Code
P27-N-016	CAT PS150 CAB MULTI ROLLER	253877	23/10/2025 0:00	8335	PREPARED FOR AUCTION., REPLACED BATTERY., Completed by:Rory.Lyne@porterplant.com.auon:Oct 14, 2025	GR - GENERAL REPAIRS
P27-N-016	CAT PS150 CAB MULTI ROLLER	232939	07/06/2024 0:00	8335	COMPLETED PREDELIVERY INSPECTION., COMPLETED FULL FUNCTION TEST. REPLACED 1kg FIRE EXTINGUISHER., Completed by:shaun.scanlan@porterplant.com.auon:Jun 07, 2024	PD - PRE-DELIVERY INSPECTION
P27-N-016	CAT PS150 CAB MULTI ROLLER	225483	01/12/2023 0:00	8335	COMPLETED PREDELIVERY INSPECTION. RED TAGGED., WAITING ON QUOTE FOR REPAIRS., Completed by: patty.rustman@porterplant.com.auon: Nov 28, 2023	PD - PRE-DELIVERY INSPECTION
P27-N-016	CAT PS150 CAB MULTI ROLLER	223003	01/11/2023 0:00	8335	REPLACED BLOWN FUSE. REPAIRED WIRING TO MAIN LOOM., MACHINE GOT STUCK ON WASH BAY. BLEW IGNITION FUSE. BLEW FUSE REPEATEDLY. CHECKED WIRING LOOM, FOUND MAIN, LOOM TO ENGINE SHOWING RUBBING SIGNS. INSULATED, RESTARTED & ALLOWED MACHINE TO WARM UP. CYCLED MACHINE, NO FAULTS. POSSIBLE WATER IN CIRCUIT AFTER BEING WASHED., Completed by:aaron.cuttler@porterplant.com.auon:Sep 22, 2023	BE - BREAKDOWN - ELECTRICAL
P27-N-016	CAT PS150 CAB MULTI ROLLER	222709	01/10/2023 0:00	8335	COMPLETED PREDELIVERY INSPECTION & REPAIRS, REPLACED & ADJUSTED LH DOOR LATCH. FITTED 2nd HAND REAR BEACON TO CAB BEACON. CLEARED BLOCKED WASHER JETS, NOZZLE, DRILLED & CLEANED, NOW WORKING. REPLACED AM/FM STEREO. REPLACED BENT LH BROOM PIECE. TOPPED UP HYDRAULIC OIL., FITTED NEW RADIO & FIRE EXTINGUISHER. MADE NEW BROOM ATTACHMENT GUIDE. SUPPLIED FIRST AID KIT., Completed by: tom.fenwick@porterplant.com.auon: Sep 19, 2023, Completed by: sieanna.slingo@porterplant.com.auon: Sep 22, 2023	PD - PRE-DELIVERY INSPECTION
P27-N-016	CAT PS150 CAB MULTI ROLLER	218545	09/06/2023 0:00	8291	S & F NEW A/C THERMOSTAT, A/C NOT WORKING, GAS & AIR TO RECHARGE A/C SYSTEM., S & F NEW THERMOSTAT FOR EVAPORATOR., PO 185916 - A1 AUTO AIR	AC - AIR-CONDITION REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	217747	02/06/2023 0:00	8291	REPAIRED LEAKING STEERING RAM., STARTED INSPECTION. DEGREASED & WASHED LEAKING PARTS TO IDENTIFY LEAKS. REPLACED ALL, SAFETY STICKERS. INSPECTED STEERING ASSEMBLY DUE TO BAD NOISES WHILE DRIVING IT. CABIN HAD, BEEN SMOKED IN & STILL HAD CIGARETTE BUTTS IN CABIN. DISASSEMBLED FRONT STEERING ASSEMBLY &, CLEANED UP PARTS. REMOVED LEAKING STEERING RAM. CLEANED UP & PREPPED FOR REASSEMBLY., REASSEMBLED FRONT STEERING ASSEMBLY & TESTED. OPERATED AROUND YART TO TRY GET OIL LEAKS OUT.	MR - MECHANICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	217834	01/06/2023 0:00	8291	REPAIRED HYDRAULIC RAM, STRIP TO INSPECT CYLINDER, RESEAL GLAND & PISTON THEN REASSEMBLE & TEST., PO 185198 - HYDRAUTECH	HR - HYDRAULIC REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	218107	31/05/2023 0:00	8291	CARRIED OUT LINE BORING, REMOVE BUSHES & MEASURE HOLES ON FRONT PIVOT POINTS., BUILD UP & LINE BORE WORN HOLES ON FRONT PIVOT PONTs., FIT NEW BUSHES & ENSURE PINS FIT., PO 185497 - CAMPBELL'S LINE BORING & MACHINING	MR - MECHANICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	217453	24/05/2023 0:00	8291	REPLACED SEAT BELT	GR - GENERAL REPAIRS
P27-N-016	CAT PS150 CAB MULTI ROLLER	215532	13/04/2023 0:00	8291	REPLACED A/C CONDENSOR, TRAVEL TO SITE, FIND A/C LOW ON GAS, PRESSURE TEST, FIND CONDENSOR HOSE FITTING CRACKED,, REMOVE & MAKE NEW HOSE, FIT & SECURE. TEST, FIND CONDENSOR ALSO LEAKING AS MOUNTS ARE, BROKEN, REMOVE CONDENSOR FROM ROOF, MODIFY MOUNTS & FAN MOUNTS, FIT TO NEW CONDENSOR., REFIT TO ROOF, REWIRE FANS, PRESSURE TEST SYSTEM, HOLDING OK, VAC & GAS SYSTEM, CHECK, PRESSURE & TEMPS, TIGHTEN A/C COMPRESSOR BELT, SYSTEM CYCLES TEMP & PRESSURE GOOD., PO 182669 - JOHNLEE TRUCK ELECTRICAL	AC - AIR-CONDITION REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	214995	24/03/2023 0:00	8291	REPLACED FAULTY UHF UNIT., UHF RADIO TRANSMIT BUTTON ON HANDSET WAS GETTING STUCK ON. REPLACED UNIT.	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	211855	24/02/2023 0:00	8239	COMPLETED 250hr SERVICE. REPLACED ENGINE OIL & FILTER., REPLACED FUEL, AIR & HYDRAULIC FILTERS. CHECKED OVER & GREASED., NB: REFER TO WO#203002 FOR PARTS, TRAVELLED TO SITE. LOCATED DRAG BROOM ASSEMBLY & REFITTED TO ROLLER., WILLIAMSTOWN 6/12/22 DRAG BROOM STUCK DOWN, GEELONG 8/1/23 DUE FOR SERVICE, GEELONG 20/2/23 AIRCON NEEDS GAS, GEELONG 20/2/23 UHF RADIO GETS STUCK ON, GEELONG 20/2/23 REAR BROOM MISSING	PS - PLANNED SERVICE
P27-N-016	CAT PS150 CAB MULTI ROLLER	213676	09/02/2023 0:00	8174	SERVICE CALL - TYRE & TUBE FITTING, CALL OUT TO CAMPERDOWN, 750-15 TYRE & TUBE FITTING & DISPOSAL X 1, PO 180574 - ASSOCIATED COLD TREAD TYRES	TP - PUNCTURE REPAIR

P27-N-016	CAT PS150 CAB MULTI ROLLER	211924	19/12/2022 0:00	8136	REPLACED DAMAGED TYRE, CALL OUT TO SALES YARD, REPLACED PUNCTURE TYRE & TUBE, 1 X MICHELIN 750R15 XLC AND 1 X 750R15 TR75A TUBE, PO 178883 - WARRNAMBOOL TYRE MART	TP - PUNCTURE REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	204738	03/10/2022 0:00	8013	, DUE FOR SERVICE, **REFER TO WO 203002 FOR PARTS - CLOSED DUE TO EOFY**	PS - PLANNED SERVICE
P27-N-016	CAT PS150 CAB MULTI ROLLER	204731	24/06/2022 0:00	8013	REPLACED 1 TYRE - POS 8, 1 X 7.50R-15 XLC MICHELIN & 1 X 700/750-15 LT TUBE TR751, PO # 171899 - ASSOC COLD TREAD TYRES	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	CAT PS150 CAB MULTI ROLLER	203002	24/06/2022 0:00	8013	****CLOSED DUE TO EOFY - REFER TO WO 204738***, DUE FOR SERVICE, Completed by:aaron.cuttler@porterplant.com.auon:Jun 23, 2022, Work Order #203002 was automatically flagged (No Signature)	PS - PLANNED SERVICE
P27-N-016	CAT PS150 CAB MULTI ROLLER	202338	01/05/2022 0:00	8013	REPAIRED CONTACTS FOR E STOP SYSTEM, TRAVEL TO SITE, CHECK E STOP SYSTEM NOT WORKING, CHECK E STOP CONTACTS,, BROKEN CONTACTS IN E STOP, REPAIR & TEST, OK., PO 169354 - STEALTH	BE - BREAKDOWN - ELECTRICAL
P27-N-016	CAT PS150 CAB MULTI ROLLER	203151	01/05/2022 0:00	8013	REPLACED FAULTY BEACON, CHECK BEACON LIGHT NOT WORKING, FOUND TO BE FAULTY, REPLACE BEACON & TEST., PO 170257 - STEALTH	BE - BREAKDOWN - ELECTRICAL
P27-N-016	CAT PS150 CAB MULTI ROLLER	202398	01/05/2022 0:00	8013	TRAVEL TO WARNCOOTE TO SUPPLY TYRE & TUBE, 7.50R15 TYRE & TUBE - WHEEL POS 9, PO 169400 - ASSOC COLD TREAD TYRES	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	CAT PS150 CAB MULTI ROLLER	200619	08/03/2022 0:00	7710	REPLACED SEAT SWING LATCH., PIN HAD SNAPPED IN TRAVEL.	GR - GENERAL REPAIRS
P27-N-016	CAT PS150 CAB MULTI ROLLER	198779	01/03/2022 0:00	7710	REPLACED A/C COMPRESSOR., REMOVED TRANSMISSION BLOCK ASSEMBLIES & CLEANED. INSPECTED TO SEE IF BLOCK WAS CRACKED, NO CRACKS WERE VISIBLE., O'RINGS VERY HARD, REPLACED BLOCK O'RINGS & UNO O'RINGS. REASSEMBLED, FILLED OIL & TESTED. FOUND NOW LEAKING AT ORFS, FITTINGS ON LOWER HOSES. ORDERED NEW KIT., REPLACED O'RING ON ALL LOWER HOSES & REASSEMBLED. STILL LEAKING. DISASSEMBLED AGAIN & FOUND A HAIR LINE CRACK NOT, PREVIOUSLY FOUND IN ONE OF THE PORTS. HAD SPARE 2nd HAND BLOCK. SOURECED BLANKING FITTING & FITTED UP BLOCK., REFITTED HOSES & TOPPED UP OIL. TEST DROVE, NO MORE LEAKS., 18/2/22 - TRAVELLED TO SITE. DEGASSED A/C IN PREPARATION FOR COMPONENT REMOVAL. REMOVED OLD COMPRESSOR & FITTED NEW, COMPRESSOR SUPPLIED BY CUSTOMER. FOUND BELT SUPPLIED TO BE WRONG SIZE. REGAS AT A LATER DATE ONCE NEW BELT IS FITTED., 28/2/22 - TRAVELLED TO SITE. MODIFIED WIRING FOR COMPRESSOR CLUTCH POWER SUPPLY. REGASSED A/C SYSTEM & TESTED. TENSIONED A/C, BELT TO SPEC. RETESTED A/C, ALL OK., PO#167937	AC - AIR-CONDITION REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	200135	01/03/2022 0:00	7710	REPLACED WORN TYRE, TRAVELED TO SITE. CHANGED TYRE OVER WITH SPARE AS IT WAS WORN OUT., REPLACED TYRE., PO#200135	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	CAT PS150 CAB MULTI ROLLER	199580	01/02/2022 0:00	7710	REPLACED INDICATOR GLOBE, CHECK LIGHTS, LH INDICATOR NOT WORKING, REPLACED INDICATOR GLOBE & TEST, OK., PO # 166411	BE - BREAKDOWN - ELECTRICAL
P27-N-016	CAT PS150 CAB MULTI ROLLER	198013	01/01/2022 0:00	7710	REPAIRED TRAILER PLUG WIRING, CHECK LIGHTS AND SIDE MARKERS, CHECK TRAILER PLUG, REPAIR TRAILER PLUG WIRING & TEST, ALL OK., PO# 164773	BE - BREAKDOWN - ELECTRICAL
P27-N-016	CAT PS150 CAB MULTI ROLLER	196828	01/11/2021 0:00	7710	REPAIRED WIRING FOR A/C, CHECK A/C, FOUND BAD CONNECTION ON HEATER FAN SWITCH, REPAIR WIRING, TEST, OK., PO# 163503	AC - AIR-CONDITION REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	194583	01/10/2021 0:00	7710	REPLACED STOLEN UHF, TRAVELLED TO GEELONG DUE TO REPORT OF UHF MISSING/STOLEN. CHECKED UHF, FOUND ONLY BRACKET, REMAINING. REPLACED UHF. REPAIRED POWER WIRING. CD - CUSTOMER DAMAGE TESTED, ALL OK., PO #161017	CD - CUSTOMER DAMAGE
P27-N-016	CAT PS150 CAB MULTI ROLLER	193083	12/08/2021 0:00	7710	REPAIRED OIL LEAK AT RH FINAL DRIVE., CHECKED FOR OIL LEAK ON FINAL DRIVE. FOUND SEAL ON INPUT SHAFT FAILED. ORDERED NEW PARTS., PICKED UP PARTS. TRAVELLED TO SITE. REPLACED SEAL & TOP CAP ON INPUT SHAFT ON RH FINAL DRIVE., TOPPED UP HYDRAULIC OIL. RAN MACHINE & CHECKED FOR LEAKS. ALL OK.	HR - HYDRAULIC REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	193242	01/08/2021 0:00	7710	CHECKED START SYSTEM, SECURE CABLES TO ISOLATOR & TEST, PO 159353	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	193190	01/08/2021 0:00	7710	CHECKED ALL LIGHTS & REPAIRED IGNITION, PO# 159312	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	191855	01/07/2021 0:00	7638	REPLACED ISOLATION SWITCH, PICK UP PARTS & PROCEED TO GEELONG SITE, REPLACE ISOLATION SWITCH & FIT RED LOCK OUT., PO 157834 - STEALTH ELECTRICS	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	190935	01/07/2021 0:00	7638	REPAIRED A/C PRESSURE SWITCH, 16/3/21 - CHECK A/C OPERATION, CONNECT GAUGES, PRESSURE TOO HIGH, NOT CYCLING, CHECK WIRING,, FOUND DAMAGED PRESSURE SWITCH WIRING, REPAIR, TEST, ALL OK., PO 156933 - STEALTH ELECTRICS	AC - AIR-CONDITION REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	190934	01/07/2021 0:00	7638	REWIRED BEACONS, 9/3/21 - REWIRE BEACONS ON ROLLER, RUN NEW WIRING TO ROOF, FIT & WIRE UP FUSE, REMOVE PANELS TO, RUN WIRES & TEST, OK., PO 156933 - STEALTH ELECTRICS	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	190251	01/06/2021 0:00	7638	R & R BRUSHES FOR TYRE COMPANY, TRAVEL TO PORT WAKEFIELD, REMOVE ROLLER BRUSH, WAIT FOR TYRES TO BE REPAIRED & REFIT BRUSH, PO 156159	BM - BREAKDOWN - MECHANICAL

P27-N-016	CAT PS150 CAB MULTI ROLLER	191246	01/06/2021 0:00	7638	REPAIRED LIGHTS, 22/3/21 - CHECK WORK LIGHT ISSUES, RHF WORK LIGHT - LED FAULTY, ORDER PARTS & REPAIR SHORT., 25/3/21 - PICK UP PARTS & TRAVEL TO GEELONG, FIT & WIRE UP 2 X LED LIGHTS TO FRONT OF ROLLER., PO 157225 - STEALTH ELECTRICS	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	191245	01/06/2021 0:00	7638	REPLACED SWITCH FOR WINDSCREEN WIPERS, 19/3/21 - CHECK WIPERS/WASHERS, FOUND FAULTY SWITCH, ORDER SWITCH FOR WIPERS & REPAIR FRONT LIGHTS., 22/3/21 - REMOVE DASH PANEL, S&F NEW SWITCH FOR WIPERS/WASHERS, TEST, OK, REFIT DASH., PO 157224 - STEALTH ELECTRICS	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	191053	01/06/2021 0:00	7638	REPLACED FUSES & FAULTY BEACONS, 24/2/21 - CHECK UHF, AM/FM, BEACONS & WIPERS NOT WORKING, DIAGNOSE BURNT OUT FUSE HOLDER, REPLACE HOLDER,, REPAIR RUBBED THROUGH POWER SUPPLY., 26/2/21 - PROCEED TO GEELONG SITE, BEACONS BLOWING FUSE, CHECK WIRING FOR SHORT, FOUND WIRING RUBBED THROUGH,, REPAIR WIRING, INSPECT BEACONS, FOUND BEACONS NOT WORKING, CHECK POWER, ALL OK, FAULTY BEACONS, PICK UP LED, BEACONS FROM SUPPLIER, PROCEED BACK TO SITE, REPLACE BEACONS, TEST, ALL OK., PO 157045	BE - BREAKDOWN - ELECTRICAL
P27-N-016	CAT PS150 CAB MULTI ROLLER	190649	01/06/2021 0:00	7638	SERVICE CALL TO BOLIVAR TO REPAIR PUNCTURE - RHR INNER, PO 156608 - ADELAIDE INDEPENDENT BANDAG	TP - PUNCTURE REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	189653	01/06/2021 0:00	7638	REPLACED BATTERIES, BREAKDOWN, TRAVEL TO ANGLE VALE, CHECK OPERATIONS, CHECK VOLTAGE - 1 X BATTERY DROPPING DOWN UNDER LOAD,, CELLS OUT, REMOVE, OBTAIN & REPLACE BATTERIES, START UP, CHECK, ALTERNATOR CHARGING AT 14.4V., PO 155504	BE - BREAKDOWN - ELECTRICAL
P27-N-016	CAT PS150 CAB MULTI ROLLER	186350	01/05/2021 0:00	7453	SWAPPED REVERSE BEEPER TO REV SQUAWKER, MOUNTED UNIT & JOINED WIRING. TESTED, ALL OK., PO 151957 - STEALTH ELECTRICS	AR - ADDITIONAL WORK
P27-N-016	CAT PS150 CAB MULTI ROLLER	189016	30/04/2021 0:00	7638	COMPLETED 250hr SERVICE. REPLACED ENGINE OIL & FILTER, CHECKED OVER MACHINE. FOUND DUE FOR SERVICE, ORDERED PARTS., TRAVELLED TO SITE. PERFORMED 250hr SERVICE. REPLACED FUEL/WATER SEPARATOR FILTER. GREASED & CHECKED, OVER MACHINE.	PS - PLANNED SERVICE
P27-N-016	CAT PS150 CAB MULTI ROLLER	188621	19/04/2021 0:00	7630	REPLACED FAULTY UHF	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	187048	05/03/2021 0:00	7547	REPAIRED WIRING TO BEACON. ALL OK., FRONT BEACON NOT WORKING. FOUND EARTH WIRE FITTED WITH POOR CONNECTION & WRONG SIZED TERMINAL., NB: BEACONS HAD JUST BEEN FITTED BY AUTO ELEC WO#186714., NEW BEACON HAD ONLY BEEN FITTED EARLIER IN THE WEEK & WAS STILL WORKING.	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	187706	01/03/2021 0:00	7547	REPAIRED AIRCON, 1/2/21 - A/C NOT WORKING, RECOVER GAS, PRESSURE TEST, FOUND HIGH SIDE HOSE FITTINGS LEAKING, ORDER PARTS., 2/2/21 - CHECK A/C, FOUND BLOWN HOSE, MAKE UP NEW HIGH PRESSURE HOSE & FIT, RE-GAS & TEST, OK., PO 151383 - STEALTH ELECTRICS	AC - AIR-CONDITION REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	185836	01/03/2021 0:00	7453	DIAGNOSE ISSUES WITH AIRCON, PROCEED TO GEELONG SITE, CHECK A/C, FOUND NO POWER TO THERMOFAN & FAULTY JUNCTION BOX, ORDER NEW BOX & RELAY., PO 152339 - STEALTH ELECTRIC	AC - AIR-CONDITION REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	186714	01/03/2021 0:00	7538	REPLACED BLOWN FUSE TO JUNCTION BOX., PROCEEDED TO CHECK THERMO FANS FOR CONDENSER NOT WORKING. FOUND BLOWN FUSE. REPLACED & TESTED. ALL, WORKING. CAUSING DAMAGE FOR JUNCTION BOX. TOOK PHOTOS, NEED TO RETURN WITH PARTS. WIP., PO#152339, PROCEEDED TO GEELONG. REMOVED DAMAGED JUNCTION BOX & MATCHED UP IN STORE. ALL WIRING HAD TO BE, DISCONNECTED & RECONNECTED IN NEW BOX. TESTED ALL SYSTEMS., PO 152339 - STEALTH ELECTRICS	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	187724	01/03/2021 0:00	7547	REPAIRED LOOSE CONNECTION AT SOLENOID FOR IDLE UP, REPAIRED & TESTED, OK., PO 153401 - STEALTH ELECTRICS	BE - BREAKDOWN - ELECTRICAL
P27-N-016	CAT PS150 CAB MULTI ROLLER	186586	24/02/2021 0:00	7538	REPLACED BLOWN BEACON GLOBE. REPAIRED WIRING TO REAR BEACON., FRONT BEACON WAS FAULTY, REPLACED BLOWN GLOBE. REAR BEACON WIRING WAS BROKEN, REPAIRED WIRING. REVERSE, CAMERA WAS NOT WORKING. FOUND CABLE TO SCREEN LOOSE, TIGHTENED & TAPED IN PLACE.	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	184901	01/02/2021 0:00	7347	REPAIRED AIRCON, CONNECT A/C GAUGES, CHECK PRESSURES, NO GAS, PRESSURISE SYSTEM, HELD PRESSURE, CHECK FOR LEAKS, NO LEAKS, RE-GAS., CHECK A/C, GETTING COLD, CHECK HEATER TAP, AIR FLOW, ALL OK., PO 150384 - STEALTH ELECTRICS	AC - AIR-CONDITION REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	184985	13/01/2021 0:00	7453	COMPLETED PLANT INSPECTION., CHECKED ROLLER & INSPECTED DOOR LOCK. DISMANTLED & FOUND TO BE WORKING., ORGANISED FOR BROKEN WINDOW TO BE REPLACED., REPLACED BROKEN RHS WINDOW, PO 150454 - B & R WINDSCREEN POWER	PI - PLANT INSPECTION

P27-N-016	CAT PS150 CAB MULTI ROLLER	171796	17/04/2020 0:00	7325	COMPLETED 250hr SERVICE. REPLACED ENGINE OIL & FILTER, REPLACED FUEL/WATER SEPARATOR FILTER. REPLACED AIR PRIMARY, & SECONDARY FILTERS. CHECKED OVER & GREASED MACHINE., TRAVELLED TO SITE. REPLACED RH & LH OUT DRIVE HUB COVER, SEAL. TOPPED UP HYDRAULIC OIL.	PS - PLANNED SERVICE
P27-N-016	CAT PS150 CAB MULTI ROLLER	172394	01/04/2020 0:00	7347	, FORWARD AND REVERSE CABLE BINDING UP.	MR - MECHANICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	171066	03/03/2020 0:00	7233.7	CALL OUT FOR PUNCTURE REPAIR, CALL OUT TO SITE LISMORE ROAD CAMPERDOWN, 1 X TUBE 7.00-15 TR75A, PO 137624 - WARRNAMBOOL TYRE MART	TP - PUNCTURE REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	171076	03/03/2020 0:00	7273	REPLACED BROKEN SEAT LOCKING PIN.	GR - GENERAL REPAIRS
P27-N-016	CAT PS150 CAB MULTI ROLLER	167553	13/12/2019 0:00	7170	WORK ORDER CANCELLED. DUPLICATED SEE 167547	GR - GENERAL REPAIRS
P27-N-016	CAT PS150 CAB MULTI ROLLER	167547	12/12/2019 0:00	7084.7	REPLACED 6 TYRES ON REAR, 6 X MICHELIN 750R15 XLC. CALL OUT TO FIT 6 TYRES ON REAR &, 2 GOOD TYRES ON REAR HAVE BEEN MOVED TO LHF POS 1/2, PO 134181 - WARRNAMBOOL TYRE MART, TRAVELLED TO SITE. ASSISTED TYRE FITTER. REMOVED ALL REAR, WHEELS & 2x FRONT WHEELS, REPLACE TYRES. REFITTED WHEELS, TO ROLLER.	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	CAT PS150 CAB MULTI ROLLER	165686	05/11/2019 0:00	7084.7	R#BUS012870664	RE - REGISTRATION
P27-N-016	CAT PS150 CAB MULTI ROLLER	165447	01/11/2019 0:00	7084.7	SWAPPED OUT THROTTLE HI/LOW CONTROL SOLENOID. TESTED ALL OK., TOOK PART OFF ANOTHER PS150 IN YARD. TRAVELLED TO SITE, JACKSON AMENDOLA: Completed by:, jackson.amendola@porterplant.com.au, on:, 13 Nov, 2019, REPAIRED AIRCON, TRAVEL TO WORKSHOP, CHECK A/C, FIND PRESSURE IN SYSTEM BUT, NOT GETTING COLD, FIND 2 OF 3 THERMO FANS SEIZED FROM BEING, FITTED INCORRECTLY, REMOVE FANS & TRAVEL TO PICK UP NEW, FANS. FIT & REMOUNT FANS PROPERLY, RECOVER SYSTEM TO FIND, NITROGEN, EVACUATE & PRESSURE TEST SYSTEM, NO LEAKS FOUND., EVACUATE & RECHARGE WITH OIL & REFRIGERANT, TEST AC, WORKING, OK, GETTING COLD & CYCLING GOOD PRESSURES, CLEAN CABIN, FILTERS & CHECK EVAPORATOR, OK, REASSEMBLE. RETURN TRAVEL., PO 131261 - WH AUTO ELECTRICS	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	163796	03/10/2019 0:00	7076	CARRY OUT PRE/DEL, REPLACED 3 X THERMAL FANS ON AIR CON, REPLACED FUEL HOSE,, GREASED HUBS, CLEANED CAB, PERFORMED AIR CON PRESSURE TEST,, MADE EXTRA BRACKETS FOR BROOM BRUSH, REPLACED RADIO ANTENNA., JC#54697	PD - PRE-DELIVERY INSPECTION
P27-N-016	CAT PS150 CAB MULTI ROLLER	162896	25/09/2019 0:00	7070	SUB TO BALLARAT AUTO GLASS, , REPLACE DOOR GLASS P/O#129512	GR - GENERAL REPAIRS
P27-N-016	CAT PS150 CAB MULTI ROLLER	159233	19/07/2019 0:00	7070	, 7000 HOUR SERVICE, HYDRAULIC LEAK FROM REAR DRIVE, PARTS ON W/O #158421. CLOSED FOR EOFY, CARRIED OUT SERVICE, REPLACED BROOM, CHECKED BELTS, LIGHTS,, UHF, GREASED NIPPLES, CLEANED CAB, REPLACED ENGINE MOUNTS,, TOPPED UP HYD OIL, FITTED WNI., JC#54704	PS - PLANNED SERVICE
P27-N-016	CAT PS150 CAB MULTI ROLLER	156673	01/06/2019 0:00	70302	W/O CLOSED FOR EOFY, NEW W/O #159233 FOR COMPLETED REPAIRS, 7000 HR SERVICE DUE, HYDRAULIC LEAK FROM REAR DRIVE., PARTS PICKED UP BY BRECK. PLANT ITEM IN YARD FOR REPAIRS, BALLARAT 31/5/19 7000HR SERVICE DUE	PS - PLANNED SERVICE
P27-N-016	CAT PS150 CAB MULTI ROLLER	157445	21/05/2019 0:00	70705	REPLACED 1 TYRE - POS 3 & REPAIRED 1 PUNCTURE - POS 10, 1 X 7.50R-15 XLC MICHELIN, 2 X TUBES - 700/750R-16 TUBE TR177A, PO 124867 - ASSOC COLD TREAD TYRES	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	CAT PS150 CAB MULTI ROLLER	155147	04/04/2019 0:00	69446	REPAIRED 2 X PUNCTURED REAR TYRES, 2 X 700/750-15LT TUBE TR 75A, JOHN ADVISED THEY WOULD BE ONSITE AT 7AM, PO 122979 - ASSOC COLD TREAD TYRES	TP - PUNCTURE REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	154297	20/03/2019 0:00	69446	REPLACED 2 TYRES - 7.50R15 XLC MICHELIN ROLLER TYRE, PO 122220 - TRANSPORT TYRES	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	CAT PS150 CAB MULTI ROLLER	153513	13/03/2019 0:00	69446	PUNCTURE REPAIRED - POS 2, 700/750-15 LT TUBE TR75A AND TRAVEL TO SITE, PO 121546 - ASSOC COLD TREAD TYRES	TP - PUNCTURE REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	151190	01/03/2019 0:00	164103	REPAIRED WIRING TO AIRCON, TRAVEL TO MT DUNEED, INSPECT A/C, FOUND NOT WORKING AT ALL,, NO POWER TO A/C, TRACE WIRING, FOUND BROKEN POWER WIRE,, REPAIR WIRING, TEST, OK. FIND LOW GAS, DEGAS, EVACUATE, SYSTEM, ADD OIL & UV DYE, CHARGE SYSTEM WITH UV DYE GAS,, CHECK OPERATION, NOW OPERATING TO FULL POTENTIAL., PO 119374 - I.C. COLD	AC - AIR-CONDITION REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	147979	01/03/2019 0:00	164103	REPLACED HI IDLE SOLINOID AND TESTED ALL OK, ORDERED., JC #50011, W.I.P	GR - GENERAL REPAIRS
P27-N-016	CAT PS150 CAB MULTI ROLLER	153132	18/02/2019 0:00	68781	FITTED NEW GLOBE., JC #51957	ER - ELECTRICAL REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	152321	05/02/2019 0:00	68781	CHECKED & ADJUSTED ENGINE BELTS., JC #48880, NTH GEELONG 08/02/19 AIRCON FANBELT NEEDS ADJUSTING	GR - GENERAL REPAIRS
P27-N-016	CAT PS150 CAB MULTI ROLLER	151427	01/02/2019 0:00	164103	REPLACED 2 OUTSIDE REAR RIGHT HAND SIDE TYRES. A/CON NOT, GETTING COLD. SYSTEM HAS LOW GAS & ONE THERMO FAN NEEDS, REPLACING., JC #53526, TYRES REPLACED ON W/O #151214. AIR CON REPAIR ON W/O #151190	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	CAT PS150 CAB MULTI ROLLER	151214	22/01/2019 0:00	164103	REPLACED 2 TYRES AND 2 TUBES, 7.50R15 XLC MICHELIN ROLLER TY X 2 & 7.50-15 TUBES X 2, PO 119391 - TRANSPORT TYRES	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	CAT PS150 CAB MULTI ROLLER	148321	19/11/2018 0:00	164103	R#BUS008011209	RE - REGISTRATION

P27-N-016	CAT PS150 CAB MULTI ROLLER	147670	01/11/2018 0:00	164103	A/CON NOT WORKING. FOUND LOW ON GAS. TOPPED UP SYSTEM., TESTED OK. FRONT WATER TANK LEAKING. COULDN'T FIND LEAK SO, DRAINED TAP., JC #50088	AC - AIR-CONDITION REPAIR
P27-N-016	CAT PS150 CAB MULTI ROLLER	147184	01/11/2018 0:00	164103	S & F REAR VIEW CAMERA SYSTEM AND TEST, INSTALL REAR VIEW CAMERA, PO 115881 - IMPULSE AUTO ELEC	MW - MODIFIED WORKS
P27-N-016	CAT PS150 CAB MULTI ROLLER	143905	01/09/2018 0:00	6739	PRE/DEL, CLEAN INTERIOR AND REPLACE REAR BEACON, PAPERWORK, CHECK LIST JC#49620	PD - PRE-DELIVERY INSPECTION
P27-N-016	CAT PS150 CAB MULTI ROLLER	142023	01/08/2018 0:00	6732	FITTED 9KG BRACKET AND EXTINGUISHER, FITTED CHOCKS AND, SPILL KIT., JC#44684	PD - PRE-DELIVERY INSPECTION
P27-N-016	CAT PS150 CAB MULTI ROLLER	141475	09/07/2018 0:00	6732	CARRY OUT SERVICE AND PRE/DEL, COMPLETED 250 HR SERVICE. REPLACED. 2 FRONT TYRES, MADE, BRACKET TO HOLD BROOM TOGETHER. REPLACED ENG OIL AND FILTER., JC#01322	PS - PLANNED SERVICE
P27-N-016	CAT PS150 CAB MULTI ROLLER	135336	01/06/2018 0:00	6405	14/03/18 - REMOVED SEAT + ASSESS OTHER PROBLEMS., 26/03/18 - TAKE BACK TO DEPO, FIT SEAT AND REPAIR DOOR LOCK., JC#45524	GR - GENERAL REPAIRS
P27-N-016	CAT PS150 CAB MULTI ROLLER	138193	01/06/2018 0:00	6690.1	CARRY OUT SERVICE, REPLACED FUEL, OIL AND AIR FILTERS., JC#01320	PS - PLANNED SERVICE
P27-N-016	CAT PS150 CAB MULTI ROLLER	137975	04/05/2018 0:00	6689	PRE/DEL, CHECKED ALL OILS. CHECKED ALL LIGHTS AND LENSES., CLEANED CAB. FIXED WASHER PUMP. REPLACED WIPER BLADES., FIXED REAR WIPER MOTOR. FIXED RADIATOR BRACKET/ REWELEDED, AND DRILLED., JC#46278	PD - PRE-DELIVERY INSPECTION
P27-N-016	MULTI WHEEL ROLLER	133157	07/02/2018 0:00	6405	SEAT NOT HOLDING UP, PINS + BEARINGS BROKEN ON ADJUSTER., WILL REQUIRE NEW SEAT BASE. ADJUST DOOR LOCK STICKING., TIGHTENED MIRROR, JC#44524	GR - GENERAL REPAIRS
P27-N-016	MULTI WHEEL ROLLER	127616	01/01/2018 0:00	6405	SUPPLY SEAT DAMPENER	MR - MECHANICAL REPAIR
P27-N-016	MULTI WHEEL ROLLER	127981	20/12/2017 0:00	6405	PRE/DEL CHECK OVER, CHECK TYRE PRESSURES AND GREASE, CHECK ALL FLUIDS AND BELTS, RE FIT LOOSE HOOD LINING, CHECK ALL OPERATIONS JC# 40003	PD - PRE-DELIVERY INSPECTION
P27-N-016	MULTI WHEEL ROLLER	130055	01/12/2017 0:00	6405	0	RE - REGISTRATION
P27-N-016	MULTI WHEEL ROLLER	121378	01/05/2017 0:00	6405	LOCATE FAULT IN REAR WIPER MOTOR AND FRONT BEACON, REPLACE BLOWN GLOBES IN FRONT INDICATORS, REWIRE BEACONS, REWIRE STEREO SO IT TURNS OFF, REPLACE BATTRIES, REPLACE, FIRE EXTINGUISHER, REPAIR HYDR LEAK NEAR FILTER HOUSING., JC# 38049 MICK	PD - PRE-DELIVERY INSPECTION
P27-N-016	MULTI WHEEL ROLLER	115849	18/12/2016 0:00	6200	CARRIED OUT 250hr SERVICE. REPLACED ENGINE OIL & FILTER., REPLACED MATCHED SET OF FAN BELTS (CAT PT # 5L-4995), REPLACED BOTH ENGINE HOOD GAS STRUTS (CAT PT # 176-0362), JC#24670	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	116129	16/12/2016 0:00	6200	GREEN TAG & CLEANED INSIDE AND OUT., JC#24671	PD - PRE-DELIVERY INSPECTION
P27-N-016	MULTI WHEEL ROLLER	115505	02/12/2016 0:00	6200	REGO PAID VIA EFRS 02.12.2016	RE - REGISTRATION
P27-N-016	MULTI WHEEL ROLLER	115398	16/11/2016 0:00	6200	PUMP PRESSURE SOLENOID FAULTY., RANDOMLY LOSING FORWARD & REVERSE MOTION, POSSIBLY, ELECTRICAL ISSUE., CHECKED CAT ROLLER INTERMITTANT PROBLEM WITH DRIVE. FOUND, PUMP PRESSURE SOLENOID FAULTY., PO#115398	BE - BREAKDOWN - ELECTRICAL
P27-N-016	MULTI WHEEL ROLLER	114782	16/11/2016 0:00	6199.8	REPLACED FAULTY STOP START REAR HYDRAULIC MOTOR SOLENOID., TESTED., JC#35680	BE - BREAKDOWN - ELECTRICAL
P27-N-016	MULTI WHEEL ROLLER	114668	14/11/2016 0:00	6198	REPLACED FAILED BATTERY. FITTED UHF. REMOVED STICKERS, GREEN TAG., INSTALL NEW UHF TO MEET CUSTOMER SITE REQUIREMENTS., REPLACE CRACKED FORWARD/REVERSE LEVER HANDLE., PO # 88647., JC#28852	ER - ELECTRICAL REPAIR
P27-N-016	MULTI WHEEL ROLLER	106522	24/05/2016 0:00	6105	REPLACED ALTERNATOR, FUEL PUMP & ASSEMBLY & RADIATOR MOUNTS., REMOVE TOP HYD VALVE BODY AND FIT TO PLANT # P27-N-025. FIT, NEW VALVE BODY TO TOP OF PROPELLOR/DRIVE PUMP., RH UPPPER & LOWER DOOR LATCHES WORN OUT. REQUIRE REPLACEMENT, RH DOOR SEAL IS DESTROYED, REQUIRES REPLACING., ALL UPPER & LOWER RADIATOR ISOLATOR MOUNTS EITHER MISSING, OR FRACTURED. REPLACED ALL., FRONT WATER TANK FILLER CAP IS MISSING., TRANS TO OIL COOLER HYD HOSE WEEPING OIL FROM CRIMPED, FITTING. NEW HOSE FITTED. PO # 82598, MODIFY DOOR OPENING LINKAGE AND NEW CAT BOTTOM DOOR LATCH TO, MAKE FIT & OPERATIONAL. PO # 82610, ALL R/H SIDE CABIN RETAINING BOLTS SNAPPED OFF AND 1 ON THE, LH SIDE ALSO. RE-DRILL OUT TO 3/8" DIAMETER AND FIT NEW, STAINLESS BOLTS AND NUTS BOTH SIDES. PO # 82706., CAB STEERING MOTOR HAS DEVELOPED A LEAK AND LOSS OF FLUID IS, ALL OVER THE FLOOR. STEERING MOTOR HAD A NEW TOP SEAL &, O RING KIT INSTALLED., ALTERNATOR CHARGE LIGHT ON DASH PARTLY GLOWING, INDICATING, THERE IS A FAULTY DIODE AND ALTERNATOR IS NOT FAR AWAY FROM, FAILING. RECON ALT FITTED., ELECTRIC FUEL PUMP RETURN PIPE IN FILTER HEAD HAS A CRACK, AND IS LEAKING DIESEL; REPLACED & FITTED NEW FILTER HEAD., FITTED SUPPLIED TYRE TO RIM. P/O 83459, WASHED DOWN, CHECKED OVER & COMPLETED GREEN TAG., JC# 33823 & 33797	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	106578	27/04/2016 0:00	81397	REPLACED BROKEN WINDOW., ROLLER RETURNED BY SPRAYLINE FLOAT OPERATOR IN WHICH RH DOOR, HAD COME OPEN DURING TRANSIT AND HAS CRACKED THE RH REAR, WINDOW BEHIND THE DOOR. DOOR HAS A FAULTY LATCH & IS ONLY, HOLDING ON FIRST STAGE. NEW GLASS TO BE CUT TO SIZE & FITTED, P/O 82314	UR - UNPLANNED REPAIR

P27-N-016	MULTI WHEEL ROLLER	107573	21/04/2016 0:00	6105	REPLACED VALVE BLOCK. WASHED DOWN ENGINE BAY., VALVE BLOCK WAS REMOVED AND FITTED TO P27-N-025 IN BREAK, DOWN., JC# 33776	Other
P27-N-016	MULTI WHEEL ROLLER	105814	12/04/2016 0:00	81397	REPLACED FLAT TYRE WITH SPARE & REPAIRED PUNCTURED TYRE., P/O 81792, JC# 31400	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	MULTI WHEEL ROLLER	106201	01/04/2016 0:00	81397	TOPPED UP WITH FUEL & BLEED FUEL SYSTEM. RAN OUT OF FUEL., JC 31392	Other
P27-N-016	MULTI WHEEL ROLLER	105621	28/03/2016 0:00	80156	REPLACED FAULY PARK BRAKE SWITCH, USED SECOND HAND PART FROM P27-N-014, JC 31383	Other
P27-N-016	MULTI WHEEL ROLLER	105315	17/03/2016 0:00	81397	REPLACED FLAT TYRE. REPLACED GLOBE IN FLASHING LIGHT., FITTED ICOM RADIO. CHANGED FLAT TYRE & HAD PUNCTURE REPAIRED, P/O 81397, JC 31362, NOTE: NO CHARGE FOR FLASHING LIGHT GLOBE.	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	MULTI WHEEL ROLLER	103541	12/02/2016 0:00	80156	FITTED SPARE TYRE & REPAIRED PUNCTURE., P/O 80156, JC 25459	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	MULTI WHEEL ROLLER	101989	11/01/2016 0:00	6009	REPLACED FAILED BATTERIES & BROKEN TERMINAL ON CABLE., CHECKED CHARGE RATE 27.7v. ALL GOOD., P/O 79007	Other
P27-N-016	MULTI WHEEL ROLLER	101343	21/12/2015 0:00	5963.5	CHARGED UP BATTERIES WITH VAN, GOT STARTED & CHECKED OVER, CHARGING AT 26v. ALL OK., BATTERIES WERE FLAT & WOULDN'T START., JC# 24104	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	100673	18/12/2015 0:00	5963.5	REPLACE FORWARD CONTROL CABLE., SERVICE AC DUE TO A/C NOT WORKING, ONE FAN NOT WORKING, CARRY OUT GREEN TAG INSPECTION.	Other
P27-N-016	MULTI WHEEL ROLLER	100611	02/12/2015 0:00	5963.5	REGO: P27-N-016 PAID	RE - REGISTRATION
P27-N-016	MULTI WHEEL ROLLER	98276	07/10/2015 0:00	5907	REPLACED FAILED MICRO SWITCH FOR BRAKE LIGHT., REPLACED FUEL SOLENOID. REPLACED NUTRAL POSITION SWITCH., TESTED - OK., JC# 30407	Other
P27-N-016	MULTI WHEEL ROLLER	95457	27/08/2015 0:00	5897	REPLACED BONNET HANDLE, JC# 32515	Other
P27-N-016	MULTI WHEEL ROLLER	95078	16/07/2015 0:00	5897	COMPLETED 6000hr SERVICE. REPLACED ALL FILTERS & OILS., CHECKED OVER & GREASED., JC# 25776	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	94647	30/06/2015 0:00	5897	REPLACED FRONT LIGHT LENS & REPLACED DAMAGED ANDERSON PLUG, ON FRONT., JC# 33574	Other
P27-N-016	MULTI WHEEL ROLLER	95042	30/06/2015 0:00	5897	REPLACED TAIL LIGHT LENS & GLOBES.	Other
P27-N-016	MULTI WHEEL ROLLER	94700	19/06/2015 0:00	5855	REPLACED DAMAGED BOTTOM GLASS ON DOOR., P/O 73332	Other
P27-N-016	MULTI WHEEL ROLLER	93536	01/05/2015 0:00	5855	FITTED SPARE TYRE & HAD PUNCTURED TYRE REPAIRED., JC# 30316	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	MULTI WHEEL ROLLER	93025	16/04/2015 0:00	5815	REPLACED FRONT BEACON GLOBE., JC# 33163	Other
P27-N-016	MULTI WHEEL ROLLER	92881	15/04/2015 0:00	5814	REPLACED FAULTY REAR BEACON. REPAIRED WIRING TO BEACONS, AS IT WAS CORRODED., JC# 33744	Other
P27-N-016	MULTI WHEEL ROLLER	92120	22/03/2015 0:00	5720	REPLACED FUSE IN INDICATOR LOOM FOR BEACONS & INDICATORS., COULD NOT FIND BREAK IN WIRES FOR BEACONS. MAY NEED CIRCUIT, REWIRED., JC# 26276	Other
P27-N-016	MULTI WHEEL ROLLER	92138	21/03/2015 0:00	5720	REPAIRED OUTER DOOR HANDLE & MODIFIED SO WIRE CAN'T FALL OUT, JC# 26267	Other
P27-N-016	MULTI WHEEL ROLLER	91136	07/03/2015 0:00	5720	COMPLETED 5750hr SERVICE. REPLACED OIL, FUEL & AIR FILTERS., TOPPED UP HYDRAULIC OIL. GREASED., JC# 23839	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	89822	22/01/2015 0:00	5528	TIGHTENED DOOR LOCK BOLTS AFTER THEY CAME LOOSE., JC# 27997	Other
P27-N-016	MULTI WHEEL ROLLER	89100	12/01/2015 0:00	5399.8	REPLACED 1x WORN TYRE., P/O 69299	Other
P27-N-016	MULTI WHEEL ROLLER	89499	08/01/2015 0:00	5528	COMPLETED 5500hr SERVICE., REMOVED & REFITTED REAR INNER RIM TO HAVE TYRE REPLACED., JC# 24973	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	88659	17/12/2014 0:00	5377	REPAIRED PUNCTURED ROLLER TYRE, P/O 68931	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	MULTI WHEEL ROLLER	88632	11/12/2014 0:00	5377	REPLACED FRONT WIPER BLADES, CHECK OVER - NO FAULTS RECORDED, JC 18427	Other
P27-N-016	MULTI WHEEL ROLLER	88209	04/12/2014 0:00	5377	REPLACED HYDRAULIC VALVE BLOCK & ORINGS., REPLACED 'O'RINGS IN HYDRAULIC VALVE BLOCK, TESTED AND STILL, LEAKED, FOUND CRACK IN VALVE BLOCK, TRAVELED TO BALLARAT AND, REMOVED BLOCK FROM SPARE ROLLER, RETURN TO GEELONG AND, FITTED, TOPPED UP OIL AND TESTED ALL OK, JC 25009, NEW VALVE BLOCK TO BE FITTED TO SPARE ROLLER.	Other
P27-N-016	MULTI WHEEL ROLLER	88231	03/12/2014 0:00	5377	12 MONTHS REGISTRATION PAID BY EFRS - EXPIRY 03/12/2015	RE - REGISTRATION
P27-N-016	MULTI WHEEL ROLLER	88394	01/12/2014 0:00	5377	CARRIED OUT TYRE ROTATION AND DELIVERED FLAT TO FOR REPAIRS, JC 18399	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	MULTI WHEEL ROLLER	88047	28/11/2014 0:00	5377	BREAKDOWN 1PM 28/11 - GOING AT 4.30PM 28/11, CALLED IN BY PETER HOFFMAN - BLOWN HYD HOSE, REPLACED HYD HOSE ON SITE, TESTED ALL OK, JC 18398	BH - BREAKDOWN - HYDRAULIC
P27-N-016	MULTI WHEEL ROLLER	86922	21/10/2014 0:00	5377	TIGHTENED UP DOOR STRIKER SO DOOR NOW STAYS CLOSED - OK, JC # 20170	Other
P27-N-016	MULTI WHEEL ROLLER	86395	09/10/2014 0:00	5355	REPLACED FAILED FLASHING LIGHT. TESTED OPERATION - OK., JC# 20152	Other
P27-N-016	MULTI WHEEL ROLLER	86401	08/10/2014 0:00	5351	REPLACED DAMAGED TYRE AFTER IT WAS RUN FLAT., TYRE WAS NOT REPAIRABLE DUE TO BEING DRIVEN ON FLAT FOR TOO LONG., JC# 21898	TC - TYRE CHANGE/REPLACEMENT
P27-N-016	MULTI WHEEL ROLLER	86214	01/10/2014 0:00	5333	REPLACED FIRE EXTINGUISHER., JC# 31797	Other
P27-N-016	MULTI WHEEL ROLLER	83947	30/07/2014 0:00	5333	REPLACED DAMAGED WINDSCREEN & WINDOW, P/O 65214, COMPLETED ON SITE AT GEELONG DEPOT.	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	83266	08/07/2014 0:00	5333	REPLACED 2 X BATTERIES AFTER ISOLATER WAS LEFT ON, NOTE: NEW BATTERIES FITTED JAN 2014, JOB CARD #20838	Other

P27-N-016	MULTI WHEEL ROLLER	83046	03/07/2014 0:00	5333	COMPLETE 250HR SERVICE,TIGHTEND WIPER ARM & UNBLOCKED WASHER, JOB CARD #20838	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	81664	29/05/2014 0:00	5200	REMOVED TYRE FOR REPAIR & REFITTED, NOTE: REAR CENTRE TYRE - JOB COMPLETED @ GEELONG DEPOT, JOB CARD #18846	Other
P27-N-016	MULTI WHEEL ROLLER	80098	07/04/2014 0:00	5200	REPLACED BLOWN FLASHING LIGHT GLOBE, JOB CARD #19767	Other
P27-N-016	MULTI WHEEL ROLLER	79622	27/03/2014 0:00	5141	REPLACED DAMAGED OVAL WINDOWDN NEAR DOOR., P/O 62004, COMPLETED ON SITE AT GEELONG DEPOT	Other
P27-N-016	MULTI WHEEL ROLLER	79621	27/03/2014 0:00	5141	BREAKDOWN - CUT OUT/BLOWING SMOKE 26/3 2.00 - 1.00PM 27/3, CALLED IN BY PETER HOFFMANN, LOCATION: APOLLO BAY, NOTE: PETER AGREED THEY ONLY NEEDED 1 ROLLER FOR REST OF THE, DAY. CREW DID NOT WORK 27/3 DUE TO RAIN., ASSESSED ISSUE WITH ROLLER RUNNING ROUGH, DIAGNOSED FUEL, LIFT PUMP INOPERATIVE. REPLACED FUEL LIFT PUMP & AIR CLEANER, JOB CARD #17649	BM - BREAKDOWN - MECHANICAL
P27-N-016	MULTI WHEEL ROLLER	79078	06/03/2014 0:00	5108	REFITTED FRONT WINDOW AFTER IT WAS PUSHED OUT, JOB CARD #18794	Other
P27-N-016	MULTI WHEEL ROLLER	78693	03/03/2014 0:00	5013	REPLACED A/C BELT, PO# 61342, JOB CARD #18792	Other
P27-N-016	MULTI WHEEL ROLLER	78172	11/02/2014 0:00	5013	COMPLETED 1000HR SERVICE & CHANGED ENGINE OIL & FILTER, CHANGED FUEL FILTER & CHECKED AIR CLEANERS, GREASED., NOTE: NEEDS HYDRAULIC FILTER, JOB CARD #0475	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	77583	30/01/2014 0:00	4946	REPAIRED DOOR LATCH BAR AFTER BOTTOM LATCH KEPT JAMMING, JOB CARD #17397, MORWELL 3/2 DUCTAPE ON DOOR LATCH FAILED DOOR DOESNT OPEN	Other
P27-N-016	MULTI WHEEL ROLLER	77630	30/01/2014 0:00	4996	FOUND LEAK IN TOP OF FUEL DRIVE - NEEDS INVESTIGATING, NOTE: ATTEMPTED TO HAVE TYRES ROTATED AT BEAUREPAIRS - DIDNT, HAPPEN AS THEY RAN OUT OF TIME., JOB CARD #17398	Other
P27-N-016	MULTI WHEEL ROLLER	77328	28/01/2014 0:00	4903	BREAKDOWN - WON'T START - 8.20am - 9.45am, CALLED IN BY DOUG RYAN, LOCATION: TRARLGN FOOTY OVAL, REPLACED 1x FAILED BATTERY	BE - BREAKDOWN - ELECTRICAL
P27-N-016	MULTI WHEEL ROLLER	77250	15/01/2014 0:00	4903	REPLACED LEAKING A/C HOSES & ORINGS. REGASSED & TESTED - OK., REPAIRED A/C , REGASSED & REASSEMBLED/TESTED, JOB CARD #17382, P/O 60011	Other
P27-N-016	MULTI WHEEL ROLLER	76631	10/01/2014 0:00	4856	BREAKDOWN FLAT BATTERIES 9.40 - 12.30 & 1.30 - 3.15, FITTED 2ND HAND BATTERY AS IT WOULDNT JUMP START. REPAIRED, TERMINAL CLAMPS. CHANGED BATTERIES & TESTED CHARGE RATE., 2ND HAND BATTERY FAILED, FITTED NEW ONE & NOW CHARGES EVENLY, TOPPED UP HYDRAULIC OIL, NOTE: A/C NEEDS TO BE REGASED, JOB CARD #17357	BE - BREAKDOWN - ELECTRICAL
P27-N-016	MULTI WHEEL ROLLER	75948	18/12/2013 0:00	4819	REPLACED PUNCTURED TUBE & REFITTED TYRE, P/O 59381	Other
P27-N-016	MULTI WHEEL ROLLER	75895	06/12/2013 0:00	4755	REPLACED BROKEN AERIAL, JOB CARD #16031	Other
P27-N-016	MULTI WHEEL ROLLER	75798	04/12/2013 0:00	4736	REGISTRATION PAID BY ERF5 4/12	RE - REGISTRATION
P27-N-016	MULTI WHEEL ROLLER	75821	29/11/2013 0:00	4736	FITTED UP SPARE TYRE TO RIM FOR ROLLER., P/O 59271	Other
P27-N-016	MULTI WHEEL ROLLER	75896	26/11/2013 0:00	4755	COMPLETED 250HRS SERVICE, JOB CARD #16032	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	75504	20/11/2013 0:00	4667	REPLACED DOOR STOP CATCH, JOB CARD #16018	Other
P27-N-016	MULTI WHEEL ROLLER	75012	15/11/2013 0:00	4667	SUPPLIED & FITTED NEW PLUG FOR WATER TANK ON ROLLER., JOB CARD #15008	Other
P27-N-016	MULTI WHEEL ROLLER	73928	22/10/2013 0:00	4665	MADE NEW GUIDE FOR BROOM. TEST OK, JOB CARD #15181	Other
P27-N-016	MULTI WHEEL ROLLER	73696	09/10/2013 0:00	4620	REPLACED FRONT WHEEL STUD, PO# 57894, JOB CARD #15329	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	72650	09/09/2013 0:00	4620	REPLACED REAR TYRES. FITTED RUNOUT TO POS 5, JOB CARD #33667, P/O 56972	Other
P27-N-016	MULTI WHEEL ROLLER	70696	19/07/2013 0:00	4620	REPLACED FRONT & REAR TYRES, STRIPPED AND REFITTED, JC-15064, P/O 55620	Other
P27-N-016	MULTI WHEEL ROLLER	68796	29/05/2013 0:00	4561	REPLACED DAMAGED WINDSCREEN., P/O 53865	Other
P27-N-016	MULTI WHEEL ROLLER	67868	27/05/2013 0:00	4561	REMOVED PUNCTURED TYRE, HAD REPAIRED & REFITTED TO ROLLER., REPAIR PUNCTURED TYRE, P/O 53381 JC# 5173	Other
P27-N-016	MULTI WHEEL ROLLER	69088	13/05/2013 0:00	4611	COMPLETED 4500hr SERVICE. GREASED. ADJUSTED BELTS., REPAIRED WIRING TO REAR WIPERS., JC# 5192	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	68352	10/05/2013 0:00	4561	REPLACED FRONT ROTATING BEACON., REPLACE BEACON, PO# 53725, JC# 5186	Other
P27-N-016	MULTI WHEEL ROLLER	66870	27/03/2013 0:00	4368	REPLACE WORN TYRE, P/O 52550	Other
P27-N-016	MULTI WHEEL ROLLER	66390	18/03/2013 0:00	4368	BREAKDOWN - REAR SEAL LEAK - 18/3 1.50pm - 18/3 6.00pm, CALLED IN BY DOUG RYAN, NOTE: DOUG SAID IT WENT DOWN @ 10.30 BUT DIDN'T CALL IT IN, UNTIL 01.50 AS THEY THOUGHT A MECHANIC WOULD BE THERE EARLY, IN THE DAY., REPLACED FINAL DRIVE SEAL & REATINING SEAL. TOPPPED UP OIL., JC# 6301	BM - BREAKDOWN - MECHANICAL
P27-N-016	MULTI WHEEL ROLLER	65752	26/02/2013 0:00	4368	COMPLETED 250hr SERVICE & REPLACED 24-12v INVERTER., PO# 51726, JC# 5062	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	65679	13/02/2013 0:00	4311	CHECKED WHY RADIO & STEREO KEPT CUTTING OUT., FOUND FAULTY 12/24v REDUCER. TO BE REPLACED AT LATER DATE., JC# 11083	Other
P27-N-016	MULTI WHEEL ROLLER	63534	11/12/2012 0:00	4085	REPAIRED PUNCTURE., P/O 49822, 11/12 CHANGED TYRE WITH SPARE DUE TO PUNCTURE. SUBLET TO, REPAIR. JOB CARD # 6172	Other
P27-N-016	MULTI WHEEL ROLLER	63318	04/12/2012 0:00	4014.5	REGISTRATION PAID EFRS 04.12.12	RE - REGISTRATION
P27-N-016	MULTI WHEEL ROLLER	63055	27/11/2012 0:00	4014.5	REPLACED 2x WORN TYRES., P/O 63055	Other
P27-N-016	MULTI WHEEL ROLLER	63276	23/11/2012 0:00	4014.5	CHANGED FLAT TYRE. (FITTED SPARE)., JOB CARD # 11125	Other

P27-N-016	MULTI WHEEL ROLLER	62219	01/11/2012 0:00	3923	FITTED 2x SPARE TYRES, REPAIRED FLAT TYRE., OUR REF: P/O 48688, ON SITE: OUYEN	Other
P27-N-016	MULTI WHEEL ROLLER	62178	29/10/2012 0:00	3923	REPLACED FUSE., SPRAYLINE HAD OPERATIONAL BEFORE ERNIE GOT THERE., **BREAKDOWN** CALLED IN BY PETER HOFFMAN @ 12.50pm, ROLLER CUT OUT & WOULD NOT START., LOCATION: SUNRAYSIA HIGHWAY, 2km NORTH LASCHELLES., UP & RUNNING @ 1.20	BM - BREAKDOWN - MECHANICAL
P27-N-016	MULTI WHEEL ROLLER	61959	16/10/2012 0:00	3923	REPLACED WIPER BLADES, AARON JOB # 11596	Other
P27-N-016	MULTI WHEEL ROLLER	61958	16/10/2012 0:00	3923	FITTED SPRAYLINE RADIO AERIAL., REQUESTED BY: PETER HOFFMAN, JOB CARD # 11595	Other
P27-N-016	MULTI WHEEL ROLLER	60006	03/09/2012 0:00	3923	CARRIED OUT 4000HR SERVICE, GREASED & STEAM CLEANED., REPLACED A/C FANS & WIRED UP., BEN JOB # 04637 & 4649, PO# 47024	Other
P27-N-016	MULTI WHEEL ROLLER	58479	21/06/2012 0:00	3923	FITTED F & R CABLE, NEW BELTS, REAR WORK LIGHT & DOOR STOP, END OF SEASON REPAIRS, JOB CARD #05732	Other
P27-N-016	MULTI WHEEL ROLLER	57585	24/05/2012 0:00	3856	FITTED NEW BACK TYRE & FRONT TYRE, INFLATED REAR TYRE, REPLACED FINAL DRIVE SEALS., JOB CARD #05636 & #05705	Other
P27-N-016	MULTI WHEEL ROLLER	57828	18/05/2012 0:00	3923	REPLACED DAMNAGED WINDSCREEN & 2 SIDE WINDOWS., ARRANGED WITH PETER HOFFMAN., JOB DONE AT CORIO 21.04.2012, OUR REF: P/O 44428	Other
P27-N-016	MULTI WHEEL ROLLER	58071	16/05/2012 0:00	3923	REPLACED 2x TYRES, OUR REF: P/O 44995, 2x TYRES & 1x STRIP & FIT.	Other
P27-N-016	MULTI WHEEL ROLLER	58635	09/05/2012 0:00	3923	REPAIRED 3x PUNCTURES, OUR REF: P/O 44784	Other
P27-N-016	MULTI WHEEL ROLLER	57409	05/05/2012 0:00	3856	3750 HR SERVICE COMPLETED, COMPLETE 3750hr SERVICE, REPAIRED BECON WIRING	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	57262	26/04/2012 0:00	3856	REPLACED FRONT TYRES., REPLACE TYRES & REPAIR PUNCTURES, P/O 44603 REPLACED 2x TYRES. 1x STRIP & FIT., PO# 44754, JOB CARD #05610	Other
P27-N-016	MULTI WHEEL ROLLER	56811	03/04/2012 0:00	3801	CHECK FOR FAULT WITH FAST IDLE. RESET CIRCUIT BREAKER AND, TEST. ALL OK, FAST IDLE NOT WORKING	Other
P27-N-016	MULTI WHEEL ROLLER	56475	23/03/2012 0:00	3695	REPLACED BALLAST BUNG, PO# 44120, JOB CARD #05604	Other
P27-N-016	MULTI WHEEL ROLLER	56242	07/03/2012 0:00	3656	REPLACED 1x TYRE., REPLACED 1x WORN TYRE, PO# 43857	Other
P27-N-016	MULTI WHEEL ROLLER	55434	13/02/2012 0:00	3388	REPLACED BENT BROOM GUIDE. REPAIRED 3x PUNCTURES., PUNTURE REPAIRS X3, BENT BROOM LEG, PO# 42989 & 43312, JOB CARD #08303	Other
P27-N-016	MULTI WHEEL ROLLER	54764	23/01/2012 0:00	3388	COMPLETED 500HR SERVICE.REPAIRED GREASE NIPPLE ON STEERING, PO# 42545,	Other
P27-N-016	MULTI WHEEL ROLLER	54750	23/01/2012 0:00	3388	REPLACED DAMAGED WINDSCREEN & 2 SIDE WINDOWS., REPLACE BROKEN GLASS x 3, OUR REF: P/O 42526	Other
P27-N-016	MULTI WHEEL ROLLER	54779	11/01/2012 0:00	3388	REFITTED NEW WINDOW, WINDOW FELL OUT, PO# 42629, JOB CARD #08123	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	54071	15/12/2011 0:00	3311	REMOVED & REPLACED WORN OUT TYRE WITH SPARE, REPLACE WORN TYRE WITH SPARE, JOB CARD #06521	Other
P27-N-016	MULTI WHEEL ROLLER	53525	29/11/2011 0:00	3237.5	FOUND FAULT WITH FLASHING LIGHT & REPAIRED., FLASHING LIGHT NOT WORKING., JOB CARD #06898	Other
P27-N-016	MULTI WHEEL ROLLER	53501	29/11/2011 0:00	3237.5	FITTED SPARES & GOT NEW TYRES FITTED TO RIMS, REPLACED 2x WORN TYRES., OUR REF: P/O 41431, JOB CARD #06894	Other
P27-N-016	MULTI WHEEL ROLLER	53631	23/11/2011 0:00	3311	COMPLETED 250hr SERVICE & REPAIRED SEAT SPRING., CHANGED OIL & REPLACED FUEL & OIL FILTERS. CHECKED OVER., CHECKED FAULT WITH SEAT & FOUND SPRING TENSIONER TOO LOOSE, & SPRING FALLEN OFF. RE-ATTACHED SPRING & SET TENSION.	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	53838	01/11/2011 0:00	3311	REPAIRED BLOWER FAN ASSEMBLY., TESTED A/C. BLOWER FAN ASSY U/S. REPLACED PARTS & TIGHTENED, A/C & ALTENATOR BELTS., OUR REF: P/O 40210	Other
P27-N-016	MULTI WHEEL ROLLER	52041	05/10/2011 0:00	3140	REMOVED & REPLACED BONNET STRUTS., REPLACE BONNET STRUTS., PO# 40212, JOB CARD #08782	Other
P27-N-016	MULTI WHEEL ROLLER	50120	26/07/2011 0:00	3140	STRIPPED & FITTED & TYRE ROTATION, PO# 38853, JOB CARD #07325	Other
P27-N-016	MULTI WHEEL ROLLER	50084	25/07/2011 0:00	3140	REPLACED DAMAGED WINDSCREEN, PO# 38786, JOB CARD # 07322	Other
P27-N-016	MULTI WHEEL ROLLER	50000	21/07/2011 0:00	3140	REPLACED BATTERIES X 2., JOB: REPLACE BATTERIES, OUR REF: P/O 38735	Other
P27-N-016	MULTI WHEEL ROLLER	48605	01/06/2011 0:00	3076	REPLACED DAMAMGED RADIATOR, ORIGINALLY CHARGED TO CUSTOMER ON W/O INV 33164., INVOICE WAS THEN CREDITED ON W/O 48603 AND RE-ISSUED AS, INSURANCE EXCESS ON W/O 48604., THIS WORK ORDER IS TO RECAPTURE LABOUR AND PARTS INTERNALLY.	Other
P27-N-016	MULTI WHEEL ROLLER	48604	01/06/2011 0:00	3076	INSURANCE EXCESS, (REPLACED DAMAGED RADIATOR IN ROLLER), REPAIRS WERE ORIGINALLY CHARGED TO CUSTOMER ON INV # 33164, BUT THAT INVOICE WAS THEN CREDITED ON W/O 48603, REPAIRS WERE THEN PROCESSED INTERNALLY ON W/O 48605	-
P27-N-016	MULTI WHEEL ROLLER	48603	01/06/2011 0:00	3076	CREDIT FOR INVOICE # 33164, THIS IS NOW BEING CLAIMED THROUGH INSURANCE., CREDIT AUTHORISED BY TIM, **THIS MAY NOT ACTUALLY GO THROUGH INSURANCE AS PER CEDRIC**, INSURANCE XS CHARGED ON W/O 48604 & INTERNAL CHARGES HAVE, BEEN PROCESSED ON W/O 48605	-

P27-N-016	MULTI WHEEL ROLLER	48043	13/05/2011 0:00	3022	COMPLETED 3000 HOUR SERVICE, JOB CARD # 09636	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	48057	06/05/2011 0:00	3022	REPLACED WORN OUT TYRE WITH SECOND HAND TYRE FROM STOCK., JOB CARD # 9626	Other
P27-N-016	MULTI WHEEL ROLLER	47435	05/04/2011 0:00	2879	REMOVE FLAT TYRE, REPAIR & REPLACE, JOB CARD #09616	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	46960	05/04/2011 0:00	2845	REPLACED RADIATOR, PO# 36637, WIP AS AT 01/04/11 (JOB COMPLETED 05/04/11)	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	47439	04/04/2011 0:00	2879	REPLACE 3 WORN OUT FRONT TYRES. REMOVED AXLE'S TO GET WHEELS, OFF. REPAIRED AND REFITTED., JOB CARD #09617	Other
P27-N-016	MULTI WHEEL ROLLER	47019	24/03/2011 0:00	2845	DISPOSED OF TYRE, PO# 36703	Other
P27-N-016	MULTI WHEEL ROLLER	46563	18/03/2011 0:00	2791	FITTED 2 RUNOUT TYRES SUPPLIED BY MELB W/SHOP, JOB CARD #09711	Other
P27-N-016	MULTI WHEEL ROLLER	46490	15/03/2011 0:00	2791	FITTED 2ND HAND TYRE TO SPARE, STRIP AND FIT 2ND HARD TYRE TO SPARE, DISPOSAL OF OLD TYRES TO ASSOC. COLD TREADS, JOB CARD #09702	Other
P27-N-016	MULTI WHEEL ROLLER	46480	02/03/2011 0:00	2791	COMPLETED 2750 HR SERVICE, JOB CARD #09691	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	46036	01/03/2011 0:00	2699	OUR REF: JOB CARD # 09690 & PO # 35999, CHANGED TYRES & TRAVELLED TO MILLICENT TO GET TYRES REPAIRED	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	46439	28/02/2011 0:00	2791	FITTED SPARE WHEEL, JOB: TYRE, ALAN JOB CARD #09688 - FIT SPARE WHEEL TO MACHINE, OTHER, TYRE WORN OUT.	Other
P27-N-016	MULTI WHEEL ROLLER	46447	16/02/2011 0:00	2791	REPAIRED WARNING BEEPER, JOB: WARNING BEEPER, ALAN JOB CARD #09674 - WARNING BEEPER NOT WORKING. CHECK, ELECTRICAL SYSTEM, REPLACE FUSE TEST	Other
P27-N-016	MULTI WHEEL ROLLER	45992	09/02/2011 0:00	2671	REPAIRED FLAT TYRE, REMOVED TYRE, REPLACED TUBE AND RE-FIT TYRE, JOB CARD # 09658	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	45275	24/01/2011 0:00	0	REPAIRED TYRE PUNCTURE.	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	44695	31/12/2010 0:00	2500	TRAVELLED TO SITE & REPAIRED TYRE PUNCTURE.	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	44693	31/12/2010 0:00	0	TRAVELLED TO SITE & REMOVED BROKEN KEY FROM IGNITION.	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	45002	20/12/2010 0:00	2502	REPAIRED LEAKING FINAL DRIVE & CLEANED UP LARGE SPILL.	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	45003	20/12/2010 0:00	2500	CARRIED OUT 2500 HOUR SERVICE.	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	44211	20/12/2010 0:00	0	WELDED FRAME ON SEAT & REPLACED TYRE WITH RUNOUT FROM W/SHOP, SEAT NEEDS REPAIR OR REPLACEMENT AS REPORTED ON DAILY, SAFETY CHECKSHEET #O10842., TYRES (WIRE PATCHES) - NEED REPLACING AS REPORTED ON SAFETY, CHECKSHEET #O10843.	Other
P27-N-016	MULTI WHEEL ROLLER	45000	08/12/2010 0:00	2459	ROTATED TYRES AND FITTED ONE TYRE.	Other
P27-N-016	MULTI WHEEL ROLLER	48819	02/12/2010 0:00	3076	REGISTRATION PAID EFRS 02/12/10	RE - REGISTRATION
P27-N-016	MULTI WHEEL ROLLER	44268	22/11/2010 0:00	2440	REPAIRED BEACON WIRING., JOB: BEACON, AARON JOB CARD #08514	Other
P27-N-016	MULTI WHEEL ROLLER	43571	17/11/2010 0:00	0	FITTED TWO SECOND HAND TYRES & REPAIRED FLAT SPARE TYRE., REPLACE TYRES & REPAIR FLAT SPARE TYRE, (OUR REF: P.O# 34121 & 34068), 11/11 - TRAVELLED TO SITE & TEMPORARY FITTED TWO SPARE TYRES, TO ROLLER. 16/11 - TRAVELLED TO SITE AND REPLACED SPARE, TYRES ON ROLLER WITH SECOND HAND TYRES. 17/11 - REPAIRED, ONE SPARE TYRE AND FITTED TO FLOAT. DISPOSED OF OTHER SPARE.	Other
P27-N-016	MULTI WHEEL ROLLER	43598	16/11/2010 0:00	0	REPAIRED TYRE PUNCTURE., (OUR REF: P.O# 34068)	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	43096	26/10/2010 0:00	0	HYDRAULIC OIL LEAK - REPLACED HYDRAULIC FILTER AND OIL., (OUR REF: P.O# 33696 & 33788), TRAVELLED TO SITE TO CHECK FOR OIL LEAK. FOUND HYDRAULIC OIL, FILTER LOOSE AND HYDRAULIC OIL LEVEL LOW. TRAVELLED TO, MILDURA AND PICKED UP NEW FILTER AND OIL. TRAVELLED BACK TO, SITE AND REPLACED OIL FILTER AND TOPPED UP HYDRAULIC OIL.	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	43269	13/10/2010 0:00	2323	COMPLETED ANNUAL FIRE EXTINGUISHER CHECK, ISSUE: FIRE EXTINGUISHER ANNUAL CHECK, OUR REF: 33827	Other
P27-N-016	MULTI WHEEL ROLLER	43435	05/10/2010 0:00	2352	COMPLETED PLANT CHECK, FOLLOWING ITEMS CHECKED & OK - WARNING LIGHTS, HAZCHECK, SHEETS, OPERATORS MANUAL, P/PLANT WARNING DECALS, SERVICE, STICKER, CHECKLIST BOOK, TOOLS/JACK & SPANNER, CHECKED BY CEDRIC	Other
P27-N-016	MULTI WHEEL ROLLER	42933	05/10/2010 0:00	2289	COMPLETED PLANT INDUCTIONS 05/10/10 x 7 PLANT OPERATORS, INDUCTOR: CEDRIC TUFFIN, PLANT OPERATORS: RUSSELL BREGJET, P.HOFFMANN, RAMON RIPPON., GREIG GILSON, WILLIAM FORBES, JASON QUINLIVIAN., DAVID ATTWELL	Other
P27-N-016	MULTI WHEEL ROLLER	43520	04/10/2010 0:00	2291	REPAIRED AIR-CON SYSTEM., (OUR REF: P.O# 34009)	Other
P27-N-016	MULTI WHEEL ROLLER	41715	03/09/2010 0:00	0	REPLACED DAMAGED WINDSCREEN, (OUR REF: P.O# 32799)	Other
P27-N-016	MULTI WHEEL ROLLER	40779	16/07/2010 0:00	2289	REPAIRED FLAT TYRE.	Other
P27-N-016	MULTI WHEEL ROLLER	40774	16/07/2010 0:00	2289	REPLACED FAN BELTS.	Other
P27-N-016	MULTI WHEEL ROLLER	39202	12/05/2010 0:00	0	REPLACED FAULTY WIRE TO FIX FLASHING LIGHTS.	Other
P27-N-016	MULTI WHEEL ROLLER	39061	11/05/2010 0:00	0	ROTATED TYRES.	Other
P27-N-016	MULTI WHEEL ROLLER	38724	07/05/2010 0:00	2242	SUPPLIED & FITTED TWO NEW TYRES., TRAVELLED TO GEELONG & FITTED TWO NEW TYRES., (OUR REF: P.O# 30457), ONE TYRE TO BE SUPPLIED & FITTED TO WHEEL BY ASSOCIATED COLD, TREAD.	Other
P27-N-016	MULTI WHEEL ROLLER	39012	06/05/2010 0:00	0	REPLACED REAR LIGHTS.	Other

P27-N-016	MULTI WHEEL ROLLER	39011	06/05/2010 0:00	0	COMPLETED 2250 HOUR SERVICE.,	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	39009	04/05/2010 0:00	0	BROOM WON'T GO UP & DOWN, BRACKET TWISTED. REPAIRED BRACKET.	Other
P27-N-016	MULTI WHEEL ROLLER	38457	08/04/2010 0:00	0	REPLACED BROKEN CLIP ON CONTROL ROD SO DOOR WOULD OPEN., PART FROM WRECKERS (NO COST).	Other
P27-N-016	MULTI WHEEL ROLLER	38456	08/04/2010 0:00	0	REMOVED, REPAIRED & REFITTED PUNCTURED TYRE.	Other
P27-N-016	MULTI WHEEL ROLLER	37120	30/03/2010 0:00	2051	REPLACED BOOT HANDLE. CHECKED SEAT, FOUND TO BE OK., SEAT DOES NOT ADJUST PROPERLY AS PER DAILY CHECK SHEET 10822, & BOOT HANDLE BROKEN AS PER DAILY CHECK SHEET 10821 (ONLY, RECEIVED THIS SHEET 09/03/10)	Other
P27-N-016	MULTI WHEEL ROLLER	37534	14/03/2010 0:00	0	CHECKED BRAKE LIGHT SYSTEM AND REPLACED GLOBES.	Other
P27-N-016	MULTI WHEEL ROLLER	37556	09/03/2010 0:00	0	REPLACED FOWARD/REVERSE CABLE.	Other
P27-N-016	MULTI WHEEL ROLLER	37558	03/03/2010 0:00	0	COMPLETED 2000HR SERVICE.	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	37525	03/03/2010 0:00	0	REPLACED BRAKE LIGHT GLOBE. CHECKED ELECTRICAL SYSTEM.	Other
P27-N-016	MULTI WHEEL ROLLER	37547	01/03/2010 0:00	0	SUPPLIED TOP UP COOLANT & CHECKED OVER MACHINE.	Other
P27-N-016	MULTI WHEEL ROLLER	36854	12/02/2010 0:00	0	REMOVED & REPAIRED FLAT TYRE.	Other
P27-N-016	MULTI WHEEL ROLLER	36277	04/02/2010 0:00	1932	REPLACED REVOLVING LIGHT & GLOBE, FRONT REVOLVING LIGHT NOT WORKING	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	36276	21/01/2010 0:00	1932	REPLACED GLOBE, LIGHT NOT WORKING - CHECKED ELECTRICALS & REPLACED GLOBE	Other
P27-N-016	MULTI WHEEL ROLLER	36274	18/01/2010 0:00	1932	ADJUSTED BELTS AS REQUIRED, FAN BELT LOOSE	Other
P27-N-016	MULTI WHEEL ROLLER	35873	15/01/2010 0:00	0	CHECKED OVER ALL LUBRICANTS. GREASED. CHECKED TYRES.	Other
P27-N-016	MULTI WHEEL ROLLER	35489	06/01/2010 0:00	1802	CARRIED OUT 1750 HR SERVICE. CHANGED WORN OUT TYRES.	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	35340	04/01/2010 0:00	1802	DAMAGED WINDSCREEN REPORTED. NO ACTION REQUIRED AT THIS TIME, DAMAGED WINDSCREEN REPORTED ON DAILY CHECK SHEET # 10813., WAS DAMAGED A COUPLE OF MONTHS AGO AND IT WAS AGREED THAT, WINDSCREEN WOULD NOT BE REPAIRED AT THIS STAGE AS CRACK IS, NOT IN LINE OF SIGHT., AF CONFIRMED THAT THIS IS STILL THE CASE AS AT 06/01/10.	Other
P27-N-016	MULTI WHEEL ROLLER	35460	16/12/2009 0:00	1802	REMOVED, TIGHTENED AND REFITTED WATER HEATER CONSUL.	Other
P27-N-016	MULTI WHEEL ROLLER	34514	04/12/2009 0:00	1708	REGISTRATION PAID EFRS 2.12.2009	RE - REGISTRATION
P27-N-016	MULTI WHEEL ROLLER	34055	17/11/2009 0:00	1671	PO# 27281 EARTHLEC, REPLACED 3 X TERMATIC FANS ON CONDENSOR., INCORRECT PARTS SENT OUT. PARTS RETURNED & NEW PARTS ORDERED, (SEE W/O 32401)	Other
P27-N-016	MULTI WHEEL ROLLER	32401	17/11/2009 0:00	1522	REPLACED A/C FANS. REPLACED FLASHING LIGHT., ISSUE: AIR CONDITIONER NEEDS TESTING, CORRECTION: EARTHLEC CALLED OUT - FOUND FAN FAULTY., ORDER PARTS & ALAN TO FIT., WRONG PART SUPPLIED. PART RETURNED AND NEW PART ON ORDER.	Other
P27-N-016	MULTI WHEEL ROLLER	33533	11/11/2009 0:00	0	CRACKED WINDSCREEN - NOT IN LINE OF SIGHT. NO REPAIR, REQUIRED AT THIS STAGE. (PLANT UNAVAILABLE ALSO)	Other
P27-N-016	MULTI WHEEL ROLLER	33577	06/11/2009 0:00	0	REPAIRED FLAT TYRE.	-
P27-N-016	MULTI WHEEL ROLLER	32838	13/10/2009 0:00	0	REPLACED BLOWN BRAKE LIGHT GLOBE	Other
P27-N-016	MULTI WHEEL ROLLER	32261	09/10/2009 0:00	1522	PLANT INDUCTION FOR SEASON 2009 - 2010, PLANT INDUCTION COMPLETED ON 09/10/09 BY RON BOYD	Other
P27-N-016	MULTI WHEEL ROLLER	30018	20/08/2009 0:00	1502	SPRAYLINE PLANT CHECK, FIRE EXTINGUISHER - CHECKED & OK TO SEPT.09, BATTERY TEST - TESTED & OK, HAZCHECK - CHECKED & IN ROLLER, OPERATORS MANUAL - CHECKED & IN ROLLER, WARNING DECALS - CHECKED & OK, PORTER PLANT DECALS - FITTED 2 NEW DECALS, DAILY CHECKLIST BOOK - CHECKED & ROLLER, TOP UP KIT - CHECKED & IN ROLLER, NON-SLIP STEP RUBBER - CHECKED & OK, PLANT ITEM TOOLS - CHECKED & OK, WARNING LIGHTS - CHECKED & 1 GLOBE FITTED - OK	Other
P27-N-016	MULTI WHEEL ROLLER	31178	20/08/2009 0:00	1522	REPAIRED SEAT LOCK, ISSUE: SEAT LOCK BROKEN, ALAN: REPAIRED & REFITTED SEAT LOCK, JOB LOCATION: GEELONG,	Other
P27-N-016	MULTI WHEEL ROLLER	30052	29/07/2009 0:00	1502	SUPPLIED & FITTED RIGHT HAND WINDOW, DAILY CHECKLIST # 001694 - WK.COM. 07/07/09, 1. NEEDS A NEW BOOK FOR THIS ROLLER - NEW BOOK SUPPLIED, 2. LOCKING PIN FOR SEAT SWIVEL HAS BROKEN - PIN CHECKED & IS, NOT BROKEN, 3. RIGHT HAND WINDOW - SUPPLIED & FITTED - SPRAYLINE TO PAY	Other
P27-N-016	MULTI WHEEL ROLLER	29990	13/07/2009 0:00	1522	REPAIRED BRAKE LIGHT, ISSUE: BRAKE LIGHT NOT WORKING, LOCATION: SPRAYLINE NORLANE, REPAIRED BY: ALAN FLEMING	Other
P27-N-016	MULTI WHEEL ROLLER	27992	25/05/2009 0:00	1453	COMPLETED 1500 HOUR SERVICE, 1500 HOUR SERVICE DUE, CALLED IN BY ALAN FLEMMING 21/05/09	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	27788	18/05/2009 0:00	1394	FITTED NEW GLOBE IN FLASHING LIGHT - GEAR STICK CHECKED OK, DAILY CHECKLIST #001690 - WK.COM. 04/05/09, 1. BULB BLOWN FLASHING LIGHT, 2.GEAR STICK GETTING HARD FORWARD & BACK, ALAN: FITTED NEW GLOBE IN FLASHING LIGHT & CHECKED GEAR, STICK - OK AT TIME OF CHECK	Other
P27-N-016	MULTI WHEEL ROLLER	29205	11/05/2009 0:00	1502	REPLACED 1 X TYRE, ISSUE: FLAT TYRE, ALAN: REPLACED TYRE WORN OUT, JOB LOCATION: GEELONG	Other

P27-N-016	MULTI WHEEL ROLLER	29213	11/05/2009 0:00	1502	FITTED NEW BRAKE SWITCH & REPAIRED BRACKET, ISSUE: BRAKE LIGHT SWITCH, ALAN: REMAKE BRAKE LIGHT SWITCH BRACKET FIT NEW SWITCH, JOB LOCATION: GEELONG	Other
P27-N-016	MULTI WHEEL ROLLER	27108	06/05/2009 0:00	1288	REPLACED FUSE & GLOBE & CHECKED WIRING, DAILY CHECKLIST # 001685 - WK. COM. 30/03/09, ROTATING LIGHT NOT WORKING, ALAN FLEMMING JOB SHEET 34977 - REPLACED FUSE & REPLACED, GLOBE & CHECKED WIRING IN FLASHING LIGHT	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	27127	08/04/2009 0:00	1288	ADJUSTED BRAKE SWITCH - TESTED OK, DAILY CHECKLIST # 001686 - WK. COM. 06/04/09, ALAN FLEMMING - JOB SHEET 34941 - BRAKE LIGHTS - ADJUST, SWITCH & TEST	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	25510	24/03/2009 0:00	1226	1200 HOUR SERVICE COMPLETED, ALAN - JOB DETAILS PASSED ON TO TRACEY 19/04/09 ORIGINAL JOB, CARD MY BE IN BALLARAT ?	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	25157	13/03/2009 0:00	1164	REPLACE FUSES, ADJUST SWITCH, CLEAN HOLDERS, CHECK ELECTRICS, DAILY CHECKLIST 001679 - WK COM. 16/02/09, NO BRAKE LIGHT - BRAKE LIGHTS NOT WORKING - CHECK ELECTRICAL, SYSTEM, REPLACE FUSE, ADJUST SWITCH, CLEAN GLOBE HOLDERS	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	25159	02/03/2009 0:00	1164	REPAIRED UNDER WARRANTY, DAILY CHECKLIST #001678 - WK COM. 09/02/09, WATER LEAK	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	24831	27/02/2009 0:00	1029	STRIP & FIT NEW TYRE, TYRE TAKEN OUT OF STORE 750/15 MICHILIN, REMOVE & REPLACE WORN OUT TYRE	Other
P27-N-016	MULTI WHEEL ROLLER	22865	13/02/2009 0:00	998	RPLACED FAULTY DOOR HANDLE & SERVICED., REPAIR FAULTY DOOR HANDLE ON ROLLER	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	24109	10/02/2009 0:00	1029	ADJUSTED A/C TO STOP SLIPPING, DAILY CHECKLIST #001676 - WK.COM.26/01/09, A/C BELT SLIPPING ON START UP	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	20766	15/01/2009 0:00	889	PLEASE FIND LOCATION AND REPLACE REGO LABEL, replaced rego sticker	Other
P27-N-016	MULTI WHEEL ROLLER	22387	24/12/2008 0:00	1003	DOUBLE UP	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	22074	24/12/2008 0:00	1009	REPLACE BENT BROOM GUIDE & REPAIR DAMAGED WIRING, BROOM DISMANTLED ? REAR RH TYRE ? REAR BRAKE LIGHT ?, REPORTED DAILY CHECKLIST 00167 - WK COMM. 08/12/08, REMOVED BENT PART ON BROOM & FITTED STRAIGHT ONE. REPAIRED, FAULTY WIRING ON BRAKE LIGHTS.	Other
P27-N-016	MULTI WHEEL ROLLER	22051	22/12/2008 0:00	929	SUPPLY & FIT HEARING PROTECTION STICKERS AS PER AREEMENT	Other
P27-N-016	MULTI WHEEL ROLLER	22073	15/12/2008 0:00	992	DOUBLE UP	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	18673	15/12/2008 0:00	7178	JOHN ARRANGO RANG AT 3:00PM FOR BREAKDOWN NUMBER, ISSUED BREAKDOWN NUMBER AND FAULT FAUND TO BE LEAKING, WHEEL SEAL L/H INNER ORDERED NEW SEAL FROM CAT., P27- N-012 WENT IN AT 7:00 16/10/2008	BH - BREAKDOWN - HYDRAULIC
P27-N-016	MULTI WHEEL ROLLER	18805	04/11/2008 0:00	7178	CHECK FOR LEAKING REAR HUB AS REQUIRED, CAT FIXED	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	18742	17/10/2008 0:00	739	750 HOUR SERVICE AS REQUIRED NEXT SERVICE 1,000 HOURS	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	17655	08/09/2008 0:00	7178	GREEN TAG CHECKLIST, BROKEN BONNET HANDLE, BROKEN ARM REST, BROKEN GLASS L/H/F OF CABIN	Other
P27-N-016	MULTI WHEEL ROLLER	16223	17/07/2008 0:00	520	ROLLER L/H/R DIFF LOCKED UP	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	15632	25/06/2008 0:00	520	REPLACE SIX TYRES AS REQUIRED	Other
P27-N-016	MULTI WHEEL ROLLER	14803	19/05/2008 0:00	520	CHECK FOR NO DRIVE IN ROLLER, CHECKED FOR NOISE. FOUND FINAL DRIVE PLATE HITTING WHEEL	BM - BREAKDOWN - MECHANICAL
P27-N-016	MULTI WHEEL ROLLER	14597	08/05/2008 0:00	456	REPLACE BROKEN BEACON, BEACON NOT BROKEN, NO POWER TO LIGHT, WILL HAVE TO CHECK, WIRING IN ROOF CONSUL, MUST HAVE POPPED OFF. WIRING IS, CONNECTED TO WIPER MOTOR	UR - UNPLANNED REPAIR
P27-N-016	MULTI WHEEL ROLLER	14374	29/04/2008 0:00	404	500 HOUR SERVICE, REPLACE FUEL, OIL AND AIR FILTERS AND OIL	PS - PLANNED SERVICE
P27-N-016	MULTI WHEEL ROLLER	14128	07/04/2008 0:00	270	REPAIRED HORN AND BLINKERS	Other
P27-N-016	MULTI WHEEL ROLLER	13866	04/04/2008 0:00	270	JOHN ARINGO RANG ROLLER BROKE DOWN AT 12:30 04/04/2008, HAD REPLACEMENT ROLLER IN AT 4:30 P27-N-018, BALLARAT AUTO AIR FIXED ROLLER ALT BRACKET ON 5/04/2008, P27-N-016 WAS PUT BACK IN ON MONDAY AT 7:30 07/04/2008	BM - BREAKDOWN - MECHANICAL
P27-N-016		13817	31/03/2008 0:00	0	TRAVEL TO CAMPERDOWN. CHECK BOOKS ON: P27-N-016 P33-A-015, AND P100-X-002.	Other
P27-N-016	MULTI WHEEL ROLLER	13522	25/03/2008 0:00	270	TRAVEL TO TERANG. FIT NEW AIR CON ADJUSTER BRACKET., REPAIR REAR FLASHING LIGHT. FIT NEW HYD BROOM RELIEF VALVE, AND ADJUST.	Other
P27-N-016	MULTI WHEEL ROLLER	13742	17/03/2008 0:00	270	REPAIR STOP LIGHTS. NEW HYDRAULIC RELIEF VALVE	Other
P27-N-016	MULTI WHEEL ROLLER	12902	26/02/2008 0:00	121	ADJUST RELIEF VALVE ON DRAG BROOM AND CLEANED RADIATOR	Other
P27-N-016	MULTI WHEEL ROLLER	12898	26/02/2008 0:00	121	ADJUST PARK BRAKE SWITCH TO RECTIFY GEAR LEVER STICKING	Other
P27-N-016	MULTI WHEEL ROLLER	12709	14/02/2008 0:00	121	CHECK FOR FLASHING LIGHT NOT WORKING FOUND TO BE FAULTY, ORDERED NEW FLASHING LIGHT	UR - UNPLANNED REPAIR

P27-N-016	MULTI WHEEL ROLLER	10767	13/02/2008 0:00	121 SET UP MULTI WHEEL ROLLER FOR SPRAYLINE.	MW - MODIFIED WORKS
P27-N-016	MULTI WHEEL ROLLER	12635	08/02/2008 0:00	121 FIT NEW BEACON LIGHT (OLD LIGHT FAILED), PUT NEW TURN KNOB ON STEERING WHEEL	Other
P27-N-016	MULTI WHEEL ROLLER	12633	08/02/2008 0:00	121 ADJUSTED TYRE PRESSURES TO STOP WEARING IN THE MIDDLE	Other