

780-836-9341
MANNING, AB

WORK ORDER
NO. 0490

Trevor
Thomas

[illegible][illegible]

QTY	PART NO. AND DESCRIPTION	PRICE
1	1 R-1808 Oil	
1	326-1643 fuel	
2	308-9679 fuel	
1	577-1435 Air	
1	558-021-329 Seal kit	



780-836-9341
MANNING, AB

WORK ORDER
NO. 0368

Thomas

[illegible]

**SAFETY MANAGEMENT SYSTEM
CHECKLIST**

PREVENTATIVE MAINTENANCE VEHICLE INSPECTION

Functional Area:
ALL

Document:
CHK-013

SECTION 1 GENERAL INFORMATION

Unit Number: **G 10**

Date: **MAR. 28. 2022**

Inspector: **Zeliko**

Work Order #:

SECTION 2- SPECIFIC REQUIREMENTS

STATUS:	N/A	Not Applicable to This Unit	M:	Passed but Maintenance Required
	P:	Passes	R:	Rejected- Replacement Necessary
	A:	Added (Show Number)		

ENGINE		STATUS	REAR OF VEHICLE		STATUS
1	Engine Oil 30 Litres	SERVICE	26	Tail Lights	P
2	Radiator	P	27	Brake Lights	P
3	Radiator Hoses	P	28	Turn Signals	P
4	Drive Belt	P	29	4 Way Flashers	P
5	Air Filter	SERVICE	30	Clearance/Marker Lights	P
6	Brake Adjustment	N/A	31	Reflectors	P
7	Brake Fluid ___ Litres	N/A	32	Mud Flaps	P
8	Transmission	SERVICE	33	License Plate	N/A
9	Transmission Fluid 65 Litres	SERVICE	34	Compartments Closed/Locked	P
10	Power Steering Fluid ___ Litres	N/A	35	Dents/Scratches	P
START ENGINE		STATUS	OUTSIDE FRONT OF VEHICLE		STATUS
11	Parking Brake (Micro-lock)	P	36	Headlights	P
12	Oil Pressure (Gauge/light)	P	37	Clearance/Marker Lights	P
13	Temperature	P	38	Turn Signals	P
14	Fuel Level	P	39	4 Way Flashers	P
15	Back-Up Alarm	P	40	Fog Lights	P
16	Horn	P	41	Dents/Scratches	P
INSIDE VEHICLE		STATUS	OTHER		STATUS
17	Cab Clean	P	42	Front Differential	
18	Instrument Panel	P	43	Rear Differential	
19	Glass (Broken or Cracked)	P	44	Front Steering Hub Oils (80/90 Synthetic Oil)	
20	Wipers & Washer	P	GREASING		STATUS
21	Heater/Defrost	P	45	Driveline	P
22	Mirrors (Inside & Out)	P	46	Rollers	
23	Steering (Excess Play)	P	47	Winch	
24	Fire Extinguisher	P	TORQUE WHEELS		STATUS
25	Hazard Warning Kit	P	48	Torque Right Side Front	
			49	Torque Right Side Rear	
			50	Torque Left Side Front	
			51	Torque Left Side Rear	

**SAFETY MANAGEMENT SYSTEM
CHECKLIST**

PREVENTATIVE MAINTENANCE VEHICLE INSPECTION

Functional Area:
ALL

Document:
CHK-013

LEFT SIDE OF VEHICLE		STATUS	MISCELLANEOUS		STATUS
52	Fuel Tank Cap On		66	Spare Tire	
53	Side Marker Lights		67	Tire Jack & Wrench	
54	Reflectors		68	Insurance & Registration	
55	Tires & Wheels				
56	Lugs Tight				
57	Compartments Closed				
58	Dents/Scratches				
RIGHT SIDE OF VEHICLE		STATUS			
59	Fuel Tank Cap On				
60	Side Marker Lights				
61	Reflectors				
62	Tires & Wheels				
63	Lugs Tight				
64	Compartments Closed				
65	Dents/Scratches				

SECTION 3 COMMENTS- CORRECTIVE ACTION MEASURES/PLAN

Comments/Action (Include # identifier)	Due Date	By Whom	Date Done

Inspection Conducted by (Print):	Management Review Conducted by (Print):
Signature:	Signature:

SAFETY MANAGEMENT SYSTEM CHECKLIST

PREVENTATIVE MAINTENANCE VEHICLE INSPECTION

Functional Area:
ALL

Document:
CHK-013

SECTION 1 GENERAL INFORMATION

Unit Number: **CO1**

Date: **APRIL 14, 2022**

Inspector: **Lejro**

Work Order #: **0415**

SECTION 2- SPECIFIC REQUIREMENTS

STATUS:

N/A

Not Applicable to This Unit

P:

Passes

A:

Added (Show Number)

M:

Passed but Maintenance Required

R:

Rejected- Replacement Necessary

ENGINE		STATUS	REAR OF VEHICLE		STATUS
1	Engine Oil ___ Litres	P	26	Tail Lights	N/A
2	Radiator	P	27	Brake Lights	N/A
3	Radiator Hoses	P	28	Turn Signals	N/A
4	Drive Belt	P	29	4 Way Flashers	N/A
5	Air Filter	P	30	Clearance/Marker Lights	N/A
6	Brake Adjustment	P	31	Reflectors	N/A
7	Brake Fluid ___ Litres	N/A	32	Mud Flaps	N/A
8	Transmission	P	33	License Plate	N/A
9	Transmission Fluid ___ Litres		34	Compartments Closed/Locked	M
10	Power Steering Fluid ___ Litres	N/A	35	Dents/Scratches	M
START ENGINE		STATUS	OUTSIDE FRONT OF VEHICLE		STATUS
11	Parking Brake (Micro-lock)	P	36	Headlights	P
12	Oil Pressure (Gauge/light)		37	Clearance/Marker Lights	N/A
13	Temperature	P	38	Turn Signals	N/A
14	Fuel Level	P	39	4 Way Flashers	N/A
15	Back-Up Alarm	P	40	Fog Lights	N/A
16	Horn	P	41	Dents/Scratches	M
INSIDE VEHICLE		STATUS	OTHER		STATUS
17	Cab Clean	P	42	Front Differential	/
18	Instrument Panel	P	43	Rear Differential	/
19	Glass (Broken or Cracked)	M	44	Front Steering Hub Oils (80/90 Synthetic Oil)	/
20	Wipers & Washer	M	GREASING		STATUS
21	Heater/Defrost		45	Driveline	N/A
22	Mirrors (Inside & Out)		46	Rollers	P
23	Steering (Excess Play)		47	Winch	P
24	Fire Extinguisher	P	TORQUE WHEELS		STATUS
25	Hazard Warning Kit		48	Torque Right Side Front	N/A
			49	Torque Right Side Rear	N/A
			50	Torque Left Side Front	N/A
			51	Torque Left Side Rear	N/A

**SAFETY MANAGEMENT SYSTEM
CHECKLIST**

PREVENTATIVE MAINTENANCE VEHICLE INSPECTION

Functional Area:
ALL

Document:
CHK-013

LEFT SIDE OF VEHICLE		STATUS	MISCELLANEOUS		STATUS
52	Fuel Tank Cap On		66	Spare Tire	
53	Side Marker Lights		67	Tire Jack & Wrench	
54	Reflectors		68	Insurance & Registration	
55	Tires & Wheels				
56	Lugs Tight				
57	Compartments Closed				
58	Dents/Scratches				
RIGHT SIDE OF VEHICLE		STATUS			
59	Fuel Tank Cap On				
60	Side Marker Lights				
61	Reflectors				
62	Tires & Wheels				
63	Lugs Tight				
64	Compartments Closed				
65	Dents/Scratches				
SECTION 3 COMMENTS- CORRECTIVE ACTION MEASURES/PLAN					
Comments/Action (Include # identifier)		Due Date	By Whom	Date Done	
Inspection Conducted by (Print):		Management Review Conducted by (Print):			
Signature:		Signature:			

Valley Printers #14010

2022

HOUR METER

9587

Changed upper block coolant hose
Changed coolant hose from reservoir to block
Pressure tested system at 15 PSI Pressure
didn't budge for 10 minutes
Refilled coolant reservoir
Blew out rad and outer air filter
Blew out cab filter

TOTAL PARTS

POS | TIRES & WHEELS

QTY	PART NO. AND DESCRIPTION
2	4 FOOT BLADES
10	BOOTS FOR BLADES
WORK COMPLETED BY: <i>Zeluo</i>	
DATE <i>SEP. 08. 2022</i>	
UNIT # <i>G10</i>	MAKE <i>CAT</i>
HOURS <i>9784.6</i>	KMS



PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-9341

WORK ORDER
NO.

0462

Zeluo
5

JOB DESCRIPTION

- REPLACE TWO END BLADES
- PUT BACK EXTENSION ON THE BLADE
- CHECK ALL LIGHTS
- REPLACE TWO LIGHT BULBS ON THE CAB & FLUD LIGHT
- CHECK FINAL DRIVE OIL
- CHECK FRONT WHEEL HUB OIL
- CHECK FRONT END
- ADJUST SHIMS ON BLADE
- RE-TORQUE WHEELS
- GREASING
- TIGHT BEARINGS ON CIRCLE DRIVE

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

JOB DESCRIPTION

Grease
check Fluid levels
change A/R Filters.
Replace mounting bolts on Hyd. Valve Body.
Locate Broken Hyd. line.
Fix coolant leak on top of the motor
checked Belt and Pulleys
Replace Hyd. line
Replace Bonnet
Washed
Changed all Pucks
changed Side Shift Sims RH Side
changed CUPS RH Side
Tightened Side Shift Sims LH Side
Mounted Snow Wing/greased
nose wrapped 3" Snow Wing hyd line
changed burnt out work lights
fixed Broken fender bolts
checked cab air filter



50 Point Inspection

PM

☐ 250
 ☐ 1000

EQUIPMENT INSPECTION

Date: Nov 9 2022
 Unit Number: G10
 Hours: 10,022 Kms: _____
 Completed By: Dan + Thomas

P Indicates Satisfactory **F** Indicates Not Satisfactory **N/A** indicates Not Applicable


P	F	ITEM	SERVICED
GENERAL WALK AROUND			
P		Grab Bars and Steps (Loose/Missing)	☒
P		Sheet Metal (Damaged/Loose)	☒
P		Glass & Mirrors (Missing/Broken/Loose)	☒
P		Fender/Bumpers (Damaged/Loose)	☒
P		Frame/Car Body/Rops/Mounting Bolts	☒
P		Check Grease Nipples	☒
WORK EQUIPMENT			
N/A		Boom Arm, Push Arms	☐
N/A		Get Condition (Worn/Missing) Pin/Bushing	☐
P		Cylinders (Leaking, Damaged)	☒
P		Cutting Edgewear	☒
		Other:	☐
PRE-STARTUP			
P		Engine Oil Level	☒
D		Transmission/PT Oil Level	☒
P		Hydraulic Oil Level	☒
P		Final Drive/Differential Oil Levels	☒
P		Swing Machinery Oil Level	☒
	F	Coolant Level	☒
CAR INTERIOR			
P		Monitor Panel Screen (Scratched/Broken)	☐
Record Error Codes From Monitor Panel:			
P		Rear Camera Functionality	☒
P		Cab Lights, Bulbs, Fuses and Switches	☒
P		Seat Operation and Safety Belt	☒
P		Fire Extinguisher (Available/Good Charge)	☒
P		Wiper Function and Blade Condition	☒
P		Windows: Latches and Glass (Missing/Function)	☒
P		Doors: Latches, Strikers, Hold Backs	☒
P		AC/Heater Operation and Louvers	☐
	F	Horn and Back up Alarm (Function)	☒

P	F	ITEM	SERVICED
START MACHINE			
N/A		Lever Control Action & Accumulation	☐
P		Ripper or Work Equipment	☐
N/A		Boom (Function, Damaged)	☐
N/A		Arm (Function, Damaged)	☐
N/A		Bucket (Function, Damaged)	☐
P		Lift (Function, Damaged)	☐
P		Tilt (Function, Damaged)	☐
P		Dump (Function, Damaged)	☐
P		Parking Break (Function)	☐
N/A		Brake Accumulation/Pedal Operation	☐
P		Head Lamps (Function/Missing/Broken)	☐
UNDERCARRIAGE			
N/A		Bushings	☐
N/A		Links	☐
N/A		Track Shoes	☐
POWERTRAIN			
	F	Hoses (Leaking/Worn/Damaged)	☒
P		Belts (Noisy, Worn, Missing)	☐
P		Engine (Leaks)	☐
P		Exhaust/Turbo (Leaks/Smoking)	☐
N/A		Doser Piping (Leaks/Damaged)	☐
N/A		EGR Assembly (Leaks/Connected)	☐
N/A		DPF Assembly and Heating Shielding	☐
N/A		SCR System & Adblue/DEF Tank (Leaks)	☐
P		Transmission/Cooler and T/C (Leaks)	☐
P		Final Drives or Differentials (Leaks)	☐
P		Hydraulic Cooler	☐
P		Radiator /Radiator Cap	☐
P		Fan Motor/Blade (Leaks/Damaged)	☐
P		Battery Electrolyte Level	☐
P		Fuel Tank Cap (Missing/Leaking)	☐
	F	Air Filter (Plugged/Missing)	☒

During this inspection, were the defective items repaired? YES ☒ NO ☐

Additional Comments: _____

QTY	PART NO. AND DESCRIPTION
1	1 INCH - 14 FOOT
1	3/8 - 14 FOOT
1	5/8 - 16 FOOT
WORK COMPLETED BY: <i>Zelko</i>	
DATE <i>NOV. 28. 2022</i>	
UNIT # <i>G10</i>	MAKE <i>CAT</i>
HOURS <i>10047.2</i>	KMS



WORK ORDER
NO. 0517

PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-9341

JOB DESCRIPTION

REPLACING THREE HOSES WHAT GOING THROUGH THE NECK TO THE BACK END
CHECK CIRCLE DRIVE OIL
CHECK FOR OTHER LEAKS.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

[illegible]

WORK ORDER
NO. 0804

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas

DATE Jan 27 2023

UNIT # 610

MAKE cont

HOURS

KMS

JOB DESCRIPTION

replaced snow wing sheer pin tightened a few
tightened a few bolts on the blade.

QTY	PART NO. AND DESCRIPTION
1	1R1808 oil Filter
2	308-9679 Fuel Filters
1	326-1644 Fuel Filter
32L	Engine oil
4L	Coolant
1	H3-24 Bulb
1	H4-24 Bulb



WORK ORDER
NO. 0832

PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-9341

WORK COMPLETED BY: Dan Boyles.		DATE Feb 2/23	
UNIT # G10	MAKE Cat	HOURS 10693	KMS

JOB DESCRIPTION

Change Engine oil, oil Filter, and Fuel Filters. Replace Left Side Headlight Bulb and Right side work light. Adjust skids on circle. Help change picks on mulboard.

NORTHPOINT
ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

Tightened bolts for circle and replaced 2

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas

DATE	Feb 11 2023
------	-------------

UNIT # 610

MAKE	Cat
------	-----

HOURS	10757
-------	-------

KMS

JOB DESCRIPTION

Replaced busted fuel line

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

DATE Feb 22/23

KMS

Go and Replace the Alternator I Put on Yesterday because pulley came loose. Remove Flat Tire.

QTY	PART NO. AND DESCRIPTION
1	577-1435 air filter
1	1 liter of Durac XL
1	H3 24v



WORK ORDER
NO. 0937

PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-9341

WORK COMPLETED BY: Harry

DATE Mar. 6

UNIT # 610

MAKE Cat

HOURS 10984.9 KMS

JOB DESCRIPTION

Stopped to see Rob at 106 and changed his air filter / light
checked circle drive fluid topped up.

[illegible]

WORK ORDER
NO. 0966

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: *Don Boyles*

DATE Mar 17 / 23

UNIT # 610

MAKE Cat


HOURS	11197.3
-------	---------

KMS

JOB DESCRIPTION

Tighten Bolts on Pick board.

QTY	PART NO. AND DESCRIPTION
1	1R1808 oil Filter
1	326-1644 Fuel Filter
2	308-9679 Fuel Filter
32L	10W40 Engine oil
20L	TRANS oil
3	H3-24 Bulbs.



WORK ORDER
NO. 0944


PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Day + Thomas + Harrison		DATE Mar 8 / 23	
UNIT # G-10	MAKE Cat	HOURS 11012.4	KMS

JOB DESCRIPTION

Change oil, oil filter, and fuel filter. Add 20L to get TRANS to ~~top of~~ Top of operating Range. Fix Hyd. leaks at Valve Body. Replace Bulbs in 3 work lights.

JOB DESCRIPTION



Charge Bulb in work light

QTY	PART NO. AND DESCRIPTION	
1	7R 1808	oil filter
1	326-1644	fuel filter
2	308 9679	fuel filter
1	245 6375	



WORK ORDER
NO. 1158

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas		DATE JUNE 6 2023	
UNIT # G10	MAKE cat	HOURS 11411	KMS

JOB DESCRIPTION

Change Oil + filter
Change fuel filters
Install new Blades
Checked for brake + circle play
checked all fluids + circle gear box
Topped off coolant
Blew out rads
checked front Belt
Installed GPS
Changed air filter

QTY	PART NO. AND DESCRIPTION



WORK ORDER
NO. 1167

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas			DATE June 22 2023	
UNIT # G10	MAKE Cat	HOURS 11472	KMS	

JOB DESCRIPTION

Charge a/c 3.5lbs Held a 24 in of Hg vacuum/ held and balanced out
at 67 PSI 0°C air blowing
tightened hose clamps for heater topped off coolant
checked fivys



50 Point Inspection

PM

☐ 250

☒ 1000

EQUIPMENT INSPECTION

Date: Oct 25/23

Unit Number: G-10

Hours: 11695 Kms: _____

Completed By: Dan Boyles

P Indicates Satisfactory

F Indicates Not Satisfactory

N/A indicates Not Applicable

P	F	ITEM	SERVICED
GENERAL WALK AROUND			
		Grab Bars and Steps (Loose/Missing)	☒
		Sheet Metal (Damaged/Loose)	☒
		Glass & Mirrors (Missing/Broken/Loose)	☒
		Fender/Bumpers (Damaged/Loose)	☒
		Frame/Car Body/Rops/Mounting Bolts	☒
		Check Grease Nipples	☒
WORK EQUIPMENT			
		Boom Arm, Push Arms	☐
		Get Condition (Worn/Missing) Pin/Bushing	☒
		Cylinders (Leaking, Damaged)	☒
		Cutting Edgewear	☒
		Other:	☐
PRE-STARTUP			
		Engine Oil Level	☒
		Transmission/PT Oil Level	☒
		Hydraulic Oil Level	☒
		Final Drive/Differential Oil Levels	☒
		Swing Machinery ^{Circle} Oil Level	☒
		Coolant Level	☒
CAR INTERIOR			
		Monitor Panel Screen (Scratched/Broken)	☒
Record Error Codes From Monitor Panel:			
		Rear Camera Functionality	☒
		Cab Lights, Bulbs, Fuses and Switches	☒
		Seat Operation and Safety Belt	☒
		Fire Extinguisher (Available/Good Charge)	☒
		Wiper Function and Blade Condition	☒
		Windows: Latches and Glass (Missing/Function)	☒
		Doors: Latches, Strikers, Hold Backs	☒
		AC/Heater Operation and Louvers	☒
		Horn and Back up Alarm (Function)	☒

P	F	ITEM	SERVICED
START MACHINE			
		Lever Control Action & Accumulation	☒
		Ripper or Work Equipment	☒
		Boom (Function, Damaged)	☐
		Arm (Function, Damaged)	☐
		Bucket (Function, Damaged)	☐
		Lift (Function, Damaged)	☒
		Tilt (Function, Damaged)	☒
		Dump (Function, Damaged)	☐
		Parking Break (Function)	☒
		Brake Accumulation/Pedal Operation	☒
		Head Lamps (Function/Missing/Broken)	☒
UNDERCARRIAGE			
		Bushings	☐
		Links	☐
		Track Shoes	☐
POWERTRAIN			
		Hoses (Leaking/Worn/Damaged)	☒
		Belts (Noisy, Worn, Missing)	☒
		Engine (Leaks)	☒
		Exhaust/Turbo (Leaks/Smoking)	☒
		Doser Piping (Leaks/Damaged)	☒
		EGR Assembly (Leaks/Connected)	☒
		DPF Assembly and Heating Shielding	☒
		SCR System & Adblue/DEF Tank (Leaks)	☐
		Transmission/Cooler and T/C (Leaks)	☒
		Final Drives or Differentials (Leaks)	☒
		Hydraulic Cooler	☒
		Radiator /Radiator Cap	☒
		Fan Motor/Blade (Leaks/Damaged)	☒
		Battery Electrolyte Level	☒
		Fuel Tank Cap (Missing/Leaking)	☒
		Air Filter (Plugged/Missing)	☒

During this inspection, were the defective items repaired? YES ☒ NO ☐

Additional Comments: Small leaks at diff on both sides.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

JOB DESCRIPTION

extracted fender bolts
tightened wiper

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

UNIT # <i>G-10</i>	MAKE <i>Cat</i>	HOURS <i>10164</i>	KMS
--------------------	-----------------	--------------------	-----

Replace O'ring in hose at power steering cylinder.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

DATE	Feb 2 29
------	----------

KMS

Replace and Set Side Shift Shims
Change lights
Weld mulboard

[illegible]

WORK ORDER
NO. 1052

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas

DATE Feb 8 24

UNIT # G10

MAKE cat

HOURS	12403
-------	-------

	KMS
--	-----

JOB DESCRIPTION

Change air filter
Change lights
Inspect

QTY	PART NO. AND DESCRIPTION
1	oil filter
1	Fuel filter
1	Fuel Filter.
WORK COMPLETED BY: Dan Boyles DATE Feb 17/24 UNIT # G-10 MAKE Cat HOURS KMS	



WORK ORDER
NO. 1566

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

JOB DESCRIPTION

Do Service
change oil + filter
change Fuel Filters.

NORTHPOINT
ENTERPRISE LTD.


PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

DATE	Feb 21 24
------	-----------

HOURS	12587
-------	-------

KMS

top up front ~~left~~ right steer hub
changed lights
changed outer air filter



50 Point Inspection

PM

☐ 250

☒ 1000

EQUIPMENT INSPECTION

Date: July 23/24

Unit Number: 610

Hours: 12903 Kms:

Completed By: Dylan

P Indicates Satisfactory

F Indicates Not Satisfactory

N/A indicates Not Applicable

P	F	ITEM	SERVICED
GENERAL WALK AROUND			
☒		Grab Bars and Steps (Loose/Missing)	☐
☒		Sheet Metal (Damaged/Loose)	☐
☒		Glass & Mirrors (Missing/Broken/Loose)	☐
☒		Fender/Bumpers (Damaged/Loose)	☐
☒		Frame/Car Body/Rops/Mounting Bolts	☐
☒		Check Grease Nipples	☐
WORK EQUIPMENT			
☒		Boom Arm, Push Arms	☒
☒		Get Condition (Worn/Missing) Pin/Bushing	☐
☒		Cylinders (Leaking, Damaged)	☐
☒		Cutting Edgewear	☐
		Other:	☐
PRE-STARTUP			
☒		Engine Oil Level	☒
☒		Transmission/PT Oil Level	☐
		Hydraulic Oil Level	☒
☒		Final Drive/Differential Oil Levels	☐
☒		Swing Machinery Oil Level	☐
☒		Coolant Level	☒
CAR INTERIOR			
		Monitor Panel Screen (Scratched/Broken)	☐
Record Error Codes From Monitor Panel:			
☒		Rear Camera Functionality	☒
☒		Cab Lights, Bulbs, Fuses and Switches	☒
☒		Seat Operation and Safety Belt	☐
☒		Fire Extinguisher (Available/Good Charge)	☐
☒		Wiper Function and Blade Condition	☐
☒		Windows: Latches and Glass (Missing/Function)	☐
☒		Doors: Latches, Strikers, Hold Backs	☐
		AC/Heater Operation and Louvers	☐
☒		Horn and Back up Alarm (Function)	☐

P	F	ITEM	SERVICED
START MACHINE			
☒		Lever Control Action & Accumulation	☐
☒		Ripper or Work Equipment	☐
		Boom (Function, Damaged) <u>N/A</u>	☐
		Arm (Function, Damaged) <u>N/A</u>	☐
		Bucket (Function, Damaged) <u>N/A</u>	☐
☒		Lift (Function, Damaged)	☒
☒		Tilt (Function, Damaged)	☒
		Dump (Function, Damaged) <u>N/A</u>	☐
☒		Parking Break (Function)	☐
☒		Brake Accumulation/Pedal Operation	☐
☒		Head Lamps (Function/Missing/Broken)	☒
UNDERCARRIAGE			
		Bushings	☐
		Links <u>N/A</u>	☐
		Track Shoes	☐
POWERTRAIN			
☒		Hoses (Leaking/Worn/Damaged)	☒
☒		Belts (Noisy, Worn, Missing)	☐
☒		Engine (Leaks)	☐
☒		Exhaust/Turbo (Leaks/Smoking)	☐
		Doser Piping (Leaks/Damaged) <u>N/A</u>	☐
		EGR Assembly (Leaks/Connected) <u>N/A</u>	☐
		DPF Assembly and Heating Shielding <u>N/A</u>	☐
		SCR System & Adblue/DEF Tank (Leaks) <u>N/A</u>	☐
☒		Transmission/Cooler and T/C (Leaks)	☐
		Final Drives or Differentials (Leaks)	☐
☒		Hydraulic Cooler	☐
☒		Radiator /Radiator Cap	☐
☒		Fan Motor/Blade (Leaks/Damaged)	☐
☒		Battery Electrolyte Level	☐
☒		Fuel Tank Cap (Missing/Leaking)	☐
☒		Air Filter (Plugged/Missing)	☒

During this inspection, were the defective items repaired? YES _____ NO _____

Additional Comments: _____

QTY	PART NO. AND DESCRIPTION
1	H3 24V bulb
1	IR-1808 oil filter
1	326-1644 fuel filter
2	308-9679 fuel filter
32L	10W-40 oil
1	577-1435 air filter
1	331-8108 air filter
1	328-3655 transmission filter



WORK ORDER
NO. 1610

PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-0611

WORK COMPLETED BY: Dylan

DATE JULY 23

UNIT # G10

MAKE CAT

HOURS 12903

KMS

JOB DESCRIPTION

- Install new wing safety chain
- replace LH side light bulb
- replace LH cab light lens
- change oil and fuel filters
- replace air filters
- check cabin air filters
- replace steering/transmission filters
- check tire pressures
- replace sideshift cylinder caps
- replace RF hub cover plate
- replace caps/regrim lift cylinders
- regrim top plates on circle

- Parts
- 1) 389-1076 steering filter
 - 1) 338-3540 hydraulic filter
 - 6) 2795267 caps #1
 - 1) 25-8163 o-ring
 - 1) 5T-0906 cover
 - 4) 75W90 oil

QTY	PART NO. AND DESCRIPTION
1	255-4646 Shim Plate
1	276-1318 Shim
1	176-1319 Shim
1	3330960-00 Shim
1	duratron XL
2	ENI-5P3863 O-ring



WORK ORDER
NO. 1618

PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-0611

WORK COMPLETED BY:	DATE	July 23/28
UNIT # G10	MAKE CAT	HOURS
		KMS

JOB DESCRIPTION

- Replace LH upper blade shims
- replace 1 lower shim and set circle
- remove stump pan and wash underneath
- top up hydraulic oil
- grease grader
- remove top cover to check for leaks
- fix transmission leaks and top up oil
- install stump pan and top cover

QTY	PART NO. AND DESCRIPTION
1	H4-24V - LIGHT BULB



WORK ORDER
NO. 1670


PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-0611

WORK COMPLETED BY: Zeljko		DATE OCT. 12. 2024	
UNIT # G10	MAKE CAT	HOURS 12908	KMS

JOB DESCRIPTION

- REPLACING HEADLIGHT BULB LH
- TIGHT ALL BOLTS ON PICK BLADES
- CHECK ALL LIQUIDS
- PUT BACK ON FRONT RH FENDER (WAS OFF)
- TIGHT UP HYDRAULIC HOSES
- CHECK ALL LIGHTS
- REPLACING ONE PICK
- ADD 7LIT HYDRAULIC OIL DURATRAM XL
- REPLACING SPILL KIT
- PUT BACK ON SERVICED FIRE EXTINGUISHER
- CHECK OIL LEVELS

QTY	PART NO. AND DESCRIPTION



WORK ORDER
NO. **1587**

PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-9341

WORK COMPLETED BY: Dan Boyles		DATE Dec 12/24	
UNIT # G10	MAKE Cat	HOURS 13218	KMS

JOB DESCRIPTION

*Diagnose steering system malfunction,
Alarm caused by 8V sensor circuit voltage too high. Fault was no longer active
and could not duplicate the error.*

[illegible]

WORK ORDER
NO. 1092

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: <i>Dan Boyles</i>		DATE <i>Dec 17/24</i>	
UNIT # <i>G-10</i>	MAKE <i>Cat</i>	HOURS <i>132.86</i>	KMS

JOB DESCRIPTION

Change engine oil + filter
check unit over.

QTY	PART NO. AND DESCRIPTION
84	BR4-348-9051-W6X ice picks



WORK ORDER
NO. 1786

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK COMPLETED BY: DY/97		DATE Dec. 22. 2024	
UNIT # G10	MAKE CAT	HOURS 13340	KMS

JOB DESCRIPTION

- Replace Ice picks

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

QTY	PART NO. AND DESCRIPTION



WORK ORDER
NO. 0661

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Day			DATE Jan 8/25	
UNIT # Q10	MAKE Cat	HOURS 13486	KMS	

JOB DESCRIPTION

Put D.S. Front Fender back on.

Add Gear oil To P.S. Front wheel (Seal seeping slowly)

[illegible]

WORK ORDER
NO. 0693

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas

DATE Jan 11 25

UNIT # G-10

MAKE CAT

HOURS	13538	KMS
-------	-------	-----

KMS

JOB DESCRIPTION

- Change Drive Pinion for circle
- Change Duo cone Seal
- Change all Sealing O rings
- Shim the Clutches
- Add 7L or duratran to gear box

[illegible]

QTY	PART NO. AND DESCRIPTION



WORK ORDER
NO. 0745

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas			DATE Feb 17 25	
UNIT # G1C	MAKE Cat	HOURS 13876	KMS	

JOB DESCRIPTION

Chang both blade side shift hoses
Change circle side shift hose

QTY	PART NO. AND DESCRIPTION
4	-2656722 - COVER
2	2534646 - PLATE AS
4	2436652 - COVER
2	2761319 - WEAR STRIP
2	2761317 - WEAR STRIP
2	526-6469 - COLLAR
12	1900627 - SHIM
2	4661604 - SPACER
8	467-5183 - BEARING - SLEE
2	PINS
6	20R 5036 Rear Intectors
6	20R 4517 Rear Quills
1	440189 O'Ring.
1	260-0113 Valve cover Gasket
1	637-2653 wiring harness
1	349-4927 Hyd. hose
1	328-3655 TRANS Filter
1	338-3540 Hyd. Filter
2	308-9679 Fuel Filters
1	326-1643 Fuel Filter
1	1R-1808 oil Filter
5	282-3736 studs 2 loaded with
1	6V5843 Bolt 5 New Int harness
3	H324 bulbs



PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK ORDER
NO. 2262

WORK COMPLETED BY: Thomas Dan.		DATE Dec 19/25	
UNIT #G10	MAKE Cat	HOURS 14392	KMS
JOB DESCRIPTION			
Change LH Blade lift hose			
Change LH Orings on steer hose			
Change hose on blade roll			
- REPLACE BOTTOM AND TOP WEAR STRIP			
- REPLACE SIDE WEAR STRIP COVER PLATES			
- PUT BLADE BACK ON THE GRADER			
- REPLACE THE SIDE PINS			
- Replace 6 Intectors + Quills.			
- Replace O'Ring on LH accessory drive			
- Replace Intector wiring harness			
- Replace 2 hoses over Drive shaft 1 cat 1 from Venture.			
Change TRANS oil and Filter			
change Hyd. Filter			
change Engine oil + Filter			
Change Fuel Filters.			
check tire pressures LH Front down 5psi LH Rear Tandem down 25psi			
Fix 3 light bulbs			
clean out Rads			
Grease.			
checked Tandem levels RH over Full, Parts ordered will bring back to Repair			

