

X05-5

WORK ORDER
NO. 1558


PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-9341

QTY	PART NO. AND DESCRIPTION
2	T299164 - TOP BRASS SHIM
2	T239757 - BOTTOM BRASS SHIM
1	AT175223 air filter
3L	COOLANT
2	T141733 - CIRCLE TABLE SHIMS
2	T163748 - CIRCLE TABLE SHIMS
1	AT458497 - INDICATOR SWITCH

WORK COMPLETED BY: Zelko	DATE June 11
UNIT # G14	MAKE John Deere
HOURS 13214	KMS 131072

JOB DESCRIPTION

- Replace Outer air filter
- TOP UP COOLANT (-30c)
- CHECK FRONT END FOR WORN OUT
- CHECK CIRCLE DRIVE
- REPLACING CIRCLE DRIVE OIL (4.6 LIT)
- CHECK ALL LIGHTS
- GREASE FRONT wheel bearings
- REPLACING CIRCLE TABLE SHIMS
- ADJUSTING CIRCLE TABLE
- REPLACING BOTTOM CIRCLE TABLE SHIMS
- REPLACING INDICATOR SWITCH ON HYDRAULIC FILTER HOUSING
- GREASE



50 Point Inspection	
PM	
☒ 250	
☐ 1000	

EQUIPMENT INSPECTION

Date: June 14
Unit Number: 614
Hours: 13214 Kms: 131072
Completed By: Zeljko

P Indicates Satisfactory

F Indicates Not Satisfactory

N/A indicates Not Applicable

P	F	ITEM	SERVICED
GENERAL WALK AROUND			
		Grab Bars and Steps (Loose/Missing)	☒
		Sheet Metal (Damaged/Loose)	☒
		Glass & Mirrors (Missing/Broken/Loose)	☒
		Fender/Bumpers (Damaged/Loose)	☒
		Frame/Car Body/Rops/Mounting Bolts	☒
		Check Grease Nipples	☐
WORK EQUIPMENT			
		Boom Arm, Push Arms	☐ N/A
		Get Condition (Worn/Missing) Pin/Bushing	☐ N/A
		Cylinders (Leaking, Damaged)	☒
		Cutting Edgewear	☒
		Other:	☐
PRE-STARTUP			
		Engine Oil Level	☒
		Transmission/PT Oil Level	☐
		Hydraulic Oil Level	☒
		Final Drive/Differential Oil Levels	☒
		Swing Machinery Oil Level	☒
		Coolant Level	☒
CAR INTERIOR			
		Monitor Panel Screen (Scratched/Broken)	☒
Record Error Codes From Monitor Panel:			
		Rear Camera Functionality	☒
		Cab Lights, Bulbs, Fuses and Switches	☒
		Seat Operation and Safety Belt	☒
		Fire Extinguisher (Available/Good Charge)	☒
		Wiper Function and Blade Condition	☒
		Windows: Latches and Glass (Missing/Function)	☒
		Doors: Latches, Strikers, Hold Backs	☒
		AC/Heater Operation and Louvers	☒
		Horn and Back up Alarm (Function)	☒

P	F	ITEM	SERVICED
START MACHINE			
		Lever Control Action & Accumulation	☒
		Ripper or Work Equipment	☒
		Boom (Function, Damaged)	☐ N/A
		Arm (Function, Damaged)	☐ N/A
		Bucket (Function, Damaged)	☐ N/A
		Lift (Function, Damaged)	☒
		Tilt (Function, Damaged)	☒
		Dump (Function, Damaged)	☐ N/A
		Parking Break (Function)	☒
		Brake Accumulation/Pedal Operation	☒
		Head Lamps (Function/Missing/Broken)	☒
UNDERCARRIAGE			
		Bushings	☐
		Links	☐ N/A
		Track Shoes	☐ N/A
POWERTRAIN			
		Hoses (Leaking/Worn/Damaged)	☒
		Belts (Noisy, Worn, Missing)	☐
		Engine (Leaks)	☒
		Exhaust/Turbo (Leaks/Smoking)	☒
		Doser Piping (Leaks/Damaged)	☐ N/A
		EGR Assembly (Leaks/Connected)	☐ N/A
		DPF Assembly and Heating Shielding	☐ N/A
		SCR System & Adblue/DEF Tank (Leaks)	☐ N/A
		Transmission/Cooler and T/C (Leaks)	☒
		Final Drives or Differentials (Leaks)	☒
		Hydraulic Cooler	☒
		Radiator /Radiator Cap	☒
		Fan Motor/Blade (Leaks/Damaged)	☒
		Battery Electrolyte Level	☒
		Fuel Tank Cap (Missing/Leaking)	☒
		Air Filter (Plugged/Missing)	☒

During this inspection, were the defective items repaired? YES _____ NO _____

Additional Comments: _____

QTY	PART NO. AND DESCRIPTION
1	D2118283 Engine oil Filter.
1	RE 525523 Fuel Filter Kit.
2	AT 335492 TRAYS / Axle Filters
1	AT 367840 Hydraulic Filter.
1	AT 175223 outer air Filter.
1	AT 191102 Cab Filter.
1	Fuel Filter inline
32L	Engine oil.



WORK ORDER
NO. 1361

PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-9341

WORK COMPLETED BY: Dan Boyles.	DATE Dec 22/23
UNIT # G-14	MAKE John Deere
HOURS 11949	KMS

JOB DESCRIPTION

1000 hr service and inspection.

Install pick boards and picks.

66L of Duratran.

40R 4' pick boards.

108 picks.

REPLACING SHIMS ON CIRCLE TABLE (TOP AND SIDE - 1-T418899 - 1-T418904)

ADD GREASE IN FRONT HUBS

ADJUST CIRCLE TABLE

PUT NEW TIRES ON STEER (SWAP FRONT TIRES TO THE LH REAR DRIVE)



ENTERPRISE LTD.

IDW8706XLE0661687

50 Point Inspection

PM

☐ 250

☒ 1000

EQUIPMENT INSPECTION

Date: Dec 22/23

Unit Number: G14

Hours: 11949 Kms: _____

Completed By: Dar Boyles

P Indicates Satisfactory

F Indicates Not Satisfactory

N/A indicates Not Applicable

P	F	ITEM	SERVICED
GENERAL WALK AROUND			
✓		Grab Bars and Steps (Loose/Missing)	☐
✓		Sheet Metal (Damaged/Loose)	☐
✓		Glass & Mirrors (Missing/Broken/Loose)	☐
✓		Fender/Bumpers (Damaged/Loose)	☐
✓		Frame/Car Body/Rops/Mounting Bolts	☐
		Check Grease Nipples	☐
WORK EQUIPMENT			
N/A		Boom Arm, Push Arms	☐
✓		Get Condition (Worn/Missing) Pin/Bushing	☒
✓		Cylinders (Leaking, Damaged)	☐
✓		Cutting Edgewear	☒
		Other:	☐
PRE-STARTUP			
✓		Engine Oil Level	☒
✓		Transmission/PT Oil Level	☒
✓		Hydraulic Oil Level	☒
✓		Hydraulic Differential Oil Levels	☒
✓		Engine Drive Machinery Oil Level	☒
✓		Coolant Level	☐
CAR INTERIOR			
✓		Monitor Panel Screen (Scratched/Broken)	☐
Record Error Codes From Monitor Panel:			
✓		Rear Camera Functionality	☐
✓		Cab Lights, Bulbs, Fuses and Switches	☐
✓		Seat Operation and Safety Belt	☐
✓		Fire Extinguisher (Available/Good Charge)	☐
✓		Wiper Function and Blade Condition	☐
✓		Windows: Latches and Glass (Missing/Function)	☐
✓		Doors: Latches, Strikers, Hold Backs	☐
✓		AC/Heater Operation and Louvers	☐
✓		Horn and Back up Alarm (Function)	☐

P	F	ITEM	SERVICED
START MACHINE			
✓		Lever Control Action & Accumulation	☐
N/A		Ripper or Work Equipment	☐
N/A		Boom (Function, Damaged)	☐
N/A		Arm (Function, Damaged)	☐
N/A		Bucket (Function, Damaged)	☐
✓		Lift (Function, Damaged)	☐
✓		Tilt (Function, Damaged)	☐
N/A		Dump (Function, Damaged)	☐
✓		Parking Break (Function)	☐
✓		Brake Accumulation/Pedal Operation	☐
✓		Head Lamps (Function/Missing/Broken)	☐
UNDERCARRIAGE			
N/A		Bushings	☐
N/A		Links	☐
N/A		Track Shoes	☐
POWERTRAIN			
✓		Hoses (Leaking/Worn/Damaged)	☐
✓		Belts (Noisy, Worn, Missing)	☐
✓		Engine (Leaks)	☐
✓		Exhaust/Turbo (Leaks/Smoking)	☐
N/A		Doser Piping (Leaks/Damaged)	☐
✓		EGR Assembly (Leaks/Connected)	☐
N/A		DPF Assembly and Heating Shielding	☐
N/A		SCR System & Adblue/DEF Tank (Leaks)	☐
✓		Transmission/Cooler and T/C (Leaks)	☐
✓		Final Drives or Differentials (Leaks)	☐
✓		Hydraulic Cooler	☐
✓		Radiator/Radiator Cap	☐
✓		Fan Motor/Blade (Leaks/Damaged)	☐
✓		Battery Electrolyte Level	☐
✓		Fuel Tank Cap (Missing/Leaking)	☐
✓		Air Filter (Plugged/Missing)	☒

During this inspection, were the defective items repaired? YES ☒ NO ☐

Additional Comments: _____

NORTHPOINT
ENTERPRISE LTD.

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

UNIT # 614	MAKE John Deere	HOURS 1215	KMS
------------	-----------------	------------	-----

Replace air Filters.

QTY	PART NO. AND DESCRIPTION
1	1R1808 oil Filter
1	1R0762 Fuel Filter
1	326-1644 Fuel Filter
30L	Engine oil
1	245-6375 air Filter.



WORK ORDER
NO. 1330

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Dan Boyles		DATE Jan 20 / 24	
UNIT # GH	MAKE Cat	HOURS 16481	KMS

JOB DESCRIPTION

Do Service
change oil, oil Filter, Fuel Filters and air Filter

[illegible]

WORK ORDER
NO. 1384

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas

DATE Jan 24 24

UNIT # G-14

MAKE here

HOURS 12243

KMS

JOB DESCRIPTION

Set Circle

Put head light back on

tighten Jam nut on artic Cylinder

QTY	PART NO. AND DESCRIPTION
1	DZ118283 - OIL FILTER
1	AT223493 - INNER FUEL FILTER
1	RE525523 - FUEL FILTERS
	WORK COMPLETED BY: <i>Zeljko</i>
	DATE <i>JAN. 26. 2024</i>
	UNIT # <i>614</i> MAKE <i>J.D.</i> HOURS <i>12311</i> KMS <i>131701</i>



WORK ORDER
NO. **0647**

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

JOB DESCRIPTION

CHANGING ENGINE OIL (28 LIT. 10W40)
 REPLACING ENGINE OIL FILTER
 REPLACING FUEL FILTERS
 TIGHT TRANSMISSION FILTER
 CHECK OIL LEVEL IN CIRCLE DRIVE

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas			DATE Feb 7 24
UNIT # G14	MAKE Deere	HOURS 12490	KMS

JOB DESCRIPTION

clean air filter
change wing hose

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

JOB DESCRIPTION

Do Service
change oil + Filter
change Fuel Filters.
weld nut on for wiring.

QTY	PART NO. AND DESCRIPTION
1	AT175223
1	BE525523
1	DZ118283
1	AT223493
32L	10W40 oil
2	H324V bulb
1	AT19102
1	AT307501




WORK ORDER
NO. 0653

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Dylan Dgn	DATE Feb. 17, 2024
UNIT # G14	MAKE Ford Deere
HOURS 12699	KMS

JOB DESCRIPTION

change engine oil, fuel, air filters
Fix ball or wing.
Blow out Rads

[illegible]

WORK ORDER
NO. 1417

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas		DATE mar 6 24	
UNIT # G14	MAKE Deere	HOURS 13054	KMS

JOB DESCRIPTION

Change oil + filter
change fuel filters x3
Change D/Vter air filter
check fluids tran/coolant/circle/coolant

QTY	PART NO. AND DESCRIPTION
1	AT335726 - HYDRAULIC FAN HOSE
1	- HYDRAULIC HOSE FOR WING
1	- H3 LIGHT BULB



WORK ORDER
NO. 1696

PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-0611

WORK COMPLETED BY: Zefko			DATE OCT. 21. 2024	
UNIT # G-14	MAKE J.D.	HOURS 13219	KMS 131072	

JOB DESCRIPTION

- REPLACING HYDRAULIC FAN HOSE
- REPLACING HYDRAULIC HOSE ON BACK END OF WING
- PUT BACK ON SNOW WING
- REPLACING PILOT BOLT ON THE WING BRACKET
- CHECK ALL LIGHTS
- REPLACING O-RINGS ON CONTROL BOX RH
- CHECK ALL LIQUIDS
- ADD 5 LIT HYDRAULIC OIL
- PUT DOT TAME ON BACK END
- REPLACING LOW BEAM LIGHT BULB LH
- FIXING BROKEN WIRE ON RH LOW BEAM
- CHECK TWO WAY RADIO



50 Point Inspection

PM

☐ 250

☐ 1000

EQUIPMENT INSPECTION

Date: OCT. 21. 2024

Unit Number: Q 14

Hours: 13219 Kms: 131072

Completed By: Zeljko

P Indicates Satisfactory

F Indicates Not Satisfactory

N/A indicates Not Applicable

P	F	ITEM	SERVICES
GENERAL WALK AROUND			
P		Grab Bars and Steps (Loose/Missing)	☐
P		Sheet Metal (Damaged/Loose)	☐
P		Glass & Mirrors (Missing/Broken/Loose)	☐
P		Fender/Bumpers (Damaged/Loose)	☐
P		Frame/Car Body/Rops/Mounting Bolts	☐
P		Check Grease Nipples	☒
WORK EQUIPMENT			
P		Boom Arm, Push Arms	☐
P		Get Condition (Worn/Missing) Pin/Bushing	☐
P		Cylinders (Leaking, Damaged)	☐
P		Cutting Edgewear	☐
		Other:	☐
PRE-STARTUP			
P		Engine Oil Level	☐
P		Transmission/PT Oil Level	☐
P		Hydraulic Oil Level	☐
P		Final Drive/Differential Oil Levels	☐
P		Swing Machinery Oil Level	☐
P		Coolant Level	☐
CAR INTERIOR			
		Monitor Panel Screen (Scratched/Broken)	☐
Record Error Codes From Monitor Panel:			
		Rear Camera Functionality	☐
P		Cab Lights, Bulbs, Fuses and Switches	☐
P		Seat Operation and Safety Belt	☐
P		Fire Extinguisher (Available/Good Charge)	☐
P		Wiper Function and Blade Condition	☐
P		Windows: Latches and Glass (Missing/Function)	☐
P		Doors: Latches, Strikers, Hold Backs	☐
P		AC/Heater Operation and Louvers	☐
P		Horn and Back up Alarm (Function)	☐

P	F	ITEM	SERVICES
START MACHINE			
P		Lever Control Action & Accumulation	☐
		Ripper or Work Equipment	☐
		Boom (Function, Damaged)	☐
P		Arm (Function, Damaged)	☐
		Bucket (Function, Damaged)	☐
P		Lift (Function, Damaged)	☐
P		Tilt (Function, Damaged)	☐
P		Dump (Function, Damaged)	☐
P		Parking Break (Function)	☐
P		Brake Accumulation/Pedal Operation	☐
P		Head Lamps (Function/Missing/Broken)	☐
UNDERCARRIAGE			
P		Bushings	☐
P		Links	☐
		Track Shoes	☐
POWERTRAIN			
P		Hoses (Leaking/Worn/Damaged)	☒
P		Belts (Noisy, Worn, Missing)	☐
P		Engine (Leaks)	☐
P		Exhaust/Turbo (Leaks/Smoking)	☐
		Doser Piping (Leaks/Damaged)	☐
P		EGR Assembly (Leaks/Connected)	☐
		DPF Assembly and Heating Shielding	☐
		SCR System & Adblue/DEF Tank (Leaks)	☐
P		Transmission/Cooler and T/C (Leaks)	☐
P		Final Drives or Differentials (Leaks)	☐
P		Hydraulic Cooler	☐
P		Radiator /Radiator Cap	☐
P		Fan Motor/Blade (Leaks/Damaged)	☐
P		Battery Electrolyte Level	☐
P		Fuel Tank Cap (Missing/Leaking)	☐
P		Air Filter (Plugged/Missing)	☐

During this inspection, were the defective items repaired? YES _____ NO _____

Additional Comments: _____

[illegible]

WORK ORDER
NO. 1745

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK COMPLETED BY: Thomas

DATE Nov 22 24

UNIT # G14

MAKE *Deere*

HOURS	13325	KMS
-------	-------	-----

JOB DESCRIPTION

changed beacon

changed work light

Switched wing - extension loses around

[illegible]

WORK ORDER
NO. 1450

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas

DATE Dec 6 24

UNIT # 614

MAKE TO

HOURS	13456
-------	-------

KMS

JOB DESCRIPTION

Change oil + filter

Change or clean outter air filter

Check circle oil

Check hyd oil

Check coolant

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

JOB DESCRIPTION

Repair Hyd. leak at sideshift cylinder with temporary fittings and hose.
Order new adaptor to repair correctly.

QTY	PART NO. AND DESCRIPTION



WORK ORDER
NO. **0672**

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: <i>Dave Boyles.</i>		DATE <i>Jan 14/25</i>	
UNIT # <i>G14</i>	MAKE <i>Schweizer</i>	HOURS	KMS

JOB DESCRIPTION

Repair loose Connection For back lights

QTY	PART NO. AND DESCRIPTION



WORK ORDER
NO. 0698

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas		DATE Feb 7 25	
UNIT # G 14	MAKE 14443	HOURS 14443	KMS

JOB DESCRIPTION

change wing hose

Deere

[illegible]

WORK ORDER
NO. 2255

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK COMPLETED BY: Dan		DATE Nov 28/25	
UNIT # G 14	MAKE John Deere	HOURS 15015	KMS
JOB DESCRIPTION Tighten RH blade slide shim.			

R47153 X4 O-Rings

AT 442924 X1 SENSOR

R28782 X1 O-Ring.


 WORK ORDER
 NO. 2081

1/2

PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-0611

QTY	PART NO. AND DESCRIPTION
1	AT223493 - FUEL FILTER
1	D2118283 - OIL FILTER
1	RE525523 - FUEL FILTERS
1	AT175224 - INAIR AIR FILTER
1	AT175223 - AIR FILTER
1	AT191102 - CAB FILTER
1	AT307501 - CAB FILTER
2	AT335492

WORK COMPLETED BY: Lefko			DATE OCT. 22, 2025	
UNIT # G 14	MAKE J.D.	HOURS 14858	KMS 131072	

JOB DESCRIPTION

- CHANGING ENGINE OIL (10W40 25 Lit)	2	H3 LIGHT BULB
- REPLACE FUEL FILTERS	8	T141733 - SHIMS
- REPLACE OIL FILTER	1	AT442924 - PRESSURE SENSOR
- REPLACE AIR FILTERS	4	R47153 - O-RINGS
- REPLACE CAB AIR FILTERS	2	BOLTS 1X5.5
- CHECK AND ADD OIL IN FINAL DRIVES (5 Lit) OIL NOT BURNED	1	JD9082 - BEARING
- CHECK THE FRONT END FOR PLAY	1	JD8255 - BEARING
- CHECK CIRCLE DRIVE GEAR (REPLACE OIL 6.5 Lit)	1	RE31702 - SEAL
- REPLACE AXLE OIL (25 Lit) + FILTER	1	JD8997 - BEARING
- REPLACE TRANSMISSION OIL (22 Lit) + FILTER	1	JD9141 - BEARING
- REPLACE TWO LIGHT BULBS, ONE ON BACK END OF THE CAB, ONE ON FRONT END.	1	BALL JOINT
- REPLACE CIRCLE TABLE SHIMS ON TOP OF THE TABLE	4	T239757 - BUSHINGS
- REPLACE PRESSURE SENSOR FOR THE ENGINE FAN	1	AT372842 - COVER
- REPLACE O-RINGS ON ENGINE OIL FILTER HOUSING	4	175R25 - TIRES
- REPLACE TWO BOLTS ON CIRCLE TABLE		
- CHECK ENGINE BELT AND PULLEY		
- REPLACE TWO O-RINGS ON HOSE		
- FIX UNDER THE BLADE HOSE BRACKET		
- FIXING THE LH REAR MUD FLAP		
- REPLACE BEARINGS AND SEAL ON FRONT RH WHEEL (WHEEL SHAFT WORKOUT)		

QTY	PART NO. AND DESCRIPTION
2	T46639 - SEAL
2	T237520 - O-RING
2	T46639
2	T237521 - O-RING
2	T231335 - BUSHING
2	T238574 - THRUST
2	T231331 - THRUST
2	T237990 - BUSHING



PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-0611

WORK ORDER
NO. 2085

2/2

WORK COMPLETED BY: Zeljko		DATE OCT. 22, 2025	
UNIT # G14	MAKE J.D.	HOURS 14838	KMS 131072

JOB DESCRIPTION

- REPLACE BALL JOINT ON RH
- REPLACE SADDLE BUSHINGS LH, RH
- REPLACE O-RINGS, SEALS AND THRUST ON SADDLE BUSHINGS ARMS
- CHECK CUTS ON THE RAMS (LITTLE BIT WORN OUT BUT STILL OK)
- CHECK TWO WAY RADIO
- CHECK ENGINE BLOCK HEATER. OK!!!
- ADJUST CIRCLE DRIVE TABLE
- REPLACING BOTTOM SHIMS ON THE BLADE
- REPLACE FRONT COVER
- REPLACE DRIVE TIRES ALL 4
- ADJUST SWING RAM.
- GREASING
- REPLACE TWO GREASE NEEDLE ON FRONT END

[illegible]

WORK ORDER
NO. 2167

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

[illegible]



WORK ORDER
NO. 2134

PO Box 930 Manning, AB T0H 2M0 Phone: 780-836-0611

WORK COMPLETED BY: Thomas

DATE Dec 14 23

UNIT # G-14

MAKE Deere

HOURS 15235

KMS

JOB DESCRIPTION

Change oil + filter

change air outter air filter

Tighten side shift shims

check coolant

Tighten VP circle

check all fluids

JDC Print Shop 780-836-3810

[illegible]

QTY	PART NO. AND DESCRIPTION
1	DZ118283 oil Filter
1	BE 525523 Fuel Filter Kit
1	AT223493 Fuel strainer
1	AF125223 Air Filter
28L	10w40 Engine oil



WORK ORDER
NO. 2192

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

[illegible]

[illegible]

WORK ORDER
NO. 2179

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

WORK COMPLETED BY:		DATE	
Daz Boyles		Jan 3/26.	
UNIT #	MAKE	HOURS	KMS
G14	Schroeder	15487	
JOB DESCRIPTION			
Replace O' Rings on elbow at Rotary manifold on the circle.			

[illegible]

WORK ORDER
NO. 1476

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

WORK COMPLETED BY: Thomas - Dylan		DATE: Jan. 24, 2026	
UNIT # G14	MAKE John Deere	HOURS	KMS

JOB DESCRIPTION

- replace cabin blower motor
- Change engine oil-oil filter
- Change 2 wing hoses

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-9341

[illegible]

WORK ORDER
NO. 2506

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

[illegible]

[illegible]

WORK ORDER
NO. 2461

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

[illegible]

[illegible]

WORK ORDER
NO. 2457

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

[illegible]

JDC Print Shop 780-836-3810



WORK ORDER
NO. 2329

[illegible]

JDC Print Shop 780-836-3810

[illegible]

[illegible]

WORK ORDER
NO. 2384

PO Box 930 Manning, AB T0H 2M0 Phone:780-836-0611

[illegible]

