

04049855

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATEManitoba Vehicle Standards and Inspect
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba 

C007016

Date Inspection Started 24 09 25
DAY MO. YR.

Date Inspection Completed 26 09 25
DAY MO. YR.

Inspection Expiry Date 30 09 26
DAY MO. YR.

Station Number A11089 Station Name MidMan Mechanical Services City Winnipeg

Mechanic Number M03910 Mechanic Signature [Signature] Station Phone Number 526-2231

Vehicle Owner James Edmondson

Address Box 338 City Glenboro Province MB Postal Code R0K 0X0 Phone

- ☒ Pass/Safe Vehicle
- ☒ Fail/Unsafe Vehicle
- ☐ Fail/Hazardous

Licence Number PDC028Prov. MBNSC # MB0692512Odometer Reading 1226390Odom. Type ☒ km ☐ mi

Vehicle Identification Number

4NHNC916J2FN1179H211Make BMWModel Year 2015Unit # ☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS ☒ Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

☒ Section 1 - Power Train: Defects (if any)

☒ Section 2 Suspension: Defects (if any)

☒ Section 3 - Brake Systems: 3H (3A) Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection

Defects (if any) Circle Brake Type

3A - 19 D ABS modulator Valve inoperative

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	<u>22</u>	<u>22</u>	<u>44.65</u>	<u>44.65</u>	<u>1.25</u>	<u>1.25</u>
2	<u>13</u>	<u>14</u>	<u>16.531</u>	<u>16.542</u>	<u>1.5</u>	<u>1.5</u>
3	<u>14</u>	<u>13</u>	<u>16.535</u>	<u>16.560</u>	<u>1.5</u>	<u>1.5</u>
4						
5						
Final Measurement						

☒ Section 4 - Steering: Defects (if any)

☒ Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

☒ Section 6 - Lamps: Defects (if any)

☒ Section 7 - Electrical System: Defects (if any)

☒ Section 8 - Body: Defects (if any) 8-18d - Passenger Side mirror Cracked

☒ Section 9 - Tire & Wheel: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	<u>6</u>	<u>6</u>			<u>100</u>	<u>100</u>		
2	<u>10</u>	<u>10</u>			<u>100</u>	<u>100</u>		
3	<u>10</u>	<u>10</u>			<u>100</u>	<u>100</u>		
4								
5								

☒ Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not