#### RECORD OF ANNUAL INSPECTION

(49 CFR 396.17-23)

12/03/2024

		riepan	a apparai	a rioport	IOI CACIT VOINCIO I	nspected		יפלאטדט	303	
		bo	1						203	
Tran	chine	1 3 Harras	IGHIOV	1	TRUCK [	TRACTO	OR DET	DAIL CONVER	TED	
S.	REPORT A	1	Cambrid I. Sales		VEHICLE MAKE	E	- 20		IIEN	S.F.
100	or Ve	alley	Acres 6	aut Post	DTI				YEAR	11/17/11
	STATE		ZIP		VEHICLE IDEN	TIFICATION	(Company	y No. Carro	XX	0
lix	H	2	5502	-/	Cd3	281		Tag No. or VI	N)	35
ME (Messe	say /	-1	1			E	APLOYEE F	10/		
	Har			- Marile		100	2	6		
CON	DITION	(For Detailed In	formation	on Inspe	ation Procedures	see FMC	SR Port	200 4	-	
OK	REPAIR		OK	REPAIR		OK	DEDAG	Appendix A)		
THE RES	1	EXHAUST	SHOW SHOW	1	STEERING	OK	m=rain	PROPERTY. CO.	OK	REPAIR
-	THE REAL PROPERTY.	Leaks	NIA		O'UN COMMON DESCRIPTION OF THE PARTY OF THE	MILE	<b>Baltisks</b>	and the second s	THE REAL PROPERTY.	The state of
1		Placement	NA	E50000000000	and the last	11/17	-			
/	BOUT AND ASSESSMENT	LIGHTING	THE REAL PROPERTY.	THE RES	Axle	10/10			-	
		Headlights	NIA	District of the	Unkege	1/04				
/	THE REAL PROPERTY.	Tail/Stop	/		SATURNATURE OF STREET, SALES	1/2		Name and Address of the Owner, where the Party of the Owner, where the Owner, which is the Owner, w	-	
		Clearance/Marker	/	MINTEN ST	Other				-	-
6		Identification	/	1,978(8)3	FUEL SYSTEM	(Callyde	A890308	and the same of th	-	-
VIA	The state of the s	Reflectors	/	Name of Street	Market Committee of the Parket	MICA		The second secon	-	-
VIA		Other	DEPOSITE OF	255	Lines	10/1		The state of the s	-	-
VA			1200000	DESCRIPTION OF THE PERSON OF T	THE PARTY OF THE	1	100 Part 100	Otries	-	4
/		GAB/BDDY	<b>CHARLES</b>	D. HOUSE	SUSPENSION	d teater	NAME OF TAXABLE PARTY.	WHEEL STOWN	Academic .	
		Access		200	Springs	1	I Berons	The same of the sa	1	-
		Eqpt./Load Secure	(		Attachments	1/			With	
100	18 TAC NO.	Tie-Downs	NIA		Control of the Contro	WITA	and the same	DISCOPURB	WA	The second second
WA		Headerboard	NIA	CALLEGE.		N/M	100 per 1100	MANDONIELD	AND DESCRIPTION OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWINCE IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO	12000
4		Motorcoach Seats	NIA	DESCRIPTION OF THE PARTY OF THE	MIRRORS	I Name		The second secon	11/1	/
Ja I		THE RESERVE OF THE PERSON NAMED IN	-		British and the same of	MA			VI	#
10000			Mar Com Co	1300000000	COMPAND AND CO. S.	11/11		vishera	11/1	4
	Der Der Der CON	Deer VA Deer VA Har CONDITION OR REPAIR	Tenching Beach  Deer Valley  Harry Chee  CONDITION (For Detailed in  OK REPAIR  EXHAUST  Leaks  Placement  LIGHTING  Headlights  Tail/Stop  Clearance/Marker  Identification  Reflectors  Other  CAB/BDDY  Access  Eqpt./Load Secure  Tie-Downs  Headerboard	Trenching Acayaston  Deer Valley  Harry Cheek  CONDITION For Detailed Information  OK REPAIR  Placement  Leaks  Placement  Lighting  Headlights  Tail/Stop  Clearance/Marker  Identification  Reflectors  Other  CAB/BDDY  Access  Eqpt.A.oad Secure  Tie-Downs  Headerboard  Motorcoach Seats  MA  MOTORCOACH  MOTORCOACH	Trenching Bacayation  Deer Valley  Water Scott Seek  CONDITION For Detailed Information on Inspector  OK REPAIR  EXHAUST Leaks Placement UGHTING Headlights Tail/Stop Clearance/Marker Identification Reflectors Other  GAB/BDDY Access Eqpt.A.oad Secure Tie-Downs Headerboard Motorcoach Seats  Motorcoach Seats  NA  Motorcoach Seats	VEHICLE TYPE  TRUCK  VEHICLE MAKE  Adjustment  Column/Gear  Akle  Linkage  Power Sieering  VHA  BERNARI  ON  ON  ON  ON  ON  ON  ON  ON  ON  O	TRUCK TRACTO VEHICLE MAKE VEHIC	VEHICLE TYPE  TRUCK TRACTOR TO VEHICLE TRUCK TRACTOR TO VEHICLE MAKE  VEHICLE DENTIFICATION (Company VEHICLE DENTIFICATION (	VEHICLE TYPE  TRUCK TRACTOR TRAILER CONVER DOLLY  VEHICLE MAKE MODEL  VEHICLE MAKE MODEL  MODEL  VEHICLE MAKE MAKE MODEL  MODEL  VEHICLE MAKE MAKE  MODEL  MODEL  VEHICLE MAKE  MODEL  MODEL  VEHICLE MAKE  MODEL  VEHICLE MAKE  MODEL  VEHICLE MAKE  MODEL  MODEL  VEHICLE MAKE  MODEL  VEHICLE MAKE  MODEL  VEHICLE MAKE  MODEL  MODEL  VEHICLE MAKE  MODEL  MODEL  VEHICLE MAKE  MODEL  MODEL  MODEL  VEHICLE MAKE  MODEL  MODEL  MODEL  VEHICLE MAKE  MODEL  MODEL  MODEL  MODEL  COMPANIE  MODEL  MODEL  MODEL  COMPANIE  MODEL  MODEL  COMPANIE  MODEL  MODEL  MODEL  COMPANIE  MODEL  MODEL  COMPANIE  MODEL  MODEL  MODEL  COMPAN	VEHICLE TYPE  TRUCK TRACTOR TRAILER CONVERTER  VEHICLE MAKE  MODEL  VEHICLE MAKE  VEHICLE MAKE  VEHICLE MAKE  MODEL  VEHICLE MAKE  VEHICLE MAKE  VEHICLE MAKE  MODEL  VEHICLE MAKE  MODE

REMARKS

Certification: This vehicle has passed all the inspection items for the annual vehicle inspection in accordance with 49 CFR Part 396.

QUALIFIED INSPECTOR'S SIGNATURE

Hay Chah

APPLY LABEL TO A CLEAN, DRY SURFACE. USE WITH AN OVERLAMINATE (2402) TO IMPROVE DURABILITY UNDER NORMAL WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED FOR USE WHEN FILLING OUT THE LABEL. INDELIBLE INK IS PERMANENT AND WILL NOT WASH OFF, BUT MAY FADE DUE TO EXPOSURE TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL DISCRETION IS ADVISED REGARDING APPLICATION OF LABEL TO AN AREA NOT **EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT** AND/OR ELEMENTS AND IT IS RECOMMENDED THAT THE READABILITY OF THE LABEL BE CHECKED PERIODICALLY.

Copyright 2021 J. J. Keller & Associates, Inc. Neenah, Wil • JJKeller.com • (800) 327-5988 Printed in the USA

9138 (Rev. 11/21)

# FEDERAL ANNUAL INSPECTION

THIS VEHICLE HAS PASSED AN ANNUAL INSPECTION CONDUCTED IN ACCORDANCE WITH 49 CFR, PART 396, FMCSR

D10859383

LOCATION OF RECORDS:

5 Trenching \* Excavation
145 Deer Valley

Phoenix AZ City, State, Zip .



Pioneer Mobile Auto Repair LLC 401 W. 1st Ave. Casa Grande, AZ 85122 (520) 371-0068 andrew@pioneermobile.org www.pioneermobile.org TR-61

Invoice #16106

Created: 9/7/2023 Invoiced: 9/11/2023 Payment Term: On Receipt

Service Writer: Douglas Robertson

Casa Technology Systems 1745 West Deer Valley Road Ste. 126 Phoenix, AZ 85027 Mobile: (928) 530-1242 helenh@cts-us.com 2000 Trailer Flatbed (#TR-01) License Plate: 94768H

Noo	d count and cost on boards, need number of bolts u	sed confirmed	Tonographic Marie Co.			
1100	Description	sed committee	Price	QTY	HRS	Subtotal
1	Trailer Deck Boards R&R				4	\$420.00
2	Cut Broken off Bolts in Trailer Frame for Trail	er Deck			0.6	\$63.00
3	Wood Decking Boards		\$297.99	1		\$297.99
4	Self Threading Hardened Deck Bolts		\$1.50	90		\$135.00
5	Route Wiring Under Trailer Frame				0.6	\$63.00
6	Electrical Connectors		\$0.99	6		\$5.94
377	S	hop Supplies (4%): \$39.40	Tax (8.7%)	): \$41.61	Total:	\$1,065.94

We appreciate your business! The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. All warranty work must be performed by Pioneer Mobile Auto Repair LLC unless previously authorized in writing by Pioneer Mobile Auto Repair LLC. All warranty work is limited to cash value charged. Please contact us promptly if you have any questions.

Signature

REMAINING BALANCE	\$0.00
Paid To Date	(\$1,065.94)
Grand Total	
Tax	
Shop Supplies	
Subtotal	
Labor	
Parts	

Payments		
9/11/2023	Credit card ending in 4792	\$1,065.94



# Receipt from Pioneer Mobile Auto Repair LLC

Receipt #15459-0000

401 W. 1st Ave. Casa Grande, AZ 85122 (520) 371-0068 andrew@pioneermobile.org

\$205.66

Visa - 4792

VISA

Wednesday, December 21, 2022 at 1:32pm MST

Date Paic

Casa Technology Systems

Customer

#15459: DOT INSPECTION and 1 More

Order

Application Name: CHASE VISA

AID: A0000000031010

If you have any questions, email us at andrew@pioneermobile.org or call us at (520) 371-0068.

Pioneer Mobile Auto Repair LLC partners with Shopmonkey.io to provide invoicing and payments processing.



Pioneer Mobile Auto Repair LLC

401 W. 1st Ave. Casa Grande, AZ 85122 (520) 371-0068 andrew@pioneermobile.org www.pioneermobile.org

### Invoice #15459

Created: 12/20/2022 Invoiced: 12/21/2022 Payment Term: On Receipt

Service Writer: Andrew Robertson

### Casa Technology Systems

1745 West Deer Valley Road

Ste. 126

Phoenix, AZ 85027 Mobile: (928) 530-1242 helenh@cts-us.com

#### 2000 Trailer Flatbed (#TR-01)

License Plate:

94768H

THE RESIDENCE OF STREET	THE REPORT OF THE PARTY OF THE
Cuetomer	Comments
Gualonie	COMMISSION

**DOT INSPECTION 57458745** 

DO	TINSPECTION				
113	Description			HRS	Subtotal
1	DOT INSPECTION			1.2	\$126.00
		Shop Supplies (4%): \$5.04	Tax (8.7%): \$0.44	Tota	d: \$131.48

	Description	Price	QTY	HRS	Subtotal
1	REAR CLUSTER LIGHTS R & R			0.6	\$63.00
2	REAR CLUSTER LIGHTS (PROVIDED)		1		\$0.00
3	Electrical Connectors	\$2.49	3		\$7.47

We appreciate your business! The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. All warranty work must be performed by Pioneer Mobile Auto Repair LLC unless previously authorized in writing by Pioneer Mobile Auto Repair LLC. All warranty work is limited to cash value charged. Please contact us promptly if you have any questions.

Signature			

Parts	\$7.47
Labor	\$189.00
Subtotal	
Shop Supplies	\$7.86
Tax	4
Grand Total	\$205.66
Paid To Date	(\$0.00)
REMAINING BALANCE	\$205.66



## Receipt from Pioneer Mobile Auto Repair LLC

Receipt #15460-0000

401 W. 1st Ave. Casa Grande, AZ 85122 (520) 371-0068 andrew@pioneermobile.org

\$445.59

Wednesday, December 21, 2022 at 1:28pm MST Date Paid

Visa - 4792

Date Faiu

VISA

Casa Technology Systems

Customer

#15460: STRAIGHTEN AND INSTALL BOLTS ON REAR DECK PLATE and 1 More

Order

Application Name: CHASE VISA AID: A00000000031010

If you have any questions, email us at andrew@pioneermobile.org or call us at (520) 371-0068.

Pioneer Mobile Auto Repair LLC partners with Shopmonkey.io to provide invoicing and payments processing.



Pioneer Mobile Auto Repair LLC 401 W. 1st Ave. Casa Grande, AZ 85122 (520) 371-0068 andrew@pioneermobile.org www.pioneermobile.org

#### Invoice #15460

Greated: 12/20/2022 Involced: 12/21/2022 Payment Term: On Receipt Service Writer: Andrew Robertson

Casa Technology Systems 1745 West Deer Valley Road Ste. 126 Phoenix, AZ 85027 Mobile: (928) 530-1242 helenh@cts-us.com 2000 Trailer Flatbed (#TR-01) License Plate: 94768H

STRAIGHTEN AND INSTALL BOLTS ON REAR DECK PLATE

Description Price QTY HRS Subtotal

1 STRAIGHTEN AND INSTALL BOLTS ON REAR DECK PLATE 1.9 \$199.50

2 GRADE 8 BOLTS \$3.38 8 \$27.04

Shop Supplies (4%): \$9.06 Tax (8.7%): \$3.14 Total: \$238.74

	Description	Price	QTY	HRS	Subtota
	REPOSITION SPRINGS	100		1.5	\$157.50
2	SPRING BOLTS	\$ 18.80	2	17/15	\$37.60

We appreciate your business! The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. All warranty work must be performed by Pioneer Mobile Auto Repair LLC unless previously authorized in writing by Pioneer Mobile Auto Repair LLC. All warranty work is limited to cash value charged. Please contact us promptly if you have any questions.

Signature

REMAINING BALANCE	\$0.00
Paid To Date	(\$445.59)
Grand Total	
Tax	
Shop Supplies	
Subtotal	
Labor	
Parts	

Paymenta		
12/21/2022	Credit card ending in 4792	\$445.59



### Receipt from Pioneer Mobile Auto Repair LLC

Receipt #14863-0000

401 W. 1st Ave. Casa Grande, AZ 85122 (520) 371-0068 pioneermobileauto@gmail.com

\$521.70

Visa - 4792

VISA

Monday, April 25, 2022 at 10:56am MST

Date Paid

**Casa Technology Systems** 

Customer

#14863: DOT INSPECTION and 3 More

Order

Application Name: CHASE VISA

AID: A000000031010

If you have any questions, email us at pioneermobileauto@gmail.com or call us at (520) 371-0068.

Pioneer Mobile Auto Repair LLC partners with Shopmonkey.io to provide invoicing and payments processing.



Pioneer Mobile Auto Repair LLC 401 W. 1st Ave. Casa Grande, AZ 85122 (520) 371-0068 pioneermobileauto@gmail.com

### Invoice #14863

Created: 4/20/2022 Invoiced: 4/21/2022

Payment Term: On Receipt Service Writer: Andrew Robertson

**Casa Technology Systems** 

1745 West Deer Valley Road Ste. 126 Phoenix, AZ 85027 Mobile: (928) 530-1242 helenh@cts-us.com 2000 Trailer Flatbed (#TR-01)

License Plate: 94768H

DOT	TINSPECTION TO THE PROPERTY OF				
	Description			HRS	Subtota
1	DOT INSPECTION	N- Love - Control - Contro		1.2	\$118.80
	Sho	p Supplies (3%): \$3.56	Tax (9.2%): \$0.33	Tota	l: \$122.69

	Description		Price	QTY	HRS	Subtotal
1	Trailer Break Away Box and Switch R & R		L. T.		1.5	\$148.50
2	Trailer Break Away Box and Switch	\$1	09.48	1 1		\$109.48
3	Electrical Connectors		\$1.99	6		\$11.94

LICE	ense Plate Light R & R			271	LIDO	Ouhtetal
	Description	P	rice	QTY	HRS	Subtotal
1	License Plate Light R & R				0.4	\$39.60
2	License Plate Light	\$14	4.99	1		\$14.99
3	Electrical Connectors	\$	1.99	2		\$3.98
		Shop Supplies (3%): \$1.76	Tax (8	3.7%): \$1.80	Tof	tal: \$62.13

Bolt	t Down Trailer Decking				STATE OF THE PARTY.	
	Description	F	Price	QTY	HRS	Subtota
1	Bolt Down Trailer Decking				0.4	\$39.60
2	Decking Bolt	\$	2.99	2		\$5.98
		Shop Supplies (3%): \$1.37	Tax (8	3.7%): \$0.64	To	tal: \$47.59



Pioneer Mobile Auto Repair LLC 401 W. 1st Ave. Casa Grande, AZ 85122 (520) 371-0068 pioneermobileauto@gmail.com

## Invoice #14863

Created: 4/20/2022 Invoiced: 4/21/2022

Payment Term: On Receipt Service Writer: Andrew Robertson

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature

REMAINING BALANCE	\$0.00
Paid To Date	(\$521.70)
Grand Total	
Tax	
Shop Supplies	\$14.79
Subtotal	
Labor	
Parts	

Payments		
4/25/2022	Credit card ending in 4792	\$521.70



Invoice #: 40232

Bill To:

CASA TECH SYSTEMS LLC

DAVID

1744 W DEER VALLEY RD

#126

PHOENIX, AZ 85027

Business: 928-530-1242

Home: Cell: 928-530-1242 970-629-8992

Fax:

970-629-8992

Ed Whitehead's Tire #4
313 N. Maricopa St.
Casa Grande, AZ 85122
520-836-3135

Pcl Chf

Pel Chase D. woods

Unit #:

Vehicle: 2018 TRAILER FLAT BED

FLAT BED

License: 1LA9COA / AZ Mileage: In: 2 / Out: 2

VIN #: Torque: 140

Air Prs: 80.0 F / 80.0 R

Salesmn: Alex Berres

		Durchmi: Alex Delles						
Item #	Size	Description	Slmn/Tec	Qty	FET	Parts	Labor	Extended
FHST11	ST235/80R16 14G	Freedom Hauler FREEDOM HAULER ALL STEEL [ALLSTEEL]	AB /AW	3	5.48	223.99	0.00	688.41
00600	VALVE	HI PRESSURE RUBBER VALVE	AB /AW	3	0.00	2.99	0.00	8.97
MB	LABOR	Mount & Balance	AB /AW	3	0.00	0.00	16.99	50.97

--- CREDIT TERMS ---

FOR ACCOUNT ENDING IN 4792: APPLABEL: VISA CREDIT

AID: A000000031010 TVR: 0080008000 IAD: 06021203A02002

FSI: E800

QC: ED3B897C9252B277

ARC: 00 CVM: S

Comments:	-		

Name Acct Auth Amount Cash: 0.00 Check: 0.00 680.94 Parts: Visa 4792 133028 817.00 Credit Card: 817.00 On Acct: 0.00 Labor: 50.97 F.E.T.: 16.44 Amount Tendered: \$817.00 Subtotal: 748.35 Total: - \$817.00 Az | Environmenta: 6.00 Change: \$0.00 Sales Tax: 62.65

ustomer Authorization: \$817.00

In QB)



Pioneer Mobile Auto Repair LLC 401 W. 1st Ave.

Casa Grande, AZ 85122 (520) 371-0068 andrew@pioneermobile.org www.pioneermobile.org

Invoice #13914

Created: 4/26/2021 Invoiced: 4/26/2021

Term: On Receipt

Service Writer: Andrew Robertson

2000 Trailer Flatbed (#TR-01)

License Plate:

947681

Casa Technology Systems 1745 West Deer Valley Road Ste. 126 Phoenix, AZ 85027 Mobile: (928) 530-1242 davew@cts-us.com

DO	INSPECTION				
	Description		- 000 4.0 - 2 - 1 - 4	HRS	Subtotal
1	DOT INSPECTION			1.24	\$110.00
6 1X		Shop Supplies (3%): \$3.30	Tax (9.2%): \$0.30	Tota	l: \$113.60

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

01	
Signature	

Parts	\$0.00
Labor	
Subtotal	\$110.00
Shop Supplies	\$3.30
Tax	\$0.30
Grand Total	
Paid To Date	(\$0.00)
REMAINING BALANCE	\$113.60

Corrected will And reso title

4GBBF1820C1023251

2012

DRSN

Unknown

TL

CASA TECHNOLOGY SYSTEMS LLC 1745 W Deer Valley Rd Ste 126 Phoenix, AZ 85027-2123

A001440327

9/22/2020

0

BH21020106010

AZ

4/15/2020

CASA TECHNOLOGY SYSTEMS LLC 1745 W Deer Valley Rd Ste 126

Phoenix, AZ 85027-2123

Owner

MVD made a
motake on the
Vin ## - Our Joshiance
Company caught 14
23251 NOT 223251
Picture Shows an correct

DISCOUNT TIRE

4/17/2020 12:01 PM

TIM HEISLER 1745 W DEER VALLEY RD SUITE #126 PHOENIX, AZ 85027 720.737.8359 (M)

2019 TRAILER ALL MODELS ALL ALL

Miles: Torque Specs:

Invoice # 1390071

AZP 54 393 8 WATSON RD BUCKEYE, AZ 85326 623.327.9353

Salesperson 89 SARAT PUN

Estima	ted C	ompietion Time	12:30 PM	FET	Price	Amount
Artlole	Olly	Description	A CONTROL OF A	A STATE OF THE PARTY OF THE PAR	NUMBER OF STREET	25 10 00 00 00
25552 NRM	4	ST285 /85 R16 HRT HARTLAND	129M Q BSW ST RADIAL	6.40 ALL STEEL	194.00	797.92
OLT PATT	TERN:					
INFLATION	F:20	R:20			88.00	.00
80017	0	PERTIFICATES FUI	A SHARENT		ACTIVISES.	
NRM	1.12	REFUND, REPL	ACEMENI		2.00	8.00
80076	4	STATE REQUIRED			图的规则	100
NRM	Parell.	TIRE FEE			2.76	.00
80224	0	WASTE TIRE			PERE BUILD	W 195 194
NRM	144E	DISPOSAL FEE			21.00	84.00
80219	4	INSTALLATION &			Constant.	No. of Parts
A1174 B.B.	100	LIPE OF TIRE M	AINTENANCE			
	e and	a	tound st			
www	disco	untilire convensiom	SL - BOLDIODLINA	co ternis	69.00	69.00
85466	31	16 X8 8-100.	In a gruess	124.00		
A A DES PARTY	1350hi?	LIO MOD TRA	La Carlo Contractor Co	DOMESTIC OF THE PERSON OF THE		2.55
WAR	RANT	Y - Lifetime struct	tural, 1 year illia	L	100	THE

The tire and/or wheel you have chosen is different from the original equipment provided with your vehicle and may change its handling or stability characteristics. Further information is available from your Discount Tire salesperson.

I understand by my signature below: The personal and vehicle information i have voluntarily provided is correct. I agree to purchase the products, pay the fees and authorize the service and repairs at the final costs specifically listed in this electronic invoice. This invoice, if and as necessary under the law, is an estimate of repair and service costs as detailed herein. Terms and Conditions for this transaction are found at www.discountiire.com/customer — service/invoice — terms

958.92 **8ub Total:** 80.62 Sales Tax: 1,039.54 Sales Total: (AMX) 1,039.54 Tendered: Tendered Today: 1,039.54

1,039.54 Tendered Total:

Signature on file

and n on tires