



Commercial Vehicle Inspection Report

Decal Number: GL08344
Decal Expiry Date: 2026-Apr-30
Inspection Number: 21543146

Inspection Result:

PASS 280

FACILITY: DYNAMIC POWERTRAIN LTD. / S7224
INSPECTOR: TIPPE, CAMERON FRAZER / 114381
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2025-Oct-17 02:00 PM PDT
INSP. COMPLETE: 2025-Oct-24 02:38 PM PDT

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 26500
VEHICLE YEAR: 1995
MAKE: WESTERN ST
MODEL:

REGI: 09089926
UNIT/FLEET#:
BODY STYLE: Flat Deck
ODOMETER: 462127 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2WLPCCH1SK938256
OWNER/LESSEE NAME: JAMES WISE, JAMES WISE
ADDRESS: 6301 228 STREET
Langley, British Columbia
V2Y2L3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) REPLACED #1, #2, #3 U-JOINTS.
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed with Caution HIGH CAM ROTATION STARTING ON ##1 & #2 D/S. REPLACED #2 D/S & #3 P/S BRAKE POTS & SLACK ADJUSTERS.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	35	35
2	Clamp	30	Automatic	35	35
3	Clamp	30	Automatic	35	35

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	14			8	✓
	7	5	5	9	
	7	5	3	4	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	100	80
2	100	90
3	75	80

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	11	14
Lining (Shoe)	9	12
Lining (Shoe)	15	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: TIPPE, CAMERON FRAZER

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Oct-24 02:39 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement

CVSE0014

10/24/2025 2:39:50 PM PDT