

Maintenance History Report

Report Generated on 21/10/25 07:41 AM

2178 International Acco 2350G Water Truck

Job No	Job Title	Start Date	Status
P0021069/0	1000hr Service	01/01/01	CA
J0000644/0	SETUP TRUCK FOR WORK	03/08/06	C
J0000644/1	AB SERVICE	10/08/06	C
J0000644/2	TRANSMISSION SERVICE	10/08/06	C
J0000644/3	FIT TX3600 RADIO AND AERIALS	17/08/06	C
J0002175/0	October 06	01/10/06	C
J0002175/1	AB Service	06/10/06	C
J0002175/3	Repair Horn	06/10/06	C
J0002175/2	Repair RF Hubseal	06/10/06	C
J0002175/4	Tyres fitted	24/10/06	C
J0002948/0	November 06	01/11/06	C
J0002948/1	AB Service	24/11/06	C
J0002948/2	Repair Front left Spray	24/11/06	C
J0004366/0	January 07	02/01/07	C
J0004366/1	AB Service	29/01/07	C
J0004366/2	Repair rear lights and washers	29/01/07	C
J0004430/0	February 07	01/02/07	C
J0004430/1	Remove, clean and lubricate spray valve	01/02/07	C
J0004430/2	Replace oil cap	09/02/07	C
J0004430/3	Replace hose	12/02/07	C
J0004430/4	Repair fault in UHF radio	19/02/07	C
J0005383/0	March 2007	01/03/07	C
J0005383/1	Modify Rear Carry Rack	08/03/07	C
J0005501/0	A-B Service	12/03/07	C
J0005383/2	Repair front spray pipe	19/03/07	C
J0006010/0	April 07	02/04/07	C
J0006010/1	Replace butterfly valves	02/04/07	C
J0006010/2	Fit breather and tube to transmission	04/04/07	C
J0006010/3	Repair front indicators	13/04/07	C
J0006010/4	Fit Cannon	17/04/07	C
J0006010/5	Adjust Belts	18/04/07	C
J0006010/6	Repair beacon	27/04/07	C
J0006626/2	AB Service	02/05/07	C
J0006626/0	May 07	02/05/07	C
J0006626/1	Service Transmission	02/05/07	C
J0006626/3	Repair broken site glass on steer axle at Neath	07/05/07	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0006626/4	Repair tail lights	11/05/07	C
J0006626/5	Tighten exhaust system	11/05/07	C
J0007570/0	June 07	01/06/07	C
J0007570/1	Replace tyres Pos 7,8,9,10	04/06/07	C
J0007570/2	Check all lighting after floods	12/06/07	C
J0007752/0	Replace 3 batteries	12/06/07	C
J0007799/0	Change Engine, gearbox and differential oils	12/06/07	C
J0007749/0	Check starter motor	18/06/07	C
J0008622/0	July 07	01/07/07	C
J0008637/0	AB Service	11/07/07	C
J0008637/1	Repair RHF Wheel bearing contamination	11/07/07	C
J0009883/0	August 07	01/08/07	C
J0009340/0	Remove water pump for repair	03/08/07	C
J0010623/0	Replace keystone valve	12/09/07	C
J0010625/0	AB Service	12/09/07	C
J0010651/0	Lubricate RHF spray and realign sprays	13/09/07	C
J0010743/0	Replace moisture ejector	17/09/07	C
J0010890/0	Replace check valves on air tanks	24/09/07	C
J0011021/0	Repaired water pump switch	02/10/07	C
J0011180/0	Replace pump control valve	04/10/07	C
J0011590/0	Repair front left air spray fitting	15/10/07	C
J0011788/0	AB Service	23/10/07	C
J0011795/0	Repair water sprays	23/10/07	C
J0011954/0	Replace exhaust flex	30/10/07	C
J0012480/0	Replace LHR drive air bag	13/11/07	C
J0012622/0	Repair RH mudguard and tighten mirror brackets	16/11/07	C
J0012744/0	Repair hose reel and switch	22/11/07	C
J0012794/0	Weekly service	23/11/07	C
J0013045/0	AB Service	03/12/07	C
J0013737/0	Replace tyres Pos 1/2	20/12/07	C
J0014368/0	Replace RH front blinker	14/01/08	C
J0014615/0	Fit fittings to fire hoses	21/01/08	C
J0014725/0	Coolant Leak	23/01/08	C
J0014806/0	Replace RHF drive brake booster	25/01/08	C
P0000526/0	500hr service (Acco W/Cart)	29/01/08	C
J0014863/0	Replace drive shocks	30/01/08	C
J0015339/0	February 08	01/02/08	C
J0015036/0	Replace LHR Spray valve	04/02/08	C
J0015464/0	Replace RH front drive upper shock mount	13/02/08	C
J0015814/0	Weekly service	27/02/08	C
J0016143/0	Weekly service	06/03/08	C
J0016302/0	Check sprays and replace switch	10/03/08	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0016546/0	Replace front rotating beacon	18/03/08	C
P0000795/0	250hr service (Acco W/Cart)	19/03/08	C
J0016697/0	Check sprays operation	26/03/08	C
J0017264/0	Replace tyre Pos 3,4,5,6	31/03/08	C
J0017151/0	April 08	01/04/08	C
J0016926/0	Replace RH Rear spray	02/04/08	C
J0017059/0	Replace fuel pump	05/04/08	C
J0017361/0	Repair coolant leak	14/04/08	C
J0017603/0	Repair fault in heater	22/04/08	C
J0017671/0	Weekly service	24/04/08	C
J0017786/0	Replace air fitting to LHF spray	30/04/08	C
J0017779/0	May 08	01/05/08	C
J0018288/0	Weekly service	01/05/08	C
P0001169/0	250hr service (Acco W/Cart)	19/05/08	C
J0018765/0	Supply 30mtr of 38mm Layflat Hose	28/05/08	C
J0018782/0	Repair heater hose coolant leak	28/05/08	C
J0018960/0	Weekly inspection	02/06/08	C
J0019470/0	Rear Main Oil Leak	16/06/08	C
J0019624/0	Check rear sprays	23/06/08	C
J0019982/0	Replace faulty 2 way radio	30/06/08	C
P0001569/1	Replace number plate light	15/07/08	C
P0001569/2	Take driver back to jobsite	15/07/08	C
P0001569/3	Take driver back to jobsite	15/07/08	CA
P0001569/0	250hr service (Acco W/Cart)	15/07/08	C
J0021574/0	Replace layflat hose and clamps	28/07/08	C
J0021619/0	Repair wiring to starter motor	28/07/08	C
J0021691/0	Replace auto ejector valve	28/07/08	C
J0021691/1	Travel to peick up part	28/07/08	C
J0021793/0	Fabricate hose basket	28/07/08	C
J0022030/0	Check coolant leak	01/08/08	C
J0022251/0	Check LHF blonker operation	05/08/08	C
J0024196/0	Repair Coolant Leak	26/08/08	C
P0001885/0	500hr service (Acco W/Cart)	29/08/08	C
J0024618/0	Replace bearings and seal in water pump	01/09/08	C
J0026566/0	Replace sight glass hose	23/09/08	C
J0027344/0	Loosing air pressure	01/10/08	C
J0029748/0	Grease for machine	01/10/08	C
J0028655/0	Replace belts	16/10/08	C
J0028655/1	Travel to Kooragang and Taylors	16/10/08	C
P0002211/1	Travel to Kooragang to return driver to site	17/10/08	C
P0002211/0	250hr service (Acco W/Cart)	17/10/08	C
J0032150/0	Repair flat tyre	17/11/08	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0032822/0	A/C not cold	03/12/08	C
P0002509/2	Repair brake booster	06/12/08	C
P0002509/3	Replaced bolts in support	06/12/08	C
P0002509/4	Resecure mudguard	06/12/08	C
P0002509/1	Resecured battery box	06/12/08	C
P0002509/0	500hr service (Acco W/Cart)	06/12/08	C
J0034491/0	Truck grease	23/12/08	C
J0034549/2	Losing Air Overnight	29/12/08	C
J0034549/3	Replace Rear Drive Tyres	29/12/08	CA
J0034549/0	Replace Spray Bar and Cannon Switch's	29/12/08	C
J0034549/1	Right Front Spray	29/12/08	C
J0034686/0	Replace beacon switch	02/01/09	C
J0034747/0	Reposition LH Front Spray	05/01/09	C
J0034837/0	Replace tyres	05/01/09	C
J0037314/0	Clearance light not working	06/02/09	C
P0002860/0	250hr service (Acco W/Cart)	06/02/09	C
J0040158/0	Replace Maxi Dump Valve	12/03/09	C
J0040158/1	Travel to Kooragang for job and RHT for parts	12/03/09	C
J0040200/0	Replace hydraulic filters	12/03/09	C
J0041249/0	Air Leak at Brakes	25/03/09	C
J0041249/1	Travel to Bechtel and return	25/03/09	C
J0041292/0	Park lights not working	25/03/09	C
P0003181/0	500hr service (Acco W/Cart)	25/03/09	C
J0047870/0	Pump control switch faulty	15/06/09	C
J0047870/1	Travel to Kooragang and return	15/06/09	C
J0049934/0	PTO oil leak	08/07/09	C
P0003872/0	250hr service (Acco W/Cart)	08/07/09	C
J0051566/0	LHF Air Bag Blown	28/07/09	C
J0051566/1	Travel to Thornton for parts	28/07/09	C
J0053127/0	Transmission noise	13/08/09	C
J0053127/1	Travel to Kooragang Island and return	13/08/09	C
J0053311/1	Travel to PWCS	17/08/09	C
J0053311/0	Water pump not working	17/08/09	C
J0053675/0	Flashing light not working	19/08/09	C
J0053675/1	Travel to Kooragang Island and return	19/08/09	C
J0055155/0	Coolant Leak	03/09/09	C
J0055155/1	Travel to PWCS	03/09/09	C
P0004352/0	500hr service (Acco W/Cart)	03/09/09	C
J0058482/0	Air Bags not Inflating	14/10/09	C
J0058482/1	Travel for parts and to job	14/10/09	C
P0004662/0	250hr service (Acco W/Cart)	14/10/09	C
J0059312/0	Replace tyres Pos 1, 2	21/10/09	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0059694/0	Exhaust leak	29/10/09	C
J0059694/1	Travel for parts	29/10/09	C
J0060311/0	Replace ride height control	09/11/09	C
J0060312/0	Replace fan belt	09/11/09	C
J0060312/1	Travel for parts	09/11/09	C
J0060397/0	Driver seat will not lock in position	10/11/09	C
J0060536/0	Leak at PTO	11/11/09	C
J0061293/0	INSPECT WIRING, HOSING & PIPING FOR FOULING THE STARTER MOTOR MAN POWER STUD	19/11/09	C
J0061293/1	Return driver to Kooragang	19/11/09	C
J0061512/0	Replace hose from tank to pump	20/11/09	C
J0061512/1	Travel to Kooragang Island	20/11/09	C
J0062609/0	Repair air leak	03/12/09	C
P0005060/0	500hr service (Acco W/Cart)	03/12/09	C
J0065187/0	Brake problem	07/01/10	C
J0065187/1	Travel to Kooragang	07/01/10	C
J0065063/0	Air Leak when Brakes are Applied	08/01/10	CA
J0065189/0	Replace switch for RF spray bar	08/01/10	C
J0066089/0	Oil leak at PTO	19/01/10	C
J0066089/1	Travel to Kooragang	19/01/10	C
J0066240/0	A/C Not Cold	21/01/10	C
P0005422/0	250hr service (Acco W/Cart)	27/01/10	C
J0066937/0	Replace transmission cooler lines	29/01/10	C
J0068671/0	Cannon Switch Not Working	16/02/10	C
J0068672/0	Park Brake Leaking	16/02/10	C
J0068777/0	Windscreen Washers Blocked	17/02/10	C
J0068810/0	Replace window winder handles	17/02/10	C
J0069180/0	Wash truck	20/02/10	C
J0069261/0	Steer hub leaking	22/02/10	C
J0069288/0	Repair rust area	22/02/10	C
J0069458/0	Beacon not working	24/02/10	C
J0070478/0	Wash & grease	05/03/10	C
J0070479/0	Brakes noisy and vibrating	05/03/10	C
J0071622/0	Replace tyres Pos 7,8,9,10	15/03/10	C
P0005807/0	500hr service (Acco W/Cart)	15/03/10	C
J0071203/0	UHF not transmitting	16/03/10	C
J0071249/0	Monitor not working	17/03/10	C
J0071387/0	Noise in waterpump	19/03/10	C
J0071387/1	Travel to Kooragang and for parts	19/03/10	C
J0071537/0	Check fault with dash light	20/03/10	C
J0072738/0	Water Pump is Leaking	06/04/10	C
J0073154/0	Cruise control not working	08/04/10	C
J0073154/1	Travel to Kooragang and return	08/04/10	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0074787/0	Replace batteries	29/04/10	C
J0074787/1	Travel to 3rd River and return	29/04/10	C
J0075265/0	Park Brake Valve Leaking	05/05/10	C
J0075265/1	Pick up parts from RH Taylors	05/05/10	C
P0006215/0	250hr service (Acco W/Cart)	05/05/10	C
J0075457/0	Spray Switch Leaking	07/05/10	C
J0075457/1	Travel to PWCS	07/05/10	C
J0077608/0	Check oil leak, assist Enzed	28/05/10	C
J0079272/0	Fuel leak from injector pump	18/06/10	C
J0079272/1	Top up trans oil	18/06/10	C
P0006655/0	12000hr service (Acco W/Cart)	23/06/10	C
P0006913/1	Engine Pipe Rusted	04/07/10	C
P0006913/0	Rego Inspection	04/07/10	C
J0081221/1	Pick up from Kooragang and return	12/07/10	C
J0081221/0	Rear Drive Brake Reline	12/07/10	C
J0083622/0	Rotating Beacon Not Working	10/08/10	C
J0083622/1	Travel to Bechtel and return	10/08/10	C
J0085203/0	Repair Wiring to Reverse Light	27/08/10	C
J0085208/0	RHR Spray Leaking	28/08/10	C
J0085209/0	RH Window Hard To Wind Up	28/08/10	C
J0085682/0	Replace tyres Pos 1/2	28/08/10	C
P0007545/0	12250hr service (Acco W/Cart)	28/08/10	C
J0085909/0	Master Spray Control Leaking	07/09/10	C
J0085975/0	Top Up Transmission Oil	07/09/10	C
J0087779/0	Repair tyre Pos 8	30/09/10	C
P0008228/0	12500hr service (Acco W/Cart)	12/10/10	C
J0088768/0	Slow to build up air	15/10/10	C
J0089047/0	Engine Run Without Oil	20/10/10	C
J0089394/0	Replace Fill Hose	22/10/10	C
J0089432/0	Pre Work Inspection	25/10/10	C
J0089463/0	LH headlight cracked - replace	26/10/10	C
J0089465/0	Transmission output shaft seal leak	26/10/10	C
J0089466/0	Fuel tank straps rusted - replace	26/10/10	C
J0089467/0	Turbo replacement	26/10/10	C
J0089468/0	Battery Isolator - Replace	26/10/10	C
J0089469/0	Mirror brackets rusted - replace	26/10/10	C
J0089470/0	LHF water spray turns on automatically	26/10/10	C
J0089563/0	Remove rock between dual wheels	27/10/10	C
J0089700/0	Wash	27/10/10	C
J0089829/0	Turbo replace	29/10/10	C
J0090239/0	Engine warnig light on	03/11/10	C
J0090452/0	Fuel leak	04/11/10	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0090431/0	SOS Investigation- Change transmission oil	05/11/10	C
J0090426/0	UHF radio U/S	06/11/10	C
J0091254/0	A/C not cold	17/11/10	C
J0091255/0	Rear spray bar bent	17/11/10	C
P0008813/0	Bi Monthly Grease and Inspection Nov/Dec	17/11/10	C
J0092370/0	Rust Repairs	01/12/10	C
J0092430/0	Replace mirror brackets	03/12/10	C
J0092835/0	RH indicator & electric horn U/S	07/12/10	C
J0092843/0	LHF and RHR sprays U/S	07/12/10	C
J0092996/0	Check Battery Earth Cables	08/12/10	C
P0009058/0	250hr service (Acco W/Cart)	15/12/10	C
J0094309/0	Engine not starting	26/12/10	C
J0094197/0	Replace Cab Ram	29/12/10	C
J0094268/0	PTO leaking oil	29/12/10	C
J0094285/0	Replace AM/FM Radio	30/12/10	C
P0009236/0	Bi Monthly Grease & Inspection	01/01/11	C
J0094756/0	Header tank U/S	07/01/11	C
J0096575/0	Repair flat tyre	31/01/11	C
J0097189/0	A/C not cold @ Bechtel	03/02/11	C
J0097475/0	Repair flat tyre Pos	07/02/11	C
P0009839/0	13,000hr service (Acco W/Cart)	09/02/11	C
J0097650/0	Headlight brackets rusted out	14/02/11	C
J0098352/0	Replace water pump drive hose	18/02/11	C
J0098763/0	HEA Inspection - FEB	23/02/11	C
P0010178/0	Bi Monthly Grease & Inspection	01/03/11	C
J0100715/0	Window winders U/S	23/03/11	C
J0100737/0	HEA Inspection - MAR	23/03/11	C
J0100738/0	Repair windscreen washers	23/03/11	C
J0100739/0	Replace RHR spray valve	23/03/11	C
J0101262/0	Repair flat tyre	23/03/11	C
J0101038/0	A/C mount bolt broken	28/03/11	C
J0101039/0	Drive axle backing plates rusted out	28/03/11	C
J0101377/0	Replace power steering filter and oil	28/03/11	C
J0101378/0	Replace drive shocks	28/03/11	C
J0101379/0	Repair LHF spray	28/03/11	C
J0101380/0	Leaking RH hubcap	28/03/11	C
P0010654/0	13,250hr service	28/03/11	C
J0101460/0	Auxillary water pump blocked	31/03/11	C
J0101826/0	Repair tyre Pos 8	31/03/11	C
J0101527/0	Tension wheels nuts LHR	01/04/11	C
J0102161/0	Repair PTO warning lights	09/04/11	C
J0102240/0	Repair front spray head	11/04/11	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0102678/0	Replace dribble bar spray heads	15/04/11	C
J0102680/0	HEA Inspection - APR	15/04/11	C
J0102859/0	Replace tyres Pos 3/7	15/04/11	C
J0103149/0	Replace tyres Pos 4	18/04/11	C
J0103105/0	Fit new Drivers Seat Cover	27/04/11	C
J0103295/0	Cannons pressure is at half	29/04/11	C
P0011118/0	Bi Monthly Grease & Inspection	01/05/11	C
J0103611/0	Replace site glass hose	05/05/11	C
J0103974/0	Check Engine Light Coming On	09/05/11	C
J0104610/0	Rear Shock Absorbers U/S	17/05/11	C
J0104683/0	Header Tank Site Glass - Replace	17/05/11	C
J0104766/0	HEA Inspection - May 2011	18/05/11	C
J0104767/0	Reseal RHF Hub Cap	18/05/11	C
J0105711/0	Replace tyres Pos 3/4/5/6/7/8/9/10	25/05/11	C
P0011593/0	13,500hr service (Acco W/Cart)	08/06/11	C
J0106799/0	Brake Reline Both Drive Axles	10/06/11	C
J0106800/0	Replace Exhaust Manifold,gaskets and studs	10/06/11	C
J0106801/0	Replace Torque Rod Bushes	10/06/11	C
J0107156/0	HEA Inspection - June 2011	15/06/11	C
J0107009/0	Reducer coupling manufactured	16/06/11	C
J0107055/0	Replace Tie Rod including ends	16/06/11	C
J0107176/0	LHR Dog Bone Missing From Suspension	17/06/11	C
J0107265/0	Oil Leak @ Transmission	17/06/11	C
J0108253/0	PTO Pump Switch u/s	29/06/11	C
J0110328/0	HEA Inspection	01/07/11	C
P0012131/0	Bi Monthly Grease & Inspection	01/07/11	C
P0011966/0	Rego Inspection	04/07/11	C
J0109621/0	LHR toolbox Loose	13/07/11	C
J0109837/0	Water Cannon Filling Exhaust	18/07/11	C
J0109945/0	Repair mud guards and refit mud flaps	18/07/11	C
J0110488/0	Hose Reel Rusted & Leaking	25/07/11	C
J0110535/0	Engine Missfiring	26/07/11	C
J0111320/0	HEA Inspection	01/08/11	C
J0111920/0	Tow Vehicle to Cummins From Cameron Park	04/08/11	C
J0113695/0	Replace Engine @ Cummins	04/08/11	C
J0111918/0	remove Radiator & Intercooler to be Serviced	09/08/11	C
J0112194/0	Replace Engine Mounts	11/08/11	CA
P0012606/0	250hr service (Acco W/Cart)	11/08/11	C
J0114384/0	Repair Cannon Wiring	30/08/11	C
J0114187/0	HEA Inspection	01/09/11	C
P0013212/0	Bi Monthly Grease & Inspection	01/09/11	C
J0114423/0	Change engine oil and filter	02/09/11	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0117435/0	Purchase Rear Bumper Bar	15/09/11	C
J0117198/0	Replace tyres 1	19/09/11	C
J0116304/0	Right rear spray not working / switch needs replacing	23/09/11	C
J0116305/0	Low pressure on hand held hose	23/09/11	C
J0117016/0	RH door doesn't close properly	29/09/11	C
J0116952/0	HEA Inspection	01/10/11	C
J0117625/0	#2178 replace tyres pos 1,2 s/sheet 0362 - vall4	07/10/11	C
J0117387/0	Install reversing Camera	10/10/11	CA
J0117389/0	Install Reverse Camera	10/10/11	C
J0117600/0	Fuel leak from tank	10/10/11	C
J0117601/0	Air leak	10/10/11	C
J0117701/0	Hard to Start	12/10/11	C
J0118350/0	56703- Fluid leaking from header tank cap	19/10/11	C
J0118565/0	Replace Heater core	21/10/11	C
P0014021/0	14000hr service (Acco W/Cart)	27/10/11	C
J0119726/0	HEA Inspection	01/11/11	C
P0014285/0	Bi Monthly Grease & Inspection	01/11/11	C
J0120192/0	Brake booster RHR U/S	02/11/11	C
J0120194/0	FM radio not working	02/11/11	C
J0120677/0	Hubseal leaking RHRD	10/11/11	C
J0121409/0	Front beacon light blown	15/11/11	C
J0121410/0	Reversing buzzer intermittent	15/11/11	C
J0121519/0	SOS Investigation - Change transmission oil and filters	22/11/11	C
J0122175/0	RH door not closing properly	28/11/11	C
J0122244/0	Low water pressure	28/11/11	C
J0123882/0	HEA Inspection	01/01/12	C
P0015310/0	Bi Monthly Grease & Inspection	01/01/12	C
J0125474/0	Cannon not working	05/01/12	C
P0015183/0	250hr service (Acco W/Cart)	09/01/12	C
J0126816/0	Hand held hose low pressure full of rocks	16/01/12	C
J0126947/0	Assemble hose fitting	17/01/12	C
J0127294/0	Fit stickers as required	18/01/12	C
J0127425/0	RH door lock assembly U/S	20/01/12	C
J0127682/0	Fit tyres to pos 1	24/01/12	C
J0127687/0	Fit tyre to pos 1	24/01/12	C
J0128747/0	HEA Inspection	01/02/12	C
J0129321/0	LH steer wheel tensioned	08/02/12	C
J0129558/0	Water cannon not working	13/02/12	C
J0130445/0	replace r/h front drive wheel spacer	21/02/12	C
J0130829/0	Moisture ejector broken off air tank	23/02/12	C
J0131283/0	fit tyres to pos 3/4/5/6	28/02/12	C
J0131289/0	Fit tyres to pos 7/8/9/10	28/02/12	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0134167/0	HEA Inspection	01/03/12	C
P0016417/0	Bi Monthly Grease & Inspection	01/03/12	C
J0132345/0	replace steer springs	09/03/12	C
J0132393/0	LH steer guard pole rusted out	09/03/12	C
J0133004/0	Repair air bags flat	15/03/12	C
J0133591/0	HEA Inspection	21/03/12	C
P0016538/0	500hr service (Acco W/Cart)	21/03/12	C
J0134102/0	Turbo timmer inop	26/03/12	C
J0135560/0	replace hose nozzle	10/04/12	C
J0135625/0	Radio not working	10/04/12	C
J0136995/0	Main pump indicator broken	24/04/12	C
J0136996/0	Air leak from front left spray console switch	24/04/12	C
J0137576/0	Check for air leak	30/04/12	C
J0137533/0	Turbo timer and radio not working	01/05/12	C
J0137563/0	Check engine missfire	01/05/12	C
P0017508/0	Bi Monthly Grease & Inspection	01/05/12	C
J0139211/0	Inspect window winder	15/05/12	C
J0139333/0	HEA Inspection	16/05/12	C
J0139878/0	Turbo timmer and radio blown fuse	21/05/12	C
J0140018/0	Repair front sprayer fittings broken	22/05/12	C
P0017900/0	250hr service (Acco W/Cart)	27/05/12	C
J0140944/0	Repair water cannon operation	30/05/12	C
J0140949/0	Oil leak from under console	30/05/12	C
J0141089/0	No 3 injector line leaking	30/05/12	C
J0141091/0	Air leak	30/05/12	C
J0141135/0	Cannon not operating	31/05/12	C
J0141432/0	HEA Inspection	01/06/12	C
J0142198/0	Repair both front sprays	12/06/12	C
J0142287/0	Repair check engine light on	13/06/12	C
J0142458/0	Rear drive brakes dragging	15/06/12	C
J0143155/0	Replace tyre Pos 10	22/06/12	C
J0143839/0	Replace air valve mount bracket	29/06/12	C
J0144018/0	Fuel tank sender leaking	29/06/12	C
J0144019/0	RH mirror bracket loose	29/06/12	C
J0144020/0	Coolant leak from engine	29/06/12	C
P0018511/0	Bi Monthly Grease & Inspection	01/07/12	C
J0144227/0	R/H Steer hubcap oil leak	03/07/12	C
J0144822/0	Check for coolant leak	09/07/12	C
J0144895/0	HEA Inspection	09/07/12	C
J0145030/0	Fan belt replaced	10/07/12	C
J0145231/0	Water monitor n/w	11/07/12	C
J0145952/0	Repair R/H Sprayer on rear leaking	18/07/12	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
P0018992/0	500hr service (Acco W/Cart)	18/07/12	C
J0146911/0	A/C hoses rubbing	25/07/12	C
P0019095/0	Rego Renewal	25/07/12	C
J0148206/0	HEA Inspection	01/08/12	C
J0148324/0	RHR clearnace light not working	08/08/12	C
J0148344/0	Transmission sump plug,replace	09/08/12	C
J0149332/0	UHF hand piece U/S	20/08/12	C
J0149556/0	Beacons n/w	21/08/12	C
J0149731/0	Replace pump speed controller	22/08/12	C
J0149732/0	Clearance light L/H replaced	22/08/12	C
J0150029/0	RH window hard to operate	24/08/12	C
J0150031/0	Pulling to right when braking	24/08/12	C
J0150032/0	Adjust A/C belt	24/08/12	C
J0150112/0	Air leaking from under cosole	27/08/12	C
J0150599/0	Cannon not going up and down	30/08/12	C
J0152611/0	HEA Inspection	01/09/12	C
P0019708/0	Bi Monthly Grease & Inspection	01/09/12	C
J0151637/0	Replace broken switch in console	11/09/12	C
J0151784/0	Hose has low pressure , Repair	12/09/12	C
J0152178/0	Alternator U/S	15/09/12	C
J0152367/0	Starting fault	17/09/12	C
J0153040/0	Tyres replace pos 1,2	17/09/12	C
J0152444/0	Ball vavle U/S	18/09/12	C
J0152505/0	Tension steer wheels	18/09/12	C
J0152506/0	Repair leaking washout hose	18/09/12	C
J0152507/0	Repair R/H Mudguard hitting tyre	18/09/12	C
P0020204/0	250hr service (Acco W/Cart)	02/10/12	C
J0154456/0	Repair front drible bar	10/10/12	C
J0154619/0	Not starting , batteries flat	11/10/12	C
J0155067/0	A/C not working	17/10/12	C
J0155489/0	Fit tarp to rear basket	22/10/12	C
J0156264/0	Low air buzzer stuck on	29/10/12	C
J0156272/0	Low air beeper staying on	29/10/12	C
J0156436/0	Brakes,adjust . Truck pulling to right	30/10/12	C
J0156437/0	Replace water tank sight tube	30/10/12	C
J0156438/0	Remove spare wheel and mount	30/10/12	C
J0156526/0	Adjust LHF spray head	30/10/12	C
J0156527/0	Plug off overflow hose	30/10/12	C
J0156491/0	Replace rear bumper bar	31/10/12	C
J0156683/0	replace lights in rear bar	01/11/12	C
J0156692/0	Repair rear spray	01/11/12	C
P0020900/0	Bi Monthly Grease & Inspection	01/11/12	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0157217/0	Tyre replaced pos 3	07/11/12	C
J0157680/0	Staighthen steering wheel	12/11/12	C
J0157681/0	Toolbox,repair	12/11/12	C
P0021068/0	500hr service (Acco W/Cart)	12/11/12	C
J0158052/0	Cannon not working	15/11/12	C
J0159135/0	UHF radio not working	26/11/12	C
J0159366/0	Repair baecon	28/11/12	C
J0160545/0	Steering pulling to right	11/12/12	C
J0161038/0	Beacon,front not working	14/12/12	C
J0161039/0	Crack in front spray bar under pressure	14/12/12	C
J0161215/0	front beacon not working	17/12/12	C
J0161447/0	lh rear spray not working	19/12/12	C
J0161448/0	Washer motor,replaced	19/12/12	C
P0022039/0	Bi Monthly Grease & Inspection	01/01/13	C
J0161960/0	Engine stalling	02/01/13	C
P0021766/0	250hr service (Acco W/Cart)	03/01/13	C
J0162316/0	Brake lights on all the time	07/01/13	C
J0162326/0	horn not working	07/01/13	C
J0162529/0	Height control valve rod U/S	08/01/13	C
J0163040/0	Fit batter spray nozzle	14/01/13	C
J0163159/0	Repair air leak	15/01/13	C
J0163753/0	Repair L/H Steer hub seal leak	21/01/13	C
J0164121/0	Repair cruise control not working	25/01/13	C
J0164390/0	Engine not starting	29/01/13	C
J0165593/0	repair hydraulic leak	04/02/13	C
J0165804/0	Speedo and tacho n/w	12/02/13	C
J0166579/0	move front sprays	19/02/13	C
J0166534/0	HEA Inspection	01/03/13	C
P0023031/0	Bi Monthly Grease & Inspection	01/03/13	C
J0167752/0	rh outer clearance light not working	04/03/13	C
P0022680/0	1000hr Service	04/03/13	C
J0167836/0	Inspect brake light fault	05/03/13	C
J0167974/0	Rear bar cracked , Repair	05/03/13	C
J0169100/0	Replace L/H Steer hub seal	18/03/13	C
J0171282/0	Tyres replaced pos 7,8	28/03/13	C
J0169937/0	HEA Inspection	01/04/13	C
J0170464/0	Repair engine light comming on	02/04/13	C
J0171023/0	Slack adjusters on steer replaced	08/04/13	C
J0171652/0	Steer U bolts replaced	13/04/13	C
J0172982/0	Engine derating	30/04/13	C
J0172914/0	HEA Inspection	01/05/13	C
J0173094/0	Repair spray switch operation	01/05/13	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0173095/0	Inspect crack in tyre	01/05/13	C
P0024268/0	Bi Monthly Grease & Inspection	01/05/13	C
J0173114/0	Speedo not working , Repair	02/05/13	C
J0173894/0	Repair L/H/R spayer inop	09/05/13	C
P0023907/0	250hr service (Acco 2350G W/Cart)	11/05/13	C
J0174162/0	a/c blowing hot air	13/05/13	C
J0174164/0	Remove R/H/F sprayer	13/05/13	C
J0174480/0	Drive wheel spacers rusted - Replace	13/05/13	C
J0174308/0	Adjust/attach front spray's	14/05/13	C
J0174309/0	Front right sprays n/w	14/05/13	C
J0174458/0	Steering wheel replaced	16/05/13	C
J0174481/0	Rebound rollers and spacers U/S	16/05/13	C
J0175065/0	Tyres replaced pos 4	23/05/13	C
J0175100/0	Tyres replaced pos 3/4	24/05/13	C
J0175336/0	Repair A/C condensor loose	27/05/13	C
J0175446/0	HEA Inspection	01/06/13	C
J0176403/0	PTO n/w	06/06/13	C
J0176608/0	Repair hold down cords on rear tarp	12/06/13	C
J0177085/0	Hose reel feed hose torn off	18/06/13	C
J0177811/0	AGL site inspection	27/06/13	C
J0177585/0	HEA Inspection	01/07/13	C
P0025284/0	Bi Monthly Safety Inspection	01/07/13	C
J0179370/0	Tenchen drive wheels	17/07/13	C
J0179372/0	Straighten L/H/F spray head	17/07/13	C
P0025447/0	500hr service (Acco 2350G W/Cart)	22/07/13	C
J0179863/0	Tyres replaced pos 3	24/07/13	C
J0180320/0	Make up fitting for extechen pipe	29/07/13	C
J0180405/0	HEA Inspection	01/08/13	C
P0025519/0	Rego Renewal	02/08/13	C
J0180951/0	Repair dipstick operation	05/08/13	C
J0180956/0	Repair R/H/R Spray stuck on	05/08/13	C
J0180964/0	Straighten L/H/F Sprayer	05/08/13	C
J0180965/0	Inspect air leak at park brake valve	05/08/13	C
J0181043/0	Transmission fault	06/08/13	C
J0181192/0	No air supply to controls	08/08/13	C
J0181963/0	Reverse alarm/lights staying on	17/08/13	C
J0182070/0	Not building up air	17/08/13	C
J0182272/0	Water pressure low - PTO	21/08/13	C
J0183093/0	Spray valve u/s	29/08/13	C
J0183162/0	Air conditioning not working	30/08/13	C
J0182756/0	HEA Inspection	01/09/13	C
P0026315/0	Bi Monthly Safety Inspection	01/09/13	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0185690/0	Batteries x 3 replaced	02/10/13	C
P0026820/0	250hr service (Acco 2350G W/Cart)	20/10/13	C
J0187621/0	Repair water leak at tank hose	28/10/13	C
J0187956/0	Radiator cap leaking	31/10/13	C
J0187994/0	Beacon switch faulty	31/10/13	C
J0188385/0	HEA Inspection	01/11/13	C
P0027206/0	Bi Monthly Safety Inspection	01/11/13	C
J0189073/0	Rear beacon n/w	12/11/13	C
J0190200/0	HEA Inspection	01/12/13	C
J0191726/0	air conditioning not working	12/12/13	C
P0027800/0	1000hr service (Acco 2350G W/Cart)	19/12/13	C
J0193192/0	Horn not working	08/01/14	C
J0193194/0	Hydraulic tank sight glass leaking	08/01/14	C
J0194757/0	Tyres replaced pos 2,9,10 - Runouts	09/01/14	CA
J0194119/0	Tyres replaced pos 2/9/10	20/01/14	C
J0194126/0	Tyres replaced pos 1/2	20/01/14	C
J0194920/0	rotating beacon not working	29/01/14	C
J0195143/0	AGL site inspection	31/01/14	C
J0195161/0	Repair foot rest	31/01/14	C
J0194827/0	HEA Inspection	01/02/14	C
J0197232/0	Carry out Pre Inspection Report	22/02/14	C
J0197459/0	Horn n/w	22/02/14	C
J0197337/0	Driver side window winder u/s - New regulator required	24/02/14	C
J0198414/0	Tyres replaced pos 9,10	24/02/14	C
P0028658/0	250hr service (Acco 2350G W/Cart)	24/02/14	C
P0029031/0	Bi Monthly Safety Inspection	01/03/14	C
J0199239/0	Hazzard lights stuck on	14/03/14	C
J0199508/0	Cannon not going up and down	19/03/14	C
J0199570/0	Drivers window fallen down	20/03/14	C
J0200449/0	Repair drivers door trim	28/03/14	C
P0029517/0	500hr service (Acco 2350G W/Cart)	18/04/14	C
J0202391/0	rh front marker light not working	24/04/14	C
J0202392/0	horn not working	24/04/14	C
J0202597/0	Oil pressure guage fluctuating	28/04/14	C
P0029969/0	Bi Monthly Safety Inspection	01/05/14	C
J0203876/0	Engine light on , engine derating	12/05/14	C
J0203965/0	Engine warning light on	12/05/14	C
J0205217/0	Repair L/H headlight operation	26/05/14	C
J0205586/0	Speedo wont go over 40 kph	29/05/14	C
J0206072/0	LH BLINKER NOT WORKING	04/06/14	C
J0206073/0	cruise control not working	04/06/14	C
J0206074/0	dash lights not working	04/06/14	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0206497/0	Check and repair coolant leak	11/06/14	C
J0207164/0	lh blinker not working	17/06/14	C
J0207166/0	coolant sight glass broken	17/06/14	C
J0207551/0	Roof clearance lights not working	20/06/14	C
J0207940/0	wipers and washers not working	25/06/14	C
J0208426/0	Tyres replaced pos 7,8	25/06/14	C
J0208005/0	rear spray bar not working	26/06/14	C
P0030544/0	250hr service (Acco 2350G W/Cart)	26/06/14	C
J0209488/0	Tyre replaced pos 2	28/06/14	C
P0031144/0	Safety Inspection 2014/2015	01/07/14	C
J0209013/0	FCR inspection for steel river job	08/07/14	C
J0209734/0	RH headlight not working	14/07/14	C
J0210231/0	Air leaking from centre console	21/07/14	C
P0031356/0	Rego Renewal	02/08/14	C
J0213578/0	Carryout Rust repairs	26/08/14	C
P0031773/0	2000hr service (Acco 2350G W/Cart)	28/08/14	C
J0216265/0	Front beacon N/W	22/09/14	C
J0217579/0	Tension pos 3/4	08/10/14	C
J0217990/0	RHR spray N/W	13/10/14	C
J0218069/0	Steering not centring	14/10/14	C
J0218070/0	Replace steering column boot	14/10/14	C
J0218228/0	Steering uni-joints worn	15/10/14	C
J0218252/0	Rear basket rusted	15/10/14	C
J0218330/0	Tyres rotated pos 3 to 4, newtyre pos 3	16/10/14	C
J0218391/0	Adjust LHF spray	16/10/14	C
J0218392/0	Hydraulic leak at rear	16/10/14	C
J0218393/0	Tension wheels , POS 3 , 4	16/10/14	C
J0218997/0	RH window winder U/S	24/10/14	C
J0219020/0	Truck out of fuel Swansea	24/10/14	C
J0219312/0	Remove hydraulic pipes	27/10/14	C
J0219401/0	Front beacon not working	29/10/14	C
J0219638/0	Oil leaking from hydraulic tank	31/10/14	C
J0219639/0	Water leaking from main hose to pump	31/10/14	C
P0032786/0	250hr service (Acco 2350G W/Cart)	06/11/14	C
J0222145/0	Fit NHVAS label	28/11/14	C
J0222157/0	Reverse lights N/W	28/11/14	C
J0222451/0	Air leak	01/12/14	C
P0033529/0	500hr service (Acco 2350G W/Cart)	21/12/14	C
J0224294/0	Batteries flat	05/01/15	C
J0225201/0	Mt. Arthur inspection	14/01/15	C
J0225456/0	Replace various stickers	16/01/15	C
J0226459/0	Power steer oil leak	31/01/15	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0227150/0	Tighten air box bolts	06/02/15	C
J0227171/0	Rear uni-joint worn	09/02/15	C
J0228062/0	LHR spray valve U/S	17/02/15	C
P0034232/0	250hr service (Acco 2350G W/Cart)	23/02/15	C
J0228711/0	Water leaking from pump feed hose	25/02/15	CA
J0228960/0	Air regulator fitting broken	27/02/15	C
J0229022/0	Steering rod bent	02/03/15	C
J0229427/0	LHR spray n/w	05/03/15	C
J0229468/0	Water leaking main inlet hose	06/03/15	C
J0229628/0	Air leak at drier	06/03/15	C
J0229676/0	Fan belt U/S	09/03/15	C
J0229947/0	Hydraulic oil leak at tank	12/03/15	C
J0230379/0	I.D. numbers	18/03/15	C
J0230556/0	Tyres replaced pos 7 - runout	20/03/15	C
P0034877/0	Pressure vessel inspection	23/03/15	C
J0231294/0	Coolant loss	30/03/15	C
J0231599/0	Tyre puncture repair pos 7	01/04/15	C
J0232509/0	Engine overheated	15/04/15	C
J0232591/0	engine protect light staying on	15/04/15	C
J0232627/0	drivers window hard to wind up	15/04/15	C
J0232628/0	Speedo not working	16/04/15	C
P0035216/0	1000hr service (Acco 2350G W/Cart)	17/04/15	C
J0232763/0	Tyres - rotate pos 1/2 - balance	20/04/15	C
J0232803/0	Hose fitting replaced	20/04/15	C
J0233710/0	Supply I.D. numbers	04/05/15	C
J0234048/0	Horn replaced	07/05/15	C
J0234049/0	Reverse alarm N/W	07/05/15	C
J0234375/0	Main hose leaking at camlock	12/05/15	C
J0234691/0	Headlights adjusted	14/05/15	C
J0235461/0	Adjust headlights	26/05/15	C
J0236199/0	Cannon not going up and down	04/06/15	C
J0236200/0	Water pressure regulator replaced	04/06/15	C
J0237425/0	Tyres replaced pos 5/6 - runouts	22/06/15	C
J0237922/0	RHR toolbox lock bent	26/06/15	C
J0237923/0	RHR toolbox bracket bent	26/06/15	C
J0237924/0	RHF Guard bracket cracked	26/06/15	C
J0240460/0	Brake booster replaced	27/07/15	C
J0240461/0	Dash valve leaking	27/07/15	C
J0240692/0	Check and repair building up to much air	29/07/15	C
J0240853/0	Header tank sight glass	31/07/15	C
J0240854/0	Reflectors L/H replaced	31/07/15	C
P0036584/0	Rego Renewal	31/07/15	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
P0036648/0	250hr service (Acco 2350G W/Cart)	03/08/15	C
P0036702/0	Safety Inspection 2015/2016	05/08/15	C
J0242584/0	Spray L/H/R inop	21/08/15	C
J0243252/0	Water pump o/hailed	01/09/15	C
P0037185/0	500hr service	11/09/15	C
J0245241/0	Coolant leaks x3	25/09/15	C
J0245242/0	Water pump frame repair	25/09/15	C
J0245557/0	Radiator replaced	01/10/15	C
J0245622/0	A/C not working	01/10/15	C
J0246734/0	UHF wont transmitt	15/10/15	C
J0246841/0	Brake Test	16/10/15	C
P0038086/0	250hr service (Acco 2350G W/Cart)	20/11/15	C
J0250619/0	Cannon & RHR spray switches replaced	01/12/15	C
J0251157/0	Air leak inside chassis	07/12/15	C
J0254130/0	Tyres replaced - Pos 7,8,9,10	16/12/15	C
J0252050/0	Drivers door speaker cover fallen off.	17/12/15	C
J0252181/0	Drivers window runners lubricated	18/12/15	C
J0253227/0	Replace A/C condenser	12/01/16	C
J0253702/0	Cannon wont go Up/Down	19/01/16	C
J0255327/0	Engine drive belt replaced	10/02/16	C
J0256299/0	Alternator replaced	22/02/16	C
J0256378/0	Wont start @ coorangbong	22/02/16	C
P0039293/0	2000hr service (Acco 2350G W/Cart)	03/03/16	C
J0257638/0	Reverse camera wiring repaired	08/03/16	C
J0257639/0	a/c condensor fan wiring repaired	08/03/16	C
J0257640/0	Dash board fault	08/03/16	C
J0257641/0	check seat operation	08/03/16	C
J0258778/0	Tyres replaced - Pos 1,2	21/03/16	C
J0259894/0	Tyres replaced pos 7,8,9,10	30/03/16	C
J0259737/0	Mud flap steer missing R/H	05/04/16	C
J0259930/0	Reverse lights inop	07/04/16	C
J0260858/0	Replace A/C discharge hose	18/04/16	C
P0039874/0	250hr service (Acco 2350G W/Cart)	21/04/16	C
J0262135/0	Drivers window hard to wind up/down	04/05/16	C
J0262136/0	Speedo N/W	04/05/16	C
P0040333/0	500hr service (Acco 2350G W/Cart)	26/05/16	C
J0264137/0	PTO shaft unis worn	30/05/16	C
J0264113/0	Hydraulic pump input movement	31/05/16	C
J0266010/0	Batteries replaced	28/06/16	C
J0266474/0	Blinker stalk replaced	04/07/16	C
P0040896/0	Safety Inspection 201/2017	07/07/16	C
J0268008/0	Hose reel replaced	22/07/16	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0268009/0	Steer guard broken	22/07/16	C
J0268010/0	Headlight wiring repaired R/H	22/07/16	C
P0041126/0	Rego Renewal	22/07/16	C
J0268797/0	Window winder D/S replaced	03/08/16	C
J0268976/0	Brake booster hose replaced L/H 1st drive	04/08/16	C
J0269390/0	Water pressure gauge replaced	09/08/16	C
J0269441/0	A/C switch replaced	10/08/16	C
J0269482/0	Grease gun	10/08/16	C
J0269491/0	Engine leaking oil	10/08/16	C
J0269769/0	Header tank hoses replaced	12/08/16	C
J0269865/0	Cannon controls repaired	15/08/16	C
J0270321/0	Air bag L/H 1st drive replaced	19/08/16	C
P0041450/0	250hr service (Acco 2350G W/Cart)	19/08/16	C
J0272345/0	Window regulator replaced D/S	16/09/16	C
J0273142/0	UHF Mic replaced	28/09/16	C
J0274055/0	RH steer guard bracket rusted	12/10/16	C
P0042055/0	1000hr service (Acco 2350G W/Cart)	13/10/16	C
J0274195/0	Drive shocks U/S - Replace	14/10/16	C
J0276295/0	Service brake air leak	11/11/16	C
J0276955/0	Replace & sample Diff oil, (check for metal)	21/11/16	C
J0277047/0	Bake test	22/11/16	C
P0042641/0	250hr service (Acco 2350G W/Cart)	29/11/16	C
J0278120/0	Tyres replaced pos 3/4 - S/S 7192	06/12/16	C
J0278124/0	Tyres replaced pos 7/8 - S/S 7197	06/12/16	C
J0278136/0	Beacon replaced	06/12/16	C
J0278140/0	Engine oil leaks	06/12/16	C
J0278373/0	Air tank fitting siezed as per VRR	08/12/16	C
J0278463/0	Diesel leak @ injector pump	10/12/16	C
J0279484/0	RHF mudflap - Replace	03/01/17	C
J0279486/0	Check A/C operation - VRR	03/01/17	C
J0279488/0	Reverse camrea fitted	03/01/17	C
J0279525/0	Wont build up air	04/01/17	C
P0043052/0	500hr service (Acco 2350G W/Cart)	09/01/17	C
J0280612/0	Water leak from Tank	18/01/17	C
J0281739/0	Repair eng oil leak	03/02/17	C
J0282122/0	Stickers replaced	08/02/17	C
J0282252/0	A/C not getting cold	09/02/17	C
J0282279/0	LHF spray switch faulty	09/02/17	C
J0283002/0	Replace ball valves	20/02/17	C
J0283010/0	Rev lights and alarm inop	20/02/17	C
J0283018/0	RH blinker broken	20/02/17	C
J0283019/0	RH hubcap leaking oil	20/02/17	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0283020/0	replace ball valves on hose reel	20/02/17	C
J0283037/0	Tyres replaced pos 1/2/5/6 - S/S 7322	21/02/17	C
J0283261/0	Tyres replaced pos 9/10 - S/S 7327	23/02/17	C
J0283617/0	Replace engine stop button	27/02/17	C
J0283618/0	Replace hazard light switch	27/02/17	C
J0283803/0	Diesel leak	01/03/17	C
J0284076/0	Replace turbo timer	03/03/17	C
J0284205/0	pto cutting out	06/03/17	C
P0043897/0	250hr service (Acco 2350G W/Cart)	16/03/17	C
J0285408/0	RHF spray not working	21/03/17	C
J0286181/0	LHR Blinker n/w	30/03/17	C
J0286734/0	Repair RH cab step	06/04/17	C
J0286754/0	PTO cutting out	06/04/17	C
J0287512/0	Engine light staying on	19/04/17	C
P0044315/0	2000hr service (Acco 2350G W/Cart)	19/04/17	C
J0288610/0	Repair toolbox mounts	03/05/17	C
J0288731/0	RHR brake booster leaking	04/05/17	C
J0289628/0	Install park brake alarm system	16/05/17	C
J0290292/0	Engine oil leaks	24/05/17	C
J0290349/0	Horn sounding when brake applied in reverse	25/05/17	C
J0290604/0	Trans. extension housing seal leaking	30/05/17	C
J0291253/0	Hydraulic tank main hose worn	07/06/17	C
J0291931/0	Drivers seat belt stalk faulty	16/06/17	C
J0292559/0	LH steer mudflap u/s	23/06/17	C
J0292560/0	RHR clearance light n/w	23/06/17	C
P0045328/0	250hr service (Acco 2350G W/Cart)	04/07/17	C
P0045345/0	Safety Inspection 2017/2018	04/07/17	C
J0300199/0	Brakes grinding	26/07/17	C
P0045650/0	Rego Renewal	02/08/17	C
P0045878/0	500hr service (Acco 2350G W/Cart)	15/08/17	C
J0302145/0	Heater hose leaking	21/08/17	C
J0302146/0	Oil leaking from oil cooler area	21/08/17	C
J0302359/0	Headlight out L/H	22/08/17	C
J0302333/0	LHF front spray leaking	22/08/17	C
J0302334/0	Muffler fastener U/S	22/08/17	C
J0302979/0	Stickers replaced	29/08/17	C
J0303366/0	Replace tyres - Pos 7/8.S/S-8086	01/09/17	C
J0304230/0	1st drive pinion nut loose	14/09/17	C
J0305218/0	Out of fuel	27/09/17	C
J0306167/0	Batteries flat	10/10/17	C
J0306201/0	Repair clearance lights	11/10/17	C
J0306247/0	Drivers side window won't wind up	12/10/17	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0309271/0	Dribble bar leaking	22/11/17	C
J0309361/0	PTO inop	22/11/17	C
J0310158/0	Tyres replaced - Pos 3,4.S/S-9325	04/12/17	C
J0310982/0	Air leak - Area unknown	14/12/17	C
J0311344/0	Horn n/w	19/12/17	C
P0047432/0	250hr service (Acco 2350G W/Cart)	05/01/18	C
P0046563/0	750hr service (Acco 2350G W/Cart)	11/01/18	C
J0312681/0	Tyres replaced - Pos 1,2,9,10.S/S-8426	16/01/18	C
J0313685/0	Brake test 2018	29/01/18	C
J0313672/0	Brake valve bkt broken	30/01/18	C
J0314047/0	Park brake alarm system n/w	02/02/18	C
J0314490/0	Hose real ball valve U/S - Replace	07/02/18	C
J0314707/0	Water leak from under vehicle	07/02/18	C
J0316134/0	Wont't select gears	28/02/18	C
J0316304/0	Repair hose reel nozzle	02/03/18	C
J0316392/0	Supply battery for night work	02/03/18	C
P0048052/0	500hr service (Acco 2350G W/Cart)	09/03/18	C
J0318133/0	Air leaking from under spray control panel	27/03/18	C
P0046912/0	1000hr service (Acco 2350G W/Cart)	11/04/18	C
P0048436/0	250hr service (Acco 2350G W/Cart)	17/04/18	C
J0319812/0	Remove pump	23/04/18	C
J0319943/0	Repair front sprays	25/04/18	C
J0319963/0	Replace LHS window winder	26/04/18	C
J0320433/0	RHR switch on control panel sticking	02/05/18	C
J0321166/0	Rear sprays slow to turn off	11/05/18	C
J0321281/0	Tyres replaced -Pos 7,8.S/S-9703	14/05/18	C
J0322208/0	Coolant leaks	26/05/18	C
J0322722/0	LH headlight N/W	01/06/18	C
J0324289/0	Camlock fittings	26/06/18	C
J0324295/0	Hose fitting u/s	26/06/18	C
P0049075/0	2000hr service (Acco 2350G W/Cart)	28/06/18	C
S0000301/0	Safety Inspection 2018-2019	01/07/18	C
J0325937/0	Fabricate & install stand pipe bracket	20/07/18	C
J0326642/0	Hydraulic oil leak	30/07/18	C
J0328086/0	Replace Air Switch	20/08/18	C
J0328080/0	Replace LH steer mudguard	20/08/18	C
P0049669/0	250hr service (Acco 2350G W/Cart)	02/09/18	C
J0329452/0	Replace tank site tube	07/09/18	C
J0329997/0	Radiator hose leaking	17/09/18	C
J0329998/0	Windscreen washers N/W	17/09/18	C
J0330020/0	Rear beacon inop	17/09/18	C
J0330021/0	Drive airbags replaced	17/09/18	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0330679/0	Tank main hose U/S	26/09/18	C
J0331448/0	Replace 100mm camlock fitting	08/10/18	C
P0050550/0	500hr service (Acco 2350G W/Cart)	29/10/18	C
J0332934/0	Tyres replaced - Pos 5/6.S/S-11033	29/10/18	C
J0333212/0	Brake Test 2018	31/10/18	C
J0333876/0	Tie rod ends replaced	10/11/18	C
J0334123/0	AC not working,making squealing noise	14/11/18	C
J0334811/0	Fill hose lelaking	23/11/18	C
J0335663/0	Slack adjusters replaced,drive	06/12/18	C
J0335664/0	Booster replaced, L/H 2nd drive	06/12/18	C
J0335677/0	Diff bracket repaired	07/12/18	C
J0336391/0	Cannon N/W	17/12/18	C
J0336923/0	Reverse lights/alarm not working	02/01/19	C
J0336924/0	UHF microphone u/s	02/01/19	C
J0337056/0	Drivers steps replaced	04/01/19	C
P0051052/0	250hr service (Acco 2350G W/Cart)	05/01/19	C
J0337726/0	Z spring replaced R/H/R drive	15/01/19	C
J0337939/0	Air cond inop	18/01/19	C
J0338153/0	QR1 valve replaced	21/01/19	C
J0338413/0	Pre-Delivery Inspection for Maitland Hospital	24/01/19	C
J0339030/0	Recover bogged vehicle	02/02/19	C
J0338960/0	Drivers seat not locking in	04/02/19	C
J0339540/0	Replace RHR Male Cam Lock	11/02/19	C
J0341094/0	Repair leaking front water pipe	02/03/19	C
J0341095/0	Replace dives seat	02/03/19	C
P0051494/0	1000hr service (Acco 2350G W/Cart)	04/03/19	C
J0341965/0	RH middle clearance light not working	13/03/19	C
J0343161/0	King pins & wheel alignment	01/04/19	C
J0343780/0	Fit hydrant fill point decal	10/04/19	C
J0343916/0	Transmission temp gauge inop	10/04/19	C
J0343917/0	Hazard lights inop	10/04/19	C
J0343928/0	Replace rear tarp bungee	11/04/19	C
P0052454/0	250hr service (Acco 2350G W/Cart)	22/04/19	C
J0344953/0	Repair indicator lights	01/05/19	C
J0346016/0	Replace standpipe seal	16/05/19	C
J0346201/0	Electrical inspection	17/05/19	C
J0347282/0	Hazzard lights not working	03/06/19	C
J0347284/0	Dribble bar not working	03/06/19	C
J0347305/0	Engine running hot	04/06/19	C
J0347753/0	Hydraulic oil leak	12/06/19	C
P0053045/0	500hr service (Acco 2350G W/Cart)	01/07/19	C
S0000786/0	Safety Inspection 2019-2020	04/07/19	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0349684/0	Replace D/S window regulator	11/07/19	C
J0350325/0	Hose reel not retracting	19/07/19	C
J0350326/0	Tighten UHF ariel bracket	19/07/19	C
J0350538/0	Main feed hose leak	24/07/19	C
J0350963/0	Horn sounding when brakes released	30/07/19	C
J0351202/0	Cannon not working	01/08/19	C
J0351551/0	Remove window tint	07/08/19	C
J0352282/0	Rear spray fittings broken	19/08/19	C
J0353672/0	Weld repair body cracks	06/09/19	C
J0355393/0	Repair cab & chassis rust & paint	10/09/19	C
P0054663/0	250hr service (Acco 2350G W/Cart)	05/10/19	C
J0357766/0	Replace jackshaft uni joint	09/11/19	C
J0357772/0	Repair air leaks	09/11/19	C
J0357773/0	Fit fleet numbers	09/11/19	C
J0357865/0	Cab Lift Ram Leaking	11/11/19	C
J0357873/0	Check A/C	11/11/19	C
J0358810/0	Hydraulic Cab Lock Line Damaged	26/11/19	C
J0359474/0	Tyres replaced - Pos 7,8.S/S-11327	05/12/19	C
J0359585/0	LH 3rd Hub Seal Leaking	07/12/19	C
J0359669/0	Pressure Vessel Inspection	09/12/19	C
J0359670/0	Intro to Site(HVO)	09/12/19	C
J0359715/0	Fire Risk Assessment	10/12/19	C
J0359825/0	Supply & fit front tow pin	11/12/19	C
J0359950/0	PS Window Handle	12/12/19	C
J0359951/0	A/C Louvre Replace	12/12/19	C
J0359957/0	Beacons Not Working	13/12/19	C
J0360693/0	Tyres replaced - Pos 4.S/S-11418	06/01/20	C
J0360697/0	96741 - Air Bag Won't Raise	06/01/20	C
J0361182/0	Truck Ran Out Of Fuel	14/01/20	C
J0361357/0	96742 & 96743 - Replace Layflat Hose	15/01/20	C
J0361371/0	Tyres replaced - Pos 9,10.S/S-11426	15/01/20	C
J0361720/0	Brake Test 2020	22/01/20	C
J0361729/0	Tighten Steer U Bolts	22/01/20	C
J0361792/0	Replace battery isolator	22/01/20	C
J0361947/0	96742 - Ball Valve For Hose Reel	24/01/20	C
J0361948/0	96742 - UHF Aerial Hangs Out To Far From Side Of Cab	24/01/20	C
J0362808/0	Tape Cab Insulation	08/02/20	C
J0362857/0	96743 & 96746 - Air Con Not Cooling	10/02/20	C
J0363039/0	94673 - Tyres Replaced Pos 1,2.S/S-11517	12/02/20	C
J0363142/0	96744 - AC Fan Not Working	13/02/20	C
J0363143/0	UHF Radio Not Working	13/02/20	C
J0363335/0	96744 - Replace Split Main Water Hose	17/02/20	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0363812/0	96745 - Water Leak Under Tank	24/02/20	C
P0055253/0	2000hr Service (Acco 2350G W/Cart)	28/02/20	C
J0366094/0	Check Engine Low Power	30/03/20	C
J0367867/0	Replace R/H Reverse Light Beeper	27/04/20	C
J0367868/0	96747 - Install Switch For Reverse Camera	27/04/20	C
P0056232/0	250hr Service (Acco 2350G W/Cart)	28/04/20	C
J0368979/0	Fit I-Face	12/05/20	C
J0369781/0	Rebulid Rear Of Main Shaft	22/05/20	C
J0370546/0	96748 - Heater Not Working	02/06/20	C
J0371539/0	Resecure Fuel Line Clamps	19/06/20	C
S0001059/0	Safety Inspection 2020-2021	01/07/20	C
J0372546/0	Replace tank sight tube	06/07/20	C
J0372783/0	Key Not Working In Ign Barrel	09/07/20	C
P0057164/0	500hr Service (Acco 2350G W/Cart)	15/07/20	C
J0373361/0	Coolant Leaks From Filter Housing And Compressor Fitting	20/07/20	C
J0373367/0	Windscreen Washers Not Working	20/07/20	C
J0373368/0	Engine Protection Light Staying On	20/07/20	C
J0373490/0	Replace Batteries	22/07/20	C
J0374997/0	RH 1st Drive Slack Adj	14/08/20	C
J0375444/0	96750 - Water Cannon Had No Pressure	21/08/20	C
J0376779/0	LH Steer Shackle Won't Take Grease	09/09/20	C
J0377424/0	Pump leaking water	18/09/20	C
J0377425/0	Drivers Seatbelt Won't Retract	18/09/20	C
P0057909/0	250hr service (Acco 2350G W/Cart)	22/09/20	C
J0378547/0	Drive spring wear pads	09/10/20	C
J0379637/0	Brake Test 2020	27/10/20	C
J0380191/0	Replace layflat hoses	05/11/20	C
P0058599/0	1000hr service (Acco 2350G W/Cart)	01/12/20	C
J0381848/0	94677 - Repair Hose Reel	03/12/20	C
J0381849/0	96477 - RH Front Spray Inop	03/12/20	C
J0381930/0	Replace leaking radiator	04/12/20	C
J0382105/0	Overhaul PTO shaft	07/12/20	C
J0382925/0	Replace hyd & fuel hoses	22/12/20	C
J0383235/0	Reseal hydraulic oil leak	08/01/21	C
J0384336/0	Spray control panel air leaks	28/01/21	C
J0384488/0	Transmission shift not working correctly	01/02/21	C
J0384742/0	Replace engine thermostat	04/02/21	C
J0385367/0	Replace air compressor	15/02/21	C
P0059382/0	250hr service (Acco 2350G W/Cart)	27/02/21	C
J0387410/0	Engine protection light on	15/03/21	C
J0387231/0	Replace damaged tyre	17/03/21	C
J0387369/0	Power steering oil contaminated	19/03/21	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0387370/0	Fuel filter housing repaired	19/03/21	C
J0387411/0	Check engine misfire	19/03/21	C
J0388409/0	No start	09/04/21	C
J0389720/0	Steer spring replaced LH	30/04/21	C
J0390419/0	Air leak foot brake applied	13/05/21	C
S0001441/0	Safety Inspection 2021-2022	01/07/21	C
J0395601/0	Replace hydraulic vane pump	11/08/21	C
P0063312/0	NHVR Annual Heavy Vehicle Inspection	01/09/21	C
J0400376/0	Engine warning light on	08/11/21	C
J0400467/0	Repair list of defects	09/11/21	C
J0401681/0	Water leak at hose fitting under pump	02/12/21	C
J0401682/0	Control panel top loose	02/12/21	C
J0401683/0	Change beacon light	02/12/21	C
J0402706/0	Water pump replaced (Engine)	21/12/21	C
J0402977/0	Fit tank capacity decals	05/01/22	C
P0062329/0	500hr service (Acco 2350G W/Cart)	05/02/22	C
J0407232/0	96478 - LH Wiper Arm	28/03/22	C
J0407233/0	Air tank bent into tailshaft	28/03/22	C
J0407268/0	Tyres replaced - Pos 5,6,7,8.S/S-14609	29/03/22	C
J0407279/0	Horn not working	29/03/22	C
J0407280/0	Radiator Leaking	29/03/22	C
J0407291/0	Timing case cover leak	29/03/22	C
J0407292/0	Inspect front exhaust bolts	29/03/22	C
P0063309/0	250hr service (2350G)	03/05/22	C
J0410107/0	Replace PTO switch leaking	25/05/22	C
J0410116/0	Water pump side hydraulic hose	25/05/22	C
J0411818/0	RH clearance light wiring	28/06/22	C
J0411829/0	Replace leaking radiator	29/06/22	C
S0001732/0	Safety Inspection 2022-2023	01/07/22	C
P0064727/0	2000hr service (2350G)	08/09/22	C
J0419255/0	Replace horn assembly	10/11/22	C
J0419356/0	Replace pump coupling	11/11/22	C
P0065527/0	250hr service (2350G)	14/11/22	C
J0419932/0	Repair hydraulic oil leak	22/11/22	C
J0420757/0	Repair horn not working	07/12/22	C
J0420775/0	Overhual water pump	08/12/22	C
P0065982/0	Yearly Pressure Vessel Inspection	08/12/22	C
J0421356/0	Replace oil filler cap	19/12/22	C
P0065937/0	500hr service (2350G)	30/12/22	C
J0422182/0	Replace header tank cap	12/01/23	C
J0422384/0	Tyres replaced - Pos 9,10.-15308	17/01/23	C
P0067047/0	1000hr service (2350G)	23/01/23	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0422925/0	Replace front beacon	25/01/23	C
J0422926/0	Repair horn wiring fault	25/01/23	C
J0422927/0	Replace clearance light	25/01/23	C
J0423743/0	Repair A/C compressor bolts	10/02/23	C
J0425413/0	LHR marker & indicator lights	09/03/23	C
J0426514/0	Replace battery isolator	28/03/23	C
P0067049/0	NHVR Annual Heavy Vehicle Inspection	29/03/23	C
J0426601/0	Repair horn contacts	29/03/23	C
J0426604/0	Engine light staying on	29/03/23	C
J0426606/0	Re route battery cables	29/03/23	C
J0427587/0	Replace belts & tensioner	20/04/23	C
J0427606/0	Replace compressor pipe	20/04/23	C
J0427613/0	Replace RHR spray switch	20/04/23	C
J0427855/0	Replace beacons & switch	27/04/23	C
J0428162/0	Replace compressor hose	03/05/23	C
P0067612/0	250hr service (2350G)	13/05/23	C
S0002059/0	Safety Inspection 2023-2024	01/07/23	C
P0068242/0	500hr service (2350G)	02/07/23	C
J0433562/0	Replace RHR spray valve	14/08/23	C
J0433563/0	Drivers window wont go up	14/08/23	C
J0434774/0	Replace LHR drive spring	05/09/23	C
J0434775/0	Drivers mirror mount loose	05/09/23	C
J0434742/0	Water pump low pressure	05/09/23	C
J0434743/0	Variable control knob broken	05/09/23	C
J0437122/0	3 x hoses rubbing on chasis	18/10/23	C
J0437123/0	LHR retention + tags	18/10/23	C
J0437124/0	Clean front hub oil caps	18/10/23	C
J0439920/0	Rear beacon not spinning	08/12/23	C
J0440786/0	Replace layflat hose 2IN	02/01/24	C
J0440693/0	Replace PTO toggle switch	02/01/24	C
P0069773/0	750hr service (2350G)	05/01/24	C
J0440877/0	LH steer brake hose leak	05/01/24	C
J0440923/0	Transmission dipstick leak	08/01/24	C
J0440987/0	Replace cab blower fan	09/01/24	C
J0441884/0	A/C not getting cold	25/01/24	C
J0442430/0	112576 - Cannon nozzle	05/02/24	C
J0442431/0	112576 - Clean out sprays	05/02/24	C
J0442432/0	112576 - New hose reel	05/02/24	C
J0442433/0	112576 - Adjust sprays	05/02/24	C
J0442434/0	112576 - Water level hose	05/02/24	C
J0442435/0	112576 - Windscreen washer	05/02/24	C
J0442436/0	112577 - UHF antenna	05/02/24	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0442437/0	112577 - A/C going hot	05/02/24	C
J0442438/0	112577 - Horn not working	05/02/24	C
J0442439/0	112577 - Cannon switch	05/02/24	C
J0442440/0	112577 - Exhaust leaking	05/02/24	C
J0442443/0	Reverse lights and alarm	05/02/24	C
J0443916/0	Replace UHF microphone	28/02/24	C
J0443970/0	Dribble bar blocked	28/02/24	C
J0443971/0	Washer jet blocked	28/02/24	C
J0445032/0	112578 - Fan belt noisy	18/03/24	C
J0445570/0	Replace differential plugs	27/03/24	C
J0445830/0	Install Navman TN360	04/04/24	C
J0447544/0	Won't build up air	06/05/24	C
P0070730/0	2000hr service (2350G)	10/06/24	C
J0449545/0	Replace batteries (3)	11/06/24	C
P0071908/0	NHVR Annual Heavy Vehicle Inspection	02/07/24	C
S0002390/0	Safety Inspection 2024-2025	05/07/24	C
J0452728/0	Repair water hose reel	06/08/24	C
J0452729/0	RH 2nd Axle brake booster	06/08/24	C
J0452783/0	Tyre runout on - Pos 2.-16660	07/08/24	C
J0456093/0	Water cannon low pressure	09/10/24	C
J0456094/0	Repair horn not working	09/10/24	C
J0457668/0	Hyd pump input shaft loose	07/11/24	C
J0458202/0	Fit UHF extension speaker	18/11/24	C
J0458233/0	Reseal ejector valve kit	19/11/24	C
J0459912/0	Compressor check valve	17/12/24	C
P0074011/0	Biennial Pressure Vessel Inspection	07/01/25	C
J0460508/0	Check for engine number	08/01/25	C
J0460644/0	Check low water pressure	10/01/25	C
J0460645/0	RHF water spray leaking	10/01/25	C
J0461172/0	Replace battery isolator	21/01/25	C
J0461179/0	Tighten loose shock bolt	21/01/25	C
J0461180/0	Rego plate & safety decals	21/01/25	C
J0461262/0	Replace amber beacon	22/01/25	C
J0464434/0	Tyres runout on - Pos 3.-79827	18/03/25	C
J0464980/0	Cannon slew motor	27/03/25	C
J0466630/0	Check for air hose leak	29/04/25	R
J0466631/0	Water sight glass hose	29/04/25	R
J0466632/0	Drivers door lock barrel	29/04/25	R
J0466764/0	Decommission Truck	30/04/25	R
S0002719/0	Safety Inspection 2025-2026	04/07/25	N

Status Codes
N - New
A - Active
P - Pending
C - Completed