

Maintenance History Report

Report Generated on 21/10/25 08:07 AM

2258 Volvo FM480 6x4 Tipper Alloy

Job No	Job Title	Start Date	Status
J0089909/0	Prepare for operations	27/10/10	C
J0090110/0	Cut spare keys	03/11/10	C
J0090192/0	fit cb radio	04/11/10	C
J0090594/0	Replace tyres Pos 3/4/5/6/7/8/9/10	09/11/10	C
J0090714/0	UHF not transmitting	10/11/10	C
J0090724/0	Bi monthly wash Nov/Dec	10/11/10	C
J0091002/0	Hydraulic filter loose	11/11/10	C
J0091016/0	Tarps not working	12/11/10	C
J0091256/0	Fit GPS tracker	17/11/10	C
J0091264/0	Engine won't start	17/11/10	C
P0008816/0	Bi Monthly Truck Wash Nov/Dec	17/11/10	C
J0092075/0	AM CB replaced	29/11/10	C
J0092333/0	Pre - start inspection	29/11/10	C
J0092371/0	Relocate switches	01/12/10	C
J0092639/0	Check phone and UHF operation	03/12/10	C
J0091248/0	1st Service at Volvo	06/12/10	C
J0092765/0	Sub frame bolts check and tighten	08/12/10	C
J0093589/0	CB Radio picking up interference	16/12/10	C
J0094339/0	Bi Monthly Truck Washing	01/01/11	C
P0009127/0	500hr Service (FM480)	01/01/11	C
P0009289/0	Bi Monthly Grease & Inspection	01/01/11	C
J0094841/0	Fit nokia phone kit	07/01/11	C
J0094869/0	Hydraulic filter loose	07/01/11	C
J0094889/0	Check CB operation	07/01/11	C
J0094890/0	LH indicator U/S	07/01/11	C
J0095472/0	AM Cb aerial U/S	15/01/11	C
J0096398/0	HEA Inspection	25/01/11	C
J0097485/0	AD Blue For Truck	11/02/11	C
J0097632/0	Fit dual pole isolator	11/02/11	C
J0097954/0	Fit TX3600 radio	16/02/11	C
J0098595/0	HEA Inspection - Feb	23/02/11	C
J0099101/0	Bi Monthly Truck Washing	01/03/11	C
P0010230/0	Bi Monthly Grease & Inspection	01/03/11	C
J0099393/0	Replace dipstick	03/03/11	C
P0010134/0	1000hr Service (FM480)	07/03/11	C
J0099969/0	Replace tyres Pos 1/2	08/03/11	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0099797/0	Fit phone aerial	11/03/11	C
J0100153/0	HEA Inspection - MAR	15/03/11	C
J0100762/0	Hydraulic filter failure	22/03/11	C
J0103108/0	AdBlue for truck	30/03/11	C
J0101966/0	Retension drive tyres	07/04/11	C
J0102568/0	Repair flat tyre	07/04/11	C
J0102046/0	Check Tipping Light Operation & Fit Buzzer	09/04/11	C
J0103012/0	Repair LHF blinker N/W	20/04/11	C
J0103163/0	Fit bin up light and buzzer	27/04/11	C
J0103426/0	Bi Monthly Truck Washing	01/05/11	C
P0011172/0	Bi Monthly Grease & Inspection	01/05/11	C
P0010994/0	1500hr Service (FM480)	06/05/11	C
J0103939/0	Replace phone hands free holder	09/05/11	C
J0103964/0	HEA Inspections May 2011	09/05/11	C
J0103994/0	AM/FM radio not working	09/05/11	C
J0104127/0	Replace tyres Pos 7	09/05/11	C
J0104628/0	Replace tyres Pos 7	10/05/11	C
J0105760/0	Blinkers on both sides of cab not working (outer Blinkers)	30/05/11	C
J0106139/0	AD BLUE FOR TRUCK	04/06/11	C
J0106382/0	HEA Inspection June 2011	07/06/11	C
J0108492/0	Bi Monthly Truck Washing	01/07/11	C
P0012185/0	Bi Monthly Grease & Inspection	01/07/11	C
P0011908/0	2000hr Servie (FM480)	03/07/11	C
J0109149/0	ABS Light On	08/07/11	C
J0109535/0	Fit Phone Aerial	13/07/11	C
J0109536/0	Repair Dash Rattle	13/07/11	C
J0109772/0	HEA Inspection - AUG 11	18/07/11	C
J0110070/0	Fit Drivers Weathershield	20/07/11	C
J0110674/0	Sump Cracked & Leaking	26/07/11	C
J0110777/0	Repair Number Plate Bracket	27/07/11	C
J0111280/0	Reverse light replaced	29/07/11	C
J0113010/0	Replace tyres pos 7,8,9,10 s/sheet 1836	04/08/11	C
J0112030/0	Replace Drive Tyres	10/08/11	C
J0112616/0	AD Blue For Truck	17/08/11	C
J0113416/0	Pre delivery Inspection	24/08/11	C
J0113483/0	LH headlight needs a new globe	25/08/11	C
J0114218/0	Bi Monthly Truck Washing	01/09/11	C
J0114219/0	HEA Inspection	01/09/11	C
P0013266/0	Bi Monthly Grease & Inspection	01/09/11	C
J0114700/0	Truck Wont Start	06/09/11	C
J0114928/0	Number plate light U/S	06/09/11	C
P0012997/0	500hr Service (FM480)	06/09/11	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0115197/0	Fit reverse quacker	12/09/11	C
J0115361/0	#2258 bolt on spares pos 1 - Valley s/sheet 1936	12/09/11	C
J0115533/0	Replace LH Door Sticker	15/09/11	C
J0117228/0	Check and repair exhaust leak	22/09/11	C
J0116972/0	HEA Inspection	01/10/11	C
J0117242/0	AM CB Aerial u/s	06/10/11	C
J0117371/0	Scales not working	07/10/11	C
J0117841/0	fit hubcaps	13/10/11	C
J0118274/0	Tyres replaced pos3,4,5,6,7,8,9 & 10	18/10/11	C
J0118290/0	#2258 replace tyres pos 3,4,5,6,7,8,9,10 del.doc. 186946 - Mara	18/10/11	C
J0119274/0	Left side mirror loose	18/10/11	C
J0119521/0	Phone kit changed over for Tuff phone	28/10/11	C
P0014044/0	Rego Renewal	31/10/11	C
J0119666/0	Bi Monthly Truck Washing	01/11/11	C
J0119711/0	HEA Inspection	01/11/11	C
P0014210/0	Bi Monthly Grease & Inspection	01/11/11	C
J0120043/0	Hydraulic valve bank mount U/S	02/11/11	C
P0014043/0	1000hr Service (FM480)	04/11/11	C
J0120723/0	AM cb not working	10/11/11	C
J0121340/0	Hydraulic oil leak at coupling	14/11/11	C
J0121300/0	Daracon door stickers replaced	17/11/11	C
J0121646/0	SOS Investigation - Change rear diff oil	23/11/11	C
J0121747/0	Replace tyres Pos 1/2	23/11/11	C
J0122242/0	Scales not working	28/11/11	C
J0122466/0	RH indicator globe U/S	01/12/11	C
J0123425/0	AdBlue for Truck	09/12/11	C
J0123903/0	HEA Inspection	01/01/12	C
J0125195/0	Bi Monthly Truck Washing	01/01/12	C
P0015314/0	Bi Monthly Grease & Inspection	01/01/12	C
J0125281/0	Jump start	03/01/12	C
P0015145/0	3500hr Service (FM480)	03/01/12	C
J0126573/0	Replace windscreen washer lid	16/01/12	C
J0127573/0	Drive reline x 4	23/01/12	C
J0130681/0	Drivers seat replaced	23/01/12	C
J0128762/0	HEA Inspection	01/02/12	C
J0128571/0	Shovel handle broken	02/02/12	C
J0130214/0	RH headlight lense broken	16/02/12	C
J0131349/0	Inspect steering shaft unis	28/02/12	C
J0131227/0	HEA Inspection	01/03/12	C
J0131564/0	Bi Monthly Truck Washing	01/03/12	C
P0016301/0	Bi Monthly Grease & Inspection	01/03/12	C
J0132770/0	Inspect AM radio operation	13/03/12	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
P0016192/0	2000hr Servie (FM480)	13/03/12	C
J0133988/0	Fit tyre to pos 19/20	26/03/12	C
J0134556/0	Fit hubcaps	28/03/12	C
J0134181/0	HEA Inspection	01/04/12	C
J0135105/0	RH luggage compartment door closing	03/04/12	C
J0135600/0	Reset Air Dryer	05/04/12	C
J0135594/0	Replace mudflaps	10/04/12	C
J0135631/0	RHF blinker not working	10/04/12	C
J0136342/0	Overhead console cover not fitting correctly	17/04/12	C
J0136372/0	Replace wiper blades	17/04/12	C
J0137097/0	RHF indicator U/S	26/04/12	C
J0137830/0	Bi Monthly Truck Washing	01/05/12	C
P0017380/0	Bi Monthly Grease & Inspection	01/05/12	C
J0138284/0	Repair to pos 10	08/05/12	C
P0017667/0	500hr Service (FM480)	08/05/12	C
J0138845/0	Tension drive wheels	11/05/12	C
J0139233/0	Adjust tarps	15/05/12	C
J0139803/0	Reair bent tailgate	21/05/12	C
J0140398/0	Replace wiper blades	25/05/12	C
J0140650/0	Repair number plate light bracket	28/05/12	C
J0142052/0	Tension wheel nuts pos 1	08/06/12	C
J0142832/0	Replace tyres Pos 1	19/06/12	C
J0143148/0	Replace tyre Pos 1/2	22/06/12	C
J0143416/0	exhaust flex leaking	25/06/12	C
J0143780/0	Inspect AM CB Squealing	28/06/12	C
P0018448/0	1000hr Service (FM480)	28/06/12	C
J0144053/0	Bi Monthly Truck Washing	01/07/12	C
P0018601/0	Bi Monthly Grease & Inspection	01/07/12	C
J0144189/0	Replace tyres Pos 7/8/9/10	03/07/12	C
J0144209/0	HEA Inspection	03/07/12	C
J0144953/0	Install ext speaker	09/07/12	C
J0145360/0	Tension 2nd axle wheels	12/07/12	C
J0146024/0	Replace tyres Pos 3/4/5/6	19/07/12	C
J0146127/0	KEP Inspection	19/07/12	C
J0148222/0	HEA Inspection	01/08/12	C
J0148504/0	Adjust tarp	10/08/12	C
J0148762/0	Tarp not working	13/08/12	C
J0149216/0	Replace wiper blades	17/08/12	C
J0149289/0	Tarp not working	18/08/12	C
J0150188/0	Truck not starting	20/08/12	C
J0149512/0	Check horton operation	21/08/12	C
P0019527/0	500hr Service (FM480)	24/08/12	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0150136/0	Replace batteries	27/08/12	C
J0150147/0	Reline steer brakes	27/08/12	C
J0150149/0	Straighton L/H/Rear tail light bracket	27/08/12	C
J0150150/0	Repair noise in drivers seat	27/08/12	C
J0150151/0	Number plate light out,repair	27/08/12	C
J0150570/0	Sway bar links worn	30/08/12	C
J0150738/0	Bi Monthly Truck Washing	01/09/12	C
J0152627/0	HEA Inspection	01/09/12	C
P0019748/0	Bi Monthly Grease & Inspection	01/09/12	C
J0153026/0	Tyre repaired pos 3	19/09/12	C
J0153490/0	Check CB operation	27/09/12	C
J0151137/0	Modify tailgate handle	28/09/12	C
J0153751/0	Adjust tarp ropes	02/10/12	C
J0153891/0	AM CB radio faulty	03/10/12	C
J0154616/0	Low oil pressure warning on	11/10/12	C
J0154880/0	Ad Blue	15/10/12	C
J0154905/0	Fit rego labels	15/10/12	C
J0155769/0	Weight scales n ot working	23/10/12	C
J0156057/0	Hub caps,replaced	26/10/12	C
P0020442/0	2000hr Servie (FM480)	26/10/12	C
J0156300/0	Tyre flat/ L/H/L outer drive flat	29/10/12	C
J0156518/0	Tyre repair pos 7	31/10/12	C
P0020629/0	Rego Renewal	31/10/12	C
J0156550/0	Bi Monthly Truck Washing	01/11/12	C
P0020926/0	Bi Monthly Grease & Inspection	01/11/12	C
J0158180/0	replace rh rear mudflap	16/11/12	C
J0159102/0	Hydraulic tank leaking	26/11/12	C
J0159475/0	rh headlight not working	29/11/12	C
J0160653/0	Door stickers,replaced	11/12/12	C
J0161354/0	Retension wheels	18/12/12	C
J0161628/0	Reprogram mines radio	20/12/12	C
J0161928/0	Bi Monthly Truck Washing	01/01/13	C
P0022064/0	Bi Monthly Grease & Inspection	01/01/13	C
P0021773/0	500hr Service (FM480)	04/01/13	C
J0162976/0	Tyres replaced pos 7,8,8,10	14/01/13	C
J0163164/0	Tarp inop	15/01/13	C
J0163493/0	Replace floor mats	18/01/13	C
J0164388/0	Engine not starting	29/01/13	C
J0164389/0	Cab leaking water	29/01/13	C
J0165095/0	rh park light not working	05/02/13	C
J0165259/0	Tyres replaced pos 11/12	07/02/13	C
J0165431/0	uhf radio not working	08/02/13	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0165958/0	mines radio not working properly	13/02/13	C
J0166115/0	Tension steer tyres	14/02/13	C
J0166733/0	Seat inspection and repair	21/02/13	C
J0167197/0	Tyres replaced pos 1/2	26/02/13	C
J0167374/0	Air dryer U/S , Replace	28/02/13	C
J0166548/0	HEA Inspection	01/03/13	C
J0167539/0	Bi Monthly Truck Washing	01/03/13	C
P0023055/0	Bi Monthly Grease & Inspection	01/03/13	C
P0023159/0	1000hr Service (FM480)	14/03/13	C
J0169641/0	Brake system fault	23/03/13	C
J0169992/0	Replace leaking fuel cap	26/03/13	C
J0171280/0	Tyre replaced pos 3,4,5,6	27/03/13	C
J0169947/0	HEA Inspection	01/04/13	C
J0170710/0	Replace wiper blades	04/04/13	C
J0170999/0	Flashing light inop	08/04/13	C
J0171969/0	Retension drive axle wheels	17/04/13	C
J0172281/0	Tyres replaced pos 7/8/9/10	22/04/13	C
J0172373/0	Seat inspection and repairs	22/04/13	C
J0172389/0	uhf aerial broken	22/04/13	C
J0172390/0	rh headlighy not working	22/04/13	C
J0172392/0	reverse lights not working	22/04/13	C
J0172686/0	Tarp cable,adjust	26/04/13	C
J0172795/0	Transmission fault	29/04/13	C
P0024294/0	Bi Monthly Grease & Inspection	01/05/13	C
J0173202/0	Repace ad blue lid	02/05/13	C
J0173762/0	am cb radio wont transmit	08/05/13	C
J0174813/0	Roof console fallen down	20/05/13	C
J0174857/0	Tension wheels	20/05/13	C
J0174994/0	Brakes,drive,replaced	22/05/13	C
P0024145/0	500hr Service (FM500 EURO 4&5)	22/05/13	C
P0024146/0	Belt tensioners & Belts (FM13 Volvo Trucks only)	22/05/13	C
J0176828/0	Auto graser plug connection	13/06/13	C
J0177494/0	Repair R/H/Front blinker operation	24/06/13	C
J0177545/0	Ad Blue	25/06/13	C
J0177940/0	Tyres replaced pos 1/2	28/06/13	C
J0177596/0	HEA Inspection	01/07/13	C
P0025309/0	Bi Monthly Safety Inspection	01/07/13	C
J0178330/0	Tarp n/w	03/07/13	C
J0178457/0	Hoist not going up	04/07/13	C
J0178458/0	Mudflaps missing	04/07/13	C
J0178697/0	Wash truck	08/07/13	C
J0178931/0	Replace mudflap	11/07/13	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0179356/0	Beacon not working	17/07/13	C
J0181564/0	HEA Inspection	01/08/13	C
P0025524/0	2000hr Service (FM500 EURO 5)	02/08/13	C
J0182153/0	Tyres replaced pos 3,4,5,6	14/08/13	C
J0181814/0	Tension frt drive wheels	15/08/13	C
J0182094/0	lh headlight not working	19/08/13	C
J0182767/0	HEA Inspection	01/09/13	C
P0026340/0	Bi Monthly Safety Inspection	01/09/13	C
J0183501/0	R/H headlight not working	04/09/13	C
J0183503/0	Wiindscreen washers not working	04/09/13	C
J0183504/0	Windscreen washers	04/09/13	C
P0026682/0	500hr Service - (FM500 EURO4)	07/10/13	C
J0186040/0	Tarp rope L/H replaced	10/10/13	C
J0186069/0	scales not reading correctly	10/10/13	C
J0186148/0	Replace steer mudguard and flap L/H	11/10/13	C
J0186149/0	Refit R/H spray supresant	11/10/13	C
J0186618/0	Tarp circuit breaker tripping	17/10/13	C
J0186651/0	Replace R/H tarp cable	17/10/13	C
J0186743/0	LH spotter mirror loose	18/10/13	C
J0186996/0	Tyres replaced pos 1/2	22/10/13	C
J0187299/0	lh front blinker keeps blowing globes	24/10/13	C
J0187305/0	Replace body rivet	24/10/13	C
P0026929/0	Rego Renewal	28/10/13	C
P0027230/0	Bi Monthly Safety Inspection	01/11/13	C
J0188287/0	Hydraulic coupling leaking	04/11/13	C
J0188931/0	ABS light on	11/11/13	C
J0189003/0	Water leaking into cab	11/11/13	C
J0189209/0	phone kit not working	13/11/13	C
J0189403/0	Tension wheels pos 7,8,9,10	15/11/13	C
J0189832/0	Install Navman GPS	20/11/13	C
J0190317/0	Tyres replaced pos 7/8/9/10	28/11/13	C
J0191499/0	Wash truck	10/12/13	C
P0027599/0	1000hr Service - (FM500 EURO4)	11/12/13	C
P0027600/0	Turbo Replacement (FM13 and FH13 SCR)	11/12/13	C
J0192028/0	lh cab marker light not working	16/12/13	C
J0192342/0	HEA Inspection	19/12/13	C
J0192364/0	R/H blinker inop	19/12/13	C
J0192658/0	Repair hydraulic hoses	03/01/14	C
J0192889/0	Tyres replaced pos 21	06/01/14	C
J0194189/0	Repair washer operation	20/01/14	C
J0195218/0	Batteries u/s - replaced	01/02/14	C
J0195563/0	HEA Inspection	01/02/14	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0195514/0	Tension L/H/Midle wheel	04/02/14	C
J0195975/0	Tyre replaced pos 1 - runout	04/02/14	C
J0195647/0	ABS light on	05/02/14	C
J0196239/0	remove old phone kit.install cc9048 kit	11/02/14	C
J0196513/0	Ring feeder pin worn	14/02/14	C
J0196959/0	Oil cooler leaking	19/02/14	C
J0196963/0	Oil pressure switches leaking	19/02/14	C
J0197418/0	Repair grain shoot handle	24/02/14	C
J0198438/0	Tyres replaced pos 3,4,5,6	27/02/14	C
P0029059/0	Bi Monthly Safety Inspection	01/03/14	C
J0199743/0	Tyres replaced pos 1,2	11/03/14	C
J0198931/0	Retension wheels	12/03/14	CA
J0198994/0	Replace ID numbers	13/03/14	C
P0028947/0	2400hr Service - (FM500 EURO 4)	13/03/14	C
J0199711/0	No ignition sometimes	19/03/14	C
J0199821/0	batteries going flat	19/03/14	C
J0199766/0	Check for losing acceleration	21/03/14	C
J0200337/0	replace dog tarp controller	27/03/14	C
J0200686/0	Inspect reverse lights and buzzer	01/04/14	C
J0200739/0	reverse lights not working	01/04/14	C
J0201267/0	replace wiper blades	08/04/14	C
J0201567/0	Water pump leaking	10/04/14	C
J0202387/0	replace power steering pump	24/04/14	C
J0202572/0	scales not working	28/04/14	C
J0202834/0	Air dryer u/s	30/04/14	C
J0203045/0	Washer bottle leaking	01/05/14	C
P0029998/0	Bi Monthly Safety Inspection	01/05/14	C
J0203189/0	Oil pressure warning light on	05/05/14	C
J0203204/0	54231 - Oil pressure light coming on	05/05/14	C
J0204360/0	Tyres replaced pos 7,8,9,10	09/05/14	C
J0204559/0	engine emission light flashing	19/05/14	C
J0204795/0	Repair loose exhaust flange	21/05/14	C
J0204796/0	Repair batteries going flat .	21/05/14	C
J0204927/0	Replace R/HRear mud flap	22/05/14	C
J0205055/0	Wont select drive	23/05/14	C
J0207418/0	Tyres - Deflated dual wheels to remove jammed rocks	28/05/14	C
P0030287/0	600hr Service - (FM500 EURO4)	03/06/14	C
J0206414/0	phone speaker broken	10/06/14	C
J0207042/0	Wash truck	16/06/14	C
J0207162/0	check engine light coming on	17/06/14	C
J0207369/0	Phone not charging	19/06/14	C
J0207672/0	fit new phone cradle and pair in phone	23/06/14	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0207747/0	resecure weight gauge	24/06/14	C
J0207748/0	replace nox sensor and add blue filter	24/06/14	C
J0207911/0	engine light on	25/06/14	C
P0031173/0	Safety Inspection 2014/2015	01/07/14	C
J0208662/0	Hoist control lever broken	03/07/14	C
J0209036/0	no phone reception	08/07/14	C
J0210679/0	Tyre replaced pos 1,2	15/07/14	C
J0209929/0	air conditioning noot working	16/07/14	C
J0209958/0	AC not working	17/07/14	C
J0209998/0	Weld up draw bar leg	17/07/14	CA
J0211066/0	lh blinker not working	29/07/14	C
J0211226/0	Replace marker plates	31/07/14	C
J0211900/0	LH shackle bushes worn	06/08/14	C
J0212557/0	interior light not working	14/08/14	C
J0212638/0	Kit hydraulic coupling	15/08/14	C
J0212655/0	replace tarp controller for dog tarp	15/08/14	C
J0212658/0	repair drawbar	15/08/14	C
J0212805/0	replace tarp circuit breakers	18/08/14	C
J0212909/0	Tailgate handle worn	19/08/14	C
P0031981/0	1200hr Service - (FM500 EURO4)	27/08/14	C
J0214600/0	Left headlight n/w - globe	06/09/14	C
J0214727/0	Beacon n/w	08/09/14	C
J0214728/0	Phone kit n/w	08/09/14	C
J0216633/0	tailgate slow to unlock	25/09/14	C
J0216970/0	Steer brakes low	30/09/14	C
J0218337/0	Tyres flipped on the rim pos 1,2	30/09/14	C
J0217205/0	Balance wheels Pos 1 + 2	02/10/14	C
J0217431/0	NCIG Inspection	07/10/14	C
J0217575/0	Coolant leak on truck	08/10/14	C
J0217576/0	Repair grain chute on truck	08/10/14	C
J0218361/0	TYRES REPLACED POS 3,4,5,6	14/10/14	C
J0218514/0	Sunvisor loose	17/10/14	C
J0218715/0	Tyres replaced 7,8,9,10	17/10/14	C
P0032694/0	Rego Renewal	17/10/14	C
J0218523/0	Tension wheels POS - 7,8,9,10	18/10/14	C
J0219473/0	Repair air bag operation	28/10/14	C
J0219481/0	Repair gear shift operation	30/10/14	C
P0032790/0	600hr Service - (FM500 EURO4)	06/11/14	C
J0220299/0	Repair R/H steer mudguard	07/11/14	C
J0220300/0	Replace stickers	07/11/14	C
J0220556/0	Replace number plates	11/11/14	C
J0221174/0	repair aerial on roof	18/11/14	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0222122/0	Tyres replaced pos 1,2	25/11/14	C
J0222551/0	Repair AM radio operation	03/12/14	C
J0223226/0	UHF Handpiece	12/12/14	C
J0223262/0	Phone charger falling out	12/12/14	C
J0224900/0	Tailgate grain shute repaired and repair LH body reinforcement	23/12/14	C
J0224504/0	F/left indicator n/w	06/01/15	C
J0224692/0	Ride height rod missing from front axle	08/01/15	C
J0224693/0	Check hoist valve leak	08/01/15	C
J0224967/0	Program NCIG channels into radio	12/01/15	C
J0225256/0	Gearbox failure - Breakdown - Selector shaft broken	12/01/15	C
J0225344/0	Bluetooth not connecting	15/01/15	C
J0225364/0	Tarp n/w	15/01/15	C
J0225365/0	Phone kit u/s	15/01/15	C
J0226202/0	Tyre repaired pos 10	15/01/15	C
J0225442/0	Tension Pos 10 wheel	16/01/15	C
J0225591/0	Replace trailer plug	16/01/15	C
J0226439/0	Inspect PTO operation	30/01/15	C
J0226719/0	Phone kit speaker u/s	03/02/15	C
P0033959/0	2400hr Service - (FM500 EURO 4)	06/02/15	C
J0227440/0	Phone not charging	10/02/15	C
J0228268/0	Transmission grinding gears under load	18/02/15	C
J0228323/0	RH clearance lights N/W	19/02/15	C
J0228539/0	ABS light on	23/02/15	C
J0229069/0	Repair phone mounting bracket	02/03/15	C
J0229747/0	Light control module u/s	10/03/15	C
J0229964/0	bypass voltage reducer	12/03/15	C
J0230313/0	Phone charger N/W	17/03/15	C
J0230314/0	Hydraulic oil leak at back of coupling	17/03/15	C
J0230422/0	brake warning light coming on dash	18/03/15	C
J0230865/0	Air leaking from Breather on booster on tailgate on truck	23/03/15	C
J0230866/0	Replace mud flap	23/03/15	C
J0231237/0	Retension position 7/8/9/10	27/03/15	C
J0231258/0	Tyres replaced pos 1/2	28/03/15	C
J0231259/0	Tyres replaced pos 7/8/9/10	28/03/15	C
J0231365/0	Rekit hydraulic coupling at rear of truck	30/03/15	C
P0034980/0	Belt tensioners & Belts (FM13 Volvo Trucks only)	31/03/15	C
P0034981/0	600hr Service - (FM500 EURO4)	31/03/15	C
J0231696/0	Replace oil cooler hoses at gearbox	02/04/15	C
J0231697/0	Replace low coolant sender unit	02/04/15	C
J0231702/0	Replace tailgate seal	02/04/15	C
J0232020/0	Joystick broken	09/04/15	C
J0232363/0	Drivers side headlight N/W	14/04/15	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0233355/0	Replace dipstick	29/04/15	C
J0233356/0	Replace park brake handle	29/04/15	C
J0233357/0	Rrear sway bar links worn	29/04/15	CA
J0233479/0	Rear sway bar link rods worn	29/04/15	C
J0233963/0	ABS light on dash	06/05/15	C
J0234312/0	Phone charger not working	11/05/15	C
J0234454/0	Tarp motor replaced	13/05/15	C
J0235442/0	Phone not pairing with kit	26/05/15	C
J0236442/0	Scales not working	09/06/15	C
J0236444/0	Hydraulic oil low	09/06/15	C
J0236500/0	UHF not transmitting	09/06/15	C
J0236503/0	ABS light on	09/06/15	C
J0236529/0	Tension wheels - POS 3,4,5,6	10/06/15	C
J0236906/0	Am/Fm radio n/w	15/06/15	C
J0237014/0	Tyres replaced pos 3/4/5/6	16/06/15	C
J0237927/0	Tail shaft bolts loose	26/06/15	C
J0237928/0	Replace boost hose	26/06/15	C
J0238376/0	Air bags not inflating	02/07/15	C
J0238408/0	replace spill kit	02/07/15	C
J0238508/0	Phone Kit n/w	03/07/15	C
J0238858/0	Air dryer wont reset	07/07/15	C
P0036233/0	1200hr Service - (FM500 EURO4)	08/07/15	C
J0240268/0	Brake reline frt drive	23/07/15	C
J0240453/0	LH headligh N/W	27/07/15	C
J0240838/0	Interior trims u/s	31/07/15	C
J0241141/0	Air dryer replaced	05/08/15	C
J0241483/0	Truck washing 2015/2016	07/08/15	C
J0241650/0	Replace steer centre caps	11/08/15	C
J0241854/0	LH headlight glass broken	12/08/15	C
J0241999/0	LH tarp cable replaced	14/08/15	C
J0242294/0	Hydraulic filter loose	17/08/15	C
P0036921/0	Safety Inspection 2015/2016	20/08/15	C
J0242566/0	EBS module replaced	24/08/15	C
J0242970/0	accessory plug inop	28/08/15	C
J0243130/0	various lights inop	31/08/15	C
J0243227/0	Engine missing	01/09/15	C
J0243518/0	Windscreen replaced	04/09/15	C
J0243643/0	LHF indicator n/w	07/09/15	C
J0243740/0	High Nox fault (Engine warning light on)	08/09/15	C
J0243741/0	SCR system performance fault	08/09/15	C
J0243987/0	Supply and fit monitoring camera to truck	10/09/15	C
J0244007/0	Phone kit u/s	10/09/15	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0244268/0	LHF indicator n/w	14/09/15	C
J0244414/0	Tarp cables adjusted	15/09/15	C
P0037358/0	600hr Service - (FM500 EURO4)	28/09/15	C
J0245327/0	No drive	29/09/15	C
J0245885/0	LH clearance lights flickering	06/10/15	C
J0246045/0	LH Indicator NW	07/10/15	C
J0246348/0	Air leak from under vehicle	10/10/15	C
J0246838/0	Brake test	16/10/15	C
J0246846/0	Brake test	16/10/15	CA
J0247053/0	Ringfeeder o/hailed	20/10/15	C
J0247315/0	Wiper ruubers replaced	22/10/15	C
J0247418/0	Mudflap L/H/R replaced	24/10/15	C
J0247422/0	Wiring to lh tail light and number plate light repaired	24/10/15	C
J0247423/0	Exhaust flex replaced	24/10/15	C
P0037672/0	Rego Renewal	24/10/15	C
J0247738/0	Tyre fitted Runout - Pos 9	27/10/15	C
J0247745/0	Tyres fitted Runout - Pos 7,8,9,10	27/10/15	C
J0248956/0	Retension wheel nuts pos 15,16,17,18	10/11/15	C
J0249284/0	Check auto tarp op	13/11/15	C
J0249418/0	Replace tyres - Pos 1,2	13/11/15	C
J0249318/0	Engine Derate countdown on - datalink resiatance, nox sensor	16/11/15	C
J0249380/0	Tension wheel nuts pos 1&2	16/11/15	C
J0249446/0	Check engine brake operation	17/11/15	C
J0250013/0	Oil leaking from PTO area	24/11/15	C
J0250961/0	RHF blinker N/W	04/12/15	C
J0250962/0	Hydraulic coupling leaking	04/12/15	C
J0251410/0	Ringfeeder worn	10/12/15	C
J0251446/0	Hydro valve fallen off	10/12/15	C
P0038382/0	2400hr Service - (FM500 EURO 4)	11/12/15	C
J0251665/0	Mudflap - Replace	14/12/15	C
J0251670/0	AM/FM radio	14/12/15	C
J0251675/0	Tip pins wont take grease	14/12/15	C
J0251907/0	various lights inop	16/12/15	C
J0252287/0	Navman screen replaced	21/12/15	C
J0253318/0	Light control module u/s	13/01/16	C
J0253476/0	Drivers floor mat replaced	15/01/16	C
J0253606/0	Various clearance light inop	18/01/16	C
J0253674/0	Air bag drive replaced	19/01/16	C
J0253684/0	Tarp n/w	19/01/16	C
J0254773/0	Retension wheels pos 7,8,9,10	02/02/16	C
J0255174/0	Tyres replaced - Pos 7,8,9,10	08/02/16	C
J0255268/0	Tyres replaced - Pos 3,4,5,6	08/02/16	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0255790/0	Bin isolator broken	16/02/16	C
J0256699/0	24v outlet n/w	25/02/16	C
J0256936/0	Blinker L/H/F inop	27/02/16	C
J0256920/0	RH steer guard bolts loose	29/02/16	C
J0257470/0	Tyre replaced - Pos 1 - Blow out @ Williamtown	07/03/16	C
J0257701/0	Tyres replaced - Pos 1,2	07/03/16	C
P0039388/0	600hr Service - (FM500 EURO4)	11/03/16	C
J0258285/0	Headlight wiring repaired R/H	15/03/16	C
J0258286/0	Reverse quacker fitted	15/03/16	C
J0258614/0	A/C inop	21/03/16	C
J0259194/0	Tyre replaced , runout - Pos 7	30/03/16	C
J0260634/0	Mudflaps x 2 replaced	14/04/16	C
J0261355/0	Tyres replaced - Pos 7,8,9,10 . Service sheet 5776	20/04/16	C
J0262317/0	Alternator replaced	06/05/16	C
J0262659/0	Interior light inop	11/05/16	C
J0262911/0	Ringfeeder stuck	14/05/16	C
J0263039/0	Phone charger lead	16/05/16	C
J0263624/0	engine fan staying on	24/05/16	C
P0040362/0	1200hr Service - (FM500 EURO4)	30/05/16	C
J0264468/0	NHVAS Label replaced	03/06/16	C
J0264611/0	Navman updated	06/06/16	C
J0264654/0	Drive hubcaps	07/06/16	C
J0264702/0	Washers jets replaced	07/06/16	C
J0265051/0	Jumpstart	14/06/16	C
J0265842/0	Air leak repaired	24/06/16	C
J0265878/0	Hoist control solenoid replace	27/06/16	C
J0266290/0	Adjust Tarp Cables	30/06/16	C
J0267026/0	Truck Washing 2016/2017	01/07/16	C
P0040933/0	Safety Inspection 2016/2017	01/07/16	C
J0266625/0	Air leak at drive	05/07/16	C
J0266626/0	Inspect fan operation	05/07/16	C
J0266775/0	Brakes,steer replaced	06/07/16	C
J0266836/0	Brake reline,drive	07/07/16	C
J0266877/0	Hydraulic filter housing & hose repair	08/07/16	C
J0266920/0	breakdown at Musso Coal replace missing hyd filter	08/07/16	C
J0267620/0	Tyre replace , runout - Pos 8 , servioce sheet 5956	10/07/16	C
J0267613/0	Tyres replaced - Pos 3,4,5,6, Wornout - Service sheet 5963	13/07/16	C
J0267907/0	Water pump leak replaced	21/07/16	C
J0268046/0	remove and replace blown hydraulic hoses	22/07/16	C
J0268566/0	Engine derate	29/07/16	C
J0268654/0	Exhaust leak	01/08/16	C
J0268979/0	Hydraulic coupling leaking	04/08/16	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0269241/0	Batteries x 2 replaced	08/08/16	C
J0269288/0	Mines radio replaced	08/08/16	C
J0269457/0	Ad-blue cap	10/08/16	C
P0041330/0	600hr Service - (FM500 EURO4)	10/08/16	C
J0269898/0	engine fan cutting in more than normal	15/08/16	C
J0270002/0	Navman mount broken	16/08/16	C
J0270460/0	Ringfeeder hard to operate	22/08/16	C
J0270751/0	UHF Mic replaced	25/08/16	C
J0270861/0	Wheel alignment	29/08/16	C
J0271179/0	LH 1st sway bar link worn	01/09/16	C
J0271257/0	L/H/R drive tyre flat	01/09/16	C
J0271319/0	Air leaking from middle area	02/09/16	C
J0271678/0	Jack shaft bolt loose	07/09/16	C
J0271717/0	Tyres replaced - Pos 1,2,7,8,9,10, Wornout , Service sheet 6207	07/09/16	C
J0271925/0	replace broken exhaust flex supplied by Wallsend	09/09/16	C
J0272169/0	Washer bottle leaking cleaned out	14/09/16	C
J0273176/0	Engine fan replaced	27/09/16	C
J0273116/0	Filler cap replaced	28/09/16	C
J0273295/0	Tyres replaced pos 3/4/5/6	30/09/16	C
J0273306/0	Compressor cooler coils u/s	30/09/16	C
J0273307/0	Tailshaft cracked	30/09/16	C
J0273938/0	LH sterr mudguard	11/10/16	C
P0042092/0	2400hr Service - (FM500 EURO 4)	13/10/16	C
P0042113/0	Turbo Replacement (FM13 and FH13 SCR)	13/10/16	C
J0274352/0	Tip pins worn - Replace @ Nationals	17/10/16	C
J0274684/0	Tarp gearbox replaced	20/10/16	C
P0042212/0	Rego Renewal	31/10/16	C
J0276345/0	Replace tyres pos 1/2 - S/S 7250 damaged tread	14/11/16	C
J0276404/0	RH park light inop	14/11/16	C
J0276544/0	Engine Oil leak @ RAFF base	15/11/16	C
J0277061/0	Brake test	22/11/16	C
J0277412/0	Tailgate seal u/s	25/11/16	C
J0277718/0	Battery box repaired	30/11/16	C
J0278103/0	Tarp replaced	06/12/16	C
J0278865/0	clearance lights flickering	15/12/16	C
J0279033/0	Drivers door check strap u/s	19/12/16	C
J0279608/0	P/S oil low	04/01/17	C
J0280452/0	Batteries x 2 replaced N150	16/01/17	C
J0280475/0	Tyres replaced - Pos 7,8,9,10 .S/S-6914	16/01/17	C
J0280525/0	Wheel chocks	17/01/17	C
J0280539/0	Mudflaps replaced	17/01/17	C
J0280540/0	LH Front indicator N/W	17/01/17	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
P0043189/0	600hr Service - (FM500 EURO4)	19/01/17	C
J0280866/0	Tyre replace pos ?? - Glen Innes	23/01/17	C
J0281884/0	Tyres replaced - Pos 5,6. S/S-7301	06/02/17	C
J0281885/0	CB antenna replaced	06/02/17	C
J0281891/0	LHF Drive hub cap bracket u/s	06/02/17	C
J0282222/0	Adjust Headlights	09/02/17	C
J0282298/0	RH steer mudguard brackets broken	10/02/17	C
J0282530/0	Tip pins wont take grease	14/02/17	C
J0282532/0	Hydraulic oil leak	14/02/17	C
J0282533/0	Indicator replaced R/H/F	14/02/17	C
J0282587/0	RH headlight surround broken	14/02/17	C
P0043599/0	Belt tensioners & Belts (FM13 Volvo Trucks only)	22/02/17	C
J0283452/0	Replace RHFblinker	24/02/17	C
J0283453/0	a/c drain blocked	24/02/17	C
J0284336/0	RH Headlight and LHF blinker not working	07/03/17	C
J0284515/0	WIndscreen washer bottle leaking	09/03/17	C
J0284937/0	windscreen washers not working	15/03/17	C
J0285280/0	Air conditioning inop	20/03/17	C
J0285653/0	fit uhf extension speaker	23/03/17	C
J0285886/0	ABS light on	27/03/17	C
J0286075/0	Drive shocks U/S	29/03/17	C
J0286077/0	LH 1st sway bar link worn	29/03/17	C
J0286666/0	Scales inop	05/04/17	C
J0286966/0	Sump leaking	10/04/17	C
J0287003/0	Tyres replaced - Pos 1,2 . S/S- 7511	10/04/17	C
P0044204/0	1200hr Service - (FM500 EURO4)	10/04/17	C
J0287969/0	power steering leak	26/04/17	C
J0287970/0	coolant leak	26/04/17	C
J0287994/0	replace missing reflectors	26/04/17	C
J0288239/0	truck runing rough	29/04/17	C
J0288736/0	ABS light on	04/05/17	C
J0288737/0	drivers window inop	04/05/17	C
J0289123/0	Cam sensor leaking	09/05/17	C
J0289235/0	T/Shaft bolts loose	10/05/17	C
J0290094/0	fill hydraulic oil	22/05/17	C
J0290222/0	breakdown MUSSO COAL compressor line	24/05/17	C
J0291365/0	Replace leaking hyd hose	24/05/17	C
J0290700/0	ABSlight staying on	30/05/17	C
J0290882/0	Tarp cover strap hanging down	01/06/17	C
J0291270/0	Steer hubcap missing	07/06/17	C
J0291523/0	Adjust headlights	09/06/17	C
J0292253/0	Exhaust brake fault	20/06/17	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0292349/0	Fit auto tarp solenoid	21/06/17	C
J0292362/0	Replace drawbar flap	21/06/17	C
J0292966/0	Replace wipers	29/06/17	C
J0293206/0	Truck Washing 2017/2018	03/07/17	C
J0293249/0	LH clearance lights N/W	03/07/17	C
P0045254/0	Safety Inspection 2017/2018	03/07/17	C
P0045317/0	600hr Service - (FM500 EURO4)	03/07/17	C
J0293342/0	Replace steer rims	04/07/17	C
J0293389/0	RH steer sway bar link worn	05/07/17	C
J0293390/0	Power steer oil leak	05/07/17	C
J0293846/0	Running rough / blowing smoke	10/07/17	C
J0293955/0	Brake warning & suspension light on dash	11/07/17	C
J0293960/0	Rear airbag fault	11/07/17	C
J0294443/0	Blowing smoke , lacking power	17/07/17	C
J0295023/0	Navman mount falling off	19/07/17	C
J0295024/0	Refit trim behind drivers seat	19/07/17	C
J0295052/0	Exhaust brake N/W	24/07/17	C
J0300031/0	Tyres replaced - Pos 7,8,9,10.S/S-7828	24/07/17	C
J0300193/0	Clearance lights out R/H/Side	26/07/17	C
J0300194/0	Knocking noise under cab	26/07/17	C
J0300201/0	Beacon wiring repaired	26/07/17	C
J0300699/0	Hydraulic oil leak at delivery valve	02/08/17	C
J0300718/0	Tyres replaced - Pos 1,2.S/S-7843	02/08/17	C
J0301232/0	Dash lights flashing	08/08/17	C
J0302779/0	Adjust headlights	28/08/17	C
J0303230/0	Replace phone cradle	02/09/17	C
J0303438/0	Engine light staying on	05/09/17	C
P0046207/0	2400hr Service - (FM500 EURO 4)	15/09/17	C
J0305815/0	Replace windscreen	19/09/17	C
J0304817/0	Engine light on	20/09/17	C
J0305968/0	Repair tailgate prop	10/10/17	C
J0306512/0	Ring feeder fault	14/10/17	C
J0306771/0	Number plate light wiring broken	18/10/17	C
J0306673/0	Fan hub bearing replaced	18/10/17	C
J0307217/0	Tyres replaced - Pos 3,4,5,6.S/S-9201	25/10/17	C
J0307267/0	Navman screen mount keeps falling off	25/10/17	C
P0046658/0	Rego Renewal	31/10/17	C
J0307794/0	Replace tarp switches	02/11/17	C
J0308682/0	Tyre replaced , runout- Pos 9 .S/S-9226	07/11/17	C
J0308689/0	Tyres replaced , runout- Pos 9.S/S-9229	07/11/17	C
J0308268/0	LH headlight n/w	08/11/17	C
J0308365/0	Replace hydraulic hose	09/11/17	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0309275/0	Check scales operation	22/11/17	C
J0309314/0	RHR drive sway bar link worn	22/11/17	C
J0309334/0	Replace steer rims	22/11/17	C
J0309570/0	Tyres replaced - Pos 1,2.S/S-9313	24/11/17	C
J0309835/0	Replace NHVAS label	30/11/17	C
P0047042/0	Water pump & thermostat (FM13 & FH13 Volvo Trucks)	03/12/17	C
J0310081/0	Replace bin weight stickers	04/12/17	C
J0310482/0	Engine oil low	07/12/17	C
J0310419/0	not building up air replace air dryer	07/12/17	C
J0310427/0	Replace NHVAS label	07/12/17	C
J0310478/0	Tarp not tripping out	08/12/17	C
J0310584/0	temp repair tarp switch	11/12/17	C
J0310950/0	Stickers replaced	13/12/17	C
J0311100/0	Replace floor mat	15/12/17	C
J0311329/0	Hydraulic oil low	20/12/17	C
J0311627/0	hydraulic tank straps broken	27/12/17	C
J0311932/0	Aerials loose on cab	04/01/18	C
J0311933/0	Reline drive brakes	04/01/18	C
J0312727/0	RH headlight N/W	17/01/18	C
J0312736/0	Replace fire extuisher & bag	17/01/18	C
J0313386/0	Coolant smell	24/01/18	C
J0313678/0	Navman fault	29/01/18	C
J0314193/0	Brake test 2018	03/02/18	C
J0314892/0	RH 1st sway bar link worn	13/02/18	C
J0315228/0	RH 2nd drive shock bolt miising - REplace	15/02/18	C
P0047225/0	600hr Service - (FM500 EURO4)	20/02/18	C
J0315637/0	Check phone bluetooth connection	21/02/18	C
P0048026/0	1200hr Service - (FM500 EURO4)	25/02/18	C
J0315989/0	Cab leaking water	26/02/18	C
J0316580/0	Tyres replaced - Pos 7,8,9,10.S/S-9553	06/03/18	C
J0316878/0	Various lights n/w	09/03/18	C
J0316888/0	Install Navman iFace	10/03/18	C
J0316994/0	Headlights loose	12/03/18	C
J0317847/0	No lights working.clearance lights flashing	22/03/18	C
J0318159/0	Air leak under cab	27/03/18	C
J0319608/0	Tarp wont go all the way out	19/04/18	C
J0319609/0	Repair drawbar prop	19/04/18	C
J0319610/0	Clearance lights not working	19/04/18	C
J0319962/0	Replace front diff input seal	26/04/18	C
J0321941/0	Mines radio mic inop	22/05/18	C
J0322328/0	Replace drivers sun visor(interior)	28/05/18	C
J0322951/0	1st Drive front airbags	06/06/18	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0323402/0	Engine miss	13/06/18	C
J0323862/0	Replace Safety Stickers	20/06/18	C
J0323941/0	Tyres replaced - Pos 1,2.S/S-8730	20/06/18	C
S0000363/0	Safety Inspection 2018-2019	01/07/18	C
S0000364/0	Truck Washing 2018-2019	01/07/18	C
J0324983/0	Engine failure	06/07/18	C
J0325410/0	Hook truck up to dog	13/07/18	C
J0325499/0	Exhaust flex U/S	14/07/18	C
J0325591/0	Replace addblue tank filler screen	16/07/18	C
J0326531/0	Check scales n/w	27/07/18	C
J0326797/0	Tyre replaced , runout - Pos 7.S/S-8787	01/08/18	C
J0326898/0	Tyres replaced - Pos 7,8,9,10.S/S-8791	01/08/18	C
J0326827/0	Dip stick U/S	01/08/18	C
J0327570/0	Replace cab shocks	13/08/18	C
J0327792/0	RHF blinker not working	16/08/18	C
J0328085/0	Rattle under cab	20/08/18	C
P0049665/0	2400hr Service - (FM500 EURO 4)	22/08/18	C
J0328332/0	Rotating beacon inop	23/08/18	C
J0328423/0	Coolant leak	24/08/18	C
J0328565/0	Replace wiper blades	27/08/18	C
J0328661/0	Fit phone cradle	28/08/18	C
J0329425/0	Phone cradle fallen off	06/09/18	C
J0330180/0	Trailer lights inop	19/09/18	C
J0330416/0	Replace faulty radiator	24/09/18	C
J0331014/0	LHF blinker assmby damaged	02/10/18	C
P0050230/0	600hr Service - (FM500 EURO4)	09/10/18	C
J0331504/0	Headlights not working	09/10/18	C
J0331667/0	Radiator & heater hoses replaced	10/10/18	C
J0331668/0	Rear of steer spring eye & shackle bushes	10/10/18	C
J0332060/0	Phone cradle keeps falling off dash	16/10/18	C
J0332141/0	Tyres replaced Pos 3,4,5,6.S/S-11022	17/10/18	C
P0050274/0	Air Compressor Replacement (Volvo Trucks)	18/10/18	C
J0332431/0	Brake test 2018	23/10/18	C
J0332517/0	Replace marker plate	23/10/18	C
J0333732/0	2nd drive air bags U/S	08/11/18	C
J0334042/0	RH headlight not working	13/11/18	C
J0334883/0	Calibrate scales	24/11/18	C
J0335509/0	1st axle brake reline	05/12/18	C
J0336072/0	UHF microphone replace	12/12/18	C
J0336843/0	Remove ad Ad blue filter	21/12/18	C
P0049849/0	Belt tensioners & Belts (FM13 Volvo Trucks only)	02/01/19	C
J0337646/0	Clean washer jets	15/01/19	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0338020/0	Tyre runout Pos 2.S/S-11186	18/01/19	C
J0338541/0	Tail gate bent	25/01/19	C
J0338658/0	Tyres replaced - Pos 1,2.S/S-10451	29/01/19	C
J0338715/0	Replace seat cushion foam	30/01/19	C
P0050526/0	1200hr Service - (FM500 EURO4)	05/02/19	C
J0339349/0	Washer Squirters Blocked	07/02/19	C
P0048763/0	600hr Service - (FM500 EURO4)	14/02/19	C
J0340545/0	ABS warning staying on	22/02/19	C
J0340990/0	LH headlight n/w	27/02/19	C
J0340985/0	Power socket N/W	28/02/19	C
J0341863/0	Washer bottle bracket broken	12/03/19	C
J0342379/0	I face not charging	20/03/19	C
J0342573/0	LHF blinker not working	21/03/19	C
J0342812/0	Air cond compressor replaced	26/03/19	C
J0343269/0	Tyres replaced - Pos 7,8,9,10.S/S-10267	02/04/19	C
J0343275/0	Replace registration plates	02/04/19	C
J0344170/0	Air cond thermistor replaced	15/04/19	C
J0345473/0	Replace ABS connector	08/05/19	C
J0346174/0	Check speedo drops out	17/05/19	C
P0052475/0	600hr Service - (FM500 EURO4)	20/05/19	C
J0346944/0	Scales fitted	29/05/19	C
J0347400/0	Replace RH headlight & surround	04/06/19	C
J0347401/0	Replace compressor oil feed line	04/06/19	C
J0347600/0	Repair air leak	06/06/19	C
J0347602/0	Replace Daracon decals	06/06/19	C
J0348089/0	Windscreen washers n/w	17/06/19	C
J0348282/0	Install work light	19/06/19	C
J0348588/0	Wiper linkages noisy	24/06/19	C
J0349140/0	Beacon switch faulty	02/07/19	C
J0349234/0	Tilt meter not working	03/07/19	C
S0000677/0	Safety Inspection 2019-2020	04/07/19	C
S0000846/0	Truck Washing 2019-2020	04/07/19	C
J0349715/0	Powersteer tight	11/07/19	C
J0350042/0	Windscreen washers not working	16/07/19	C
J0350426/0	Windscreen washers not working	22/07/19	C
J0350427/0	No power to scales unit and cigarette lighter	22/07/19	C
J0350616/0	Disconnect trailer	24/07/19	C
J0350711/0	Loose sun visor	26/07/19	C
P0053384/0	2400hr Service - (FM500 EURO 4)	10/08/19	C
J0352394/0	Replace TX3600 handpiece	20/08/19	C
J0352445/0	Tyres runout on - Pos 1.S/S-10927	21/08/19	C
J0352892/0	Tyres replaced Pos 1,2.S/S-10929	27/08/19	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0353107/0	Tyres replaced Pos 3,4,5,6.S/S-10939	29/08/19	C
J0353507/0	Mines radio inop	04/09/19	C
J0353508/0	Washers blocked	04/09/19	C
J0354314/0	Exhaust brake not working correctly	17/09/19	C
J0354315/0	Handle on ring feeder bent	17/09/19	C
J0354317/0	Replace glovebox lid	17/09/19	C
J0354761/0	Accident damage incident 61794	23/09/19	C
J0356034/0	Tighten LH Spotter Mirror	15/10/19	C
J0356766/0	LH headlight not working	25/10/19	C
J0357039/0	Tailgate hinge bent	28/10/19	C
J0357077/0	I-face not charging	30/10/19	C
J0357334/0	Replace LH headlight	04/11/19	C
J0357346/0	Top up engine oil	04/11/19	C
J0357449/0	Windscreen washers N/W	06/11/19	C
J0357963/0	Knock under cab	12/11/19	C
P0054217/0	600hr Service - (FM500 EURO4)	13/11/19	C
J0358117/0	Tyres replaced - Pos 7,8,9,10.S/S-11291	14/11/19	C
J0358478/0	Check Navman Operation	20/11/19	C
J0358646/0	Grain chute repairs	22/11/19	C
J0358647/0	Tighten D/S Cab Grab Handles	22/11/19	C
J0358809/0	3rd Axle Brake Lines	25/11/19	C
J0358811/0	Replace Ringfeeder	26/11/19	C
J0359149/0	Replace Starter Motor	29/11/19	C
J0359789/0	Tarp Gearbox Bracket	11/12/19	C
J0359918/0	Tyres replaced - Pos 10.S/S-76190	11/12/19	C
J0360795/0	Tyre replaced - Pos 3.S/S-76190	11/12/19	C
J0359921/0	Tyres replaced - Pos 1,2.S/S-11337	12/12/19	C
J0360391/0	Phone Not Charging	19/12/19	C
J0360672/0	Pre-Start Check Over	06/01/20	C
J0360780/0	93621 - Replace Front Windscreen	07/01/20	C
J0362120/0	Replace TX4500 Radio	29/01/20	C
J0362376/0	Check Air Dryer Fault	03/02/20	C
J0362502/0	Engine Light On Dash	05/02/20	C
J0362691/0	Tyre repair on Pos 7.M251747	06/02/20	C
J0362801/0	Brake Test 2020	07/02/20	C
J0362914/0	Apply NHVAS Label	11/02/20	C
J0362919/0	Replace RHR mudflap	11/02/20	C
P0051459/0	1200hr Service - (FM500 EURO4)	22/02/20	C
J0363921/0	96320 - Washer Bottle Leak	25/02/20	C
J0363948/0	96320 - AC Blower Fan Inop	26/02/20	C
J0364937/0	Brake Lining Wear Sensor Fault	11/03/20	C
J0365350/0	Universal Joint Failure	18/03/20	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0365875/0	96323 - RH Headlight Not Working	26/03/20	C
J0365884/0	Brake fault on dash	27/03/20	C
J0367178/0	108951 - Airbags Dropping	16/04/20	C
J0367179/0	108951 - Brakes Squeal	16/04/20	C
J0367712/0	108952 - Tarp Cables & Pulleys	24/04/20	C
J0367713/0	Repair Tailgate Fault	24/04/20	C
J0368382/0	108952 & 108956 - Check Body Sticking Up	05/05/20	C
J0368489/0	Coolant Leak At Radiator	06/05/20	C
J0368673/0	108954 - Drivers Electric Window Not Working	07/05/20	C
J0368867/0	108955 - Air Drier Warning On Dash, Keeps Exhausting	11/05/20	C
J0369366/0	Tilt Meter Not Working	18/05/20	C
J0369954/0	Cut spare ignition key	26/05/20	C
J0370290/0	Replace Sticker & Reflector	30/05/20	C
J0370473/0	Tyre runout on - Pos 4.S/S-12047	02/06/20	C
J0370602/0	Tyres replaced - Pos 3,4,5,6.S/S-12049	03/06/20	C
P0056701/0	600hr Service - (FM500 EURO4)	12/06/20	C
J0371277/0	Replace Cab Marker Lights	15/06/20	C
J0371352/0	Install Phone Cradle	16/06/20	C
J0371767/0	Navman Not Charging	23/06/20	C
J0371850/0	108956 - Interior Light Not Working	24/06/20	C
J0371930/0	108956 - Replace Header Tank	25/06/20	C
J0371931/0	Air Leak Above Drive	25/06/20	C
S0001041/0	Safety Inspection 2020/2021	01/07/20	C
S0001107/0	Truck Washing 2020-2021	01/07/20	C
J0372374/0	Fit Phone Kit	02/07/20	C
J0372986/0	Tarp Won't Travel Full Range	13/07/20	C
J0372988/0	Charge Equalizer Not Working	13/07/20	C
J0372948/0	Replace Two Batteries	14/07/20	C
J0373048/0	108956 - Driver seat cover	14/07/20	C
J0373049/0	Beacon Not Working	14/07/20	C
J0373050/0	Replace RH Steer Guard Bracket	14/07/20	C
J0373051/0	Tyre Repair - Pos 5 S/S-11596	14/07/20	C
J0374360/0	Tyres replaced - Pos 7,8,9,10.S/S-11613	05/08/20	C
J0374566/0	I-Face Fault	07/08/20	C
J0375736/0	Tarp Not Cutting Out	26/08/20	C
J0375737/0	RHF Clearance Light Not Working	27/08/20	C
J0375738/0	Repair Airleak At LH 3rd Airbag	27/08/20	C
J0376335/0	Brake Test 2020	03/09/20	C
J0376455/0	Tyre runout on - Pos 1.S/S-12086	04/09/20	C
J0376553/0	Tyres replaced - Pos 1,2.S/S-12088	07/09/20	C
J0376664/0	108951 - Calibrate Weigh Scales	08/09/20	C
J0376946/0	Check Suspension Fault	11/09/20	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0377328/0	Repair LH Park Light	17/09/20	C
J0377329/0	Replace RH Reverse Light	17/09/20	C
P0057756/0	2400hr Service - (FM500 EURO 4)	20/09/20	C
J0377840/0	108953 & 108957 - Bin Getting Stuck Up	25/09/20	C
J0378001/0	108957 - PTO Not Working	28/09/20	C
J0378172/0	Replace Headlight Globe	30/09/20	C
J0379501/0	Replace cab lock hose	23/10/20	C
J0379504/0	Replace Side Marker Light	24/10/20	C
J0380249/0	108959 - Windscreen Washers Not Working	05/11/20	C
J0380578/0	I-Face not working	11/11/20	C
J0380749/0	108959 - Replace Battery Isolator	13/11/20	C
J0380880/0	Replace through shaft	17/11/20	C
J0381088/0	Crack in grain chute	19/11/20	C
J0381683/0	108958 - Subframe Bolt Broken	30/11/20	C
J0381684/0	108958 - LH Windscreen Washer Not Working	30/11/20	C
J0382201/0	Airleak at compressor	08/12/20	C
J0382205/0	Wiper blades	09/12/20	C
J0382266/0	Crack fuel tank J bracket	09/12/20	C
J0382343/0	Steering heavy	10/12/20	C
P0058697/0	600hr Service - (FM500 EURO4)	27/12/20	C
J0383232/0	Front of 2nd drive airbags	07/01/21	C
J0383940/0	108960 - Windscreen washers N/W	20/01/21	C
J0383941/0	108960 - Seat locking up	20/01/21	C
J0383942/0	108958 & 108960 - Scales out of calibration	20/01/21	C
J0384491/0	I-Face not charging	01/02/21	C
J0384790/0	Repair phone cradle	04/02/21	C
J0385221/0	108961 - Front brakes rattling	11/02/21	C
J0385222/0	108961 - UHF radio no range	11/02/21	C
J0386500/0	Replace heater hoses	04/03/21	C
J0387606/0	Replace tailgate seal	25/03/21	C
J0387789/0	108963 - LH Headlight Needs Replacing	29/03/21	C
J0387817/0	Replace scale fittings	29/03/21	C
J0388286/0	Replace Adblue sticker	08/04/21	C
J0388432/0	LH spotter mirror loose	09/04/21	C
J0388435/0	Inspect tarps	10/04/21	C
J0388635/0	Update scale readings	14/04/21	C
P0059960/0	1200hr Service (FM500 EURO4)	25/04/21	C
P0059845/0	Belt tensioners & Belts (FM13 Volvo Trucks only)	26/04/21	C
J0389688/0	Tyres replaced - Pos 1,2.S/S-12534	30/04/21	C
J0389915/0	Tyres replaced - Pos 7,8,9,10.S/S-12538	05/05/21	C
J0389953/0	Navman iFace screen blank	05/05/21	C
J0390128/0	Replace UHF aerial base	07/05/21	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0390488/0	Replace UHF radio coax cable	14/05/21	C
J0390659/0	LH 3rd drop arm	18/05/21	C
J0390660/0	3rd axle brake reline	18/05/21	C
J0391616/0	LH indicator assembly broken	02/06/21	C
J0392604/0	Tyres replaced - Pos 3,4,5,6.S/S-14284	21/06/21	C
J0393086/0	108964 - LH 3rd Brake Locked Up	28/06/21	C
J0393117/0	108964 - Knocking Noise Under Cab	29/06/21	C
P0055730/0	1200hr Service - (FM500 EURO4)	30/06/21	C
S0001550/0	Safety Inspection 2021-2022	01/07/21	C
S0001551/0	Truck Washing 2021-2022	01/07/21	C
P0060689/0	600hr Service - (FM500 EURO4)	05/07/21	C
J0393800/0	Tarp n/w	08/07/21	C
J0393851/0	108965 & 108966 - LH headlight cracked	09/07/21	C
J0394821/0	Replace drag link end	28/07/21	C
J0394822/0	Ringfeeder rebuilt	28/07/21	C
J0394829/0	Replace rear marker decals	29/07/21	C
J0395003/0	108966 - Beacon Warning Light Not Working	30/07/21	C
J0395004/0	108966 - LH Clearance Light Not Working	31/07/21	C
J0395007/0	Replace UHF mic holder	31/07/21	C
J0395235/0	108967 - Drive airbags dropping when motor turned off	04/08/21	C
J0396081/0	Repair windscreen washers	18/08/21	C
J0396486/0	Replace headlight globe	26/08/21	C
P0061538/0	NHVR Annual Heavy Vehicle Inspection	01/09/21	C
J0397086/0	Tyre runout on - Pos 8.S/S-13929	06/09/21	C
J0397190/0	Tyres repair on - Pos 8.S/S-13930	07/09/21	C
J0398111/0	108969 - Overhead console broken	24/09/21	C
P0061481/0	Turbo Replacement (FM480)	27/09/21	C
P0061537/0	2400hr Service - (FM500 EURO 4)	30/09/21	C
J0398907/0	Exhaust silencer U/S	12/10/21	C
J0400971/0	RH headlight and parklight n/w	17/11/21	C
J0400972/0	Calibrate scales	17/11/21	C
J0401014/0	Replace headlight surround	18/11/21	C
J0401024/0	Air dryer fault on display	18/11/21	C
J0401038/0	Battery isolator wont turn	18/11/21	C
J0401233/0	Tyres replaced - Pos 1,2.S/S-13621	23/11/21	C
J0401412/0	Drivers door handle notchy	26/11/21	C
J0401484/0	2nd axle brakes and rotors replacement	29/11/21	C
J0401894/0	108972 & 109969 - Engine Derate	07/12/21	C
J0402463/0	108791 - Replace tarp motor	16/12/21	C
P0062540/0	600hr Service - (FM500)	30/12/21	C
J0403475/0	108973 - Dash Panels	14/01/22	C
J0403649/0	108974 - Replace light control module	18/01/22	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0404837/0	Clearance lights flickering	10/02/22	C
J0404838/0	Repair LH cab door lock	10/02/22	C
J0405128/0	Stuck in Gear Wiring Fault	16/02/22	C
J0405132/0	Brake warning coming on	16/02/22	C
J0405424/0	RHF 1st drive airbag	22/02/22	C
J0405746/0	Tyres replaced - Pos 7,8,9,10.S/S-13472	01/03/22	C
J0406209/0	Replace Navman mount	08/03/22	C
J0407038/0	113401 - Headlight stuck on	23/03/22	C
J0407039/0	113401 - LH Headlight out	23/03/22	C
J0407040/0	113401 - Windscreen washers	23/03/22	C
J0407108/0	113402 - Reset Navman	24/03/22	C
J0407288/0	Repair I-Face mount	29/03/22	C
J0407427/0	Alternator replaced	31/03/22	C
J0407428/0	Horton fan replaced	31/03/22	C
J0407502/0	113403 - Dropping air when parked up	01/04/22	C
P0063285/0	Water pump & thermostat (FM480)	15/04/22	C
J0408615/0	113404 - LH steer mudflap	27/04/22	C
J0408960/0	Engine harness replaced & damaged wiring repaired	04/05/22	C
J0409343/0	113406 - Windscreen Washers N/W	11/05/22	C
J0409344/0	113406 - Bolt in bin subframe broken	11/05/22	C
J0409826/0	3rd axle LH bearing replaced	19/05/22	C
P0063674/0	1200hr Service - (FM500)	31/05/22	C
J0410445/0	LHF shock rubber missing	31/05/22	C
J0410526/0	Replace battery isolator	01/06/22	C
J0411274/0	113407 - No accessory power	17/06/22	C
J0411576/0	Reseal hydraulic coupling	24/06/22	C
S0001748/0	Safety Inspection 2022-2023	01/07/22	C
S0001749/0	Truck Washing 2022-2023	01/07/22	C
J0412681/0	Tyres replaced - Pos 3,4,5,6.S/S-12867	18/07/22	C
J0413004/0	113408 - Headlight glass	22/07/22	C
J0413005/0	113408 - Window washers	22/07/22	C
J0413249/0	113311 - LH step panel	26/07/22	C
J0413680/0	113409 - Navman not working	03/08/22	C
J0414418/0	Tyres replaced - Pos 1,2.S/S-12676	15/08/22	C
J0414542/0	113410 - Navman keeps cutting	16/08/22	C
P0064656/0	600hr Service - (FM500)	18/08/22	C
J0415011/0	Repair wiring to LH tail light	23/08/22	C
J0415911/0	Replace 1st drive rear airbags	07/09/22	C
J0417015/0	Tyre runout on - Pos 10 .S/S-14450	30/09/22	C
J0417045/0	Repair charge air cooler hole	30/09/22	C
J0417046/0	RH middle mudlap split	30/09/22	C
P0065458/0	NHVR Annual Heavy Vehicle Inspection	07/10/22	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0418612/0	Replace rego plate cover	01/11/22	C
J0418712/0	Accident damage IN72950	02/11/22	C
P0065457/0	2400hr Service - (FM500)	05/11/22	C
J0419084/0	113412 - New windscreen	08/11/22	C
J0419221/0	Tyres replaced - Pos 7,8,9,10.S/S-15118	10/11/22	C
J0419455/0	Engine derate, Adblue fault	14/11/22	C
J0419493/0	Repalce steer tie rod ends	15/11/22	C
J0419631/0	LH window going down automatically	16/11/22	C
J0419632/0	Replace air dryer unit	16/11/22	C
J0419716/0	113415 - 3rd axle swaybar bushes	17/11/22	C
J0420891/0	113417 - LHF blinker loose	09/12/22	C
J0420993/0	113418 - Red stop triangle came on dash	12/12/22	C
J0420994/0	113418 - ABS light comes on and off	12/12/22	C
J0420995/0	113418 - Brake pad wear sensor	12/12/22	C
J0421263/0	Tyres replaced - Pos 7,8.S/S-15236	16/12/22	C
J0421287/0	113419 - Passenger window automatically opening	16/12/22	C
J0421390/0	Jack Shaft	20/12/22	C
J0421610/0	113420 - Headlight globes	23/12/22	C
J0421793/0	Manufacture new tarp	05/01/23	C
J0421876/0	Measure body for tarps	06/01/23	C
J0421985/0	113422 - Clearance lights on truck not working	09/01/23	C
J0422081/0	Replace rear drive V-stay	11/01/23	C
J0422588/0	Replace horn clock spring	19/01/23	C
J0422652/0	Tyres replaced - Pos 7,8,9,10-15319	20/01/23	C
J0422672/0	Replace starter motor	20/01/23	C
J0423730/0	113424 - Trailer plug wires need attention at back of drawbar & front of dog	09/02/23	C
P0066644/0	600hr Service - (FM500)	10/02/23	C
J0424544/0	113425 - Bracket to hold hand piece for CB gone	23/02/23	C
J0424545/0	113425 - LH headlight housing	23/02/23	C
J0424878/0	Tyre runout on - Pos 2.SS-15432	02/03/23	C
J0425191/0	Tyres replaced - Pos 1,2.-15436	07/03/23	C
J0425326/0	Scales not working	08/03/23	C
J0425878/0	Check LH rear brake light	16/03/23	C
J0425886/0	LHR clearance light N/W	16/03/23	C
J0426142/0	Trans output shaft movement	22/03/23	C
J0427201/0	Repair LH front blinker lens	13/04/23	C
J0427249/0	111927 - Clearance light out	14/04/23	C
J0427886/0	Check coolant level low	27/04/23	C
J0427880/0	111929 - LH cab shock	27/04/23	C
J0428607/0	Replace coolant hose leak	11/05/23	C
P0067529/0	1200hr Service - (FM500)	12/05/23	C
J0428727/0	LHF blinker broken off	13/05/23	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0428768/0	Repair light control module	15/05/23	C
J0428943/0	Check engine hard to start	17/05/23	C
J0429152/0	Fit phone cradle and charger	19/05/23	C
P0067530/0	Belt tensioners & Belts (FM13)	11/06/23	C
J0430581/0	Compressor charge pipe	16/06/23	C
J0430595/0	Hydraulic fitting leak at rear	16/06/23	C
J0430927/0	111931 - LHR wheel locking up	22/06/23	C
J0430997/0	Tyres runout on - Pos 7,9.-15590	26/06/23	C
J0431092/0	Tyres replaced - Pos 7,8.-15591	27/06/23	C
S0002085/0	Safety Inspection 2023-2024	01/07/23	C
S0002086/0	Truck Washing 2023-2024	01/07/23	C
J0432706/0	Tyres replaced - Pos 3,4,5,6-15643	27/07/23	C
J0432901/0	111933 - 12 volt sockets not working. Weight scales not working	31/07/23	C
J0433097/0	Brake fault Stop warning on	03/08/23	C
J0433128/0	Reline drive axles brakes	04/08/23	C
J0433446/0	Replace LH tarp cable	10/08/23	C
P0068594/0	600hr Service - (FM500)	25/08/23	C
P0068595/0	Air Compressor Replacement	25/08/23	C
J0434284/0	111934 - Blinker arm snapped off	29/08/23	C
J0434605/0	111935- clearance lights on truck inop	01/09/23	C
J0434764/0	LH steer spring bushes	05/09/23	C
J0434994/0	Install new Navman	09/09/23	C
J0435292/0	111936 - A/C operation	14/09/23	C
J0435297/0	Rekit Ringfeeder	14/09/23	C
J0435443/0	Replace A/C condenser	18/09/23	C
J0437521/0	Ride height control valve	26/10/23	C
J0437773/0	RH body lock	31/10/23	C
J0437852/0	Repair LCM fault	02/11/23	C
J0437869/0	Replace seat covers	02/11/23	C
J0437881/0	Tyres replaced - Pos 1,2.-16094	02/11/23	C
J0437961/0	Replace wheel nut indicators	04/11/23	C
J0438420/0	Tyres replaced - Pos 9,10.-16210	13/11/23	C
P0068596/0	NHVR Annual Heavy Vehicle Inspection	14/11/23	C
J0438527/0	Tyres replaced - Pos 7,8.-16213	14/11/23	C
J0438684/0	Repair air leak at LHS of grill	16/11/23	C
J0438685/0	Hard to start & running rough	16/11/23	C
J0439073/0	Check low coolant level	24/11/23	C
J0439115/0	Replace LHR cab shock	24/11/23	C
J0439116/0	Replace lower intercooler pipe	24/11/23	C
J0439117/0	Replace LH drive shocks	24/11/23	C
P0069770/0	2400hr Service - (FM500)	28/11/23	C
J0439452/0	111939 - 12V power sockets	30/11/23	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0439532/0	Replace tailgate prop bearings	01/12/23	C
J0439679/0	111940 - 24V acc sockets	05/12/23	C
J0440836/0	Repair coolant hose leak	04/01/24	C
J0442233/0	111941 - Tarp not extending	01/02/24	C
J0442965/0	Replace steer brake pads	13/02/24	C
J0443866/0	111942 - New tarp pulleys	27/02/24	C
J0443882/0	Repair Tiltmeter wiring	27/02/24	C
J0444041/0	Replace eng oil filler pipe	29/02/24	C
J0444042/0	Replace both batteries (2)	29/02/24	C
J0444437/0	111943 - Scales not working	07/03/24	C
J0444691/0	111944 - Tarp not extending	12/03/24	C
J0445055/0	LH 1st drive wheel bearing	18/03/24	C
J0445064/0	LH 2nd axle pad wear sensor	18/03/24	C
J0445148/0	Tyre runout on - Pos 3.SS-16427	20/03/24	C
P0070897/0	600hr Service - (FM500)	26/03/24	C
J0445462/0	Tyre repaired - Pos 3.S/S-16432	26/03/24	C
J0445624/0	Replace LH side mirror	28/03/24	C
J0445698/0	Replace front engine mount	02/04/24	C
J0446483/0	111945 - Nylon air hose leak	15/04/24	C
J0447097/0	Tyre repaired - Pos 7.S/S-16485	27/04/24	C
J0447182/0	111946 - RH indicator fault	29/04/24	C
J0447263/0	111947 - Clearance light wiring	30/04/24	C
J0447288/0	Tyres replaced - Pos 1,2.-16485	01/05/24	C
J0449577/0	Centre cab marker light	11/06/24	C
J0450084/0	LH 2nd drive brake caliper	20/06/24	C
J0450315/0	Repair rego number plate	25/06/24	C
J0450621/0	111949 - Mudflap ripped off	28/06/24	C
J0450908/0	Replace Tarp Cables	03/07/24	C
J0450909/0	Replace RH steer guard bracket	03/07/24	C
J0451073/0	Disconnect trailer	05/07/24	C
S0002403/0	Safety Inspection 2024-2025	05/07/24	C
S0002404/0	Truck Washing 2024-2025	05/07/24	C
J0451248/0	111950 - Hookup hoist hose	10/07/24	C
J0451630/0	112476 - Exh temp sensor	18/07/24	C
J0451638/0	Replace exhaust flex pipe	18/07/24	C
J0452240/0	112477 - RH headlight globe	29/07/24	C
J0452414/0	Tyres replaced - Pos 7,8,9,10.	01/08/24	C
J0452760/0	LH 2nd drive brake locked on	07/08/24	C
P0072363/0	1200hr Service - (FM500)	09/08/24	C
J0453588/0	Tyres runout on - Pos 4	22/08/24	C
J0453590/0	Tyres replaced - Pos 3,4,5,6.	23/08/24	C
J0455107/0	112480 - Repair cab air hose	18/09/24	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0455113/0	Inspect front differential SOS	18/09/24	C
J0455617/0	Replace NOX Sensor	27/09/24	C
P0072904/0	NHVR Annual Heavy Vehicle Inspection	30/09/24	C
J0455704/0	Repair RH brake light wiring	30/09/24	C
J0456051/0	112481 - Clearance lights	08/10/24	C
J0456699/0	2nd Axle brake pads	21/10/24	C
P0073388/0	600hr Service - (FM500)	06/11/24	C
J0458490/0	112483 - Disconnect trailer	22/11/24	C
J0458559/0	112484 - Connected hose	25/11/24	C
J0459080/0	112485 - Hard to start	03/12/24	C
J0459335/0	112486 - Hydraulic coupling	06/12/24	C
J0459480/0	112487 - Navman not turning on	10/12/24	C
J0459628/0	Repair LH door blinker wiring	12/12/24	C
J0459629/0	112488 - Clutch replaced	12/12/24	C
J0460732/0	Replace Tarp Cables	13/01/25	C
J0461708/0	112490 - Navman cable	30/01/25	C
J0461841/0	1st Diff failure	03/02/25	C
J0462648/0	112491 - Coolant level minimum	17/02/25	C
J0462839/0	Replace headlight globe	20/02/25	C
J0463096/0	112493 - Steer tyre bald	24/02/25	C
J0463116/0	Tyres replaced - Pos 1,2.-15791	25/02/25	C
J0463313/0	Tyre punctured - Pos 7	27/02/25	C
J0463403/0	Replace air tank drain cord	28/02/25	C
J0463501/0	112494 - Steering column cable	03/03/25	C
J0463693/0	Replace steer guard bracket	06/03/25	C
J0464296/0	Tyre runout on - Pos 1.SS-15815	07/03/25	C
J0463867/0	Front & rear wheel alignment	10/03/25	C
J0464287/0	Tyres replaced - Pos 1,10.-15809	17/03/25	C
J0464561/0	Tyre repairs on - Pos 10.-15827	20/03/25	C
P0074727/0	2400hr Service - (FM500)	30/03/25	C
J0465224/0	RH steer spring eye bushes	01/04/25	C
J0466628/0	Replace number plates	29/04/25	C
J0466909/0	Replace fleet numbers	02/05/25	C
J0467174/0	112495 - RH clearance lights	07/05/25	C
J0468270/0	Calibrate weigh scales	27/05/25	C
J0469278/0	Tyre runout on - Pos 6.SS17061	13/06/25	C
J0469483/0	Tyre repairs on - Pos 6.SS17064	17/06/25	C
S0002732/0	Safety Inspection 2025-2026	04/07/25	N
S0002733/0	Truck Washing 2025-2026	04/07/25	N
J0471143/0	Replace tarp power plug	15/07/25	C
J0471154/0	Replace battery isolator	16/07/25	C
J0471573/0	Battery isolator lockout	22/07/25	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
P0076148/0	Turbo Replacement (FM13 & FH13 SCR)	30/07/25	C
J0473423/0	112497 - LH spotter mirror	26/08/25	C
J0475158/0	Check engine low power	19/09/25	C
J0475031/0	Decommission Truck	25/09/25	C
J0475084/0	Tyre runout on - Pos 14.SS16000	26/09/25	N
J0475823/0	Tyre runout on- Pos 1,2.SS17170	13/10/25	C