

Maintenance History Report

Report Generated on 21/10/25 08:11 AM

2161 Isuzu NPR200 with Hiab

Job No	Job Title	Start Date	Status
J0001215/0	Repair charge system for hi-ab	07/07/06	C
J0001375/0	Modify Tool Boxs	01/08/06	C
J0001375/2	Fit new E Stop to compressor	14/08/06	C
J0001375/1	5000 Klm Service	17/08/06	C
J0002050/0	September 06	01/09/06	C
J0002050/1	Jump Start Vehicle	19/09/06	C
J0002279/1	Jump start vehicle	01/10/06	C
J0002279/0	October 06	01/10/06	C
J0002711/0	November 06	01/11/06	C
J0002711/1	Repair reverse alarm	01/11/06	C
J0002711/2	Jump Start	21/11/06	C
J0003411/0	December 06	01/12/06	C
J0003411/2	Jump Start	01/12/06	C
J0003411/1	Repair A/C	01/12/06	C
J0003411/3	Repair door	21/12/06	C
J0004162/0	January 07	01/01/07	C
J0004162/1	Jump Start	03/01/07	C
J0004162/3	Repair rear accident damage	03/01/07	C
J0004162/2	Replace Front Windscreen	04/01/07	C
J0004162/4	Change fuel filters	15/01/07	C
J0004948/0	February 07	01/02/07	C
J0004948/1	Fix flag	14/02/07	C
J0005812/0	General repairs to truck	30/03/07	C
J0006511/0	April 07	01/04/07	C
J0005986/0	AB Service	03/04/07	C
J0006122/0	Registration Inspection	10/04/07	C
J0006511/1	Repair truck crane	23/04/07	C
J0006511/2	Repair Beacon	26/04/07	C
J0006874/0	Repair flat tyre	07/05/07	C
J0008284/0	June 07	01/06/07	C
J0008284/1	Service compressor	06/06/07	C
J0008284/2	Wash truck	26/06/07	C
J0008743/0	80,000 Klm Service	10/07/07	C
J0008652/0	Inspection of Portable Air Receiver	11/07/07	C
J0009916/0	Repair compressor motor	22/08/07	C
J0009976/0	Puncture repair	27/08/07	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0010575/0	Clean truck	03/09/07	C
J0010708/0	Clean vehicle	03/09/07	CA
J0010576/0	Install compressor	04/09/07	C
J0011140/0	Replace A/C belt	26/09/07	C
J0011271/0	Wash truck	04/10/07	C
J0011303/0	90,000 Klm Service	08/10/07	C
J0011595/0	Repair A/C	16/10/07	C
J0011915/0	Wash vehicle	26/10/07	C
J0012456/0	November 07	01/11/07	C
J0012456/1	Regas A/C	02/11/07	C
J0013210/0	December 07	01/12/07	C
J0013210/1	Change flat tyre and wash truck	05/12/07	C
J0014004/0	100,000 Klm Service	07/01/08	C
J0014604/0	Replace AM/FM radio	21/01/08	C
J0014861/0	Replace front tyres	24/01/08	C
J0014862/0	Clean vehicle	24/01/08	C
J0015377/0	Change compressor for tools	05/02/08	C
J0015583/0	Puncture repair	12/02/08	C
J0016080/0	Clean vehicle	29/02/08	C
J0017175/0	Repair flat tyre	19/03/08	C
J0016845/0	Fit tool box	29/03/08	C
J0017176/0	Replace tyres on rear	08/04/08	C
J0017726/0	Wash vehicle	21/04/08	C
J0018024/0	Rego check	01/05/08	C
J0018770/0	Refit compressor to body	26/05/08	C
J0019554/0	june 08	01/06/08	C
J0019554/1	check for brake fault	19/06/08	C
J0019656/0	Replace starter motor	24/06/08	C
J0019667/0	Replace windscreen	25/06/08	C
P0001471/0	130,000k service (Isuzu Service Truck)	01/07/08	C
J0020209/0	Reline rear brakes and fit new wheel cylinders	04/07/08	C
J0021115/0	Prepare for changeover of driver	16/07/08	C
J0021315/0	Repair headlight and check fault in interior light switch	22/07/08	C
J0026707/0	Replace starter motor	24/09/08	C
J0028200/0	Wash vehicle	06/10/08	C
J0028124/0	Clean and prepare for operations	10/10/08	C
J0031720/0	Repair flat tyre	20/11/08	C
P0002448/0	140,000k service (Isuzu Service Truck)	26/11/08	C
J0032570/0	Repaired number plate light	28/11/08	C
J0035150/0	Repair flat tyre	07/01/09	C
J0035627/0	Replace tyre pos 1	12/01/09	C
J0036110/0	front wheel alignment	21/01/09	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0036508/0	Replace tyre Pos 2	21/01/09	C
J0036618/0	Replace spark plug on air compressor	29/01/09	C
J0036669/0	Replace wheel chocks	30/01/09	C
J0036957/0	10,000klm service	04/02/09	C
J0038449/0	Manufacture & fit new earth strap, replace horn relay	16/02/09	C
J0038584/0	Repair wiring to hiab	23/02/09	C
J0038637/0	Replace AM/FM radio	24/02/09	C
J0040501/0	Repair faulty tail light / fuse blown	17/03/09	C
J0040929/0	Fix electrical problem (Moore & Baxter)	17/03/09	C
J0040930/0	Wire up 24-12v converter, replace wire on front RHS park light	17/03/09	C
J0042205/0	Drain water from fuel in air compressor, remove and clean spark plugs	01/04/09	C
P0003254/1	Repair both # plate lights	07/04/09	C
P0003254/0	10,000k service (Isuzu Service Truck)	07/04/09	C
J0043326/0	Remove & replace batteries and terminals	21/04/09	C
J0043972/0	Jump Start truck	27/04/09	C
J0043623/0	Rego inspection	28/04/09	C
J0044855/0	Replace pull start for compressor	11/05/09	C
J0045650/0	Fan belt cracked & splitting	20/05/09	C
P0003562/0	10,000k service (Isuzu Service Truck)	20/05/09	C
J0047003/0	Reverse lights on all the time	03/06/09	C
J0047589/0	Repair hiab by Nova Cranes	11/06/09	C
J0049610/0	Wash truck	29/06/09	C
J0049368/0	Rear batteries for hiab not charging	02/07/09	C
J0049745/0	Rear diff pinion seal leaking	06/07/09	C
J0049857/0	Repair wiring to R tail light & replace bulb in RF park light	06/07/09	C
J0050808/0	Repair damaged fuel tank	17/07/09	C
P0004041/0	A&B service (Isuzu Service Truck)	03/08/09	C
J0052433/0	Replace tyres - P1, 2, 3, 4, 5 & 6	04/08/09	C
J0052541/0	82228- Brakes squeaking	04/08/09	C
J0052647/0	82226 - Front wheels need alignment / pro axle	07/08/09	C
J0055454/0	Wash & detail truck	05/09/09	C
J0055560/0	Replace Seat Covers	09/09/09	C
J0055561/0	Body Repairs	09/09/09	C
J0055561/1	Hose Reel Missing	09/09/09	C
J0055561/2	Repair Roof Light Bar	09/09/09	C
J0055657/0	Fit UHF Radio	09/09/09	C
J0055863/0	Fit Reverse Alarm	11/09/09	C
P0004955/0	60,000k service (Isuzu Service Truck)	23/11/09	C
J0062187/0	Check clutch	30/11/09	C
J0064373/0	Repair overheating, drain and refill coolant, R&R fan hub and radiator cap	24/12/09	C
J0064994/0	Diff Has No Drive	06/01/10	C
J0065066/0	Repaired dash	07/01/10	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0071734/0	Prepare for operation	23/03/10	C
J0072704/0	Bleed fuel system	29/03/10	C
J0073093/0	Repair wiring for hiab & trailer plug	07/04/10	C
P0006176/0	Rego Inspection	30/04/10	C
J0076039/0	Air compressor oil leak	12/05/10	C
J0076080/0	Replace drive belt	13/05/10	C
J0076278/0	Fit wheel nut indicators	14/05/10	C
J0077339/0	Tacho not reading correctly	29/05/10	C
J0078102/0	Flat Batteries	07/06/10	C
P0006718/0	190,000k service (Isuzu NPR Truck)	25/06/10	C
J0080044/0	Check Brake Adjustment	29/06/10	C
J0080093/0	Prepare For Operations	29/06/10	C
J0080093/1	Return from Mt Thorley	29/06/10	C
J0080205/0	Fit Voltage Reducer For Trailer	01/07/10	C
J0080494/0	Service Hiab	05/07/10	C
J0080533/0	Replace Radio Hand Sets	05/07/10	C
J0081531/0	Adjust Brakes	15/07/10	C
J0081653/0	Set Up Lifting Equipment	15/07/10	C
J0082692/0	Dash Loose	29/07/10	C
J0083061/0	Relocate hiab isolation switch	03/08/10	C
J0083419/0	Replace Tool Box Lock	09/08/10	C
J0084517/0	Install Tie Down Points	20/08/10	C
J0088665/0	Replaced batteries	20/09/10	C
J0088575/0	Supply Tie Downs	14/10/10	C
J0089173/0	Number Plate Lights Not Working	20/10/10	C
P0008227/0	200,000k service (Isuzu NPRTruck)	20/10/10	C
J0089392/0	Truck Inspection (NCIG)	21/10/10	C
J0089338/0	Programme UHF radio Channels for NCIG	25/10/10	C
J0092277/0	Pressure Vessel Inspection	26/10/10	C
J0092296/0	Fit Phone Kit	29/11/10	C
J0093401/0	Replace Tool Box Lock	16/12/10	C
P0009508/0	60,000k service (Isuzu NPR Truck)	31/12/10	CA
J0094529/0	Flat batteries	04/01/11	C
J0095681/0	Check G V M Of Truck	14/01/11	C
J0096669/0	Radiator core split and heater core replaced	01/02/11	C
J0098072/0	Repair flat tyre Pos2	16/02/11	C
J0098177/0	Thermostats replaced	18/02/11	C
J0098178/0	HEA Inspection	18/02/11	C
P0009836/0	10,000k service (Isuzu NPRTruck)	18/02/11	C
J0098397/0	Dash lights staying on	22/02/11	C
J0098794/0	Replace Alternator	22/02/11	C
J0098680/0	LH mirror keeps moving around when driving	25/02/11	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0098681/0	LHR hiab leg seized not lining up for retaining pin	25/02/11	C
J0098682/0	Hand washing bottle needs replacing	25/02/11	C
J0098683/0	No jack in cab	25/02/11	C
J0098684/0	Drivers seat u/s	25/02/11	C
J0098686/0	Brakes noisy - shuddering truck getting harder to pull up	25/02/11	C
J0098689/0	Leak at fuel tank	25/02/11	C
J0098966/0	Unload & Wash Truck	25/02/11	C
J0100021/0	Supply jack	15/03/11	C
J0100278/0	Replace tyres Pos 1/2	15/03/11	C
P0010610/0	Rego Inspection	03/04/11	C
J0102154/0	Replace LH window glass	11/04/11	C
J0102982/0	Rear Brakes - replace	20/04/11	C
J0103028/0	Windscreen U/S	21/04/11	C
J0103907/0	Replace Windscreen	21/04/11	C
J0103857/0	Replace Batteries	05/05/11	C
J0105302/0	Replace damaged tyre	25/05/11	C
J0105558/0	Replace oxy & ace bottles on vehicle	30/05/11	C
J0105740/0	Vehicle Wont Start	30/05/11	C
J0105885/0	Air Conditioning Not Working	30/05/11	C
J0107297/0	Replace tyre Pos	18/06/11	C
J0107726/0	Repair flat tyre	22/06/11	C
J0115390/0	#2161 replace tyres pos 1,2 - Mara del.doc. 184903	06/09/11	C
P0013666/0	230,000k service (Isuzu NPRTruck)	22/09/11	C
J0117194/0	Replace tyres 3/4	27/09/11	C
J0118477/0	Supply Hand washing container	20/10/11	C
J0119760/0	Replace Fire Extinguisher	01/11/11	C
P0014457/0	10,000k service (Isuzu NPRTruck)	10/11/11	C
J0122286/0	Supply Vice	30/11/11	C
J0127929/0	Compressor pull start U/S	30/01/12	C
J0128618/0	Clutch bearing noisy	03/02/12	C
J0128682/0	Auxiliary batteries replaced	03/02/12	C
P0015863/0	250,000k service (Isuzu NPRTruck)	03/02/12	C
J0136452/0	Fit Water Tank & Storage Tray	18/04/12	C
J0136453/0	Replace front brakes	18/04/12	C
J0136516/0	Replace front tyres	19/04/12	C
J0137702/0	Replace windscreen	03/05/12	C
P0017182/0	Rego Renewal	03/05/12	C
J0140404/0	Install toolbox alarm	25/05/12	C
J0140427/0	LHF indicator U/S	25/05/12	C
P0017657/0	10,000k service (Isuzu NPRTruck)	25/05/12	C
J0140796/0	Compressor repairs	29/05/12	C
J0146953/0	Beacon, replaced	24/07/12	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0149195/0	Tyre replaced pos 4	07/08/12	C
J0148585/0	Replace Rear Tyre	10/08/12	C
P0019318/0	10,000k service (Isuzu NPRTruck)	14/08/12	C
J0148939/0	Seat covers torn , Replace	15/08/12	C
J0149321/0	Rear shackles rubbers,replaced	20/08/12	C
J0152135/0	Tyre repair pos 5	06/09/12	C
J0151912/0	Replace batteries	12/09/12	C
J0151913/0	Fuel sender,replaced	12/09/12	C
J0152748/0	Tyre repaired pos 4	17/09/12	C
J0154214/0	Puncture Repair Pos 2	06/10/12	C
J0154653/0	Tyre repaired pos 2	08/10/12	C
J0155788/0	Lights inop,repair	22/10/12	C
P0020619/0	10,000k service (Isuzu NPRTruck)	22/10/12	C
J0155696/0	Tyres replaced at pos 1,2	23/10/12	C
J0155826/0	Prepare for operations	24/10/12	C
J0156052/0	Starter motor,replaced	26/10/12	C
J0156611/0	Supply I.D. numbers	01/11/12	C
J0156774/0	Service Palfinger	02/11/12	C
J0161308/0	Thermostat replaced	18/12/12	C
P0023904/0	Rego Renewal	29/04/13	C
P0025364/0	10,000k service (Isuzu NPRTruck)	16/07/13	C
J0180357/0	Recover vehicle	29/07/13	C
J0180460/0	Engine overheated	30/07/13	C
J0181633/0	Exhaust leak	13/08/13	C
J0181634/0	Check for coolant leak	13/08/13	C
J0182306/0	Water temp gauge n/w	20/08/13	C
P0026489/0	60,000k service (Isuzu NPR Truck)	28/08/13	C
J0185766/0	Muffler replaced	03/10/13	C
J0185774/0	Repair number plate light	03/10/13	C
J0185775/0	Repair wirring to fuel water seperator	03/10/13	C
P0026490/0	300,000k service (Isuzu NPRTruck)	10/12/13	C
J0194635/0	Replace pos 3 & 4 tyres	24/01/14	C
J0194891/0	Tyres replaced pos 3,4	28/01/14	C
J0195054/0	Replace coolant bypass hose	30/01/14	C
P0029212/0	Annual Crane/VLC Inspection	01/02/14	C
J0198184/0	Replace Tyres Pos 1 & 2	04/03/14	C
J0198466/0	Tyres replaced pos 1,2	04/03/14	C
J0199374/0	Supply I.D. numbers	18/03/14	C
J0199445/0	Number plate lights not working	18/03/14	C
J0202026/0	Repair Chain Box Lid	16/04/14	C
P0029730/0	Rego Renewal	03/05/14	C
J0206055/0	Tyre flat	04/06/14	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
P0030754/0	310,000k service (Isuzu 4HF1)	11/07/14	C
J0209947/0	RHR Park light not working	16/07/14	C
J0210144/0	Tension wheels pos 5 , 6	18/07/14	C
J0217464/0	RH headlight , taillight N/W	07/10/14	C
J0217558/0	A/C evaporator blocked	08/10/14	C
J0218433/0	Drive tyre puncture	15/10/14	C
P0032683/0	3 Monthly Safety Inspection	01/11/14	C
P0032880/0	320,000k service (Isuzu 4HF1)	11/11/14	C
J0222421/0	Replace bent swaybar bolt	02/12/14	C
J0222428/0	R/H Reverse light	02/12/14	C
P0033888/0	Annual Crane/VLC Inspection	01/02/15	C
P0033889/0	3 Monthly Safety Inspection	01/02/15	C
J0227601/0	Drive belts replaced	12/02/15	C
J0227602/0	Engine mount brackets cracked	12/02/15	C
P0035220/0	Rego Renewal	17/04/15	C
P0035482/0	3 Monthly Safety Inspection	11/05/15	C
J0234783/0	Replace 24V Beacon	18/05/15	C
P0036449/0	330,000k service (Isuzu 4HF1)	21/07/15	C
J0241742/0	Repair Flat Tyre Pos 5	12/08/15	C
J0242925/0	LH rear view mirror broken	28/08/15	C
J0243003/0	Fire extinguisher service	29/08/15	C
J0245316/0	Hiab motor replaced	29/09/15	C
J0246951/0	Air Compressor Will Not Start	19/10/15	C
P0037811/0	3 Monthly Safety Inspection	30/10/15	C
J0249181/0	RHR mudguard bracket broken	12/11/15	C
J0249563/0	Check electrical system	17/11/15	C
J0250971/0	Condenser Fan Motor	02/12/15	C
J0252312/0	Supply Cargo Net	22/12/15	C
J0252316/0	Install Extra Tie Down Points	22/12/15	C
P0038934/0	Annual Crane/VLC Inspection	05/02/16	C
P0038935/0	3 Monthly Safety Inspection	05/02/16	C
P0039883/0	3 Monthly Safety Inspection	21/04/16	C
J0261851/0	Carry out rego	02/05/16	C
J0261913/0	Horn inop	02/05/16	C
P0039999/0	Rego Renewal	03/05/16	C
J0264046/0	Batteries x 2 replaced	30/05/16	C
J0264047/0	Headlight wiring changed from constantly on	30/05/16	C
J0268387/0	Replace tyres on Pos 3&4	26/07/16	C
J0268409/0	Tyres replaced - POS 3,4	27/07/16	C
P0041241/0	340,000k service (Isuzu 4HF1)	01/08/16	C
J0274030/0	Batteries flat	12/10/16	C
J0274487/0	Wash Truck And Detail	18/10/16	C

Status Codes
N - New
A - Active
P - Pending
C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
P0042337/0	3 Monthly Safety Inspection	04/11/16	C
J0276089/0	Oil leak at crane	09/11/16	C
J0276113/0	Tyres replaced,steer	10/11/16	C
J0276583/0	Batteries x 2 replaced	15/11/16	C
J0280294/0	A/C not cold	13/01/17	C
J0280295/0	Beacon inop	13/01/17	C
P0043361/0	350,000k service (Isuzu 4HF1)	03/02/17	C
P0043362/0	Annual Crane/VLC Inspection	03/02/17	C
J0282055/0	number plate ligt inop	07/02/17	C
J0282291/0	Clutch slave cylinder replaced	10/02/17	C
J0282746/0	Alternator replaced	16/02/17	C
J0283146/0	Washer bottle motor u/s	21/02/17	C
J0285149/0	Seat frame broken	17/03/17	C
J0286405/0	Rego check	03/04/17	CA
J0286643/0	Tyres x 2 replaced	03/04/17	C
P0044114/0	Rego Renewal	03/04/17	C
P0046358/0	360,000k service (Isuzu 4HF1)	05/09/17	C
J0303713/0	Replace windscreen	07/09/17	C
J0304105/0	Gearbox grinding 2nd gear	12/09/17	C
J0304461/0	Repair Seat Mount	13/09/17	C
J0305018/0	Prepare for operation	25/09/17	C
J0307010/0	Paint & body repairs	20/10/17	C
J0307757/0	Replace LHS mirror	01/11/17	C
P0049618/0	370,000k service (Isuzu 4HF1)	07/12/17	C
J0313082/0	Install Tie Down Points	22/01/18	C
P0047656/0	Annual Crane/VLC Inspection	01/02/18	C
P0052051/0	380,000k service (Isuzu 4HF1)	23/02/18	C
J0316162/0	Replace Alternator	28/02/18	C
J0318691/0	Drivers seat belt U/S	06/04/18	C
J0318986/0	Drivers seat U/S	11/04/18	C
P0048336/0	Rego Renewal	03/05/18	C
J0327827/0	Mudguards replaced,front	16/08/18	C
J0327828/0	Starter motor replaced	16/08/18	C
J0327829/0	Steering box top seal replaced	16/08/18	C
J0327830/0	Engine fan replaced	16/08/18	C
J0330019/0	Repair wiring to trailer plug	17/09/18	C
J0331447/0	Repair Rear Body Drop Sides	08/10/18	C
J0331910/0	Fabricate Pipe Rack	15/10/18	C
J0333164/0	Air cond not cold	31/10/18	C
P0051346/0	Annual Crane/VLC Inspection	01/02/19	C
J0339908/0	Change Flat Tyre Pos 2	15/02/19	C
J0343191/0	Fit phone kit	01/04/19	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
J0343714/0	Reverse switch & Neaural switch u/s	09/04/19	C
J0343950/0	Various stickers u/s	11/04/19	C
P0052021/0	Rego Renewal	03/05/19	C
J0345392/0	Fit Number plates	07/05/19	C
J0353437/0	Replace Batteries	04/09/19	C
J0355225/0	Replace seat belt buckle	01/10/19	C
J0355275/0	Repair temp gauge sender	01/10/19	C
J0355276/0	Clutch pedal rubber replace	01/10/19	C
P0054128/0	390,000k service (Isuzu 4HF1)	16/10/19	C
J0358428/0	Check-In Repairs	19/11/19	C
J0358371/0	Check-In Inspection	19/11/19	C
J0358972/0	Replace ID numbers	27/11/19	C
P0055214/0	Annual Crane/VLC Inspection	01/02/20	C
J0363110/0	Tyre Puncture Repairs	13/02/20	C
J0366647/0	Replace Rain Hat	07/04/20	C
P0056019/0	400,000klm Service (Isuzu 4HF1)	17/04/20	C
P0056016/0	Rego Renewal	03/05/20	C
J0372180/0	Water In Fuel Light On	01/07/20	C
J0373221/0	LHR Outer Tyre Repair	17/07/20	C
J0377052/0	Tyres x 4 replaced	15/09/20	C
P0058244/0	410,000k service (Isuzu 4HF1)	23/10/20	C
P0058934/0	Annual Crane/VLC Inspection	01/02/21	C
J0386275/0	Jumpstart flat batteries	02/03/21	C
J0388079/0	Replace LHR blinker lens	01/04/21	C
J0388164/0	Tyres replaced Pos 5,6	06/04/21	C
P0059647/0	420,000k service (Isuzu 4HF1)	10/04/21	C
P0059881/0	Rego Renewal	03/05/21	C
J0390696/0	Install GPS	19/05/21	C
S0001670/0	Truck Washing	22/07/21	C
P0061482/0	430,000k service (Isuzu 4HF1)	18/09/21	C
J0397968/0	LHR outer tyre replace	22/09/21	C
J0401090/0	Engine wont turn off	19/11/21	C
J0401091/0	Repair speedometer wiring	19/11/21	C
J0403057/0	Batteries flat	06/01/22	C
J0403557/0	Check A/C n/w	17/01/22	C
J0403558/0	Drivers seat broken	17/01/22	C
P0062570/0	Annual Crane/VLC Inspection	01/02/22	C
J0407167/0	Instrument cluster not working	25/03/22	C
J0407738/0	LH rear veiw mirror	06/04/22	C
P0063548/0	Rego Renewal	03/05/22	C
J0409107/0	RH stop light N/W	06/05/22	C
J0411014/0	Refit spare wheel & tyre	11/06/22	C

Status Codes
 N - New
 A - Active
 P - Pending
 C - Completed

Maintenance History Report

Job No	Job Title	Start Date	Status
P0063972/0	440,000k service (Isuzu 4HF1)	12/06/22	C
S0001731/0	Truck Washing 2022-2023	01/07/22	C
J0420629/0	Wont start	06/12/22	C
J0420992/0	AM/FM radio wiring	12/12/22	C
J0421166/0	Replaced batteries (2)	15/12/22	C
J0422388/0	Ram bolt broken/Missing	17/01/23	C
P0066315/0	Annual Crane/VLC Inspection	01/02/23	C
J0425244/0	Charge flat batteries	07/03/23	C
J0427698/0	Replace fuel tank straps	22/04/23	C
J0428104/0	Tyres replaced Pos 1	02/05/23	C
J0429216/0	Repair engine oil leak	23/05/23	C
J0430916/0	Check clutch slipping	22/06/23	C
S0002058/0	Truck Washing 2023-2024	01/07/23	C
P0068409/0	450,000k service (4HF1)	03/08/23	C
J0434052/0	Adjust clutch slipping	23/08/23	C
J0436404/0	Replace flat batteries	05/10/23	C
J0437894/0	key locked in vehicle	02/11/23	C
J0439128/0	Check engine oil low	27/11/23	C
J0443079/0	Replace engine belts	15/02/24	C
J0443085/0	Replace rear shocks	15/02/24	C
J0443103/0	Secure crane control box	15/02/24	C
P0070416/0	460,000k service (4HF1)	04/03/24	C
J0444906/0	Tyre puncture repairs	15/03/24	C
J0446220/0	Check engine oil low	11/04/24	C
P0071326/0	Rego Renewal	23/04/24	C
P0071522/0	Annual Crane/VLC Inspection	14/05/24	C
J0449189/0	Engine oil & coolant low	04/06/24	C
J0449737/0	Change UHF radio	14/06/24	C
J0449789/0	Temp guage switch	15/06/24	C
S0002389/0	Truck Washing 2024-2025	05/07/24	C
P0072212/0	470,000k service (4HF1)	25/07/24	C
J0452166/0	Repair beacon wiring	26/07/24	C
J0454908/0	Oil spray over engine	16/09/24	C
J0457665/0	Regas A/C system	06/11/24	C
J0460401/0	Jumpstart flat batteries	07/01/25	C
P0074309/0	Rego Renewal	30/01/25	C
P0074308/0	480,000k service (4HF1)	04/02/25	N
J0463136/0	Tyre tube replaced	25/02/25	C
J0464957/0	Replaced batteries (3)	27/03/25	C
P0076416/0	Annual Crane/VLC Inspection	19/06/25	N
S0002718/0	Truck Washing 2025-2026	04/07/25	N

Status Codes
N - New
A - Active
P - Pending
C - Completed