

Work Order History Report

22-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		Plant Hire 51 Cat D3K2 LGP dozer used 2021					
	54061	Sandblast and paint unit - hrs	12/03/2025 7:	Hours	.00	.00	\$11751.80
	54008	Tenkate Upgrades & Pre-Hire Inspection - 670 hrs - Rust proof machine, spiral wrapped hoses, Fabricated & Paint beacon mount. Sampled all compartments. replace all fluids & engine oil filter & hydraulic oil filter, Fit missing engine door bolts. replace missing track frame cover. Replaced FM radio.	11/04/2025 6:	Hours	.00	.00	\$3508.01
	54287	Replaced air & fuel filters - 670 hrs, replace seized secondary fuel filter housing.	9/06/2025 12:	Hours	.00	.00	\$873.06
		: <u>3</u>	Asset Total:	1136	0.0	0.0	\$16,132.87
		: <u>3</u>	Parent Total:	TPH	0.0	0.0	\$16,132.87
		Grand Total <u><u>3</u></u>			0.0	0.0	\$16,132.87