

Asset Code :		PM78		XQ08CB 2016 Kenworth K200		Operation No :													
Registration :		XQ08CB		KEN		K200													
Work Order		00001412		Work Order Date :		06/11/2016		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration					
Service Code:		WEICAL		Weight Gauge Calibration		Meter Reading :		0				Units		Rate		Extension			
Task Code		Employee		Product Code		Warehouse		Category		Supplier		Invoice		Details					
AIRG 15.75 & WB 15.8																Total for Service		0.00	
																Total for Work Order		0.00	
Work Order		00001524		Work Order Date :		15/11/2016		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration					
Service Code:		WEICAL		Weight Gauge Calibration		Meter Reading :		0				Units		Rate		Extension			
Task Code		Employee		Product Code		Warehouse		Category		Supplier		Invoice		Details					
Air gauge 16.25. WB 16.																Total for Service		0.00	
																Total for Work Order		0.00	
Work Order		00001527		Work Order Date :		18/11/2016		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration					
Service Code:		WEICAL		Weight Gauge Calibration		Meter Reading :		0				Units		Rate		Extension			
Task Code		Employee		Product Code		Warehouse		Category		Supplier		Invoice		Details					
Airgauge 13.00 WB 12.26.																Total for Service		0.00	
																Total for Work Order		0.00	
Work Order		00002194		Work Order Date :		18/11/2016		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration					
Service Code:		WEICAL		Weight Gauge Calibration		Meter Reading :		0				Units		Rate		Extension			
Task Code		Employee		Product Code		Warehouse		Category		Supplier		Invoice		Details					
AIR GAUGE 13.00 WB 12.26																Total for Service		0.00	
																Total for Work Order		0.00	
Work Order		00001587		Work Order Date :		19/11/2016		Repair Location :		EX0103		Yatala Workshop Exodas		Repairs					
Service Code:		GEN		General Repair		Meter Reading :		160,606				Units		Rate		Extension			
Task Code		Employee		Product Code		Warehouse		Category		Supplier		Invoice		Details					
FLUSHED ADBLUE LINES REPLACED INLINE FILTER IN FITTING CLEANED INJECTOR NOZZLE TOOK TO BROWN AND HURLEY PUT ON LAPTOP TO CHECK AFTER TREAT LIGHT STILL ON ADVISED IT WILL TURN OFF AFTER APPROX 1 HOUR OF DRIVING																Total for Service		0.00	
																Total for Work Order		0.00	
Work Order		00001529		Work Order Date :		22/11/2016		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration					
Service Code:		WEICAL		Weight Gauge Calibration		Meter Reading :		0				Units		Rate		Extension			
Task Code		Employee		Product Code		Warehouse		Category		Supplier		Invoice		Details					
Airgauge 14. WB 14.																Total for Service		0.00	
																Total for Work Order		0.00	
Work Order		00001538		Work Order Date :		24/11/2016		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5					

Work Order Service History

Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	165,694	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
'A' service completed.							

Total for Service 0.00

Total for Work Order 0.00

Work Order	00001711	Work Order Date :	07/12/2016	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------

Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	177,101	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

'A' service completed. Topped up engine oil bottle.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00001789	Work Order Date :	13/12/2016	Repair Location :	EX0103	Yatala Workshop Exodas	Eco Wind Service
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-------------------------

Service Code:	ECO	Eco Wind Service	Meter Reading :	660	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

Sleeper Air service completed.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00001856	Work Order Date :	17/12/2016	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------

Service Code:	CUMBE5	B Service Cummins E5	Meter Reading :	185,897	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

'B' SERVIC ECOMPLETED. DG KIT IS COMPLETE.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00001899	Work Order Date :	17/12/2016	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------------

Service Code:	TYRES	Tyres Service - Trailer	Meter Reading :	183,988	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

2x new Yoko steers fitted and balanced.

TYR295/80YOK	15	TYRMOR01	EX00000359	17/12/16	Yokohama 295/80R22.5,QV12DC 78	0.00	481.82	0.00
--------------	----	----------	------------	----------	--------------------------------	------	--------	------

TYR295/80YOK	15	TYRMOR01	10755	17/12/16	Yokohama 295/80R22.5,QV12DC 78	2.00	481.82	963.64
--------------	----	----------	-------	----------	--------------------------------	------	--------	--------

Total : Tyres 963.64

Total for Service 963.64

Total for Work Order 963.64

Work Order	00002009	Work Order Date :	04/01/2017	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------

Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	195,840	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

'A' SERVICE COMPLETED. TOPPED UP ENGINE OIL.
FIRE EXT #90 EXP 31/05/2017

Total for Service 0.00

Total for Work Order 0.00

Work Order	00002161	Work Order Date :	14/01/2017	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------

Service Code:	GEN	General Repair	Meter Reading :	208,092	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

S/F 2X A/C DASH VENTS

Work Order Service History

						Total for Service		0.00
						Total for Work Order		0.00
Work Order	00002192	Work Order Date :		21/01/2017	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :		0		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension
AIR GAUGE 14.00								
WB 14.00								
						Total for Service		0.00
						Total for Work Order		0.00
Work Order	00002183	Work Order Date :		23/01/2017	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :		209,577		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension
Replaced LHS head light and 2 park lights								
'A' SERVICE COMPLETED. REPLACED 2X PARK GLOBES AND 1X HEADLIGHT GLOBE								
						Total for Service		0.00
						Total for Work Order		0.00
Work Order	00002202	Work Order Date :		30/01/2017	Repair Location :	EX0103	Yatala Workshop Exodas	WARRANTY
Service Code:	GEN	General Repair		Meter Reading :		203,172		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension
WARRANTY REPAIR. B&H YATALA R/R LHF DRIVE SHOCKY.								
						Total for Service		0.00
						Total for Work Order		0.00
Work Order	00002229	Work Order Date :		01/02/2017	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5
Service Code:	CUMBE5	B Service Cummins E5		Meter Reading :		217,024		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension
'B' SERVICE COMPLETED. TIGHTENED LOAD LIGHTS AND MIRRORS.								
						Total for Service		0.00
						Total for Work Order		0.00
Work Order	00002646	Work Order Date :		15/02/2017	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :		227,584		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension
SERVICE COMPLETED. LHR DRIVE SHOCKY LEAKING.R/RHUB CAP AND EBS PLUG.								
						Total for Service		0.00
						Total for Work Order		0.00
Work Order	00003013	Work Order Date :		27/02/2017	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :		236,532		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension
AIR LEAK UNDER THE SEAT								
						Total for Service		0.00
						Total for Work Order		0.00
Work Order	00003108	Work Order Date :		02/03/2017	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
Service Code:	GEN	General Repair		Meter Reading :		241,386		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension

Work Order Service History

EBS/ABS PLUG FITTED. B&H YATALA R/R LHR DRIVE SHOCKY. B&H YATALA REPAIRED VOLTAGE GAUGE.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00003170	Work Order Date :	10/03/2017	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5			
Service Code:	CUMBE5	B Service Cummins E5		Meter Reading :		248,958		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
FLYWHEEL HOUSING LEAKING, WILL MONITOR.										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00003350	Work Order Date :	27/03/2017	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :		259,594		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
B&H YATALA REPLACED DISTORTED TANK STRAP RUBBERS, AND FIXED ESC CODE CONERN.										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00003830	Work Order Date :	28/04/2017	Repair Location :	EX0103	Yatala Workshop Exodas	Exodas Annual Roadworthy NHVAS			
Service Code:	EXOINS	Exodas Annual Roadworthy NHVAS		Meter Reading :		283,057		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
PASSED										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00003831	Work Order Date :	28/04/2017	Repair Location :	EX0103	Yatala Workshop Exodas	C Service Cummins E5			
Service Code:	CUMCE5	C Service Cummins E5		Meter Reading :		283,057		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
TANK STRAP RUBBERS U/S, exhuast flex leak,MANIFOLD LEAK. FLUSHED AD BLUE SYSTEM										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00004084	Work Order Date :	17/05/2017	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :		293,416		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
REPLACED FUSE IN CIGARETTE LIGHTER LUBED SEAT PINIONS										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00004239	Work Order Date :	26/05/2017	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :		301,194		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
INPUT SHAFT LEAKING ON GEARBOX (WARRANTY) REPLACE TRAILER PLUG REPAIRED HOSES FIRE EXP 05/17										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00004556	Work Order Date :	14/06/2017	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------	--	--	--

Work Order Service History

Service Code:		CUMBE5	B Service Cummins E5			Meter Reading :		315,897			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension
	FIRE EXP 5/17 - NONE IN STOCK TO UPDATE										
	REAR MAIN SEAL LEAKING (WARRANTY)										
	EXHAUST MANIFOLD GASKETS (WARRANTY)										
	ENGINE OIL DIPSTICK NEEDS RECALIBRATING (WARRANTY)										
									Total for Service		0.00
									Total for Work Order		0.00

Work Order		00004622		Work Order Date :		16/06/2017		Repair Location :		EX0103		Yatala Workshop Exodas		Tyres Service		
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		0						
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
NO CHARGE INVOICE																
														Total for Service		0.00
														Total for Work Order		0.00

Work Order		00004925		Work Order Date :		10/07/2017		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5				
Service Code:		CUMAE5		A Service Cummins E5		Meter Reading :		337,375				Units		Rate		Extension		
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details										
SERVICE COMPLETED. PARK LIGHT GLOBES R/R. LOCKER BOXES WERE LOCKED, UNABLE TO CHECK DG KIT AND FIRE EXTINGUISHER. INTERNAL RR RAISED 00000258																		
															Total for Service		0.00	
Service Code:		DEFECT		Defect Repair		Meter Reading :		0				Units		Rate		Extension		
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details										
Reported Defect :- Defect Code : 00000018 Defect Reference : 4086 Date : 19/05/2017 Description of Defect : PARKLIGHT OUT ON LEFT RONT OF TRUCK. CURTAINS NEED ATTENTION. RIP IS GETTING LONGER																		
															Total for Service		0.00	
															Total for Work Order		0.00	

Work Order		00005277		Work Order Date :		29/07/2017		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5					
Service Code:		CUMAE5		A Service Cummins E5		Meter Reading :		357,767				Units		Rate		Extension			
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details											
SERVICE COMPLETED. SALINE REPLACED, EXP 28/02/2020																Total for Service		0.00	
Service Code:		DEFECT		Defect Repair		Meter Reading :		357,767				Units		Rate		Extension			
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details											
Reported Defect :-																			
Defect Code : 00000018																			
Defect Reference : 4086																			
Date : 19/05/2017																			
Description of Defect :																			
PARKLIGHT OUT ON LEFT RONT OF TRUCK.																			
CURTAINS NEED ATTENTION. RIP IS GETTING LONGER																			
PARK LIGHT WORKING																			

Work Order Service History

										Total for Service		0.00			
										Total for Work Order		0.00			
Work Order		00005325		Work Order Date :		01/08/2017		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		357,767					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details		Units	Rate	Extension			
		33000084		15	BRI AUS01	EX00002274	01/08/17	FIT TBR TYRE,PM78		0.00	0.00	0.00			
		77000194		15	BRI AUS01	EX00002274	01/08/17	case stock 295/80-22.5,PM78		0.00	20.00	0.00			
		TYRRUN	YAT	15			01/08/17	Tyre Runouts		1.00	0.00	0.00			
		33000084		15	BRI AUS01	4420370346	01/08/17	FIT TBR TYRE,PM78		1.00	0.00	0.00			
		77000194		15	BRI AUS01	4420370346	01/08/17	case stock 295/80-22.5,PM78		-1.00	20.00	-20.00			
										Total : Tyres				-20.00	
										Total for Service				-20.00	
										Total for Work Order				-20.00	
Work Order		00005376		Work Order Date :		05/08/2017		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		360,854					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details		Units	Rate	Extension			
3 TYRES HELD FOR RUN OUTS															
		33000084		15	BRI AUS01	EX00002304	05/08/17	FIT TBR TYRE,PM78		0.00	0.00	0.00			
		33000370		15	BRI AUS01	EX00002304	05/08/17	TYRE HELD FOR RUNOUT,PM78		0.00	0.00	0.00			
		77000180		15	BRI AUS01	EX00002304	05/08/17	CASE STOCK 11-22.5,PM78		0.00	20.00	0.00			
		11002831	YAT	15			05/08/17	TYRE 11R22.5 146/143L		8.00	495.00	3,960.00			
		77000180		15	BRI AUS01	4420370730	05/08/17	CASE STOCK 11-22.5,PM78		-5.00	20.00	-100.00			
		33000370		15	BRI AUS01	4420370730	05/08/17	TYRE HELD FOR RUNOUT,PM78		3.00	0.00	0.00			
		33000084		15	BRI AUS01	4420370730	05/08/17	FIT TBR TYRE,PM78		8.00	0.00	0.00			
										Total : Tyres				3,860.00	
										Total for Service				3,860.00	
										Total for Work Order				3,860.00	
Work Order		00005419		Work Order Date :		08/08/2017		Repair Location :		EX0103		Yatala Workshop Exodas		B Service Cummins E5	
Service Code:		CUMBE5		B Service Cummins E5				Meter Reading :		366,485					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details		Units	Rate	Extension			
REAR MAIN SEAL STILL NEEDS WARRANTY REPLACING.															
										Total for Service				0.00	
										Total for Work Order				0.00	
Work Order		00005471		Work Order Date :		10/08/2017		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		366,485					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details		Units	Rate	Extension			
		33000084		15	BRI AUS01	EX00002358	10/08/17	FIT TBR TYRE,PM78		0.00	0.00	0.00			
		33000051		15	BRI AUS01	EX00002358	10/08/17	BALANCE TBR,PM78		0.00	25.00	0.00			
		11001553	YAT	15			10/08/17	TYRE 295/80R22.5 152/148M BS R150		2.00	494.00	988.00			
		33000084		15	BRI AUS01	4420371031	10/08/17	FIT TBR TYRE,PM78		2.00	0.00	0.00			
		33000051		15	BRI AUS01	4420371031	10/08/17	BALANCE TBR,PM78		2.00	25.00	50.00			

Work Order Service History

Total : Tyres	1,038.00
Total for Service	1,038.00
Total for Work Order	1,038.00

Work Order		00005602		Work Order Date :		21/08/2017		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair	
Service Code:		GEN		General Repair				Meter Reading :		0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details					Units	Rate	Extension	
	MAIN ROADS DEFECT HVN0449727.														
	HEADLIGHT BLOWN.														
	SELF CLEARING DEFECT.														
	FORMAL WARNING.														

Total for Service	0.00
Total for Work Order	0.00

Work Order		00005761		Work Order Date :		28/08/2017		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration	
Service Code:		WEICAL		Weight Gauge Calibration				Meter Reading :		0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details					Units	Rate	Extension	
	AIR GAUGE		11.00												
	ADJUSTED														
	WEIGHBRIDGE		10.24												

Total for Service	0.00
Total for Work Order	0.00

Work Order		00005852		Work Order Date :		06/09/2017		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		391,652					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details					Units	Rate	Extension	
PRESSURE TESTED COOLANT SYSTEM.															

Total for Service	0.00
--------------------------	-------------

Service Code:		DEFECT		Defect Repair			Meter Reading :		0				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension

Reported Defect :-
Defect Code : 00000382
Defect Reference : 4089
Date : 15/08/2017
Description of Defect :
SPEEDO STOPS WORKING INTERMITTANTLY.
Reported Defect :-
Defect Code : 00000383
Defect Reference : 4089
Date : 15/08/2017
Description of Defect :
ENGINE BRAKE STOPS WORKING INTERMITTANTLY
Reported Defect :-
Defect Code : 00000384
Defect Reference : 4089
Date : 18/08/2017
Description of Defect :
TRUCK HAS NO POWER, IT STRUGGLES TO REACH 100KMS.
ONT HOLD SPEED ON A FLAT ROAD.

Work Order Service History

Reported Defect :-
 Defect Code : 00000397
 Defect Reference : 4090
 Date : 18/08/2017
 Description of Defect :
 LHS HEADLIGHT BLOWN AGAIN.
 SPARE GLOBES NEEDED.
 COULD NOT FAULT.
 COULD NOT FAULT

Reported Defect :-
 Defect Code : 00000384
 Defect Reference : 4089
 Date : 18/08/2017
 Description of Defect :
 TRUCK HAS NO POWER, IT STRUGGLES TO REACH 100KMS.
 ONT HOLD SPEED ON A FLAT ROAD.
 COULD NOT FAULT
 FIT NEW GLOBE.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00006127	Work Order Date :	23/09/2017	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	404,814					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
		SERVICE COMPLETED.								
		REAR MAIN ENGINE SEAL NEEDS REPLACING URGENTLY.								

Total for Service 0.00

Total for Work Order 0.00

Work Order	00006255	Work Order Date :	04/10/2017	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :	0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
		ADJUSTED AIR GAUGE	14.00							
		WEIGHBRIDGE	13.50							

Total for Service 0.00

Total for Work Order 0.00

Work Order	00006400	Work Order Date :	11/10/2017	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5			
Service Code:	CUMBE5	B Service Cummins E5		Meter Reading :	417,490					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
		SERVICE COMPLETED.								
		REPLACED BATTERY CLAMP.								
		REAR MAIN ENGINE SEAL STILL LEAKING.								

Total for Service 0.00

Service Code:	DEFECT	Defect Repair		Meter Reading :	0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension

Work Order Service History

Reported Defect :-
Defect Code : 00000382
Defect Reference : 4089
Date : 15/08/2017
Description of Defect :
SPEEDO STOPS WORKING INTERMITTANTLY.

COULD NOT FAULT.
Reported Defect :-
Defect Code : 00000383
Defect Reference : 4089
Date : 15/08/2017
Description of Defect :
ENGINE BRAKE STOPS WORKING INTERMITTANTLY

DID NOT FAULT
Reported Defect :-
Defect Code : 00000384
Defect Reference : 4089
Date : 18/08/2017
Description of Defect :
TRUCK HAS NO POWER, IT STRUGGLES TO REACH 100KMS.
ONT HOLD SPEED ON A FLAT ROAD.

ROAD TESTED, ALL OK.
Reported Defect :-
Defect Code : 00000397
Defect Reference : 4090
Date : 18/08/2017
Description of Defect :
LHS HEADLIGHT BLOWN AGAIN.
SPARE GLOBES NEEDED.

SUPPLIED.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00006507	Work Order Date :	16/10/2017	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
	AIR GAUGE		10.00							
	ADJUSTED									
	WEIGHBRIDGE		9.98							
										Total for Service 0.00
										Total for Work Order 0.00
Work Order	00006552	Work Order Date :	24/10/2017	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
	FITTED A NEW EBS PLUG									
										Total for Service 0.00

							Total for Work Order	0.00
Work Order	00006661	Work Order Date :	30/10/2017	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5	
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	433,111			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension
SERVICE COMPLETED. REPLACED LHS LOW/HIGH BEAM GLOBE. REAR MAIN SEAL STILL LEAKING.								Total for Service 0.00
							Total for Work Order	0.00
Work Order	00006742	Work Order Date :	03/11/2017	Repair Location :	EX0103	Yatala Workshop Exodas	Eco Wind Service	
Service Code:	ECO	Eco Wind Service		Meter Reading :	1,670			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension
SLEEPER AIR SERVICED. CLEANED AIR FILTER. TUNED FUEL REGULATOR.								Total for Service 0.00
							Total for Work Order	0.00
Work Order	00007097	Work Order Date :	29/11/2017	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5	
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	456,372			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension
SERVICE COMPLETED. REPLACED AFTER TREATMENT NOX SENSOR, (2nd HAND STOCK) ADJUSTED THE CLUTCH.								Total for Service 0.00
							Total for Work Order	0.00
Work Order	00007373	Work Order Date :	19/12/2017	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5	
Service Code:	CUMBE5	B Service Cummins E5		Meter Reading :	474,260			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension
SERVICE COMPLETED. REPLACED FITTING ON THE THROW OUT BEARING. FITTED THE NEW MAINTENANCE LABEL. COOLANT LEAK AT RHS OF HEAD (WTY).								Total for Service 0.00
							Total for Work Order	0.00
Work Order	00007697	Work Order Date :	29/12/2017	Repair Location :	EX0103	Yatala Workshop Exodas	Warranty Work	
Service Code:	DEFECT	Defect Repair		Meter Reading :	0			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units Rate Extension
Reported Defect :- Defect Code : 00000258 Defect Reference : INTERNAL RR Date : 10/07/2017 Description of Defect : REAR MAIN SEAL LEAKING (WARRANTY) COMPLETED BY B&H YATALA 29/12/2017								

Work Order Service History

Reported Defect :-

Defect Code : 00000860

Defect Reference : W/O 7373

Date : 19/12/2017

Description of Defect :

COOLANT LEAK AT RHS OF HEAD (WTY).

REPAIRED BY B&H YATALA 29/12/2017

Service Code: WARRANT Warranty Work							Meter Reading :	480,000	Total for Service 0.00		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension
BROWN & HURLEY YATALA REPAIRED THE ENGINE REAR MAIN SEAL LEAK.											
AND BROWN & HURLEY YATALA REPAIRED THE COOLANT LEAK.											
							Total for Service 0.00				
							Total for Work Order 0.00				

Work Order		00007646		Work Order Date :		09/01/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair	
Service Code:		GEN		General Repair				Meter Reading :		483,958					
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension	
R/R GOVENOR VALVE															
R/R WIPER BLADES															
												Total for Service		0.00	
												Total for Work Order		0.00	

Work Order		00007659		Work Order Date :		09/01/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair	
Service Code:		GEN		General Repair				Meter Reading :		0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
R/R AERIAL AND CABLE FOR UHF.															
												Total for Service		0.00	
												Total for Work Order		0.00	

Work Order		00007785		Work Order Date :		11/01/2018		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration	
Service Code:		WEICAL		Weight Gauge Calibration				Meter Reading :		0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
	AIR GAUGE	16.25													
	ADJUSTED	16.00													
	WEIGHBRIDGE	16.00													
												Total for Service		0.00	
												Total for Work Order		0.00	

Work Order		00007857		Work Order Date :		18/01/2018		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5		
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		495,125				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									
SERVICE COMPLETED.																
REPLACED LHR TAIL LIGHT.																
LHF SHOCKY LEAKING OIL.																
														Total for Service		0.00

Service Code: DEFECT Defect Repair							Meter Reading :	0			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension

Work Order Service History

Reported Defect :-

Defect Code : 00000849

Defect Reference : 5966

Date : 16/12/2017

Description of Defect :

'B' SERVICE DUE AT 614,000KMS.

INCORRECT DETAIL

Total for Service 0.00

Total for Work Order 0.00

Work Order	00008042	Work Order Date :		29/01/2018	Repair Location :		EX0103	Yatala Workshop Exodas	General Repair/Maintenance		
Service Code:		TYRES	Tyres Service - Trailer		Meter Reading :		497,896		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				
WHEEL ALIGNMENT CARRIED OUT.											
STEER TYRE ROTATION CARRIED OUT.											
		WHEALI		15	dllas01	EX00004008	29/01/18	Wheel Alignment,PM78	0.00	450.00	0.00
		TYRROT		15	dllas01	EX00004008	29/01/18	Tyre Rotated,PM78	0.00	30.00	0.00
		WHEALI		15	dllas01	Q57453	29/01/18	Wheel Alignment,PM78	1.00	450.00	450.00
		TYRROT		15	dllas01	Q57453	29/01/18	Tyre Rotated,PM78	1.00	30.00	30.00
Total : Tyres											480.00
Total for Service											480.00
Total for Work Order											480.00
Work Order	00008072	Work Order Date :		31/01/2018	Repair Location :		EX0103	Yatala Workshop Exodas	A Service Cummins E5		
Service Code:		CUMAE5	A Service Cummins E5		Meter Reading :		499,673		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				
SERVICE COMPLETED.											
Total for Service											0.00
Total for Work Order											0.00
Work Order	00008073	Work Order Date :		31/01/2018	Repair Location :		EX0103	Yatala Workshop Exodas	Eco Wind Service		
Service Code:		ECO	Eco Wind Service		Meter Reading :		2,230		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				
SERVICE COMPLETED.											
Total for Service											0.00
Total for Work Order											0.00
Work Order	00008287	Work Order Date :		14/02/2018	Repair Location :		EX0103	Yatala Workshop Exodas	A Service Cummins E5		
Service Code:		CUMAE5	A Service Cummins E5		Meter Reading :		511,246		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				
SERVICE COMPLETED.											
TOPPED UP ENGINE OIL.											
Total for Service											0.00
Service Code:		DEFECT	Defect Repair		Meter Reading :		0		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				

REPLACED TYRES. NOW MONITOR.

Total for Work Order	0.00
-----------------------------	-------------

Total for Work Order	0.00
-----------------------------	-------------

Total for Work Order	948.00
-----------------------------	---------------

Total for Work Order	0.00
-----------------------------	-------------

Service Code:		DEFECT		Defect Repair			Meter Reading :		0				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension

Work Order Service History

Reported Defect :-

Defect Code : 00000955

Defect Reference : W/O 7858

Date : 18/01/2018

Description of Defect :

LHF SHOCKY LEAKING OIINSPECTED, PLEASE MONITOR.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00008613	Work Order Date :	28/02/2018	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

rhs windscreen replaced.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00008795	Work Order Date :	15/03/2018	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	532,357			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

SERVICE COMPLETED.
TOPPED UP ENGINE OIL.
FLUSHED AD BLUE SYSTEM AND DOSER PUMP.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00008796	Work Order Date :	15/03/2018	Repair Location :	EX0103	Yatala Workshop Exodas	Eco Wind Service			
Service Code:	ECO	Eco Wind Service		Meter Reading :	2,520			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

CLEANED AIR FILTER.
TIGHTENED FUEL PUMP BOLTS.
WASHED MOTOR.
RESET SLEEPER UNIT.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00009017	Work Order Date :	29/03/2018	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	540,292			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

R/R 4x BATTERIES.
REPLACED BATTERY CLAMP.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00009244	Work Order Date :	13/04/2018	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	550,994			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

SERVICE COMPLETED.
FITTED LHS INDICATOR.
ADJUSTED CLUTCH.
TOPPED UP ENGINE OIL.

Work Order Service History

										Total for Service		0.00			
										Total for Work Order		0.00			
Work Order		00009313		Work Order Date :		18/04/2018		Repair Location :		EX0103		Yatala Workshop Exodas		C Service Cummins E5	
Service Code:		CUMCE5		C Service Cummins E5				Meter Reading :		553,966					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension				
SERVICE COMPLETED.															
										Total for Service		0.00			
										Total for Work Order		0.00			
Work Order		00009314		Work Order Date :		18/04/2018		Repair Location :		EX0103		Yatala Workshop Exodas		Exodas Annual Roadworthy NHVAS	
Service Code:		EXOINS		Exodas Annual Roadworthy NHVAS				Meter Reading :		553,966					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension				
PASSED															
										Total for Service		0.00			
										Total for Work Order		0.00			
Work Order		00009599		Work Order Date :		28/04/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		GEN		General Repair				Meter Reading :		562,308					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension				
TURBO FITTED IN YARD 21/04/2018.															
										Total for Service		0.00			
										Total for Work Order		0.00			
Work Order		00009557		Work Order Date :		03/05/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension				
		33000096		15	BRIAUS01	EX00004998	03/05/18	PUNCTURE REPAIR TBR,PM78	0.00	25.00	0.00				
		33000096		15	BRIAUS01	95683618	03/05/18	PUNCTURE REPAIR TBR,PM78	1.00	25.00	25.00				
										Total : Tyres		25.00			
										Total for Service		25.00			
										Total for Work Order		25.00			
Work Order		00009600		Work Order Date :		04/05/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		GEN		General Repair				Meter Reading :		562,308					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension				
FULL CREDIT FOR W/O 9599, THIS WAS OVERCHARGED.															
										Total for Service		0.00			
										Total for Work Order		0.00			
Work Order		00009601		Work Order Date :		04/05/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		GEN		General Repair				Meter Reading :		562,308					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension				
CORRECT CHARGES APPLIED FOR TURBO FITMENT. REFER W/O 9599, 9600 & 9601.															
										Total for Service		0.00			
										Total for Work Order		0.00			
Work Order		00009786		Work Order Date :		19/05/2018		Repair Location :		EX0103		Yatala Workshop Exodas		B Service Cummins E5	

Work Order Service History

Service Code: CUMBE5 B Service Cummins E5 Meter Reading : 576,778 Units Rate Extension
 Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED.
 DEFECTS REPAIRED.

Total for Service 0.00

Service Code: DEFECT Defect Repair Meter Reading : 0 Units Rate Extension
 Task Code Employee Product Code Warehouse Category Supplier Invoice Details

Reported Defect :-
 Defect Code : 00001282
 Defect Reference : 06303
 Date : 18/04/2018
 Description of Defect :
 SPEEDO BOUNCING. THEN NOT WORKING.
 REPAIR COMPLETED.
 Reported Defect :-
 Defect Code : 00001276
 Defect Reference : 06305
 Date : 28/04/2018
 Description of Defect :
 OVER DUE AN 'A' & 'B' SERVICE.
 BRAKES ARE HOLDING ON AND WONT RELEASE.
 TO BE MONITORED.
 Reported Defect :-
 Defect Code : 00001273
 Defect Reference : 6307
 Date : 09/05/2018
 Description of Defect :
 TURBO ONLY BOOSTING TO 190KPA. LACKS POWER. WONT PULL.
 TO BE MONITORED.

Total for Service 0.00

Total for Work Order 0.00

Work Order 00009920 Work Order Date : 25/05/2018 Repair Location : EX0103 Yatala Workshop Exodas Tyres Service

Service Code: TYRES Tyres Service - Trailer Meter Reading : 570,270 Units Rate Extension
 Task Code Employee Product Code Warehouse Category Supplier Invoice Details

33000085	YAT	15	25/05/18	ROTATE TBR TYRE	2.00	0.00	0.00
33000188	YAT	15	25/05/18	B FLEET PRESSURE CHECK	2.00	0.00	0.00
33000188	YAT	15	25/05/18	B FLEET PRESSURE CHECK	8.00	0.00	0.00

Total : Tyres 0.00

Total for Service 0.00

Total for Work Order 0.00

Work Order 00010197 Work Order Date : 07/06/2018 Repair Location : EX0103 Yatala Workshop Exodas Tune Up 200,000kms

Service Code: DEFECT Defect Repair Meter Reading : 0 Units Rate Extension
 Task Code Employee Product Code Warehouse Category Supplier Invoice Details

Reported Defect :-
Defect Code : 00001312
Defect Reference : INTERNAL ORDER
Date : 25/05/2018
Description of Defect :
ENGINE TUNE NEEDED URGENTLY.
COMPLETED.

											Total for Service		0.00		
											Total for Work Order		0.00		
Work Order		00010198		Work Order Date :		07/06/2018		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		590,697					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
SERVICE COMPLETED. ENGINE TUNE COMPLETED. HEADLIGHT GLOBES REPLACED. ENGINE OIL TOPPED UP. AIR COMPRESSOR HEAD GASKET LEAKING COOLANT.															
											Total for Service		0.00		
											Total for Work Order		0.00		
Work Order		00010472		Work Order Date :		22/06/2018		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		603,920					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
SERVICE COMPLETED. BRAKE RELINE NEEDED ON REAR AXLE. ENGINE REAR MAIN SEAL LEAKING.															
											Total for Service		0.00		
											Total for Work Order		0.00		
Work Order		00010553		Work Order Date :		26/06/2018		Repair Location :		EX0103		Yatala Workshop Exodas		Tyres Service	
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		603,920					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
		33000188	YAT	15			26/06/18	B FLEET PRESSURE CHECK			10.00	0.00	0.00		
											Total : Tyres		0.00		
											Total for Service		0.00		
											Total for Work Order		0.00		
Work Order		00010821		Work Order Date :		11/07/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair	
Service Code:		GEN		General Repair				Meter Reading :		0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
REPLACED NUMBER PLATES. WAS QV12DC, NOW XQ08CB.															
											Total for Service		0.00		
											Total for Work Order		0.00		
Work Order		00010965		Work Order Date :		20/07/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair	
Service Code:		GEN		General Repair				Meter Reading :		624,320					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		

Work Order Service History

REPLACED BACK LEFT TANK STRAP RUBBER, HAD TO PULL OFF CHROME STRIP/LIGHTS OFF TO ACCESS WHICH TOOK EXTRA TIME
TIGHTNED UP FRONT GRILL
PUT NEW PROTECTIVE SLEEVEWRAP ON AIR LINES/ELECTRICAL CORDS TO TRAILER

Total for Service 0.00

Total for Work Order 0.00

Work Order	00011007	Work Order Date :	21/07/2018	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
PARTS ONLY							

Total for Service 0.00

Total for Work Order 0.00

Work Order	00010953	Work Order Date :	23/07/2018	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------

Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	624,320	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

SERVICE COMPLETED
BRAKE SHOE RELINED
REPAIRED BACK LEFT CLEARANCE LIGHT

Total for Service 0.00

Service Code:	DEFECT	Defect Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

Reported Defect :-
Defect Code : 00001444
Defect Reference : W/O 10472
Date : 22/06/2018
Description of Defect :
BRAKE RELINE NEEDED ON REAR AXLE.
RELIN COMPLETED
Reported Defect :-
Defect Code : 00001507
Defect Reference : 06315
Date : 13/07/2018
Description of Defect :
'A' SERVICE DUE 4000K'S AGO.
SERVICE COMPLETED

Total for Service 0.00

Total for Work Order 0.00

Work Order	00011079	Work Order Date :	24/07/2018	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

REPAIRS COMPLETED BY B&H COFFS HARBOUR

Total for Service 0.00

Total for Work Order 0.00

Work Order	00011109	Work Order Date :	27/07/2018	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------

Service Code:	CUMBE5	B Service Cummins E5	Meter Reading :	628,352	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

Work Order Service History

SERVICE COMPLETE
REPLACED BOTH BELTS AND TENSIONOR
NO REGO LABEL
REAR MAIN SEAL LEAKING
RIGHT HAND CAB RAM LEAKING
COOLANT LEAK ON COMPRESSOR

Total for Service 0.00

Service Code:	DEFECT	Defect Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

Reported Defect :-
Defect Code : 00000850
Defect Reference : 4095
Date : 10/12/2017
Description of Defect :
STEERING PULLING TO THE LEFT. WEARING DOWN THE STEER TYRE SHOULDERS.
COMPLETED 29/01/2018

Total for Service 0.00

Total for Work Order 0.00

Work Order	00011139	Work Order Date :	30/07/2018	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------------

Service Code:	TYRES	Tyres Service - Trailer	Meter Reading :	628,352	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

BRIDGESTONE CHARGED RE-TORQUE, WAITING FOR CREDIT

Total for Service 0.00

Total for Work Order 0.00

Work Order	00011141	Work Order Date :	30/07/2018	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------------

Service Code:	TYRES	Tyres Service - Trailer	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

FLIP TYRE AND BALANCE - YATALA YARD

33000051	15	BRIAUS01	EX00005937	30/07/18	BALANCE TBR,PM78	0.00	25.00	0.00
33000051	15	BRIAUS01	95952973	30/07/18	BALANCE TBR,PM78	2.00	25.00	50.00

Total : Tyres 50.00

Total for Service 50.00

Total for Work Order 50.00

Work Order	00011197	Work Order Date :	01/08/2018	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------

Service Code:	DEFECT	Defect Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

Reported Defect :-
Defect Code : 00001443
Defect Reference : W/O 10472
Date : 22/06/2018
Description of Defect :
ENGINE REAR MAIN SEAL LEAKING.
COMPLETED BY CUMMINS CAROLE PARK

Total for Service 0.00

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

Work Order Service History

REAR MAIN SEAL AND CLUTCH REPAIR - BY CUMMINS CAROLE PARK
WAITING ON INVOICE
REAR MAIN SEAL AND CLUTCH REPAIR - CUMMINS

Total for Service 0.00

Total for Work Order 0.00

Work Order	00011204	Work Order Date :	02/08/2018	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------	--	--	--

Service Code: GEN General Repair Meter Reading : 0

Task Code Employee Product Code Warehouse Category Supplier Invoice Details Units Rate Extension

PARTS ONLY

Total for Service 0.00

Total for Work Order 0.00

Work Order	00011202	Work Order Date :	03/08/2018	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------	--	--	--

Service Code: GEN General Repair Meter Reading : 0

Task Code Employee Product Code Warehouse Category Supplier Invoice Details Units Rate Extension

PARTS ONLY

Total for Service 0.00

Total for Work Order 0.00

Work Order	00011620	Work Order Date :	30/08/2018	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------	--	--	--

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 647,938

Task Code Employee Product Code Warehouse Category Supplier Invoice Details Units Rate Extension

SERVICE COMPLETED
CHECKED MALE LIGHT PLUG

Total for Service 0.00

Service Code: DEFECT Defect Repair Meter Reading : 0

Task Code Employee Product Code Warehouse Category Supplier Invoice Details Units Rate Extension

Reported Defect :-
Defect Code : 00001358
Defect Reference : W/O 10198
Date : 07/06/2018
Description of Defect :
AIR COMPRESSOR HEAD GASKET LEAKING COOLANT.
COMPLETED - SEAN

Total for Service 0.00

Total for Work Order 0.00

Work Order	00011737	Work Order Date :	06/09/2018	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------	--	--	--

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 652,684

Task Code Employee Product Code Warehouse Category Supplier Invoice Details Units Rate Extension

SERVICE COMPLETED
REPLACED H4 LOW/HIGH BULBS WITH LED

Total for Service 0.00

Total for Work Order 0.00

Work Order	00011758	Work Order Date :	08/09/2018	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------	--	--	--

Service Code: GEN General Repair Meter Reading : 654,637

Task Code Employee Product Code Warehouse Category Supplier Invoice Details Units Rate Extension

R&R EXHAUST FLEX & GASKET

Work Order Service History

										Total for Service		0.00			
										Total for Work Order		0.00			
Work Order		00011824		Work Order Date :		11/09/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		GEN		General Repair		Meter Reading :		0				Units	Rate	Extension	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details								
PARTS ONLY - BUMPER															
										Total for Service		0.00			
										Total for Work Order		0.00			
Work Order		00012109		Work Order Date :		03/10/2018		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5		Meter Reading :		670,202				Units	Rate	Extension	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details								
SERVICE COMPLETED TOPPED UP ENGINE OIL 2.5LT															
										Total for Service		0.00			
										Total for Work Order		0.00			
Work Order		00012154		Work Order Date :		05/10/2018		Repair Location :		EX0103		Yatala Workshop Exodas		B Service Cummins E5	
Service Code:		CUMBE5		B Service Cummins E5		Meter Reading :		673,144				Units	Rate	Extension	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details								
SERVICE COMPLETED NEEDS TANK STRAP RUBBERS, DOING NEXT TIME IT IS IN															
										Total for Service		0.00			
										Total for Work Order		0.00			
Work Order		00012164		Work Order Date :		05/10/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer		Meter Reading :		670,602				Units	Rate	Extension	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details								
R&R TYRES															
		33000051		15	BRIAUS01	EX00006580	05/10/18	BALANCE TBR,PM78		0.00	25.00	0.00			
		11001553	YAT	15			05/10/18	TYRE 295/80R22.5 152/148M BS R150		2.00	494.00	988.00			
		33000051		15	BRIAUS01	96165824	05/10/18	BALANCE TBR,PM78		2.00	25.00	50.00			
										Total : Tyres		1,038.00			
										Total for Service		1,038.00			
										Total for Work Order		1,038.00			
Work Order		00012221		Work Order Date :		11/10/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer		Meter Reading :		678,392				Units	Rate	Extension	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details								
R&R TYRES															
		77000194		15	BRIAUS01	EX00006616	11/10/18	case stock 295/80-22.5,PM78		0.00	20.00	0.00			
		TYRRUN	YAT	15			11/10/18	Tyre Runouts		1.00	0.00	0.00			
		77000194		15	BRIAUS01	96184886	11/10/18	case stock 295/80-22.5,PM78		-1.00	20.00	-20.00			
										Total : Tyres		-20.00			
										Total for Service		-20.00			
										Total for Work Order		-20.00			
Work Order		00012284		Work Order Date :		15/10/2018		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair	

Work Order Service History

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
		CLEANED ADBLUE LINES					
		CLEANED ADBLUE INJECTOR					
		FLUSHED DOSER PUMP WITH HOT WATER					
		FLUSHED AIR SYSTEM WITH HOT WATER					
		FITTED NEW FILTER					
		MONITOR FOR RESULTS					
Total for Service							0.00
Total for Work Order							0.00

Work Order	00012345	Work Order Date :	18/10/2018	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
		SERVICE COMPLETED					
		FITTED WEIGHT GAUGE, LINE, FITTINGS & MOUNTING PLATE					
		NEEDS TO BE CALIBRATED					
Total for Service							0.00
Total for Work Order							0.00

Work Order	00012365	Work Order Date :	20/10/2018	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	685,409	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
		SERVICE COMPLETED					
		TOPPED UP ENGINE OIL (3LT) & FILLED SPARE OIL (5LT)					
		REPLACED LIGHT PLUG					
Total for Service							0.00

Service Code:	DEFECT	Defect Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
		Reported Defect :-					
		Defect Code : 00001919					
		Defect Reference : WO12284					
		Date : 15/10/2018					
		Description of Defect :					
		NEW ADBLUE FILTER FITTED ON 15/10/2018 DUE TO AFTER TREAT LIGHT UP WITH CODE 2772, PLEASE MONITOR					
		COMPLETED					
Total for Service							0.00
Total for Work Order							0.00

Work Order	00012637	Work Order Date :	05/11/2018	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	699,755	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
		SERVICE COMPLETED					
		REPLACED RHS REAR & LHS FRONT TANK STRAP RUBBER ALSO REPAIRED BENT TANK STRAP RHS					
Total for Service							0.00
Service Code:	DEFECT	Defect Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

Defect Code : 00001896

Defect Reference : WO12154

Date : 05/10/2018

Description of Defect :

NEEDS TANK STRAP RUBBERS, DOING NEXT TIME IT IS IN REPAIRED

Total for Service	0.00
--------------------------	-------------

Total for Work Order	0.00
-----------------------------	-------------

Work Order	00013478	Work Order Date :	18/12/2018	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
-------------------	-----------------	-------------------	------------	-------------------	--------	------------------------	----------------------------

Work Order Service History

Service Code:		TYRES	Tyres Service - Trailer			Meter Reading :			735,172			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			Units	Rate	Extension
R&R TYRES PLUS ROTATION & BALANCE												
		33000051		15	BRIAUS01	EX00007344	18/12/18	BALANCE TBR,PM78		0.00	25.00	0.00
		11002831	YAT	15			18/12/18	TYRE 11R22.5 146/143L M766		4.00	495.00	1,980.00
		33000051		15	BRIAUS01	96414359	18/12/18	BALANCE TBR,PM78		2.00	25.00	50.00
										Total : Tyres		2,030.00
										Total for Service		2,030.00
										Total for Work Order		2,030.00

Work Order		00013539		Work Order Date :		19/12/2018		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5		Meter Reading :		737,129							
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
SERVICE COMPLETED.															
REPLACED BLOWN BULB IN LEFT SIDE PARKER LIGHT.															
REPLACED BLOWN BULB IN LEFT HIGH BEAM LIGHT.															
REPAIRED FAULTY WIRING ON BAKC LEFT CLEARANCE LIGHT.															
												Total for Service		0.00	
												Total for Work Order		0.00	

Work Order		00013587		Work Order Date :			29/12/2018		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5					
Service Code:		CUMAE5		A Service Cummins E5					Meter Reading :		742,142				Units	Rate	Extension			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details													
SERVICE COMPLETED																				
ADJUSTED CLUTCH																				
TOPPED UP ENGINE OIL																				
																Total for Service		0.00		
Service Code:		DEFECT		Defect Repair					Meter Reading :		0				Units	Rate	Extension			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details													
Reported Defect :-																				
Defect Code : 00002061																				
Defect Reference : 06319																				
Date : 04/12/2018																				
Description of Defect :																				
HAD TO RESET SLEEPER AIR - NEEDS SERVICE																				
COMPLETED																				
																Total for Service		0.00		
																Total for Work Order		0.00		

Work Order		00014079		Work Order Date :		18/01/2019		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5		Meter Reading :		755,528							
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
	SERVICE COMPLETED														
	FRONT TORQUE ROD BUSHES NEED REPLACING														
	TOPPED UP COOLANT														
	FRONT DRIVE SHOCKS MISTING														
	REAR DRIVE BRAKE SHOES ARE LOW														
	TOPPED UP SPARE OIL BOTTLE														
	RECORDED FUEL BURN														

Work Order Service History

Total for Service 0.00

Total for Work Order 0.00

Work Order	00014344	Work Order Date :	02/02/2019	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------

Service Code: CUMBE5 B Service Cummins E5 Meter Reading : 766,580

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED
 REPALCED LHS HI BEAM GLOBE
 REPLACED RHS LOWER GRILLE BOLT
 HAD NO COMPLAINTS ABOUT "MISSING" IN ENGINE
 REPLACED STEER HUB CAP
 REQUIRES BRAKE RELINE ASAP
 REPLACED FIRE EXTINGUISHER

Total for Service 0.00

Service Code: DEFECT Defect Repair Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

Reported Defect :-
 Defect Code : 00002139
 Defect Reference : 6317
 Date : 29/10/2018
 Description of Defect :
 TRUCK SURGING - MISSING AS PER DISCUSSION WITH MICK
 COMPLETED

Total for Service 0.00

Total for Work Order 0.00

Work Order	00014473	Work Order Date :	04/02/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------

Service Code: TYRES Tyres Service - Trailer Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

R&R TYRES PLUS ROTATION

77000180		15	BRIAUS01	EX00007848	04/02/19	CASE STOCK 11-22.5,PM78	0.00	20.00	0.00
11002831	YAT	15			04/02/19	TYRE 11R22.5 146/143L M766	1.00	495.00	495.00
77000180		15	BRIAUS01	96546696	04/02/19	CASE STOCK 11-22.5,PM78	-4.00	20.00	-80.00

Total : Tyres 415.00

Total for Service 415.00

Total for Work Order 415.00

Work Order	00014652	Work Order Date :	13/02/2019	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 775,789

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED
 REPLACED WIPER BLADES
 REPALCED EBS & LIGHT PLUGS, CUT & REFITTED FEMALE AIR HOSE
 REPLACED RHS PARK LIGHT
 TRIED TO FLUSH AD BLUE SYSTEM, COULDN'T GET IT TO CIRCULATE, TRIED NEW FITTING STLL NOTHING, CLEANED & CHECKED INJECTOR,
 CHECKED HOSES - SENT TO BROWN & HURLEY

Total for Service 0.00

Total for Work Order 0.00

Work Order	00014676	Work Order Date :	14/02/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------

Work Order Service History

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
							REPLACED TORQUE ROD BUSHES RHS FRONT DIFF REMOVED REAR DRIVE TYRES, DRUM & BRAKE SHOES REPLACED BRAKE SHOES & DRUMS REFITTED TYRES & TENSIONED

Total for Service 0.00

Total for Work Order 0.00

Work Order	00014740	Work Order Date :	15/02/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------

Service Code:	GEN	General Repair	Meter Reading :	775,791	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
							AFTERTREAT WARNING LIGHT ON & DERATED CHECKED CODES ENGINE HAD VERY HIGH COUNTS OF DOSER UNIT ABNORMAL UPDATE RATE & NOX SENSOR DATA ERRATIC. CHECK POWER SUPPLIES AS DOSERUNIT & FOUND IGNITION FEED MISSNG CHECK IGNITION FEED AR ENGINE HARNESS, ALL OK. REMOVE REAR WALK PLATE TO GAIN ACCESS & REMOVE SCR HARNESS BEHIND GEARBOX & CHECK OUTPUT. NO IGINTION FEED CUT OPEN HARNESS & FOUND IGINTION FEED & EARTH WIRE VERY BADLY CORRODED REPAIRED BOTH SECTIONS OF THE WIRING HARNESS & RECONNECTED, TEST OPERATION CLEARED FAULT CODES & UPDATE ECM CALIBRATIONS REFIT WALK PLATE

Total for Service 0.00

Total for Work Order 0.00

Work Order	00014764	Work Order Date :	20/02/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
							PARTS ONLY

Total for Service 0.00

Total for Work Order 0.00

Work Order	00015057	Work Order Date :	06/03/2019	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------

Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	791,173	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
							SERVICE COMPLETED TOPPED UP ENGINE OIL REPLACED RHS PARKLIGHT BULB REPLACED RHS HIGH BEAM BULB REPLACED MISSING BOLT RHS OF GRILL

Total for Service 0.00

Service Code:	DEFECT	Defect Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
							Reported Defect :- Defect Code : 00002261 Defect Reference : WO14344 Date : 02/02/2019 Description of Defect : REQUIRES BRAKE RELINE ASAP completed

Work Order Service History

Reported Defect :-

Defect Code : 00002226

Defect Reference : WO14079

Date : 18/01/2019

Description of Defect :

REAR DRIVE BRAKE SHOES ARE LOW
completed

Total for Service 0.00

Total for Work Order 0.00

Work Order	00015373	Work Order Date :	14/03/2019	Repair Location :	EX0103	Yatala Workshop Exodas	Eco Wind Service			
Service Code:	ECO	Eco Wind Service		Meter Reading :	3,680			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		SERVICE COMPLETED								
		REPAIRED FUEL LEAK								

Total for Service 0.00

Total for Work Order 0.00

Work Order	00015452	Work Order Date :	19/03/2019	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	801,188			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		SERVICE COMPLETED								
		EXTENDED AIRLINES AS REQUIRED, PULLED THROUGH EXTRA ELECTRICAL CORD & ABS CORD								

Total for Service 0.00

Service Code:	DEFECT	Defect Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

Reported Defect :-

Defect Code : 00002225

Defect Reference : WO14079

Date : 18/01/2019

Description of Defect :

FRONT TORQUE ROD BUSHES NEED REPLACING
2 X HAVE BEEN REPLACED AT SOME STAGE

Total for Service 0.00

Total for Work Order 0.00

Work Order	00015559	Work Order Date :	22/03/2019	Repair Location :	EX0103	Yatala Workshop Exodas	Warranty Work			
Service Code:	WARRANT	Warranty Work		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		CUMMINS EXTENDED WARRANTY NEW DATE 24 APR 21 1,2000,000KMS								

Total for Service 0.00

Total for Work Order 0.00

Work Order	00015646	Work Order Date :	24/03/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		FITTED NEW WINDSCREEN LHS								

Total for Service 0.00

Total for Work Order 0.00

Work Order	00015689	Work Order Date :	27/03/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------	--	--	--

Work Order Service History

Service Code:	GEN	General Repair	Meter Reading :	807,727	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
							REPLACED 2 X DAMAGED FUEL LINES AS REQUIRED & WASHED SLEEPER AIR

Total for Service 0.00

Total for Work Order 0.00

Work Order	00015971	Work Order Date :	04/04/2019	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------

Service Code:	CUMBE5	B Service Cummins E5	Meter Reading :	815,727	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

SERVICE COMPLETED
TENSIONED PITMAN ARM BOLT
COOLING SYSTEM FOAMING WHILE ENGINE RUNNING
REPLACED ABS PLUG
STEERING COLUMN TILT NOT WORKING PROPERLY

Total for Service 0.00

Total for Work Order 0.00

Work Order	00016040	Work Order Date :	05/04/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------

Service Code:	TUNE	Tune Up 200,000kms	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

TUNED AS REQUIRED

Total for Service 0.00

Total for Work Order 0.00

Work Order	00016042	Work Order Date :	05/04/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------

Service Code:	DEFECT	Defect Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

Reported Defect :-
Defect Code : 00002414
Defect Reference : WO15971
Date : 04/04/2019
Description of Defect :
COOLING SYSTEM FOAMING WHILE ENGINE RUNNING
FLUSHED SYSTEM

Total for Service 0.00

Service Code:	GEN	General Repair	Meter Reading :	815,727	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

REMOVED OLD COOLANT, FLUSHED WITH WATER TWICE, CHANGED COOLANTFILTER, FILLED SYSTEM WITH 50 LT OF 50/50% GREEN
COOLANT, RINSED OFF TRUCK
INSERTED NEW BOLT INTO BOTTOM LEFT OF GRILL

Total for Service 0.00

Total for Work Order 0.00

Work Order	00016076	Work Order Date :	08/04/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------

Service Code:	GEN	General Repair	Meter Reading :	817,682	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

CHECK ENGINE LIGHT ON - REMOVED FILTER & REPLACED ORING AS REQUIRED
NO ORING ON FILTER
WAS LEAKING COOLANT WHICJ WAS BRINGING ON CHECK ENGINE LIGHT
WASHED TRUCK DOWN

Work Order Service History

										Total for Service	0.00					
										Total for Work Order	0.00					
Work Order		00016092		Work Order Date :		08/04/2019		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance		
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		815,727				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									
R&R TYRES STEER																
		33000051		15	BRI AUS01	EX00008724	08/04/19	BALANCE TBR,PM78				0.00	25.00	0.00		
		11001553	YAT	15			08/04/19	TYRE 295/80R22.5 152/148M BS R150				2.00	494.00	988.00		
		33000051		15	BRI AUS01	96756811	08/04/19	BALANCE TBR,PM78				2.00	25.00	50.00		
										Total : Tyres	1,038.00					
										Total for Service	1,038.00					
										Total for Work Order	1,038.00					
Work Order		00016385		Work Order Date :		26/04/2019		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair		
Service Code:		GEN		General Repair				Meter Reading :		828,438				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									
REPLACED ALL BATTERIES AS 3 FAILED																
										Total for Service	0.00					
										Total for Work Order	0.00					
Work Order		00016425		Work Order Date :		30/04/2019		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance		
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		0				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									
R&R TYRES - DRIVE 826,399KMS																
		77000180		15	BRI AUS01	EX00008918	30/04/19	CASE STOCK 11-22.5,PM78				0.00	20.00	0.00		
		11002831	YAT	15			30/04/19	TYRE 11R22.5 146/143L M766				4.00	495.00	1,980.00		
		77000180		15	BRI AUS01	96816712	30/04/19	CASE STOCK 11-22.5,PM78				-1.00	20.00	-20.00		
										Total : Tyres	1,960.00					
										Total for Service	1,960.00					
										Total for Work Order	1,960.00					
Work Order		00016439		Work Order Date :		30/04/2019		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance		
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		830,613				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									
R&R TYRE POS 6																
		33000241		15	BRI AUS01	EX00008933	30/04/19	SCRAP TYRES TBR,PM78				0.00	14.00	0.00		
		TYRRUN	YAT	15			30/04/19	Tyre Runouts				1.00	0.00	0.00		
		33000241		15	BRI AUS01	96816730	30/04/19	SCRAP TYRES TBR,PM78				1.00	14.00	14.00		
										Total : Tyres	14.00					
										Total for Service	14.00					
										Total for Work Order	14.00					
Work Order		00016528		Work Order Date :		02/05/2019		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5		
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		832,807				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									

Work Order Service History

SERVICE COMPLETED
TOPPED UP ENGINE OIL - 5LT
REFITTED ABS PLUG TO REAR SUZI COILS

Total for Service 0.00

Total for Work Order 0.00

Work Order	00016814	Work Order Date :	18/05/2019	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------	--	--	--

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 843,856

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED
REPLACED ALL DRIVE SHOCKS
REPLACED FITTING TO HORTON FAN FILTER
REPLACED BUNG IN FRONT OF TIMING COVER
ADJUSTED STEERING WHEEL LOCK MECHANISM
REPLACED 2 X WALK PLATE CLAMPS
TIGHTENED GRILL BOLTS
REPLACED RHS FRONT PARK LIGHT

Total for Service 0.00

Service Code: DEFECT Defect Repair Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

Reported Defect :-
Defect Code : 00002415
Defect Reference : WO15971
Date : 04/04/2019
Description of Defect :
STEERING COLUMN TILT NOT WORKING PROPERLY
Reported Defect :-
Defect Code : 00002377
Defect Reference : 06321
Date : 19/03/2019
Description of Defect :
CRACKED WINDSCREEN
Reported Defect :-
Defect Code : 00002457
Defect Reference : 06324
Date : 14/04/2019
Description of Defect :
ICE PACK DUE FOR SERVICE

Total for Service 0.00

Total for Work Order 0.00

Work Order	00016815	Work Order Date :	18/05/2019	Repair Location :	EX0103	Yatala Workshop Exodas	C Service Cummins E5			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------	--	--	--

Service Code: CUMCE5 C Service Cummins E5 Meter Reading : 843,856

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED
ADJUSTED RHS STEER WHEEL BEARINGS
TENSIONED PINCH BOLT ON PITMAN ARM
RHS TIE ROD END U/S

Total for Service 0.00

Total for Work Order 0.00

Work Order	00016816	Work Order Date :	18/05/2019	Repair Location :	EX0103	Yatala Workshop Exodas	Exodas Annual Roadworthy NHVAS			
------------	----------	-------------------	------------	-------------------	--------	------------------------	--------------------------------	--	--	--

[illegible]

Work Order Service History

Work Order	00017933	Work Order Date :	27/06/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	TYRES	Tyres Service - Trailer		Meter Reading :	872,414			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		TYRE ROTATION & BALANCE STEER								
		33000051		15	BRIAUS01	EX00009696	27/06/19 BALANCE TBR,PM78	0.00	30.00	0.00
		33000051		15	BRIAUS01	97007800	27/06/19 BALANCE TBR,PM78	2.00	30.00	60.00
								Total : Tyres		60.00
								Total for Service		60.00
								Total for Work Order		60.00
Work Order	00017912	Work Order Date :	28/06/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	872,415			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		FITTED LED HEADLIGHTS AS REQUIRED								
								Total for Service		0.00
								Total for Work Order		0.00
Work Order	00018389	Work Order Date :	13/07/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		BROKEN EXHAUST CLAMP - REMOVED BROKEN CLAMP & FITTED NEW GASKET & 2ND HAND CLAMP								
								Total for Service		0.00
								Total for Work Order		0.00
Work Order	00018417	Work Order Date :	16/07/2019	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	887,864			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		SERVICE COMPLETED REPLACED RH RAKE LIGHT REPLACED PUSH SCREEN/TOP HALF OF TURBO TIMER AS REQUIRED								
								Total for Service		0.00
								Total for Work Order		0.00
Work Order	00018544	Work Order Date :	20/07/2019	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	891,595			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		SERVICE COMPLETED								
								Total for Service		0.00
								Total for Work Order		0.00
Work Order	00019162	Work Order Date :	24/07/2019	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		EXODAS YATALA AIR GAUGE - 13.75 ADJUSTED - NA WEIGHBRIDGE - 13.20								
								Total for Service		0.00
								Total for Work Order		0.00

Work Order Service History

Work Order		00019253		Work Order Date :		10/08/2019		Repair Location :		EX0103		Yatala Workshop Exodas		B Service Cummins E5	
Service Code:		CUMBE5		B Service Cummins E5				Meter Reading :		904,755					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
SERVICE COMPLETED															
REPLACED EBS PLUG															
CHANGED FUEL FILTER/WATER SEPERATOR															
													Total for Service		0.00
													Total for Work Order		0.00
Work Order		00019404		Work Order Date :		16/08/2019		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair	
Service Code:		GEN		General Repair				Meter Reading :		909,203					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
DEFECT REPAIRS															
SWAPPED HEAD REST OVER FROM ANOTHER SEAT															
CHECKED HOSE CLAMPS FOR NTERCOOLER & VISUALLY CHECKED HOSES LOOK FINE, FUEL W/S LOOKS NEW															
PUT SOME DOUBLE SIDED TAPE ON DRIVERS SIDE WEATHER SHIELD, SMALL SECTION MISSING BUT NOT WORRIED, LET IT DEVELOPE															
CHANGED OUT TOP 3 GLOBES FOR GAUGES AS REQUIRED WITH NORMAL BULBS															
CHECKED PYRO GAUGE BY HEATING UP, SEEMS TO BE WORKING, CHECKED TO SEE IF ARM IS CONNECTED TO TURBO SEEMS FINE															
													Total for Service		0.00
													Total for Work Order		0.00
Work Order		00019802		Work Order Date :		31/08/2019		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		921,869					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
SERVICE COMPLETED															
TOPPE DUP OIL															
WIRED FRIDGE INTO CONSTANT POWER															
GLUED RUBBER AROUND DOOR															
													Total for Service		0.00
													Total for Work Order		0.00
Work Order		00019889		Work Order Date :		05/09/2019		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair	
Service Code:		GEN		General Repair				Meter Reading :		0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
WEATHER SHIELD BROKEN - REPLACED															
HOOK UP LIGHTS DON'T WORK - FITTED 2 x NEW LOAD LIGHT INSERTS AS BOTH WERE BLOWN															
CONSTANT POWER FOR FRIDGE - WIRED FRIDGE FOR CONSTANT POWER															
													Total for Service		0.00
													Total for Work Order		0.00
Work Order		00019890		Work Order Date :		05/09/2019		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		925,048					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
SERVICE COMPLETED															
REPLACED FRONT DRIVE SLACK ADJUSTERS ASA REQUIRED															
													Total for Service		0.00
													Total for Work Order		0.00
Work Order		00020162		Work Order Date :		12/09/2019		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		930,407					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		

Work Order Service History

PUNCTURE REPAIR & BALANCE POS 1

33000051	15	BRIAUS01	EX00010686	12/09/19	BALANCE TBR,PM78	0.00	30.00	0.00
33000096	15	BRIAUS01	EX00010686	12/09/19	PUNCTURE REPAIR TBR,PM78	0.00	25.00	0.00
33000096	15	BRIAUS01	97273055	12/09/19	PUNCTURE REPAIR TBR,PM78	1.00	25.00	25.00
33000051	15	BRIAUS01	97273055	12/09/19	BALANCE TBR,PM78	1.00	30.00	30.00
Total : Tyres								55.00
Total for Service								55.00
Total for Work Order								55.00

Work Order	00020706	Work Order Date :	12/09/2019	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
AIR GAUGE: 13.500 ADJUSTED: 0.000 WEIGH BRIDGE: 13.500										
Total for Service										0.00
Total for Work Order										0.00

Work Order	00020399	Work Order Date :	21/09/2019	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	937,743			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED TIGHENED GRILL										
Total for Service										0.00
Total for Work Order										0.00

Work Order	00020746	Work Order Date :	30/09/2019	Repair Location :	EX0103	Yatala Workshop Exodas	Tyres Service			
Service Code:	TYRES	Tyres Service - Trailer		Meter Reading :	942,438			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
STEER & DRIVE TYRE ROTATION - DAVE										
Total for Service										0.00
Total for Work Order										0.00

Work Order	00020795	Work Order Date :	01/10/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	TYRES	Tyres Service - Trailer		Meter Reading :	942,438			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
STEER & DRIVE TYRE ROATTION PLUS BALANCE										
		33000051	15	BRIAUS01	EX00011036	01/10/19	BALANCE TBR,PM78	0.00	30.00	0.00
		33000051	15	BRIAUS01	97368636	01/10/19	BALANCE TBR,PM78	2.00	30.00	60.00
Total : Tyres										60.00
Total for Service										60.00
Total for Work Order										60.00

Work Order	00020756	Work Order Date :	09/10/2019	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5			
Service Code:	CUMBE5	B Service Cummins E5		Meter Reading :	949,901			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

Work Order Service History

SERVICE COMPLETED
 REPLACED JAW & WEAR RING IN TURNTABLE
 SERVICED SLEEPER AIR
 REPLACED WIPER BLADES
 REPLACED BRAKE SHOES ON FRONT DRIVE AS WELL AS DRUMS
 REPLACED WHEEL NUT COVERS x10
 REPLACED 1 x A/C VENT AS REQUIRED

Total for Service 0.00

Total for Work Order 0.00

Work Order	00020763	Work Order Date :	09/10/2019	Repair Location :	EX0103	Yatala Workshop Exodas	Eco Wind Service			
Service Code:	ECO	Eco Wind Service		Meter Reading :	0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension

SERVICE COMPLETED
 REPLACED AIR FILTER
 REPLACED BOLT BELTS

Total for Service 0.00

Total for Work Order 0.00

Work Order	00020930	Work Order Date :	09/10/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	TYRES	Tyres Service - Trailer		Meter Reading :	949,901					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension

PUNCTURE REPAIR

33000096	15	BRI AUS01	EX00011106	09/10/19	PUNCTURE REPAIR TBR,PM78	0.00	25.00	0.00
33000096	15	BRI AUS01	97412576	09/10/19	PUNCTURE REPAIR TBR,PM78	1.00	25.00	25.00

Total : Tyres 25.00

Total for Service 25.00

Total for Work Order 25.00

Work Order	00021413	Work Order Date :	10/10/2019	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :	0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension

AIR GAUGE READING: 16.000
 ADJUSTED: 0.000
 WEIGH BRIDGE: 15.500

Adjustment completed correctly.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00021369	Work Order Date :	17/10/2019	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :	0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension

AIR GAUGE READING: 15.750
 ADJUSTED: 15.300
 WEIGH BRIDGE: 15.000

Adjustment completed correctly.

Total for Service 0.00

Total for Work Order 0.00

Work Order Service History

Work Order		00021380		Work Order Date :		17/10/2019		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration	
Service Code:		WEICAL		Weight Gauge Calibration				Meter Reading :		0					
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension	
		AIR GAUGE READING: 15.750													
		ADJUSTED: 16.000													
		WEIGH BRIDGE: 15.400													
		Adjustment completed incorrectly.													
												Total for Service		0.00	
												Total for Work Order		0.00	
Work Order		00021578		Work Order Date :		23/10/2019		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration	
Service Code:		WEICAL		Weight Gauge Calibration				Meter Reading :		0					
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension	
		AIR GAUGE - 13.00													
		ADJUSTED -NA													
		WEIGHBRIDGE -NA													
		NOT CORRECT													
												Total for Service		0.00	
												Total for Work Order		0.00	
Work Order		00021586		Work Order Date :		25/10/2019		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration	
Service Code:		WEICAL		Weight Gauge Calibration				Meter Reading :		0					
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension	
		AIR GAUGE - 17.00													
		ADJUSTED - NA													
		WEIGHBRIDGE - NA													
		NOT CORRECT													
												Total for Service		0.00	
												Total for Work Order		0.00	
Work Order		00021558		Work Order Date :		28/10/2019		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		963,581					
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension	
		SERVICE COMPLETED													
		LOOKED FOR ETAG - CAN'T FIND IT NOT ON DASH, NOT ON WINDOW, CAN'T SEE IT													
												Total for Service		0.00	
												Total for Work Order		0.00	
Work Order		00021726		Work Order Date :		30/10/2019		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration	
Service Code:		WEICAL		Weight Gauge Calibration				Meter Reading :		0					
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension	
		AIR GAUGE - 16.00													
		ADJUSTED - 16.25													
		WEIGHBRIDGE - 15.80													
												Total for Service		0.00	
												Total for Work Order		0.00	
Work Order		00022383		Work Order Date :		16/11/2019		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		978,554					
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension	

Work Order Service History

									Total for Service	0.00			
									Total for Work Order	0.00			
Work Order		00023525		Work Order Date :		27/12/2019		Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance		
Service Code:		GEN		General Repair		Meter Reading :		0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details						
COMPLETED BY BRIDGESTONE 27.12.2019													
INVOICE # 97832831													
		33000085		15	BRIAUS01	EX00012198	27/12/19	PM78,ROTATE TBR TYRE			0.00	0.00	0.00
		77000194		15	BRIAUS01	EX00012198	27/12/19	PM78,case stock 295/80-22.5			0.00	20.00	0.00
		11001553		15	BRIAUS01	EX00012198	27/12/19	PM78,TYRE 295/80R22.5 152/148M BS R150			0.00	0.00	0.00
		33000084		15	BRIAUS01	EX00012198	27/12/19	PM78,FIT TBR TYRE			0.00	0.00	0.00
		33000051		15	BRIAUS01	EX00012198	27/12/19	PM78,BALANCE TBR			0.00	30.00	0.00
		33000051		15	BRIAUS01	97832831	27/12/19	PM78,BALANCE TBR			2.00	30.00	60.00
		33000084		15	BRIAUS01	97832831	27/12/19	PM78,FIT TBR TYRE			2.00	0.00	0.00
		11001553		15	BRIAUS01	97832831	27/12/19	PM78,TYRE 295/80R22.5 152/148M BS R150			1.00	0.00	0.00
		77000194		15	BRIAUS01	97832831	27/12/19	PM78,case stock 295/80-22.5			-2.00	20.00	-40.00
		33000085		15	BRIAUS01	97832831	27/12/19	PM78,ROTATE TBR TYRE			8.00	0.00	0.00
												Total : Tyres	20.00
												Total for Service	20.00
												Total for Work Order	20.00
Work Order		00023540		Work Order Date :		03/01/2020		Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5		
Service Code:		CUMAE5		A Service Cummins E5		Meter Reading :		0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details						
SERVICE COMPLETED BY BILLY / KEIRAN / MICK 03.01.2020													
REPAIRED SPOT MIRROR													
TOPPED UP ENGINE OIL													
TOPPED UP COOLANT													
												Total for Service	0.00
Service Code:		DEFECT		Defect Repair		Meter Reading :		0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details						
DEFECT # 12706													
REPLACE R/H SPOTTER MIRROR													
DEFECT CLEARED BY MICK 03.01.2020													
												Total for Service	0.00
												Total for Work Order	0.00
Work Order		00023759		Work Order Date :		08/01/2020		Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration		
Service Code:		WEICAL		Weight Gauge Calibration		Meter Reading :		0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details						

Work Order Service History

AIR GAUGE: 16.5
ADJUSTED: 0
WEIGHBRIDGE: 16.25

AIR GAUGE CALIBRATION COMPLETED CORRECTLY.

Total for Service 0.00
Total for Work Order 0.00

Work Order		00024049		Work Order Date :		22/01/2020		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		1,029,062					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			Units	Rate	Extension			
SERVICE COMPLETED BILLY / SEAN 22.01.2020															
TOPPED UP ENGINE OIL, TOPPED UP COOLANT															
REPLACED LEFT INDICATOR IN BULLBAR															
REPLACED LEFT STEER HUB CAP															
ADJUSTED CLUTCH AS REQUIRED.															

Work Order		00024103		Work Order Date :		23/01/2020		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance		
Service Code:		GEN		General Repair		Meter Reading :		0								
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			Units	Rate	Extension				
COMPLETED BY BRIDGESTONE 23.01.2020																
INVOICE # 97957744																
		33000096		15	BRIAUS01	EX00012601	23/01/20	PM78,PUNCTURE REPAIR TBR		0.00	25.00	0.00				
		33000096		15	BRIAUS01	97957744	23/01/20	PM78,PUNCTURE REPAIR TBR		1.00	25.00	25.00				
											Total : Tyres		25.00			
											Total for Service		25.00			
											Total for Work Order		25.00			

Work Order		00024228		Work Order Date :		30/01/2020		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		GEN		General Repair				Meter Reading :		0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
SUPPLIED BY BROWN & HURLEY 30.01.2020															
INVOICE # 1821110															
												Total for Service		0.00	
												Total for Work Order		0.00	

Work Order		00024239		Work Order Date :		30/01/2020		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		GEN		General Repair		Meter Reading :		0							
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
COMPLETED BY BROWN & HURLEY 30.01.2020															
INVOICE # 1820758															
RIVET RH CORNER PANEL BACK ON TRUCK															
												Total for Service		0.00	
												Total for Work Order		0.00	

Work Order Service History

Work Order	00024280	Work Order Date :	30/01/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		COMPLETED BY AJ'S TOTAL TRUCK GEAR 30.01.2020 INVOICE # 17778								
										Total for Service 0.00
										Total for Work Order 0.00
Work Order	00024281	Work Order Date :	04/02/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		COMPLETED BY AJ'S TOTAL TRUCK GEAR 04.02.2020 ADJUSTMENT NOTE # 17823 ORIGINAL TAX INVOICE # 17778								
										Total for Service 0.00
										Total for Work Order 0.00
Work Order	00024353	Work Order Date :	05/02/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		COMPLETED BY FLEET IMAGING 05.02.2020 INVOICE # INV-7394								
		TO REPAIR, PRIME, PAINT & PIN-LINE FRONT OF K200 AS REQUESTED								
										Total for Service 0.00
										Total for Work Order 0.00
Work Order	00024370	Work Order Date :	07/02/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		REPAIR COMPLETED BY SEAN / KEIRAN 07.02.2020								
		REMOVED BENT BULL BAR, LIGHTS AND DAMAGED PANEL AND GRILL FITTED NEW PANEL, SENT TO GET PAINTED, FITTED LIGHTS AND CHECKED ADJUSTMENTS. REFITTED GRILL REMOVED BULL BAR FROM XQ36BA AND FITTED REWired DRIVING LIGHTS AND INDICATORS								
										Total for Service 0.00
										Total for Work Order 0.00
Work Order	00024749	Work Order Date :	25/02/2020	Repair Location :	EX0103	Yatala Workshop Exodas	Steer Tyre Rotatioln			
Service Code:	STEROT	Steer Tyre Rotation		Meter Reading :	1,044,667			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		STEER TYRE ROTATION COMPLETED.								
		COMPLETED BY BRIDGESTONE - DAVE 25.02.2020								
										Total for Service 0.00
										Total for Work Order 0.00
Work Order	00024783	Work Order Date :	25/02/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			

Work Order Service History

Service Code:		GEN	General Repair		Meter Reading :		0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details					
COMPLETED BY BRIDGESTONE 25.02.2020												
INVOICE # 98137404												
		33000085		15	BRIAUS01	EX00013006	25/02/20	PM78,ROTATE TBR TYRE		0.00	0.00	0.00
		33000051		15	BRIAUS01	EX00013006	25/02/20	PM78,BALANCE TBR		0.00	30.00	0.00
		33000051		15	BRIAUS01	98137404	25/02/20	PM78,BALANCE TBR		2.00	30.00	60.00
		33000085		15	BRIAUS01	98137404	25/02/20	PM78,ROTATE TBR TYRE		2.00	0.00	0.00
Total : Tyres												60.00
Total for Service												60.00
Total for Work Order												60.00

Work Order		00024870		Work Order Date :		29/02/2020		Repair Location :		EX0103		Yatala Workshop Exodas		B Service Cummins E5			
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		1,048,372				Units	Rate	Extension	
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details									
SERVICE COMPLETED.																	
															Total for Service		0.00

Service Code:		CUMBE5	B Service Cummins E5		Meter Reading :		1,048,372				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details						
SERVICE COMPLETED BY SEAN / BILLY / KEIRAN 29.02.2020													
REPLACED COMPLETED WIPER ARMS													
REPLACED RHS REAR GUARD													
TOPPED UP COOLANT, COULDN'T FIND ANY LEAKS													
NOTE TO BE ADDED TO DRAWER.													
Total for Service													0.00
Total for Work Order													0.00

Work Order		00024899		Work Order Date :		02/03/2020		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair				
Service Code:		GEN		General Repair		Meter Reading :		0				Units		Rate		Extension		
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details										
REPAIR COMPLETED.																		
REMOVED + REPLACED A/C FAN.																		
															Total for Service		0.00	
															Total for Work Order		0.00	

Work Order		00025496		Work Order Date :		25/03/2020		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5			
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		1,064,474				Units	Rate	Extension	
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details									
SERVICE COMPLETED BY BILLY 25.03.2020																	
CHANGED OUT FIRE EXTINGUISHER AS REQUIRED																	
CHANGED SPOTTER MIRROR ON DRIVERSIDE AS REQUIRED																	
USING COOLANT - INFORMED MICK - IS LOOKING LIKE REBUILD																	
															Total for Service		0.00
															Total for Work Order		0.00

Work Order		00025558	Work Order Date :		25/03/2020	Repair Location :		EX0103	Yatala Workshop Exodas		Drive Tyre Rotation	
------------	--	----------	-------------------	--	------------	-------------------	--	--------	------------------------	--	---------------------	--

Work Order Service History

Service Code:	ROTDRI	Drive Tyre Rotatioin	Meter Reading :	1,064,474	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

DRIVE TYRE ROTATION COMPLETED.

COMPLETED BY BRIDGESTONE - DAVE 25.03.2020

Total for Service 0.00

Total for Work Order 0.00

Work Order	00025738	Work Order Date :	27/03/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------------

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

COMPLETED BY BROWN & HURLEY 27.03.2020

INVOICE # 1867911

Total for Service 0.00

Total for Work Order 0.00

Work Order	00027222	Work Order Date :	30/03/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------------

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

COMPLETED BY BROWN & HURLEY 30.03.2020

INVOICE # 1869271

Total for Service 0.00

Total for Work Order 0.00

Work Order	00025886	Work Order Date :	01/04/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------------

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

Work Order Service History

COMPLETED BY CUMMINS 01.04.2020
INVOICE # 8516226

COMPLAINT:
CUSTOMER CONTRIBUTION
CAUSE:
CUSTOMER CONTRIBUTION TO REBUILD KIT
BELTS CRACKED
RADIATOR CAP DOES NOT HOLD PRESSURE
CUSTOMER OPTED TO REPLACE CYCLINDER HEAD
CORRECTION:
GUIDANZ SERVICE ORDER # 4900

HRS/KLMS: 1 064 517KLMS / 14 302 HRS
FUEL BURN: 548619 LTRS

DROVE VEHICLE INTO WORKSHOP
CARRY OUT ECM DOWNLOAD AND PRECHECKS
TROUBLESHOOT CUSTOMER COMPLAINT OF USING COOLANT
INSPECTED OIL FILL CAP TO FIND MILKY RESIDUE
CARRY OUT COMBUSTION GAS TEST TO FIND COLOUR DID NOT CHANGE
DRAIN OIL AND REMOVE OIL PAN
PRESSURE TESTED COOLING SYSTEM TO FIND COOLANT LEAKING FROM OUTSIDE OF LINER NUMBER 1
DRAIN COOLANT AND STRIP ENGINE TO REMOVE CYCLINDER HEAD
REMOVED CYCLINER HEAD AND MEASURE LINER HEIGHTS
FOUND LINERS # 1 AND # 5 TO HAVE BROKEN SHIMS AND # 2, # 3, # 4 AND # 6 TO HAVE FRETTING ON THE SHIMS
CLEANED AND INSPECTED COUNTERBORE LEDGES TO FIND OKAY - NO FRETTING
PRESSURE TESTED CAC TO FIND OKAY - 1 PSI DROP IN 15 SECS (SPEC IS NO MORE THEN 5 PSI IN 15 SECONDS)
CARRY OUT INCHASSIS REBUILD AS PER BELOW:
LINERS (WARRANTY)
PISONTS (RETAIL)
PISTON RINGS (WARRANTY)
MAIN BEARINGS (RETAIL)
CONNECTING ROD BEARINGS (WARRANTY)
UPPER GASKET SET (WARRANTY)
RECON CYCLINDER HEAD (RETAIL)
REFIT ALL REMOVED COMPONENTS
FILLED WITH NEW OIL AND COOLANT AND FITTED NEW FILTERS
START AND RUN ENGINE, OPERATE ON CHASSIS DYNO TO RUN IN CYLINDERS AND CONFIRM REPAIRS
STEAM CLEAN ENGINE BAY AND RETURN VEHICLE BACK INTO SERVICE

Total for Service 0.00

Total for Work Order 0.00

Work Order	00025930	Work Order Date :	02/04/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		COMPLETED BY BRIDGESTONE 02.04.2020								
		INVOICE # 4420414980								
		33000096		15	BRIAUS01	EX00013504	02/04/20 PUNCTURE REPAIR TBR,PM78	0.00	25.00	0.00
		33000096		15	BRIAUS01	4420414980	02/04/20 PUNCTURE REPAIR TBR,PM78	1.00	25.00	25.00
								Total : Tyres		25.00

Work Order Service History

Total for Service 25.00

Total for Work Order 25.00

Work Order	00026472	Work Order Date :	22/04/2020	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		AIR GAUGE: 17.5								
		ADJUSTED: 15.75								
		WEIGHBRIDGE: 15.4								
		AIR GAUGE CALIBRATION COMPLETED CORRECTLY.								

Total for Service 0.00

Total for Work Order 0.00

Work Order	00026512	Work Order Date :	22/04/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		COMPLETED BY CORRECT AUTO ELECTRICAL 22.04.2020								
		INVOICE # 00017376								
		PROCEED TO SITE								
		CHECK A/C, COMPRESSOR CLUTCH BROKEN								
		COLLECTED NEW COMPRESSOR AND DRIER FROM KENWORTH FOR CUSTOMER								
		COUPLE GAUGES AND RECOVER GAS								
		REMOVE AND FIT NEW COMPRESSOR AND RECEIVER DRIER (SUPPLIED BY CUSTOMER)								
		REPLACED O RINGS, PRESSURE TESTED, HELD PRESSURE, VACUUM SYSTEM, ADD OIL AND DYE								
		REGAS AND TESTED, WORKING FINE								

Total for Service 0.00

Total for Work Order 0.00

Work Order	00026516	Work Order Date :	27/04/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		COMPLETED BY BROWN & HURLEY 27.04.2020								
		INVOICE # 1888504								

Total for Service 0.00

Total for Work Order 0.00

Work Order		00026668		Work Order Date :		01/05/2020		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance		
Service Code:		GEN		General Repair				Meter Reading :		0						
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension			
COMPLETED BY BRIDGESTONE 01.05.2020																
INVOICE # 2720078010																
		11002831		15	BRIAUS01	EX00013869	01/05/20	TYRE 11R22.5 146/143L M766,PM78				0.00	503.00	0.00		
		33000084		15	BRIAUS01	EX00013869	01/05/20	FIT TBR TYRE,PM78				0.00	0.00	0.00		
		33000241		15	BRIAUS01	EX00013869	01/05/20	SCRAP TYRES TBR,PM78				0.00	15.50	0.00		
		33000096		15	BRIAUS01	EX00013869	01/05/20	PUNCTURE REPAIR TBR,PM78				0.00	25.00	0.00		
		33000096		15	BRIAUS01	2720078010	01/05/20	PUNCTURE REPAIR TBR,PM78				1.00	25.00	25.00		
		33000241		15	BRIAUS01	2720078010	01/05/20	SCRAP TYRES TBR,PM78				1.00	15.50	15.50		

Work Order Service History

33000084	15	BRIAUS01	2720078010	01/05/20	FIT TBR TYRE,PM78	1.00	0.00	0.00
11002831	15	BRIAUS01	2720078010	01/05/20	TYRE 11R22.5 146/143L M766,PM78	1.00	503.00	503.00
Total : Tyres								543.50
Total for Service								543.50
Total for Work Order								543.50

Work Order	00026681	Work Order Date :	02/05/2020	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5		
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------	--	--

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 1,084,263 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED.

Total for Service 0.00

Service Code: CUMBE5 B Service Cummins E5 Meter Reading : 1,084,263 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED BY SEAN / BILLY 02.05.2020

REPLACED MISSING EBS PLUG

Total for Service 0.00

Service Code: DEFECT Defect Repair Meter Reading : 0 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

Reported Defect :-
Defect Code : 00003899
Defect Reference : INTERNAL
Date : 02/03/2020
Description of Defect :
MONITOR
COOLANT LEAK

DEFECT CLEARED BY SEAN 02.05.2020
(NO LEAK)

Total for Service 0.00

Total for Work Order 0.00

Work Order	00026876	Work Order Date :	05/05/2020	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration		
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	---------------------------------	--	--

Service Code: WEICAL Weight Gauge Calibration Meter Reading : 0 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

AIR GAUGE: 12.5
ADJUSTED: 0
WEIGHBRIDGE: 12.2

AIR GAUGE CALIBRATION COMPLETED CORRECTLY.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00027291	Work Order Date :	21/05/2020	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5		
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------	--	--

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 1,097,716 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

Work Order Service History

SERVICE COMPLETED BY BILLY / KEIRAN / BEN 21.05.2020

WILL NEED TO CHECK DATE ON CABIN AIR FILTER NEXT SERVICE
WILL NEED TO CHECK U BOLTS NEXT SERVICE AS WAS OUT OF TIME
WILL NEED TO ADJUST STEER WHEEL BEARING NEXT B SERVICE - RAN OUT OF TIME
NEED TO REPLACE THRUST WASHER IN THE POWER DIVIDER AS A LOT OF COPPER WAS PULLED OUT OF FRONT DRIVE
REPLACED BOTH AIR LINES TO RUN TO TRAILER AS REQUIRED
ONE NYLON HOSE WAS KINKED SO REPLACED BOTH WITH RUBBER BRAKE HOSE AS REQUIRED

Total for Service 0.00

Total for Work Order 0.00

Work Order	00027292	Work Order Date :	21/05/2020	Repair Location :	EX0103	Yatala Workshop Exodas	C Service Cummins E5			
Service Code:	CUMCE5	C Service Cummins E5		Meter Reading :	1,097,716			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED BY BILLY / KEIRAN 21.05.2020										

REPLACED DIFF OIL, GEARBOX OIL, DIFF FILTER, GEARBOX FILTER, AIR DRYER FILTER, POWERSTEERING FILTER

Total for Service 0.00

Total for Work Order 0.00

Work Order	00027293	Work Order Date :	21/05/2020	Repair Location :	EX0103	Yatala Workshop Exodas	Exodas Annual Roadworthy NHVAS			
Service Code:	EXOINS	Exodas Annual Roadworthy NHVAS		Meter Reading :	1,097,716			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1										

INSPECTION COMPLETED BY SEAN 21.05.2020

Total for Service 0.00

Total for Work Order 0.00

Work Order	00027294	Work Order Date :	22/05/2020	Repair Location :	EX0103	Yatala Workshop Exodas	Steer Tyre Rotatioin			
Service Code:	STEROT	Steer Tyre Rotation		Meter Reading :	1,097,716			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
STEER TYRE ROTATION COMPLETED.										

COMPLETED BY BRIDGESTONE - JOHNNY 22.05.2020

Total for Service 0.00

Total for Work Order 0.00

Work Order	00027344	Work Order Date :	22/05/2020	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
AIR GAUGE: 17.5 ADJUSTED: 16 WEIGHBRIDGE: 15.68										

AIR GAUGE CALIBRATION COMPLETED CORRECTLY.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00027500	Work Order Date :	22/05/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------	--	--	--

Work Order Service History

Service Code: GEN		General Repair		Meter Reading : 0				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
COMPLETED BY BRIDGESTONE 22.05.2020										
INVOICE # 98534552										
		77000180		15	BRI AUS01	EX00014249	22/05/20 CASE STOCK 11-22.5,PM78	0.00	20.00	0.00
		11002831		15	BRI AUS01	EX00014249	22/05/20 TYRE 11R22.5 146/143L M766,PM78	0.00	0.00	0.00
		33000084		15	BRI AUS01	EX00014249	22/05/20 FIT TBR TYRE,PM78	0.00	0.00	0.00
		33000085		15	BRI AUS01	EX00014249	22/05/20 ROTATE TBR TYRE,PM78	0.00	0.00	0.00
		77000180		15	BRI AUS01	98534552	22/05/20 CASE STOCK 11-22.5,PM78	-2.00	20.00	-40.00
		11002831		15	BRI AUS01	98534552	22/05/20 TYRE 11R22.5 146/143L M766,PM78	1.00	0.00	0.00
		33000084		15	BRI AUS01	98534552	22/05/20 FIT TBR TYRE,PM78	2.00	0.00	0.00
		33000085		15	BRI AUS01	98534552	22/05/20 ROTATE TBR TYRE,PM78	2.00	0.00	0.00
Total : Tyres										-40.00
Total for Service										-40.00
Total for Work Order										-40.00

Work Order	00027656	Work Order Date :	08/06/2020	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------

Service Code: CUMAE5		A Service Cummins E5		Meter Reading : 1,108,673				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED BY SEAN / BEN 08.06.2020										
TENSIONED U BOLTS										
ADJUSTED LHS STEER BEARINGS AND REPLACED HUB CAP										
Total for Service										0.00

Service Code: DEFECT		Defect Repair		Meter Reading : 0				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
Reported Defect :-										
Defect Code : 00004328										
Defect Reference : INTERNAL										
Date : 21/05/2020										
Description of Defect :										
NEED TO CHECK DATE ON CABIN AIR FILTER NEXT SERVICE										
NEED TO CHECK U BOLTS										
NEED TO REPLACE THRUST WASHER IN THE POWER DIVIDER AS A LOT OF COPPER WAS PULLED OUT OF FRONT DRIVE										
DEFECT CLEARED BY SEAN 08.06.2020										
Reported Defect :-										
Defect Code : 00004329										
Defect Reference : INTERNAL										
Date : 21/05/2020										
Description of Defect :										
WILL NEED TO ADJUST LEFT STEER WHEEL BEARING NEXT B SERVICE										
DEFECT CLEARED BY SEAN 08.06.2020										
Total for Service										0.00
Total for Work Order										0.00

Work Order	00027751	Work Order Date :	11/06/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------

Work Order Service History

Service Code:	DEFECT	Defect Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

DEFECT CLEARED.

SERVICE COMPLETED BY BILLY 11/6/20

CHANGED OUT STALK FOR INDICATORS + WASHERS AS REQUIRED

TRUCK CUT OUT ON THE WAY IN TO THE WORKSHOP, CHECKED ALL WIRING POSSIBLE COULDN'T FAULT , CHECKED BATTERIES, EARTH GROUND, + STARTER BOLTS NUTS COULDN'T FAULT

Total for Service 0.00

Service Code:	GEN	General Repair	Meter Reading :	1,110,917	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

REPAIR COMPLETED.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00027952	Work Order Date :	23/06/2020	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------

Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	1,119,654	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

SERVICE COMPLETED.

service completed 23/06/20 by duane

front left hand side wheel hub cap replacement

right hand side level tank strap replacement

check right hand side hub for oil level next service

Total for Service 0.00

Total for Work Order 0.00

Work Order	00028130	Work Order Date :	25/06/2020	Repair Location :	EX0103	Yatala Workshop Exodas	Drive Tyre Rotatoin
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	----------------------------

Service Code:	ROTDRI	Drive Tyre Rotatoin	Meter Reading :	1,121,116	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

DRIVE TYRE ROTATION COMPLETED.

COMPLETED BY BRIDGESTONE - johnny 25/6/20

Total for Service 0.00

Total for Work Order 0.00

Work Order	00028219	Work Order Date :	25/06/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

service completed by sean 25/6/20

checked nox sensor for power had 10.4 v

removed wiring harness ran 2 new wires + refitted harness checked for power had 11.3v

Total for Service 0.00

Total for Work Order 0.00

Work Order	00028704	Work Order Date :	29/06/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------------

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

Work Order Service History

REPAIR COMPLETED BY CUMMINS 29.06.2020

INV: 8620980

CLIP CAME OFF TURBO WASTGATE.
FOUND WASTE GATE ACTUATOR ROD HAD FALLEN OFF, NO CLIP ON LEVER, LEVER BENT.
VISUALLY INSPECTED TURBO.
NOX SENSOR INTERNAL MALFUNCTION.
CARRIED OUT TURBO WASTE GATE CAMPAIGN.
REMOVED TURBO, SET UP NEW AND THEN FITTED.
WASTE-GAT TRAVEL 0.054" AT 31PSI.
RAN, WASHED AND ROAD TESTED TO VERIFY REPAIRS.

STUD
SENSOR, NOX
RECON TURBO HE600WG
NUT REGULAR HEXAGON.

Total for Service 0.00
Total for Work Order 0.00

Work Order	00028506	Work Order Date :	09/07/2020	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5			
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------	--	--	--

Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	1,131,667	Units	Rate	Extension
---------------	--------	----------------------	-----------------	-----------	-------	------	-----------

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED.

Total for Service 0.00

Service Code:	CUMBE5	B Service Cummins E5	Meter Reading :	1,131,667	Units	Rate	Extension
---------------	--------	----------------------	-----------------	-----------	-------	------	-----------

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED.

service completed keiran ben mick
adjusted turntable
reverse beeper not working

Total for Service 0.00

Service Code:	DEFECT	Defect Repair	Meter Reading :	0	Units	Rate	Extension
---------------	--------	---------------	-----------------	---	-------	------	-----------

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

DEFECT CLEARED. duane 9/7/20

Reported Defect :-
Defect Code : 00002674
Defect Reference : WO17815
Date : 24/06/2019
Description of Defect :
LEFT CAB SHOCK U/S

Total for Service 0.00

Total for Work Order 0.00

Work Order	00028522	Work Order Date :	09/07/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------	--	--	--

Service Code:	DEFECT	Defect Repair	Meter Reading :	0	Units	Rate	Extension
---------------	--------	---------------	-----------------	---	-------	------	-----------

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

DEFECT CLEARED.replaced by keiran signed by duane 09/07/20

Work Order Service History

Reported Defect :-

Defect Code : 00001013

Defect Reference : W/O 8556

Date : 28/02/2018

Description of Defect :

RHS CAB RAM LEAKING. NEW ONE \$1065.00 INC. SEE QUOTE 168431. B&H

Total for Service 0.00

Service Code: GEN General Repair Meter Reading : 1,131,667

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

REPAIR COMPLETED.

job completed by duane 09/07/20

removed old wlt front drive bag

replace with new one

remove and replaced rlts cab ram with repaired one at hydraulics / sent leaking one over to be replaced

Total for Service 0.00

Total for Work Order 0.00

Work Order 00029049 **Work Order Date :** 27/07/2020 **Repair Location :** EX0103 **Yatala Workshop Exodas** **A Service Cummins E5**

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 1,146,081

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED.BY Keiran 25/07/20

Total for Service 0.00

Total for Work Order 0.00

Work Order 00029152 **Work Order Date :** 29/07/2020 **Repair Location :** EX0103 **Yatala Workshop Exodas** **Steer Tyre Rotation**

Service Code: STEROT Steer Tyre Rotation Meter Reading : 1,149,063

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

STEER TYRE ROTATION COMPLETED.

COMPLETED BY BRIDGESTONE - DAVE - 29.07.2020.

Total for Service 0.00

Total for Work Order 0.00

Work Order 00029381 **Work Order Date :** 05/08/2020 **Repair Location :** EX0103 **Yatala Workshop Exodas** **General Repair/Maintenance**

Service Code: GEN General Repair Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

77000194 15 BRIAUS01 EX00015080 05/08/20 case stock 295/80-22.5,PM78 0.00 20.00 0.00

11001553 15 BRIAUS01 EX00015080 05/08/20 TYRE 295/80R22.5 152/148M BS R150,PM78 0.00 0.00 0.00

33000084 15 BRIAUS01 EX00015080 05/08/20 FIT TBR TYRE,PM78 0.00 0.00 0.00

33000051 15 BRIAUS01 EX00015080 05/08/20 BALANCE TBR,PM78 0.00 30.00 0.00

33000051 15 BRIAUS01 98944530 05/08/20 BALANCE TBR,PM78 2.00 30.00 60.00

33000084 15 BRIAUS01 98944530 05/08/20 FIT TBR TYRE,PM78 2.00 0.00 0.00

11001553 15 BRIAUS01 98944530 05/08/20 TYRE 295/80R22.5 152/148M BS R150,PM78 1.00 0.00 0.00

77000194 15 BRIAUS01 98944530 05/08/20 case stock 295/80-22.5,PM78 -2.00 20.00 -40.00

Total : Tyres 20.00

Total for Service 20.00

Total for Work Order 20.00

Work Order Service History

Work Order		00029417		Work Order Date :		11/08/2020		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5				
Service Code:		CUMAE5		A Service Cummins E5		Meter Reading :		1,155,609				Units		Rate		Extension		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details											
SERVICE COMPLETED BY SEAN AND BEN 11.08.2020																		
REMOVED G/BOX, CLUTCH AND FLYWHEEL. INSTALLED NEW MACHINED FLYWHEEL + NEW CLUTCH. SWAPPED ALL WIRING, SENSORS + FITTINGS TO NEW G/BOX, FITTED NEW G/BOX. REPLACED FIRST UNI JOINT FROM REAR OF G/BOX.																		
															Total for Service		0.00	
Service Code:		DEFECT		Defect Repair		Meter Reading :		0				Units		Rate		Extension		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details											
DEFECT CLEARED. Reported Defect :- Defect Code : 00004538 Defect Reference : 07960 Date : 03/07/2020 Description of Defect : bunny hop violently under load when taking off requires low low when heavy Reported Defect :- Defect Code : 00004541 Defect Reference : 07958 Date : 25/06/2020 Description of Defect : headlight need adjusting or need new lights 2.3 metres they shine Reported Defect :- Defect Code : 00004543 Defect Reference : Date : 25/06/2020 Description of Defect : gear box jumps out of gears while making a bang sound under load i feel tailshaft vibration changing down gears splits and gears will make truck jump and jerk Reported Defect :- Defect Code : 00004545 Defect Reference : 07954 Date : 09/07/2020 Description of Defect : releasing clutch on take off while loaded truck bunny hops and yerks Reported Defect :- Defect Code : 00004692 Defect Reference : 07958 Date : 25/06/2020 Description of Defect : Headlight needs adjusting or need new lights 2 - 3 metres when they shine																		
															Total for Service		0.00	
															Total for Work Order		0.00	
Work Order		00030075		Work Order Date :		02/09/2020		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance				

Work Order Service History

Service Code: GEN General Repair Meter Reading : 1,169,438 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

Repaired By: EXPRESS TRUCK MAINTENANCE 02/09/2020.

REBUILD FAN HUB ASSEMBLY, R&R.

Total for Service 0.00

Total for Work Order 0.00

Work Order 00030832 Work Order Date : 28/09/2020 Repair Location : EX0103 Yatala Workshop Exodas B Service Cummins E5

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 1,187,134 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED.

Total for Service 0.00

Service Code: CUMBE5 B Service Cummins E5 Meter Reading : 1,187,134 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED BY BEN AND JESSE 28.09.2020

REPLACED RHS STEER HUB SEAL
 REPLACED FUEL FILTER
 FITTED NEW EBS PLUG
 FITTED NEW HUB CAP TO LHS STEER
 FITTED NEW HUB CAP GASKET TO LHS STEER
 FITTED NEW HUB CAP AND GASKET TO RHS STEER
 FITTED NEW BRAKE SHOES TO LHS + RHS OF STEER AXLE.

Total for Service 0.00

Service Code: DEFECT Defect Repair Meter Reading : 0 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

DEFECT CLEARED BY JESSE 28.09.2020

Reported Defect :-
 Defect Code : 00004981
 Defect Reference : 07967
 Date : 10/09/2020
 Description of Defect :
 LHS HUB LEAKING OIL

Total for Service 0.00

Total for Work Order 0.00

Work Order 00030833 Work Order Date : 28/09/2020 Repair Location : EX0103 Yatala Workshop Exodas Eco Wind Service

Service Code: ECO Eco Wind Service Meter Reading : 5,120 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED.

Total for Service 0.00

Total for Work Order 0.00

Work Order 00032109 Work Order Date : 05/11/2020 Repair Location : EX0103 Yatala Workshop Exodas General Repair/Maintenance

Service Code: GEN General Repair Meter Reading : 0 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED BY BROWN AND HURLEY

Work Order Service History

Total for Service 0.00

Total for Work Order 0.00

Work Order	00032120	Work Order Date :	05/11/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	1,207,341			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
REPAIR COMPLETED BY SEAN05/11/20										
REPLACED LHS STEER HUB GASKET REPLACED RHS STEERWHEEL BEARINGS AND SEAL TIGHTENED RHS REAR DRIVE AXLE GASKET										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00032125	Work Order Date :	05/11/2020	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	1,207,341			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED.										
REPLACED LHS STEER HUB GASKET REPLACED RHS STEER WHEEL BEARINGS AND SEAL TIGHTENED RHS REAR DRIVE AXLE GASKET										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00032132	Work Order Date :	05/11/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	TYRDRI	Tyre Service - Drive		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		33000096		15	BRIAUS01	EX00016384	05/11/20 PUNCTURE REPAIR TBR, ODO 1204366	0.00	25.00	0.00
		33000115		15	BRIAUS01	EX00016384	05/11/20 SVC CALL OUT NORMAL HOURS/15MINS, ODO 1204366	0.00	20.00	0.00
		33000115		15	BRIAUS01	99415618	05/11/20 SVC CALL OUT NORMAL HOURS/15MINS, ODO 1204366	4.00	20.00	80.00
		33000096		15	BRIAUS01	99415618	05/11/20 PUNCTURE REPAIR TBR, ODO 1204366	1.00	25.00	25.00
Total : Tyres										105.00
Total for Service										105.00
Total for Work Order										105.00

Work Order	00032373	Work Order Date :	05/11/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED BY										
Total for Service										0.00

Total for Work Order 0.00

Work Order	00032569	Work Order Date :	21/11/2020	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	1,220,457			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

SLIP JOINT BEHIND TURBO LEAKING
GEAR STICK BOOT U/S

TOPPED UP COOLANT

Total for Service	0.00
--------------------------	-------------

Service Code:	DEFECT	Defect Repair	Meter Reading :	0
---------------	--------	---------------	-----------------	---

Units	Rate	Extension
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
-----------	----------	--------------	-----------	----------	----------	---------	---------

Reported Defect :-
Defect Code : 00005376
Defect Reference : 07972
Date : 19/11/2020
Description of Defect :
OVERDUE FOR "A" SERVICE

DEFECT CLEARED BY SEAN 21/11/20

Reported Defect :-
Defect Code : 00005375
Defect Reference : 07972
Date : 19/11/2020
Description of Defect :
AIC CON DOESN'T WORK

DEFECT CLEARED BY SEAN 21/11/20

Reported Defect :-
Defect Code : 00005374
Defect Reference : 07972
Date : 19/11/2020
Description of Defect :
DRIVER WINDOW WON'T WORK

DEFECT CLEARED BY SEAN 21/11/20

Reported Defect :-
Defect Code : 00005373
Defect Reference : 07972
Date : 19/11/2020
Description of Defect :
TRAILER LIGHTS WON'T WORK

DEFECT CLEARED BY SEAN 21/11/20

Total for Service	0.00
--------------------------	-------------

Total for Work Order	0.00
-----------------------------	-------------

Work Order	00033074	Work Order Date :	12/12/2020	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------

Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	1,237,670
---------------	--------	----------------------	-----------------	-----------

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
-----------	----------	--------------	-----------	----------	----------	---------	---------

Units	Rate	Extension
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100

SERVICE COMPLETED.

Total for Service	0.00
--------------------------	------

Service Code:	CUMBE5	B Service Cummins E5	Meter Reading :	1,237,670
---------------	--------	----------------------	-----------------	-----------

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
-----------	----------	--------------	-----------	----------	----------	---------	---------

Units	Rate	Extension
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100

Work Order Service History

SERVICE COMPLETED BY MICK

REPALCED BEARING IN PULLEY ON AC SYSTEM
 REPALCED GEAR STICK BOOT
 CHECKED AIR LEAK (COULD NOT FAULT)
 SLIP JOINT LEAKING

*FITTING ON AC COMPRESSOR MISTING

Total for Service 0.00

Service Code: DEFECT Defect Repair Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

Reported Defect :-
 Defect Code : 00005394
 Defect Reference : WO32569
 Date : 21/11/2020
 Description of Defect :
 GEAR STICK BOOT U/S

DEFECT CLEARED BY MICK
 Reported Defect :-
 Defect Code : 00005377
 Defect Reference : 07972
 Date : 19/11/2020
 Description of Defect :
 HOLES IN FLOOR

NEEDS GEAR STICK BOOT

DEFECT CLEARED BY MICK
 Reported Defect :-
 Defect Code : 00004851
 Defect Reference : 07965
 Date : 24/08/2020
 Description of Defect :
 TRUCK HAS AIR LEAK, CAN HEAR AIR LEAKING FROM BEHIND CAB + FRONT OF GRILL.

CHECK AT B SERVICE
 DEFECT CLEARED BY MICK

Total for Service 0.00

Total for Work Order 0.00

Work Order	00033107	Work Order Date :	14/12/2020	Repair Location :	EX0103	Yatala Workshop Exodas	Warranty Work
------------	----------	-------------------	------------	-------------------	--------	------------------------	---------------

Service Code: WARRANT Warranty Work Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

CAB SHOCK ABSORBER FRONT AIR, REPLACE
 REPLACE BUMP STOPS
 REPLACE LHS CAB SUSPENSION CONTROL ROD
 REPLACE TWO GRILL CLIPS

Total for Service 0.00

Total for Work Order 0.00

Work Order	00033373	Work Order Date :	31/12/2020	Repair Location :	EX0103	Yatala Workshop Exodas
------------	----------	-------------------	------------	-------------------	--------	------------------------

Work Order Service History

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 1,251,495 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED BY SEAN

Total for Service 0.00

Total for Work Order 0.00

Work Order 00033631 Work Order Date : 12/01/2021 Repair Location : EX0103 Yatala Workshop Exodas General Repair

Service Code: GEN General Repair Meter Reading : 1,254,419 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

REPAIR COMPLETED BY KEIRAN

RH SPOT LIGHT BRACKET WAS BROKEN, DIDN'T HAVE A SPARE BRAKET SO REPLACED BOTH LIGHTS

Total for Service 0.00

Total for Work Order 0.00

Work Order 00033861 Work Order Date : 13/01/2021 Repair Location : EX0103 Yatala Workshop Exodas Weight Gauge Calibration

Service Code: WEICAL Weight Gauge Calibration Meter Reading : 0 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

AIR GAUGE: 14,500
ADJUSTED: 15,500
WEIGHBRIDGE: 15,170

AIR GAUGE CALIBRATION COMPLETED CORRECTLY.

Total for Service 0.00

Total for Work Order 0.00

Work Order 00033879 Work Order Date : 18/01/2021 Repair Location : EX0103 Yatala Workshop Exodas Weight Gauge Calibration

Service Code: WEICAL Weight Gauge Calibration Meter Reading : 0 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

AIR GAUGE: 1800
ADJUSTED: 16,500
WEIGHBRIDGE: 16,230

AIR GAUGE CALIBRATION COMPLETED CORRECTLY.

Total for Service 0.00

Total for Work Order 0.00

Work Order 00034034 Work Order Date : 23/01/2021 Repair Location : EX0103 Yatala Workshop Exodas Eco Wind Service

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 0 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED.

Total for Service 0.00

Service Code: CUMBE5 B Service Cummins E5 Meter Reading : 1,263,315 Units Rate Extension

Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED BEN, KEIRAN AND MICK

FITTED ANDERSON LEAD
REPLACED LHS HI BEAM BULB

Work Order Service History

								Total for Service	0.00	
Service Code:	DEFECT	Defect Repair			Meter Reading :		0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
Reported Defect :- Defect Code : 00005506 Defect Reference : 07974 Date : 25/11/2020 Description of Defect : NEEDS NEW DRIVERS SEAY IT IS WORN OUT AND VERY UNCOMFORTABLE NEW DRIVER SAYS ITS OK DEFECT CLEARED BY MICK 23.01.21										
								Total for Service	0.00	
Service Code:	ECO	Eco Wind Service			Meter Reading :		1,263,315	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED BY BEN										
								Total for Service	0.00	
								Total for Work Order	0.00	
Work Order	00034169	Work Order Date :		28/01/2021		Repair Location :		EX0103	Yatala Workshop Exodas	General Repair/Maintenance
Service Code:	TYRES	Tyres Service - Trailer		Meter Reading :		0		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		77000180		15	BRIAUS01	EX00017463	28/01/21 CASE STOCK 11-22.5,PM78	0.00	20.00	0.00
		77000180		15	BRIAUS01	85297027	28/01/21 CASE STOCK 11-22.5,PM78	-1.00	20.00	-20.00
								Total : Tyres		-20.00
								Total for Service		-20.00
								Total for Work Order		-20.00
Work Order	00034738	Work Order Date :		15/02/2021		Repair Location :		EX0103	Yatala Workshop Exodas	Weight Gauge Calibration
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :		0		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
AIR GAUGE: 17800 ADJUSTED: 14500 WEIGHBRIDGE: 14060 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.										
								Total for Service	0.00	
								Total for Work Order	0.00	
Work Order	00034988	Work Order Date :		23/02/2021		Repair Location :		EX0103	Yatala Workshop Exodas	B Service Cummins E5
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :		1,286,366		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED.										
								Total for Service	0.00	
Service Code:	CUMBE5	B Service Cummins E5		Meter Reading :		1,286,366		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

Work Order Service History

SERVICE COMPLETED BY SEAN AND KEIRAN

TIGHTENED LOAD LIGHTS
TIGHTENED BELLY BAR
REPLACED WIPER BLADES

Total for Service 0.00
Total for Work Order 0.00

Work Order		00035027		Work Order Date :		23/02/2021		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance			
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		0							
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details							Units	Rate	Extension	
		11001553		15	BRIAUS01	EX00017869	23/02/21	TYRE 295/80R22.5 152/148M BS R150,PM78							0.00	507.50	0.00
		33000051		15	BRIAUS01	EX00017869	23/02/21	BALANCE TBR,PM78							0.00	30.00	0.00
		33000051		15	BRIAUS01	85439688	23/02/21	BALANCE TBR,PM78							2.00	30.00	60.00
		11001553		15	BRIAUS01	85439688	23/02/21	TYRE 295/80R22.5 152/148M BS R150,PM78							2.00	507.50	1,015.00
														Total : Tyres		1,075.00	
														Total for Service		1,075.00	
														Total for Work Order		1,075.00	

Work Order		00035118		Work Order Date :		23/02/2021		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration	
Service Code:		WEICAL		Weight Gauge Calibration		Meter Reading :		0							
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension				
	AIR GAUGE: 16500 ADJUSTED: 17000 WEIGHBRIDGE: 16580														
	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.														
											Total for Service		0.00		
											Total for Work Order		0.00		

Work Order		00035210		Work Order Date :		01/03/2021		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair	
Service Code:		GEN		General Repair		Meter Reading :		0							
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension				
REPAIR COMPLETED BY SEAN															
R&R WEIGHT GAUGE															
											Total for Service		0.00		
											Total for Work Order		0.00		

Work Order		00035236		Work Order Date :		01/03/2021		Repair Location :		EX0103		Yatala Workshop Exodas		
Service Code:		WEICAL		Weight Gauge Calibration				Meter Reading :		0				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			Units	Rate	Extension		
AIR GAUGE: 12200 ADJUSTED: 13600 WEIGHBRIDGE: 13350														
AIR GAUGE CALIBRATION COMPLETED CORRECTLY.														

Work Order Service History

Total for Service 0.00

Total for Work Order 0.00

Work Order	00035373	Work Order Date :	01/03/2021	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	1,289,885			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
REPAIR COMPLETED BY KEIRAN										
REFITTED WIPERS AND SQUEEZED SITES IN, REMOVED BOTH ARMS AND CLEANED SPLINES										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00035564	Work Order Date :	08/03/2021	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	1,298,380			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED BY SEAN AND KEIRAN										
REPLACED REAR DRIVE SHOCKS REPLACED 1X STEP FOR CAB LIFTS TOPPED UP COOLANT CLEANED, TIGHTENED AND CHECKED STEER HUBS TIGHTENED GRILL REPLACED 1X SUN VISOR CLIP										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00035897	Work Order Date :	09/03/2021	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
AIR GAUGE: 15250 ADJUSTED:15750 WEIGHBRIDGE:15470										
AIR GAUGE CALIBRATION COMPLETED CORRECTLY.										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00036022	Work Order Date :	18/03/2021	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
AIR GAUGE: 13400 ADJUSTED: 12700 WEIGHBRIDGE: 12460										
AIR GAUGE CALIBRATION COMPLETED INCORRECTLY.										

Total for Service 0.00

Total for Work Order 0.00

Work Order	00035987	Work Order Date :	19/03/2021	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------	--	--	--

Work Order Service History

Service Code:		TYRES	Tyres Service - Trailer			Meter Reading :			0			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension	
		33000051		39	BRIAUS01	EX00018225	19/03/21	BALANCE TBR,PM78	0.00	30.00	0.00	
		33000051		39	BRIAUS01	85578531	19/03/21	BALANCE TBR,PM78	2.00	30.00	60.00	
										Total : Tyres		60.00
										Total for Service		60.00
										Total for Work Order		60.00

Work Order		00036118		Work Order Date :		24/03/2021		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			Units	Rate	Extension			
		33000096		15	BRIAUS01	EX00018293	24/03/21	PUNCTURE REPAIR TBR,PM78		0.00	25.00	0.00			
		33000096		15	BRIAUS01	85604116	24/03/21	PUNCTURE REPAIR TBR,PM78		1.00	25.00	25.00			
												Total : Tyres		25.00	
												Total for Service		25.00	
												Total for Work Order		25.00	

Work Order		00036145		Work Order Date :		26/03/2021		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5		Meter Reading :		1,309,715							
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
SERVICE COMPLETED BY SEAN															
R&R LHS STOP/PARK LIGHT															
REPLACED DRAW FRIDGE															
REPLACED FAN ON SLEEPER AIR															
REPLACED 3 X BOOST HOSES															
CHECKED WASTE GATE ADJUSTMENT ON TURBO AND REPLACED MISSING C CLIP ON WASTE GATE															
												Total for Service		0.00	
												Total for Work Order		0.00	

Work Order		00036722		Work Order Date :		26/03/2021		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration	
Service Code:		WEICAL		Weight Gauge Calibration				Meter Reading :		0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details						Units	Rate	Extension
AIR GAUGE: 15000 ADJUSTED: 15500 WEIGHBRIDGE: 15190 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.															
													Total for Service		0.00
													Total for Work Order		0.00

Work Order	00036619	Work Order Date :	10/04/2021	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	1,319,343		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details
SERVICE COMPLETED BY BEN AND MICK							
REQUIRES ALL DRIVE BRAKE RELINE DUE TO WEARING UNEVEN FITTED GPS TRACKER - 1106885324							

Work Order Service History

Total for Service 0.00

Total for Work Order 0.00

Work Order	00038834	Work Order Date :	22/04/2021	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------

Service Code: GEN General Repair Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

REPAIR COMPLETED BY KEIRAN AND RYAN

BOTH STEER HUB CAP GASKETS LEAKING, REMOVED CAPS AND FOUND GLITTER IN RH HUB
PULLED BEARINGS AND FOUND DENTS ON OUTER BEARING AND CUP, REPLACED BEARINGS BOTH SIDES (KEIRAN RH AND RYAN LH)

NEED TO CHECK WHEEL BEARING ADJUSYMENT ON NEXT SERVICE

Total for Service 0.00

Total for Work Order 0.00

Work Order	00037569	Work Order Date :	12/05/2021	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 1,331,272

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED.

Total for Service 0.00

Service Code: CUMBE5 B Service Cummins E5 Meter Reading : 1,331,272

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED BY MICK AND RYAN

FITTED MISSING BOLTS TO INTAKE BRACKET
REPLACED AIR FILTER
SLIP JOINT BEHIND TURBO IS ALL OK
DISASSEMBLED WHEELS BRAKE DRUMS AND SHOES
ASSEMBLED NEW SHOES, DRUM AND WHEELS, ADJUSTED THE BRAKES

Total for Service 0.00

Service Code: DEFECT Defect Repair Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

Reported Defect :-
Defect Code : 00005393
Defect Reference : WO32569
Date : 21/11/2020
Description of Defect :
SLIP JOINT BEHIND TURBO LEAKING

Total for Service 0.00

Total for Work Order 0.00

Work Order	00037756	Work Order Date :	13/05/2021	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------

Service Code: GEN General Repair Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

REPAIR COMPLETED BY SEAN AND BEN

R&R BATTERIES
R&R ALTERNATOR, REPAIRED BY BEN AND SEAN

Total for Service 0.00

Total for Work Order 0.00

Work Order Service History

Work Order	00037757	Work Order Date :	13/05/2021	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
REPAIR COMPLETED BY RYAN AND KEIRAN										
REMOVED RHS REAL DRIVE AND BRAKE DRUM WHEELS, BROUGHT ABS SENSOR IN PLACE ASSEMBLED HUB AND WHEELS BACK										
CHECKED THE VOLTAGE FROM THE AFTER TREATMENT HOUSING COULDN'T FIND ANY PROBLEM REPLACED NOX SENSOR										
Total for Service										0.00
Total for Work Order										0.00
Work Order	00037800	Work Order Date :	20/05/2021	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	TYRES	Tyres Service - Trailer		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		33000051		15	BRIAUS01	EX00019041	20/05/21 BALANCE TBR,PM78	0.00	30.00	0.00
		33000051		15	BRIAUS01	85901964	20/05/21 BALANCE TBR,PM78	2.00	30.00	60.00
Total : Tyres										60.00
Total for Service										60.00
Total for Work Order										60.00
Work Order	00038822	Work Order Date :	14/06/2021	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	TYRES	Tyres Service - Trailer		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		33000096		15	BRIAUS01	EX00019435	14/06/21 PUNCTURE REPAIR TBR,PM78	0.00	25.00	0.00
		33000115		15	BRIAUS01	EX00019435	14/06/21 SVC CALL OUT NORMAL HOURS/15MINS,PM78	0.00	20.00	0.00
		33000115		15	BRIAUS01	4340184953	14/06/21 SVC CALL OUT NORMAL HOURS/15MINS,PM78	4.00	20.00	80.00
		33000096		15	BRIAUS01	4340184953	14/06/21 PUNCTURE REPAIR TBR,PM78	1.00	25.00	25.00
Total : Tyres										105.00
Total for Service										105.00
Total for Work Order										105.00
Work Order	00038525	Work Order Date :	15/06/2021	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	1,340,918			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED BY SEAN										
R&R RHS AXLE CAP WITH NEW TRP CAP - MONITOR RESULTS COULDN'T FAULT WINDOW COULDN'T FAULT FRIDGE TOPPED UP ENGINE OIL										
Total for Service										0.00
Service Code:	DEFECT	Defect Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

Work Order Service History

Reported Defect :-

Defect Code : 00006528

Defect Reference : 12727

Date : 14/06/2021

Description of Defect :

RIGHT HAND WINDOW NOT WORKING

L/H, R/H FRONT WHEEL BEARING COVER LEAKING

DEFECT CLEARED BY SEAN 15.06.21

Reported Defect :-

Defect Code : 00005600

Defect Reference : 07975

Date : 08/12/2020

Description of Defect :

FRIDGE UNDER BUNK NOT WORKING

COULDN'T FAULT

Reported Defect :-

Defect Code : 00005964

Defect Reference : 07977

Date : 17/02/2021

Description of Defect :

FRIDGE UNDER BUNK NOT WORKING

COULDN'T FAULT

Reported Defect :-

Defect Code : 00005633

Defect Reference : 07976

Date : 19/12/2020

Description of Defect :

FRIDGE UNDER BUNK NOT WORKING

COULDN'T FAULT

Total for Service 0.00

Total for Work Order 0.00

Work Order	00038662	Work Order Date :	18/06/2021	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
REPAIR COMPLETED BY SEAN										
R&R DRIVERS WINDOW SWITCH										
										Total for Service 0.00
										Total for Work Order 0.00
Work Order	00039685	Work Order Date :	17/07/2021	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	DEFECT	Defect Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

Work Order Service History

Reported Defect :-

Defect Code : 00006686

Defect Reference : 12725

Date : 17/07/2021

Description of Defect :

L/HSTEER WHEEL LEAKING HUB SEAL REPLACE EXHAUST PIPE RUSTING OUT IF YOU CAN

DEFECT CLEARED BY SEAN 17.07.2021

Total for Service 0.00

Service Code: GEN General Repair Meter Reading : 1,350,565

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

REPAIR COMPLETED BY SEAN

R&R LHS STEER HUB CAP

Total for Service 0.00

Total for Work Order 0.00

Work Order 00040171 **Work Order Date :** 02/08/2021 **Repair Location :** EX0103 **Yatala Workshop Exodas** **General Repair/Maintenance**

Service Code: TYRES Tyres Service - Trailer Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

		77000180		15	BRIAUS01	EX00020025	02/08/21	CASE STOCK 11-22.5,PM78	0.00	20.00	0.00
--	--	----------	--	----	----------	------------	----------	-------------------------	------	-------	------

		77000180		15	BRIAUS01	86292361	02/08/21	CASE STOCK 11-22.5,PM78	-3.00	20.00	-60.00
--	--	----------	--	----	----------	----------	----------	-------------------------	-------	-------	--------

Total : Tyres -60.00

Total for Service -60.00

Total for Work Order -60.00

Work Order 00040195 **Work Order Date :** 03/08/2021 **Repair Location :** EX0103 **Yatala Workshop Exodas** **General Repair/Maintenance**

Service Code: TYRES Tyres Service - Trailer Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

		33000051		15	BRIAUS01	EX00020038	03/08/21	BALANCE TBR,PM78	0.00	30.00	0.00
--	--	----------	--	----	----------	------------	----------	------------------	------	-------	------

		33000051		15	BRIAUS01	86294801	03/08/21	BALANCE TBR,PM78	2.00	30.00	60.00
--	--	----------	--	----	----------	----------	----------	------------------	------	-------	-------

Total : Tyres 60.00

Total for Service 60.00

Total for Work Order 60.00

Work Order 00040742 **Work Order Date :** 12/08/2021 **Repair Location :** EX0103 **Yatala Workshop Exodas** **General Repair**

Service Code: GEN General Repair Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

REPAIR COMPLETED BY SEAN.

R&R RHS SPOT MIRROR

Total for Service 0.00

Total for Work Order 0.00

Work Order 00041508 **Work Order Date :** 04/09/2021 **Repair Location :** EX0103 **Yatala Workshop Exodas** **A Service Cummins E5**

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 1,364,839

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED BY KEIRAN AND BEN

REPLACED LH REAR BRAKE BOOSTER

Work Order Service History

										Total for Service		0.00
Service Code:		CUMCE5	C Service Cummins E5				Meter Reading :		1,364,839			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			Units	Rate	Extension

SERVICE COMPLETED BY KEIRAN AND BEN

COMPLETED FULL C/D SERVICE
ADJUSTED CLUTCH

										Total for Service		0.00
Service Code:		EXOINS		Exodas Annual Roadworthy NHVAS			Meter Reading :		1,364,839			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension	

VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION.
ATTEMPT # 1

INSPECTION COMPLETED BY KEIRAN

								Total for Service	0.00
								Total for Work Order	0.00

Work Order	00042220	Work Order Date : 23/09/2021		Repair Location : EX0103		Yatala Workshop Exodas		General Repair		
-------------------	-----------------	-------------------------------------	--	---------------------------------	--	------------------------	--	----------------	--	--

Service Code:	GEN	General Repair		Meter Reading :		1,137,283		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

REPAIR COMPLETED BY BEN.

REPLACED DRIVER SIDE HEADLIGHT CHROME COVER.

								Total for Service	0.00
								Total for Work Order	0.00

Work Order	00042667	Work Order Date : 08/10/2021		Repair Location : EX0103		Yatala Workshop Exodas		General Repair/Maintenance		
-------------------	-----------------	-------------------------------------	--	---------------------------------	--	------------------------	--	----------------------------	--	--

Service Code:	TYRES	Tyres Service - Trailer		Meter Reading :		0		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

		77000194		15	BRIAUS01	EX00020815	08/10/21	case stock 295/80-22.5,PM78	0.00	20.00	0.00
		33000051		15	BRIAUS01	EX00020815	08/10/21	BALANCE TBR,PM78	0.00	30.00	0.00
		33000051		15	BRIAUS01	86609513	08/10/21	BALANCE TBR,PM78	2.00	30.00	60.00
		77000194		15	BRIAUS01	86609513	08/10/21	case stock 295/80-22.5,PM78	-2.00	20.00	-40.00

Total : Tyres 20.00**Total for Service** 20.00**Total for Work Order** 20.00

Work Order	00042858	Work Order Date : 18/10/2021		Repair Location : EX0103		Yatala Workshop Exodas		B Service Cummins E5		
-------------------	-----------------	-------------------------------------	--	---------------------------------	--	------------------------	--	----------------------	--	--

Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :		1,378,983		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

SERVICE COMPLETED.

										Total for Service		0.00
Service Code:		CUMBE5	B Service Cummins E5				Meter Reading :		1,378,983			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			Units	Rate	Extension

SERVICE COMPLETED MICK AND KEIRAN

- SERVICE COMPLETED

Total for Service 0.00

Work Order Service History

										Total for Work Order	0.00			
Work Order		00043384		Work Order Date :		02/11/2021		Repair Location :		EX0103	Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		0				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension			
		77000180		15	BRIAUS01	EX00021142	02/11/21	CASE STOCK 11-22.5,PM78	0.00	20.00	0.00			
		77000180		15	BRIAUS01	86734564	02/11/21	CASE STOCK 11-22.5,PM78	-8.00	20.00	-160.00			
										Total : Tyres	-160.00			
										Total for Service	-160.00			
										Total for Work Order	-160.00			
Work Order		00043815		Work Order Date :		24/11/2021		Repair Location :		EX0103	Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		1,390,656				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension			
SERVICE COMPLETED BY BEN														
DIAGNOSED AND REPAIRED BRAKE AND REVERSE WIRE IN MALE ELECTRICAL PLUG FOR TRAILER														
TOPPED ENGINE COOLANT														
COMPLETED SLEEPER AIR SERVICE														
										Total for Service	0.00			
Service Code:		ECO		Eco Wind Service				Meter Reading :		1,390,656				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension			
SERVICE COMPLETED BY BEN														
REPLACED SUMP PLUG WASHER														
										Total for Service	0.00			
										Total for Work Order	0.00			
Work Order		00043943		Work Order Date :		01/12/2021		Repair Location :		EX0103	Yatala Workshop Exodas		General Repair	
Service Code:		GEN		General Repair				Meter Reading :		1,392,141				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension			
REPAIR COMPLETED BY MICK														
										Total for Service	0.00			
										Total for Work Order	0.00			
Work Order		00044285		Work Order Date :		15/12/2021		Repair Location :		EX0103	Yatala Workshop Exodas		General Repair	
Service Code:		GEN		General Repair				Meter Reading :		1,395,944				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension			
REPAIR COMPLETED BY BEN														
EXTENDED AIR LINES														
EXTENDED EBS & ELECTRICAL LINES														
										Total for Service	0.00			
										Total for Work Order	0.00			
Work Order		00044408		Work Order Date :		17/12/2021		Repair Location :		EX0103	Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		0				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension			
		33000051		15	BRIAUS01	EX00021799	17/12/21	BALANCE TBR,XQ08CB	0.00	30.00	0.00			
		33000051		15	BRIAUS01	4420430784	17/12/21	BALANCE TBR,XQ08CB	2.00	30.00	60.00			

Work Order Service History

Total : Tyres 60.00
Total for Service 60.00
Total for Work Order 60.00

Work Order	00044374	Work Order Date :	20/12/2021	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	1,397,221			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
REPAIR COMPLETED BY BEN										
REPLACED 5 PSI HOBBS SWITCH										
REPLACED LHS LOAD LIGHT										
LUBED TRAILER SUPPLY BUTTON AND PARK BRAKE BUTTON										
Total for Service										0.00
Total for Work Order										0.00

Work Order	00044404	Work Order Date :	20/12/2021	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	TYRES	Tyres Service - Trailer		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		33000051		15	BRIAUS01	EX00021794	20/12/21 BALANCE TBR,PM78	0.00	30.00	0.00
		33000085		15	BRIAUS01	EX00021794	20/12/21 ROTATE TBR TYRE,PM78	0.00	13.00	0.00
		33000085		15	BRIAUS01	87003620	20/12/21 ROTATE TBR TYRE,PM78	2.00	13.00	26.00
		33000051		15	BRIAUS01	87003620	20/12/21 BALANCE TBR,PM78	2.00	30.00	60.00
Total : Tyres										86.00
Total for Service										86.00
Total for Work Order										86.00

Work Order	00044507	Work Order Date :	04/01/2022	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	1,399,109			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED KEIRAN										
- REPLACED ALL 4 FRONT TORQUE ROD BUSHES AND THE 2 REAR LH BUSHES.										
Total for Service										0.00
Total for Work Order										0.00

Work Order	00044721	Work Order Date :	13/01/2022	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
REPAIR COMPLETED BY MICK										
REPAIRED RHS DOOR STOPPER										
Total for Service										0.00
Total for Work Order										0.00

Work Order	00044971	Work Order Date :	27/01/2022	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	1,405,343			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

Work Order Service History

REPAIR COMPLETED BY KEIRAN

-REFITTED EBS PLUG

- REMOVED OLD STEERING WHEEL AND FITTED SECOND HAND STOCK

Total for Service 0.00

Total for Work Order 0.00

Work Order	00045408	Work Order Date :	17/02/2022	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	1,410,599			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

SERVICE COMPLETED BY IAN, BEN AND BRENDON

TOP UP ENGINE OIL

Total for Service 0.00

Total for Work Order 0.00

Work Order	00045831	Work Order Date :	03/03/2022	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	1,415,251			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

REPAIR COMPLETED BRENDAN

- R+R WINDOW REGULATOR RHS

Total for Service 0.00

Total for Work Order 0.00

Work Order	00046164	Work Order Date :	15/03/2022	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	1,418,489			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

REPAIR COMPLETED KEIRAN AND MICK

REMOVED GEAR BOX REPLACED CLUTCH BRAKE

Total for Service 0.00

Total for Work Order 0.00

Work Order	00046483	Work Order Date :	25/03/2022	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	1,420,813			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

REPAIR COMPLETED BY IAN

ADJUST CLUTCH

SECURE ARM TO CROSS SHAFT AT GEAR TOWER, ALIGN AND LUBRICATE JOINTS ON GEAR CABLES

Total for Service 0.00

Total for Work Order 0.00

Work Order	00046472	Work Order Date :	26/03/2022	Repair Location :	EX0103	Yatala Workshop Exodas	Eco Wind Service			
Service Code:	ECO	Eco Wind Service		Meter Reading :	1,421,129			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

SERVICE COMPLETED BY BEN

Total for Service 0.00

Total for Work Order 0.00

Work Order	00046691	Work Order Date :	06/04/2022	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------	--	--	--

Work Order Service History

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 1,423,063 Units Rate Extension
 Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED.

Total for Service 0.00

Service Code: CUMBE5 B Service Cummins E5 Meter Reading : 1,423,063 Units Rate Extension
 Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED BY KEIRAN AND TYLER

COMPLETED TOP TUNE, ADJUSTED ALL ROCKERS AND FITTED TUNE UP KIT TO
 ADJUSTED WASTE GATE TO 68" FROM 140"
 ADJUSTED TURNTABLE/SNIPPED END
 *TURNTABLE AT IT'S END
 *FRONT DRIVE WILL NEED A RELINE
 REPLACED COOLANT AND FILTER
 *NEED TO ORDER NHVR STICKER
 REPLACED AC BELT AND TENSIONER

Total for Service 0.00

Total for Work Order 0.00

Work Order 00047613 Work Order Date : 13/05/2022 Repair Location : EX0103 Yatala Workshop Exodas General Repair

Service Code: GEN General Repair Meter Reading : 1,432,396 Units Rate Extension
 Task Code Employee Product Code Warehouse Category Supplier Invoice Details

REPAIR COMPLETED BY BEN

REPLACED HEATER TAP

Total for Service 0.00

Total for Work Order 0.00

Work Order 00047683 Work Order Date : 18/05/2022 Repair Location : EX0103 Yatala Workshop Exodas General Repair

Service Code: GEN General Repair Meter Reading : 1,433,653 Units Rate Extension
 Task Code Employee Product Code Warehouse Category Supplier Invoice Details

REPAIR COMPLETED BY KEIRAN

REPLACED BOTH SUZI AIR LINES

Total for Service 0.00

Total for Work Order 0.00

Work Order 00048050 Work Order Date : 02/06/2022 Repair Location : EX0103 Yatala Workshop Exodas A Service Cummins E5

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 1,438,743 Units Rate Extension
 Task Code Employee Product Code Warehouse Category Supplier Invoice Details

SERVICE COMPLETED BY BEN TYLER AND KEIRAN

REPLACED FIRE EXT

Total for Service 0.00

Total for Work Order 0.00

Work Order 00048591 Work Order Date : 21/06/2022 Repair Location : EX0103 Yatala Workshop Exodas Weight Gauge Calibration

Service Code: WEICAL Weight Gauge Calibration Meter Reading : 0 Units Rate Extension
 Task Code Employee Product Code Warehouse Category Supplier Invoice Details

Work Order Service History

AIR GAUGE: 11000
ADJUSTED: 9750
WEIGHBRIDGE: 9500

AIR GAUGE CALIBRATION COMPLETED CORRECTLY.

Total for Service 0.00
Total for Work Order 0.00

Work Order	00049083	Work Order Date :	10/07/2022	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
Service Code:	WEICAL	Weight Gauge Calibration		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
	AIR GAUGE: 15750 ADJUSTED: 16900 WEIGHBRIDGE: 16760									

AIR GAUGE CALIBRATION COMPLETED CORRECTLY.

Total for Service 0.00
Total for Work Order 0.00

Work Order	00048951	Work Order Date :	11/07/2022	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	1,448,877			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
	REPAIR COMPLETED BY KEIRAN AND MICK									

CHECKED TEMP GAUGE TO CUMMINS COMPUTER, ANALOGUE GAUGE IS ABOUT 15* OUT, HORTON COMES ON AT 99* ON COMPUTER
CHECKED CODES, CHECKED VOLTAGE AT NOX OK, FITTED SECOND HAND NOX SENSOR AFTER TREAT LIGHT CLEARED

Total for Service 0.00
Total for Work Order 0.00

Work Order	00049503	Work Order Date :	28/07/2022	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	1,453,162			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
	REPAIR COMPLETED BY BEN									

REPALCED LOAD LIGHT RHS

Total for Service 0.00
Total for Work Order 0.00

Work Order	00049932	Work Order Date :	15/08/2022	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
Service Code:	CUMAE5	A Service Cummins E5		Meter Reading :	1,458,188			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
	SERVICE COMPLETED BY BEN									

TOPPED ENGINE OIL (7L)

Total for Service 0.00
Total for Work Order 0.00

Work Order	00049996	Work Order Date :	17/08/2022	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

Work Order Service History

REPAIR COMPLETED BY KEIRAN AND TYLER

RELINED FIRST DRIVE AND REPLACED WHEEL BEARINGS

Total for Service 0.00

Total for Work Order 0.00

Work Order	00050304	Work Order Date :	31/08/2022	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------	--	--	--

Service Code: GEN General Repair Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

REPAIR COMPLETED BY BROWN & HURLEY
PLEASE REFER TO ATTCAHED INVOICE - 2569424

Total for Service 0.00

Total for Work Order 0.00

Work Order	00050750	Work Order Date :	21/09/2022	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
------------	----------	-------------------	------------	-------------------	--------	------------------------	--------------------------	--	--	--

Service Code: WEICAL Weight Gauge Calibration Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

AIR GAUGE: 11000
ADJUSTED: 10000
WEIGHBRIDGE: 9680

AIR GAUGE CALIBRATION COMPLETED CORRECTLY.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00050776	Work Order Date :	22/09/2022	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------	--	--	--

Service Code: CUMAE5 A Service Cummins E5 Meter Reading : 1,468,141

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED.

Total for Service 0.00

Service Code: CUMBE5 B Service Cummins E5 Meter Reading : 1,468,141

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

SERVICE COMPLETED BY MICK AND TYLER

REPLACED LHS HI BEAM LIGHT ASSM
REPLACED NUMBER PLATE LIGHT
REPAIRED RHS LOAD LIGHT
FLUSHED ADBLUE SYSTEM

Total for Service 0.00

Total for Work Order 0.00

Work Order	00050946	Work Order Date :	29/09/2022	Repair Location :	EX0103	Yatala Workshop Exodas	Weight Gauge Calibration			
------------	----------	-------------------	------------	-------------------	--------	------------------------	--------------------------	--	--	--

Service Code: WEICAL Weight Gauge Calibration Meter Reading : 0

Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
-----------	----------	--------------	-----------	----------	----------	---------	---------	-------	------	-----------

AIR GAUGE: 14750
ADJUSTED: 15750
WEIGHBRIDGE: 15400

AIR GAUGE CALIBRATION COMPLETED CORRECTLY.

Work Order Service History

										Total for Service	0.00	
										Total for Work Order	0.00	
Work Order		00051730	Work Order Date :		29/10/2022	Repair Location :		EX0103	Yatala Workshop Exodas	General Repair		
Service Code:		GEN	General Repair			Meter Reading :		0				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension	
REPAIR COMPLETED BY KEIRAN												
REPLACED LH LOADLIGHT												
										Total for Service	0.00	
										Total for Work Order	0.00	
Work Order		00051970	Work Order Date :		09/11/2022	Repair Location :		EX0103	Yatala Workshop Exodas	C Service Cummins E5		
Service Code:		CUMCE5	C Service Cummins E5			Meter Reading :		1,483,495				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension	
REPLACED TURNTABLE												
SERVICE COMPLETED BY MICK, TYLER AND FLYNN												
										Total for Service	0.00	
										Total for Work Order	0.00	
Work Order		00051971	Work Order Date :		09/11/2022	Repair Location :		EX0103	Yatala Workshop Exodas	Exodas Annual Roadworthy NHVAS		
Service Code:		EXOINS	Exodas Annual Roadworthy NHVAS			Meter Reading :		1,483,495				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension	
VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1												
INSPECTION COMPLETED BY MICK												
										Total for Service	0.00	
										Total for Work Order	0.00	
Work Order		00051972	Work Order Date :		09/11/2022	Repair Location :		EX0103	Yatala Workshop Exodas	Eco Wind Service		
Service Code:		ECO	Eco Wind Service			Meter Reading :		1,483,495				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension	
SERVICE COMPLETED BY KEIRAN												
										Total for Service	0.00	
										Total for Work Order	0.00	
Work Order		00052610	Work Order Date :		01/12/2022	Repair Location :		EX0103	Yatala Workshop Exodas	General Repair/Maintenance		
Service Code:		TYRES	Tyres Service - Trailer			Meter Reading :		1,487,759				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension	
		33000051		15	BRIAUS01	EX00026219	01/12/22	BALANCE TBR,PM78	0.00	30.00	0.00	
		33000051		15	BRIAUS01	88792710	01/12/22	BALANCE TBR,PM78	2.00	30.00	60.00	
										Total : Tyres	60.00	
										Total for Service	60.00	
										Total for Work Order	60.00	
Work Order		00052431	Work Order Date :		02/12/2022	Repair Location :		EX0103	Yatala Workshop Exodas	A Service Cummins E5		
Service Code:		CUMAE5	A Service Cummins E5			Meter Reading :		1,490,923				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension	

Total for Service	0.00
--------------------------	-------------

Total for Work Order	0.00
-----------------------------	-------------

Total for Service	0.00
--------------------------	-------------

Total for Work Order	0.00
----------------------	------

Units	Rate	Extension
10	10	100
20	20	400
30	30	900
40	40	1600
50	50	2500
60	60	3600
70	70	4900
80	80	6400
90	90	8100
100	100	10000

Total for Service	0.00
--------------------------	-------------

[illegible]

Total for Service	0.00
--------------------------	-------------

Total for Work Order	0.00
-----------------------------	-------------

Units	Rate	Extension
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100

Total for Service	0.00
--------------------------	-------------

Total for Work Order	0.00
-----------------------------	-------------

Units	Rate	Extension
-------	------	-----------

Work Order Service History

DEFECT CLEARED.

REPLACED LH FRONT AXEL GASKET

Total for Service	0.00
--------------------------	-------------

Service Code: GEN General Repair

Meter Reading : 0

Service Code		SEN	General Repair		Meter Reading	0					
Task Code	Employee		Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension

REPAIR COMPLETED.

Total for Service	0.00
--------------------------	-------------

Total for Work Order	0.00
-----------------------------	-------------

Work Order		00055170		Work Order Date :		28/03/2023		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance		
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		1,523,822						
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension			
		11004496		15	BRIAUS01	EX00027806	28/03/23	295/80R22.5 152M BS R154,PM78				0.00	0.00	0.00		
		77000194		15	BRIAUS01	EX00027806	28/03/23	case stock 295/80-22.5,PM78				0.00	20.00	0.00		
		33000084		15	BRIAUS01	EX00027806	28/03/23	FIT TBR TYRE,PM78				0.00	0.00	0.00		
		33000517		15	BRIAUS01	EX00027806	28/03/23	REMOVAL: CUSTOMER PULL POINT,PM78				0.00	0.00	0.00		
		33000051		15	BRIAUS01	EX00027806	28/03/23	BALANCE TBR,PM78				0.00	30.00	0.00		
		33000051		15	BRIAUS01	89403631	28/03/23	BALANCE TBR,PM78				2.00	30.00	60.00		
		33000517		15	BRIAUS01	89403631	28/03/23	REMOVAL: CUSTOMER PULL POINT,PM78				2.00	0.00	0.00		
		33000084		15	BRIAUS01	89403631	28/03/23	FIT TBR TYRE,PM78				2.00	0.00	0.00		
		77000194		15	BRIAUS01	89403631	28/03/23	case stock 295/80-22.5,PM78				-2.00	20.00	-40.00		
		11004496		15	BRIAUS01	89403631	28/03/23	295/80R22.5 152M BS R154,PM78				1.00	0.00	0.00		
													Total : Tyres		20.00	
													Total for Service		20.00	
													Total for Work Order		20.00	

Work Order		00055218		Work Order Date :		30/03/2023		Repair Location :		EX0103		Yatala Workshop Exodas		B Service Cummins E5		
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		1,524,070				Units	Rate	Extension
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details								
SERVICE COMPLETED.																
														Total for Service		0.00
Service Code:		CUMBE5		B Service Cummins E5				Meter Reading :		1,524,070				Units	Rate	Extension
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details								
SERVICE COMPLETED.																
REPLACED WIPERS & RH REAR TORQUE ROD BUSHES																
														Total for Service		0.00
Service Code:		DEFECT		Defect Repair				Meter Reading :		1,524,070				Units	Rate	Extension
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details								

DEFECT CLEARED.

Work Order Service History

Reported Defect :-

Defect Code : 00008653

Defect Reference : 12736

Date : 31/01/2023

Description of Defect :

REPLACE ABS PLUG & LENGTHEN CHECK AFTER TREAT COMING ON, TIGHTEN LEFT HAND MARKER LIGHT ON LEFT HAND TAIL LIGHT OR

REPLACE L/H TAIL LIGHT & BRACKET

Reported Defect :-

Defect Code : 00008203

Defect Reference : 51970

Date : 09/11/2022

Description of Defect :

NEEDS JAW KIT AND RHR TORQUE ROD BUSHES

Total for Service 0.00

Total for Work Order 0.00

Work Order	00055871	Work Order Date :	27/04/2023	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------	--	--	--

Service Code:	CUMAE5	A Service Cummins E5				Meter Reading :	1,534,999	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

SERVICE COMPLETED.

MONITOR ENGINE MOUNTS

Total for Service 0.00

Service Code:	DEFECT	Defect Repair				Meter Reading :	1,534,999	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

DEFECT CLEARED.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00056471	Work Order Date :	23/05/2023	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------	--	--	--

Service Code:	DEFECT	Defect Repair				Meter Reading :	1,544,175	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

DEFECT CLEARED.

Total for Service 0.00

Service Code:	GEN	General Repair				Meter Reading :	1,544,175	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

REPAIR COMPLETED.

REMOVE COVER OVER THRU HOLE & REINSTALL NEW POLL PIN & REASSEMBLE FLOOR COVERS

Total for Service 0.00

Total for Work Order 0.00

Work Order	00056602	Work Order Date :	25/05/2023	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------	--	--	--

Service Code:	TYRES	Tyres Service - Trailer				Meter Reading :	1,544,175	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

		33000096		15	BRIAUS01	EX00028735	25/05/23	PUNCTURE REPAIR TBR,	0.00	26.30	0.00
--	--	----------	--	----	----------	------------	----------	----------------------	------	-------	------

		33000096		15	BRIAUS01	89710329	25/05/23	PUNCTURE REPAIR TBR,	1.00	26.30	26.30
--	--	----------	--	----	----------	----------	----------	----------------------	------	-------	-------

Total : Tyres 26.30

										Total for Service	26.30					
										Total for Work Order	26.30					
Work Order		00056856		Work Order Date :		05/06/2023		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5		
Service Code:		CUMAE5		A Service Cummins E5				Meter Reading :		1,546,868				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									
SERVICE COMPLETED. ADBLUE FLUSH TO REMOVE LIGHT ON DASH CHANGED UNLOADER VALVE TO STOP EXCESSIVE UNLOADING, SLOW ISSUE DOWN BUT DRIER UNIT NEEDS TO BE REPLACED																
										Total for Service	0.00					
Service Code:		DEFECT		Defect Repair				Meter Reading :		1,546,868				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									
DEFECT CLEARED.																
										Total for Service	0.00					
										Total for Work Order	0.00					
Work Order		00057236		Work Order Date :		13/06/2023		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair		
Service Code:		DEFECT		Defect Repair				Meter Reading :		1,549,592				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									
REPLACED COMPRESSOR 13/06/2023.																
										Total for Service	0.00					
Service Code:		GEN		General Repair				Meter Reading :		1,549,592				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									
REPAIR COMPLETED.																
										Total for Service	0.00					
										Total for Work Order	0.00					
Work Order		00058116		Work Order Date :		17/07/2023		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance		
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		1,557,367				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									
		33000096		15	BRIAUS01	EX00029564	17/07/23	PUNCTURE REPAIR TBR,				0.00	26.30		0.00	
		33000096		15	BRIAUS01	89986153	17/07/23	PUNCTURE REPAIR TBR,				3.00	26.30		78.90	
										Total : Tyres	78.90					
										Total for Service	78.90					
										Total for Work Order	78.90					
Work Order		00058126		Work Order Date :		17/07/2023		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance		
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		0				Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details									
		33000084		15	BRIAUS01	EX00029574	17/07/23	FIT TBR TYRE,				0.00	4.75		0.00	
		33000085		15	BRIAUS01	EX00029574	17/07/23	ROTATE TBR TYRE,				0.00	3.50		0.00	
		33000084		15	BRIAUS01	89986067	17/07/23	FIT TBR TYRE,				4.00	4.75		19.00	
		33000085		15	BRIAUS01	89986067	17/07/23	ROTATE TBR TYRE,				4.00	3.50		14.00	
										Total : Tyres	33.00					
										Total for Service	33.00					

Work Order Service History

												Total for Work Order	33.00		
Work Order		00058133		Work Order Date :		20/07/2023		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5		Meter Reading :		1,558,648				Units	Rate	Extension	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details								
SERVICE COMPLETED. LED DASH GLOBES REPLACED. POWER STEER SEEPING - REQUIRES FURTHER INVESTIGATION.														Total for Service	0.00
Service Code:		DEFECT		Defect Repair		Meter Reading :		1,558,648				Units	Rate	Extension	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details								
DEFECT CLEARED. Reported Defect :- Defect Code : 00009509 Defect Reference : 12739 Date : 16/07/2023 Description of Defect : REPLACE DASH LIGHT IN SUSP'N PRESS, FRONT AIR, VOLTMETER, AXLE OIL FRT RR. TIGHTEN LEFT HAND REAR MARKER LIGHT ON REAR BUMPER, R/H DOOR TRIM COMING LOOSE AGAIN.														Total for Service	0.00
												Total for Work Order	0.00		
Work Order		00058331		Work Order Date :		26/07/2023		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer		Meter Reading :		1,558,899				Units	Rate	Extension	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details								
		33000085		15	BRIAUS01	EX00029661	26/07/23	ROTATE TBR TYRE,				0.00	3.50	0.00	
		33000085		15	BRIAUS01	187048822	26/07/23	ROTATE TBR TYRE,				2.00	3.50	7.00	
												Total : Tyres	7.00		
												Total for Service	7.00		
												Total for Work Order	7.00		
Work Order		00059524		Work Order Date :		04/09/2023		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		GEN		General Repair		Meter Reading :		1,569,845				Units	Rate	Extension	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details								
		33000084		15	BRIAUS01	EX00030300	04/09/23	FIT TBR TYRE,				0.00	4.75	0.00	
		33000084		15	BRIAUS01	187267695	04/09/23	FIT TBR TYRE,				1.00	4.75	4.75	
												Total : Tyres	4.75		
												Total for Service	4.75		
												Total for Work Order	4.75		
Work Order		00059548		Work Order Date :		05/09/2023		Repair Location :		EX0103		Yatala Workshop Exodas		B Service Cummins E5	
Service Code:		CUMAE5		A Service Cummins E5		Meter Reading :		1,571,079				Units	Rate	Extension	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details								
SERVICE COMPLETED.														Total for Service	0.00
Service Code:		CUMBE5		B Service Cummins E5		Meter Reading :		1,571,079				Units	Rate	Extension	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details								

Work Order Service History

SERVICE COMPLETED 04/09/2023
ADJUSTED STEER BEARINGS

								Total for Service		0.00
Service Code:		DEFECT	Defect Repair		Meter Reading :		1,571,079			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension

DEFECT CLEARED.

Total for Service 0.00
Total for Work Order 0.00

Work Order		00059731		Work Order Date :		06/09/2023		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		GEN		General Repair		Meter Reading :		0							
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details		Units	Rate	Extension			
		33000096		15	BRIAUS01	EX00030385	06/09/23	PUNCTURE REPAIR TBR,		0.00	26.30	0.00			
		33000096		15	BRIAUS01	187278495	06/09/23	PUNCTURE REPAIR TBR,		1.00	26.30	26.30			
												Total : Tyres		26.30	
												Total for Service		26.30	
												Total for Work Order		26.30	

Work Order		00059741		Work Order Date :		11/09/2023		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		GEN		General Repair				Meter Reading :		1,572,507					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details		Units	Rate	Extension			
		33000096		15	BRI AUS01	EX00030398	11/09/23	PUNCTURE REPAIR TBR,		0.00	26.30	0.00			
		33000125		15	BRI AUS01	EX00030398	11/09/23	ETA MIN FEE,		0.00	362.00	0.00			
		33000125		15	BRI AUS01	187298441	11/09/23	ETA MIN FEE,		1.00	362.00	362.00			
		33000096		15	BRI AUS01	187298441	11/09/23	PUNCTURE REPAIR TBR,		1.00	26.30	26.30			
												Total : Tyres		388.30	
												Total for Service		388.30	
												Total for Work Order		388.30	

Work Order		00060331		Work Order Date :		28/09/2023		Repair Location :		EX0103		Yatala Workshop Exodas		General Repair/Maintenance	
Service Code:		TYRES		Tyres Service - Trailer				Meter Reading :		199,820					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details					Units	Rate	Extension	
		33000096		15	BRIAUS01	EX00030699	28/09/23	PUNCTURE REPAIR TBR,					0.00	26.30	0.00
		33000237		15	BRIAUS01	EX00030699	28/09/23	JOB DONE BRUCE HWY BP BURPENGARY POS3 FS,					0.00	0.00	0.00
		33000237		15	BRIAUS01	187396388	28/09/23	JOB DONE BRUCE HWY BP BURPENGARY POS3 FS,					1.00	0.00	0.00
		33000096		15	BRIAUS01	187396388	28/09/23	PUNCTURE REPAIR TBR,					1.00	26.30	26.30
												Total : Tyres		26.30	
												Total for Service		26.30	
												Total for Work Order		26.30	

Work Order		00060332		Work Order Date :		28/09/2023		Repair Location :		EX0103		Yatala Workshop Exodas		Tyres Service - Trailer	
Service Code:		DEFECT		Defect Repair				Meter Reading :		0					
Task Code	Employee	Product Code		Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension	

DEFECT CLEARED.

Work Order Service History

								Total for Service	0.00	
Service Code:		TYRES	Tyres Service - Trailer		Meter Reading :		1,572,507	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		33000096		15	BRIAUS01	EX00030704	28/09/23 PUNCTURE REPAIR TBR,	0.00	26.30	0.00
		33000125		15	BRIAUS01	EX00030704	28/09/23 ETA MIN FEE,	0.00	362.00	0.00
		33000125		15	BRIAUS01	187395988	28/09/23 ETA MIN FEE,	-1.00	362.00	-362.00
		33000096		15	BRIAUS01	187395988	28/09/23 PUNCTURE REPAIR TBR,	-1.00	26.30	-26.30
								Total : Tyres		-388.30
								Total for Service		-388.30
								Total for Work Order		-388.30
Work Order		00060334	Work Order Date :		28/09/2023	Repair Location :		EX0103	Yatala Workshop Exodas	General Repair/Maintenance
Service Code:		TYRES	Tyres Service - Trailer		Meter Reading :		1,572,507	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		33000096		15	BRIAUS01	EX00030706	28/09/23 PUNCTURE REPAIR TBR,	0.00	26.30	0.00
		33000096		15	BRIAUS01	187396064	28/09/23 PUNCTURE REPAIR TBR,	1.00	26.30	26.30
								Total : Tyres		26.30
								Total for Service		26.30
								Total for Work Order		26.30
Work Order		00060617	Work Order Date :		10/10/2023	Repair Location :		EX0103	Yatala Workshop Exodas	A Service Cummins E5
Service Code:		CUMAE5	A Service Cummins E5		Meter Reading :		1,582,490	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED BY MATT & FLYNN ON 09/10/2023.										
								Total for Service		0.00
Service Code:		DEFECT	Defect Repair		Meter Reading :		1,582,490	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
DEFECT CLEARED.										
								Total for Service		0.00
								Total for Work Order		0.00
Work Order		00060679	Work Order Date :		11/10/2023	Repair Location :		EX0103	Yatala Workshop Exodas	General Repair/Maintenance
Service Code:		GEN	General Repair		Meter Reading :		1,582,957	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
		33000084		15	BRIAUS01	EX00030845	11/10/23 FIT TBR TYRE,POSITION: 11	0.00	4.75	0.00
		33000084		15	BRIAUS01	187459650	11/10/23 FIT TBR TYRE,POSITION: 11	1.00	4.75	4.75
								Total : Tyres		4.75
								Total for Service		4.75
								Total for Work Order		4.75
Work Order		00060942	Work Order Date :		20/10/2023	Repair Location :		EX0103	Yatala Workshop Exodas	RIGHT PLUG NEEDS REPLACING
Service Code:		DEFECT	Defect Repair		Meter Reading :		1,585,769	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

Total for Service	0.00
--------------------------	-------------

Units	Rate	Extension
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100

Total for Service	0.00
--------------------------	-------------

Total for Work Order	0.00
-----------------------------	-------------

Work Order	00062650	Work Order Date :	05/12/2023	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------

Units	Rate	Extension
10	10	100
20	20	400
30	30	900
40	40	1600
50	50	2500
60	60	3600
70	70	4900
80	80	6400
90	90	8100
100	100	10000

Total : Tyres	44.25
----------------------	--------------

Total for Service	44.25
--------------------------	--------------

Total for Work Order	44.25
-----------------------------	--------------

Work Order Service History

Work Order		00062858		Work Order Date :		13/12/2023		Repair Location :		EX0103		Yatala Workshop Exodas		A Service Cummins E5				
Service Code:		CUMAE5		A Service Cummins E5		Meter Reading :		1,601,404				Units		Rate		Extension		
Task Code	Employee	Product Code		Warehouse		Category		Supplier		Invoice		Details						
SERVICE COMPLETED BY AARON ON 13/12/2023.																		
															Total for Service		0.00	
Service Code:		DEFECT		Defect Repair		Meter Reading :		1,601,404				Units		Rate		Extension		
Task Code	Employee	Product Code		Warehouse		Category		Supplier		Invoice		Details						
DEFECT CLEARED.																		
															Total for Service		0.00	
															Total for Work Order		0.00	
Work Order		00062859		Work Order Date :		13/12/2023		Repair Location :		EX0103		Yatala Workshop Exodas		C Service Cummins E5				
Service Code:		CUMCE5		C Service Cummins E5		Meter Reading :		1,601,404				Units		Rate		Extension		
Task Code	Employee	Product Code		Warehouse		Category		Supplier		Invoice		Details						
SERVICE COMPLETED BY AARON & BEN ON 13/12/25023.																		
REPLACE STEERING WHEEL WITH 2ND HAND UNIT.																		
REPLACE SLEEPER AIR ENGINE WITH RECONDITIONED ENGINE.																		
REPLACE TURNTABLE LOCKING JAW																		
NOTED: MONITOR ENGINE & TRANSMISSION MOUNTS. DEFECT NO. 00010489 CREATED																		
															Total for Service		0.00	
Service Code:		DEFECT		Defect Repair		Meter Reading :		1,601,404				Units		Rate		Extension		
Task Code	Employee	Product Code		Warehouse		Category		Supplier		Invoice		Details						
DEFECT CLEARED.																		
Reported Defect :-																		
Defect Code : 00009543																		
Defect Reference : PM78																		
Date : 19/07/2023																		
Description of Defect :																		
GEARBOX MOUNTS REQUIRE REPLACEMENT.																		
Reported Defect :-																		
Defect Code : 00010060																		
Defect Reference : 00060617																		
Date : 09/10/2023																		
Description of Defect :																		
ENGINE/GEARBOX MOUNTS TO BE REPLACED WHEN AVAILABLE																		
Reported Defect :-																		
Defect Code : 00009115																		
Defect Reference : PM78																		
Date : 27/04/2023																		
Description of Defect :																		
MONITOR ENGINE MOUNTS																		

Work Order Service History

Reported Defect :-
 Defect Code : 00010385
 Defect Reference : 12742
 Date : 20/11/2023
 Description of Defect :
 REPAIR ICE PACK PLEASE

Total for Service 0.00

Total for Work Order 0.00

Work Order	00062860	Work Order Date :	13/12/2023	Repair Location :	EX0103	Yatala Workshop Exodas	Exodas Annual Roadworthy NHVAS			
------------	----------	-------------------	------------	-------------------	--------	------------------------	--------------------------------	--	--	--

Service Code:	DEFECT	Defect Repair				Meter Reading :	1,601,404			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension

DEFECT CLEARED.

Total for Service 0.00

Service Code:	EXOINS	Exodas Annual Roadworthy NHVAS				Meter Reading :	1,601,404			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension

VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION.
 ATTEMPT # 1

INSPECTION COMPLETED BY WORKSHOP - AARON ON 13/12/2023
 NO FAULTS APPARENT

Total for Service 0.00

Total for Work Order 0.00

Work Order	00063677	Work Order Date :	19/01/2024	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
------------	----------	-------------------	------------	-------------------	--------	------------------------	----------------------------	--	--	--

Service Code:	TYRES	Tyres Service - Trailer				Meter Reading :	1,602,724			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension

		77000180		15	BRIAUS01	EX00032294	20/12/23	CASE STOCK 11-22.5,	0.00	20.00	0.00
		33000084		15	BRIAUS01	EX00032294	20/12/23	FIT TBR TYRE,	0.00	4.75	0.00
		33000517		15	BRIAUS01	EX00032294	20/12/23	REMOVAL: CUSTOMER PULL POINT,	0.00	0.00	0.00
		33000118		15	BRIAUS01	EX00032294	20/12/23	SCHEDULED DEPOT SERVICE 15MIN,	0.00	5.00	0.00
		77000180		15	BRIAUS01	187983103	20/12/23	CASE STOCK 11-22.5,	-8.00	20.00	-160.00
		33000084		15	BRIAUS01	187983103	20/12/23	FIT TBR TYRE,	8.00	4.75	38.00
		33000517		15	BRIAUS01	187983103	20/12/23	REMOVAL: CUSTOMER PULL POINT,	8.00	0.00	0.00
		33000118		15	BRIAUS01	187983103	20/12/23	SCHEDULED DEPOT SERVICE 15MIN,	9.00	5.00	45.00

Total : Tyres -77.00

Total for Service -77.00

Total for Work Order -77.00

Work Order	00065195	Work Order Date :	06/03/2024	Repair Location :	EX0103	Yatala Workshop Exodas	Eco Wind Service			
------------	----------	-------------------	------------	-------------------	--------	------------------------	------------------	--	--	--

Service Code:	DEFECT	Defect Repair				Meter Reading :	1,620,416			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension

DEFECT CLEARED.

Work Order Service History

Reported Defect :-
 Defect Code : 00010830
 Defect Reference : 50254
 Date : 01/02/2024
 Description of Defect :
 SLEEPER AIR DUE FOR A SERVICE.

DEFECT CLEARED 06/03/2024
 SERVICE CARRIED OUT

Total for Service 0.00

Service Code:	ECO	Eco Wind Service	Meter Reading :	1,620,416	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

SERVICE COMPLETED BY JOSEPH ON 06/03/2024.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00065196	Work Order Date :	06/03/2024	Repair Location :	EX0103	Yatala Workshop Exodas	B Service Cummins E5
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------

Service Code:	CUMAE5	A Service Cummins E5	Meter Reading :	1,620,410	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

SERVICE COMPLETED.

Total for Service 0.00

Service Code:	CUMBE5	B Service Cummins E5	Meter Reading :	1,620,410	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

SERVICE COMPLETED BY NICK & ETHAN ON 06/03/2024.

REPLACED NOX SENSOR
 REPLACED WASTEGATE ON TURBO
 AIR CON GETTING COLD
 REPAIRED DOOR CARD
 REPLACED DOOR RUBBER SEAL.

Total for Service 0.00

Service Code:	DEFECT	Defect Repair	Meter Reading :	1,620,410	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

DEFECTS CLEARED ON 06/03/2024
 REPLACED NOX SENSOR
 REPLACED WASTEGATE ON TURBO
 AIR CON GETTING COLD
 REPAIRED DOOR CARD
 REPLACED DOOR RUBBER SEAL.

Reported Defect :-
 Defect Code : 00010540
 Defect Reference : 12746C
 Date : 12/12/2023
 Description of Defect :
 AFTER TREAT LIGHT ON. CHECK AIR CON NOT GETTING COLD

Work Order Service History

Reported Defect :-

Defect Code : 00010539

Defect Reference : 12746B

Date : 12/12/2023

Description of Defect :

CHECK DRIVE TYRES

Reported Defect :-

Defect Code : 00010538

Defect Reference : 12746A

Date : 12/12/2023

Description of Defect :

R/H DOOR FRAME RUBBER COMING OFF

R/H DOOR RUBBER COMING OFF

R/H DOOR TRIM COMING LOOSE

Reported Defect :-

Defect Code : 00010833

Defect Reference : 50254

Date : 01/02/2024

Description of Defect :

AFTER TREAT LIGHT STILL COMING ON

Reported Defect :-

Defect Code : 00010832

Defect Reference : 50254

Date : 01/02/2024

Description of Defect :

REPLACE SCREWS ON R/H INNER DOOR PANEL

Reported Defect :-

Defect Code : 00010831

Defect Reference : 50254

Date : 01/02/2024

Description of Defect :

REPLACE BOTH HOOK UP LIGHTS

Reported Defect :-

Defect Code : 00010386

Defect Reference : 12742

Date : 20/11/2023

Description of Defect :

RH DOOR FRAME RUBBER COMING OFF, RH DOOR RUBBER COMING OFF AS WELL.

RH DOOR TRIM COMING AWAY FROM DOOR

Reported Defect :-

Defect Code : 00010537

Defect Reference : 12746

Date : 12/12/2023

Description of Defect :

FIX ICE PACK PLEASE

Reported Defect :-

Defect Code : 00010781

Defect Reference : 50253

Date : 20/01/2024

Description of Defect :

PLEASE REPLACE BOTH LOAD LIGHTS WITH LOAD LIGHTS

ICE PAK DUE FOR SERVICE

Work Order Service History

Reported Defect :-

Defect Code : 00011024

Defect Reference : 50257

Date : 06/03/2024

Description of Defect :

B SERVICE DUE, SLEEPER AIR DUE FOR SERVICE, RH LOAD LIGHT NOT WORKING.
DRIVER'S DOOR INSIDE METAL PANEL NEEDS SCREWS NEED REPLACING.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00065519	Work Order Date :	18/03/2024	Repair Location :	EX0103	Yatala Workshop Exodas	FAN NEEDS REPLACING			
Service Code:	DEFECT	Defect Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

DEFECT CLEARED.

Total for Service 0.00

Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

REPAIR COMPLETED BY NICK ON 18/03/2024
REPLACED A/C FAN.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00065798	Work Order Date :	18/03/2024	Repair Location :	EX0103	Yatala Workshop Exodas	SLEEPER AIR REPAIR			
Service Code:	DEFECT	Defect Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

DEFECT CLEARED.

Reported Defect :-

Defect Code : 00011077

Defect Reference : 50259

Date : 12/03/2024

Description of Defect :

SLEEPER AIR BLOWING HOT AIR. NEED RE-GASSING. PLEASE CHECK TRUCK A/C AS WELL PLEASE.

Total for Service 0.00

Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

Work Order Service History

REPAIR COMPLETED BY ON TRACK GROUP ON 18/03/2024
INVOICE NO. INV-8207

- Locate vehicle.
- Hook up gauges to sleeper air bunk cooler - refrigerant levels low.
- Topped up system to ensure rest of system operating correctly - gauge readings good compressor engaging/disengaging correctly and air at vents icy cold.
- Recover refrigerant from system and pressure test - found discharge line from compressor to condenser leaking from fitting.
- *** showed customer and informed them how time consuming it is having to run a new hose up to 10m long and removing existing line and they said they will reschedule for that task ***
- Hook up gauges to main truck A/C and check operation
- Refrigerant levels slightly low, adjusted and rechecked.
- Gauge readings good compressor.
- Engaging/disengaging correctly and air at vents icy cold.
- Recover refrigerant from system and pressure test.
- Holding pressure.
- Remove and replace receiver drier.
- Vacuum system for 30 mins and add oil/dye to system.
- Regas system and check A/C operation.
- Gauge readings good, compressor engaging/disengaging correctly and air at vents icy cold.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00065906	Work Order Date :	22/03/2024	Repair Location :	EX0103	Yatala Workshop Exodas	REPAIR SLEEPER SYSTEM			
Service Code:	DEFECT	Defect Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

DEFECT CLEARED.

Total for Service 0.00

Service Code:	GEN	General Repair		Meter Reading :	0			Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			

REPAIR COMPLETED BY ON TRACK GROUP ON 22/03/2024.
INVOICE NO. INV-8251

ATTEND SITE,
REMOVE SUCTION AND DISCHARGE HOSE FROM SLEEPER SYSTEM
RUN NEW A/C HOSE FROM FRONT TO BACK
CABLE TIE APPROPRIATELY TO ELIMINATE FUTURE RUB
CRIMP NEW A/C FITTING CONNECT AND SEAL SYSTEM REPLACED RECEIVER DRYER.
VACCUMED SYSTEM AND REGASSED, TEST OPERATION OF SLEEPER AIR.
VENT DEGREES AT 10 DEGREES AND CYCLING. TIDY WORK AREA.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00066390	Work Order Date :	15/04/2024	Repair Location :	EX0103	Yatala Workshop Exodas	RUB IN CAB RAM HOSE			
------------	----------	-------------------	------------	-------------------	--------	------------------------	---------------------	--	--	--

Work Order Service History

Service Code:		DEFECT		Defect Repair		Meter Reading :		1,632,123		Units	Rate	Extension		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details							
DEFECT CLEARED.														
											Total for Service	0.00		
Service Code:		GEN		General Repair		Meter Reading :		1,632,123		Units	Rate	Extension		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details							
REPAIR COMPLETED BY BEN ON 15/04/2024 REPLACED CAB RAM HOSE.														
											Total for Service	0.00		
											Total for Work Order	0.00		
Work Order		00066726		Work Order Date :		18/04/2024		Repair Location :		EX0103		Yatala Workshop Exodas	FAULT CODE: 559 - PRECISION TRUCK	
Service Code:		DEFECT		Defect Repair		Meter Reading :		1,632,343		Units	Rate	Extension		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details							
DEFECT CLEARED.														
											Total for Service	0.00		
Service Code:		GEN		General Repair		Meter Reading :		1,632,343		Units	Rate	Extension		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details							
REPAIR COMPLETED BY PRECISION TRUCK MECHANICAL ON 18/04/2024. INVOICE NO. INV-0013														
Traveled to site. Plugged computer in- Fault code: 559 inactive with multiple counts. Went through trouble shooting. Carried out high pressure leak test. Found leaking fuel rail pressure relief valve. Found number 6 pass through connector wasn't sealed completely- re sealed. Carried out high pressure pump test- failed. Pulled fuel filter off, pulled power steering pump off. Pulled governor valve off. Removed high pressure pump fuel head-disassembled head and found multiple cracks around plunger sealing surface. High pressure pump head not serviceable. Fitted new high pressure pump head and fuel pump regulator. Fitted new fuel filter. Fitted power steering pump. Carried out high pressure pump test- passed. Fuel rail relief valve not in stock- coming next day. Found waste gate arm not connected- advised workshop of findings														
											Total for Service	0.00		
											Total for Work Order	0.00		
Work Order		00066986		Work Order Date :		10/05/2024		Repair Location :		EX0103		Yatala Workshop Exodas	DIFF LEAKING	

Work Order Service History

Service Code:	DEFECT	Defect Repair	Meter Reading :	1,638,629	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

DEFECT CLEARED.

Total for Service 0.00

Service Code:	GEN	General Repair	Meter Reading :	1,638,629	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

 REPAIR COMPLETED BY JOSEPH & NICK ON 10/05/2024.
 REPLACED LINING ON COVER PLATE ON FRONT DIFF.

Total for Service 0.00

Total for Work Order 0.00

Work Order	00067109	Work Order Date :	14/05/2024	Repair Location :	EX0103	Yatala Workshop Exodas	AIRBAGS LEAKING
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	------------------------

Service Code:	DEFECT	Defect Repair	Meter Reading :	1,640,029	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

DEFECT CLEARED.

Total for Service 0.00

Service Code:	GEN	General Repair	Meter Reading :	1,640,029	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

 REPAIR COMPLETED BY BEN & ETHAN ON 14/05/2024.
 REPLACED REAR DIFF FRONT AIRBAG BOTH SIDES

Total for Service 0.00

Total for Work Order 0.00

Work Order	00067740	Work Order Date :	30/05/2024	Repair Location :	EX0103	Yatala Workshop Exodas	WORKING LIGHT NEEDS REPLACING
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	--------------------------------------

Service Code:	DEFECT	Defect Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

DEFECT CLEARED.

Total for Service 0.00

Service Code:	GEN	General Repair	Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

 REPAIR COMPLETED BY JOSEPH ON 30/05/2024.
 REPLACED LHS WORKING LIGHT

Total for Service 0.00

Total for Work Order 0.00

Work Order	00068104	Work Order Date :	11/06/2024	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------------

Service Code:	GEN	General Repair	Meter Reading :	1,648,621	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details

33000096 15 BRIAUS01 EX00034722 10/06/24 PUNCTURE REPAIR TBR, 0.00 26.30 0.00

33000096 15 BRIAUS01 188756303 10/06/24 PUNCTURE REPAIR TBR, 1.00 26.30 26.30

Total : Tyres 26.30

Total for Service 26.30

Total for Work Order 26.30

Work Order	00068108	Work Order Date :	11/06/2024	Repair Location :	EX0103	Yatala Workshop Exodas	A Service Cummins E5
-------------------	-----------------	--------------------------	-------------------	--------------------------	---------------	-------------------------------	-----------------------------

Work Order Service History

Service Code:		CUMAE5	A Service Cummins E5				Meter Reading :	1,648,611				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension	
	'A' SERVICE COMPLETED BY BEN & ETHAN ON 11/06/2024. REPLACED 1.5KG FIRE EXTINGUISHER AFTERTREAT LIGHT BEEN FIXED CHECK ENGINE LIGHT FIXED. AIR LEAKS HAVE BEEN FIXED. REPLACED ENGINE TEMP LIGHT REPLACED ENGINE RETARDER AND CRUISE CONTROL DASH LIGHTS											

Total for Service 0.00

Service Code:		DEFECT	Defect Repair			Meter Reading :		1,648,611			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension
DEFECT CLEARED.											
Reported Defect :-											
Defect Code : 00011731											
Defect Reference : 50265											
Date : 11/06/2024											
Description of Defect :											
A SERVICE DUE 1,643,500 KM											

DEFECT CLEARED ON 11/06/2024
SERVICE CARRIED OUT
Reported Defect :-
Defect Code : 00011160
Defect Reference : 50261
Date : 19/03/2024
Description of Defect :
AFTER TREAT LIGHT COMING ON NOW AND THEN. CHECK ENGINE LIGHT DOING THE SAME.
BAD AIR LEAK AROUND DRIVE
TURN TRUCK OFF AND CHECK ENGINE LIGHT STAYS OFF. START IT UP AGAIN, LIGHT STAYS OFF.

DEFECT CLEARED ON 11/06/2024
AFTERTREAT LIGHT HAS BEEN FIXED
CHECK ENGINE LIGHT FIXED.
AIR LEAKS HAVE BEEN FIXED
Reported Defect :-
Defect Code : 00011324
Defect Reference : 50258
Date : 16/04/2024
Description of Defect :
AFTERTREAT COMING ON ATT: BENNY.
AIRLEAK AROUND DRIVE AREA,
EVERY TIME YOU STOP TO UNLOAD DUMPS AIR. THIS HAAPENS WHEN LOADED.
A SERVICE DUE

DEFECT CLEARED ON 11/06/2024
AFTERTREAT LIGHT HAS BEEN FIXED
AIR LEAKS HAVE BEEN FIXED

Total for Service 0.00
Total for Work Order 0.00

Work Order Service History

Work Order		00068276		Work Order Date :		14/06/2024		Repair Location :		EX0103		Yatala Workshop Exodas		Weight Gauge Calibration	
Service Code:		WEICAL		Weight Gauge Calibration				Meter Reading :		0					
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Units	Rate	Extension		
AIR GAUGE: 13250															
ADJUSTED: 12600															
WEIGHBRIDGE: 12260															
AIR GAUGE CALIBRATION COMPLETED CORRECTLY.															
												Total for Service		0.00	
												Total for Work Order		0.00	
												Total for Asset		16,365.79	
												Total for Report		16,365.79	

no