

81358	XS76EE / F	Micka	A	672424 km	grease and brake adjust , check all lights work , check turn table adjustment and grease , top up auto grease , check all fluid levels , grease clutch , top up engine oil ,	Adelaide Depot Alex , Anthony , Dave	8-Jul-25		2.5 ltr engine oil
81131	XS76EE / F	Micka		670506 km	light issue with lead - replaced 7 pin plug ,	TTT	3-Jul-25	Inv - 304122-00	1 x 82161BL plug 7 pin
81069	XS76EE / F	Micka	Call Out	661559 km	having trouble selecting gears ? Transmission fault J1939 - checked all wiring OK , replaced shifter and check operation all OK / remove and replaced alternator & replaced belt ,	TTT / Alex , Adelaide Depot C MV Adelaide	18-Jun-25	Inv - I31142832 303836-00	1 x LBP2189GH alternator 12V 160A pad mount , 1 x 12PK2290 belt / 1 x Q21-6155-1174 control RH stalk shifter
80791	XS76EE / F	Micka	C	652388 km	change engine oil & filters & fuel filters , grease and brake adjust , check all lights work , top up auto greaser , check all other fluid levels , carry out tune up , grease clutch & clear GI code , clean alternator terminals , replace diff drain plug	CHM Shed	30-May-25	CHM - 12880	49 ltr x engine oil , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter , 38 ltr x 85W/140 diff oil , 1 x LF3335 fleet guard filter oil , 1 x LF637 oil filter , 1 x BS.230.N70 diff filter O-ring , 1 x UF110 replacement element AdBlue , 1 x AS2474 air filter , 1 x A3380W1687 filter , 1 x A488 A/C filter , 1 x AF1968M air filter , 1 x 1250E473 diff plug ,
80790	XS76EE / F	Micka			checked out put on alternator - all good thinking it's a clamp / wiring on	CHM Shed	28-May-25		

					back of starter motor !				
80745	XS76EE / F	Micka		649896 km	leaking heater tap ! - remove and replaced leaking heater tap , bleed system and top up with coolant ,	Cummins / Campbellfield	27-May-25	Inv - 1642018	1 x 157098 valve needle water , 1 x PGXLVITAL x 5ltr coolant
80440	XS76EE / F	Micka		639876 km	fuel water light came on ! , plug in and check calibrations & update , check tanks & drain all OK , replaced fuel filters ,	TTT	8-May-25	Inv - 303080-00	1 x element 10 micron fuel filter
80334	XS76EE / F	Micka	A	633302 km	check all fluid levels . Grease and brake adjust , check all lights work , found rubbed wiring under cab LH side - repaired , unblock 1-way valve for washer bottle , fit new wiper blades , top up auto greaser , grease clutch	CHM Shed	17-Apr-25	CHM - 12728	1 x auto grease ,
80227	XS76EE / F	Micka		628654 km	fuel light has come on code 102-142 ! , please change fuel filter - had to trace broken wire , also replaced blown fuse for indicators	TTT	8-Apr-25	CHM - 12517 302586-00 Inv -	1 x N52920BL fuse
78841	XS76EE / F	Micka			remove and replace windscreen KW1610E (R446090) , replaced turn table latch cord	Obrien's / M-Bridge L ou	14-Mar-25	SC - 106078 1303 Inv -	1 x TT8819G cord latch for handle
78760	XS76EE / F	Micka	B	611370 km	change engine oil & filters & fuel filters , grease and brake adjust , top up auto greaser (DON'T OVER FILL) , grease & adjust turn table , check	CHM Shed	7-Mar-25	CHM - 12113	1 x LF14000NN engine oil filter , 1 x FS19764 element 10 micron fuel filter , 1 x FF5776 fuel

					all other fluid levels - good check over , grease clutch				filter , 49 ltr x engine oil ,
78604	XS76EE / F	Micka		603385 km	warning light - for water in fuel separator / found code 0418 , drain filter	CHM Shed	21-Feb-25		
78822	XS76EE / F	Micka		594105 km	check radio fault - still playing up / replaced battery bank connecting cable ,	TTT	20-Feb-25	Inv - 301385-00	
78605	XS76EE / F	Micka	A	590798 km	check fluid levels , grease and brake adjust , top up auto greaser , refit fuel tank & step , replace Suzi coil and 7 pin plug lead , clear GI code & grease clutch	CHM Shed	29-Jan-25	CHM - 11870	1 x SC3MTSTSET Suzi coil , 1 x 82524 Suzi coil 7 core 4mm , 1 x 82560 12/24V 7 core EBS Suzi , 2 x ASA93-23-1/2"female adaptor , 2 x ASA93-35 self-sealing 1/2"NP
78207	XS76EE / F	Micka			repair tank - crack in bottom	ACE Engineerin g	15-Jan-25	Inv - 16793	
78200	XS76EE / F	Micka			leaking fuel tank removed	CHM Shed	13-Jan-25		
78180	XS76EE / F	Micka		579918 km	check radio fault & bunk A/C drawing power out instead of in !	TTT	9-Jan-25	Inv - 300847-00	replace radio head unit
80406	XS76EE / F	Micka	B	580501 km	change engine oil & filters & fuel filters , grease and brake adjust , grease clutch , top up auto greaser (DON'T OVER FILL) , grease & adjust turn table , check all other fluid levels - good check over ,	CHM Shed	19-Dec-24	CHM - 11624	49 ltr x engine oil , 1 x engine oil filter , 1 x element 10 micron , 1 x fuel filter , 1 x top up auto greaser

78778	XS76EE / F	Micka	A	559767 km	check fluid levels , grease and brake adjust , top up auto greaser , replace wiper blades and repair 7 pin plug , grease clutch	CHM Shed	15-Nov-24	CHM - 1277	2 x WW710R8-10 wiper refill 710x8mm
80589	XS76EE / F	Micka			tank repair / tank wrap	BMG	24-Oct-24	Inv - KWCP386905	
78792	XS76EE / F	Micka	C	539880 km	change engine oil & filter , grease and brake adjust , top up auto greaser , change diff oils & filter , change air filters , re-set GI code and grease clutch , clear AdBlue fault , replace all drive shock absorbers , replace all drive brakes	CHM Shed	1-Oct-24	CHM - 10942	1 x engine oil filter , 1 x element 10 micron fuel filter euro 5 , 1 x fuel filter , 1 x fleet guard filter oil , 1 x AS2474 air filter , 1 x clear/amber led stainless , 1 x A3380W1687 filter , 1 x LF637 oil filter , 49 ltr engine oil , 35 ltr x 85W/140 diff oil , 1 x UF110 replacement element inline , 1 x AF1968 air filter , 4 x shock absorber rear , 4 ltr x PG coolant RED , 4 x TRP16.5 x 7 steel jacket , 4 x brake lining 312 , 1 x A488 A/C filter , 1 x diff filter O-ring
78226	XS76EE / F	Micka			tank repair	Barry Stoodley / Adelaide	19-Sep-24	Inv - 393548	Paid Lou : Trans Credit Card
78620	XS76EE / F	Micka		529879 km	remove fuel tank	CHM Shed	16-Sep-24	CHM - 10800	
78618	XS76EE / F	Micka	A	522604 km	refit new Suzi coil / check all fluid levels , grease and brake adjust , top up auto greaser , grease clutch	CHM Shed	10-Sep-24	CHM - 10800	1x Suzi coil 7 core 4mm

77872	XS76EE / F	Micka		515944 km	truck not selecting gear !	TTT	14-Aug-24	Inv - 298262-00	found clutch dry - so greased , drain gear box oil and fit seal kit , also fit new gear selector Q21-6155-114
77920	XS76EE / F	Micka		512604 km	DIDN'T Disconnect again - replace Suzi coils air & electric , EBS cord , and new PBR fittings	CHM Shed	6-Aug-24	CHM - 10459	1 x SC3MTSTSET Suzi coil , 1 x 82560 12/24V 7 core EBS Suzi , 1 x suzi coil long tail , 1 x ASA93-35 self-sealing 1.2"NPSF , 2 x ASA93-23 1/2 female adaptor ,
77573	XS76EE / F	Micka	B	504758 km	change engine oil & filters , grease and brake adjust , check all lights work , clear GI code and grease clutch , replaced both belts	CHM Shed	19-Jul-24	CHM - 10329	49 ltr engine oil , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter euro 5 , 1 x auto grease , 1 x 3103233 fan belt , 1 x 3100189 belt , /
77532	XS76EE / F	Micka		501879 km	come up with fault code - plus not using any AdBlue , but has not De-rated	TTT	15-Jul-24	Inv - 297795-00	
77460	XS76EE / F	Micka			clear all fault codes and monitor	TTT	9-Jul-24		
76786	XS76EE / F	Micka	B	480657 km	change engine oil & filters , grease and brake adjust , top up auto greaser , check all lights work , clean AdBlue lines and flush doser unit ,	CHM Shed	14-June-24		1 x FS19764 element 10 micron fuel filter euro 5 , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 49 ltr engine oil , 1 x UF110 AdBlue filter , 1 x AS2474 air filter

76698	XS76EE / F	Micka	A	456987 km	check fluid levels , grease and brake adjust , top up auto greaser , grease clutch and clear GI code	CHM Shed	1- May-24		
76477	XS76EE / F	Micka			1 x HM073-1 plug fusible vent 1/2 " , 1 x 2101GT vent fuel tank	CMV / Adelaide	22- Mar-24	Inv - I31095464	
76457	XS76EE / F	Micka	Call Out	432172 km	found exhaust leaking , fit new clamp and gasket	TTT	21- Mar-24	Inv - 295874-00	
77022	XS76EE / F	Micka	A	437207 km	check fluid levels , grease and brake adjust , top up auto greaser , grease clutch	CHM Shed	15- Mar-24	CHM - 9671	repair tank lights , replace O-ring in power steering reservoir , 1 x K134-283 power steering reservoir gasket
76448	XS76EE / F	Micka			remove fuel tank as leaking / repair fuel tank	CHM Shed AC E Engineering	12- Mar-24	Inv - 13851	
76459	XS76EE / F	Micka		432172 km	truck would not select gear , on inspection found sensor covered in dirt & oil , clean sensor & connection & clear faults	TTT	8- Mar-24	Inv - 295506-00	
77042	XS76EE / F	Micka	C	418615 km	change engine oil & filter , grease and brake adjust , top up auto greaser , change diff oils & filter , change air filters , re-set GI code and grease clutch	CHM Shed	9- Feb-24	CHM - 9246	1 x LF14000NN engine oil filter , 1 x FS19764 element 10 micron fuel filter euro 5 , 1 x FF5776 fuel filter , 1 x fleet guard filter oil , 1 x UF110 replacement element inline , 1 x LF637 oil filter , 1 x A3380W1687 filter , 1 x BS.230.N70 diff

									filter O-ring , 1 x AS2474 air filter , 55 ltr engine oil , 40 ltr diff oil , 1 x AF1968M air filter , 5 ltr extended life PG coolant red ,
76023	XS76EE / F	Micka			remove and replace windscreen - KW1610E (R446090)	Obrien's / M-Bridge	12-Dec-23	Inv - 144795	
76344	XS76EE / F	Micka	A	392087 km	check all fluid levels , grease and brake adjust , top up auto greaser , grease clutch , replace LH steer hub seal , check all lights work	CHM Shed	6-Jan-23	CHM - 8882	1 x 43764S wheel seal , 1 x kit brake shoes steer 16
75866	XS76EE / F	Micka			bunk cooler not shutting down - on inspection found broken wire to stop solenoid	Ryans Auto	5-Dec-23	Inv - 0175	
75627	XS76EE / F	Micka		374511 km	after treat light on ? - flush unit and clear lines and test , couldn't find anything wrong with unit - MONITOTR	TTT	7-Nov-23	Inv - 293325-00	
76045	XS76EE / F	Micka		370601 km	remove and replace 4 x drive brake shoes & drums	CHM Shed	1-Nov-23	CHM - 8743	4 x DB017TRP-TRP 16.5 x 7 steel jacket , 4 x KSMA3124707QP drive brake shoes ,
76431	XS76EE / F	Micka	B	369112 km	change engine oil & filters , grease and brake adjust , top up auto greaser , grease clutch and clear GI code , check all lights work , clean AdBlue lines and flush doser unit , found doser unit failed (WARRANTY)	CHM Shed	27-Oct-23	CHM - 8615	1 x FS19764 element 10 micron fuel filter euro 5 , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 49 ltr engine oil , 1 x UF110 AdBlue filter , 1 x AS2474 air filter

75804	XS76EE / F	Micka		345148 km	repair tank light wiring	CHM Shed	26-Sep-23	CHM - 8416	
75524	XS76EE / F	Micka	A	333607 km	check fluid levels , grease and brake adjust , top up auto greaser ,	CHM Shed	11-Sep-23	CHM - 8067	1 x auto grease
75291	XS76EE / F	Micka	Call Out		blown steer tyre LH front & damaged rim - fit new tyre & rim	Bridgestone / Horsham	6-Sep-23	Inv - 207524	1 x rim 11.75 x 22.5 armoury chrome \$1450.00 + GST
75240	XS76EE / F	Micka	Call Out	324511 km	Travel to Nhill - possible starter motor ??	TTT	30-Aug-23	Inv - 292107-00	remove and replace starter motor
75212	XS76EE / F	Micka	A	334148 km	check fluid levels , grease and brake adjust , top up auto greaser , (MONITOR - next service may need drive brakes getting low) , grease clutch	Corey , Reece	23-Aug-23		
74976	XS76EE / F	Micka		324511 km	rekit Horton fan - heavy duty kit with new bearings & seals ,	TTT	4-Aug-23	Inv - 291667-00	
74925	XS76EE / F	Micka			change out RH blinker as wrong one was fitted - Trans had correct one , put CHM light back in his container	Corey	26-Jul-23		
74859	XS76EE / F	Micka	C	323323 km	change engine oil & filters , grease and brake adjust , check all lights work , top up auto greaser , replace RHR indicator , change diff oil & filter , change air filters , grease	Josh , Corey , Reece	24-Jul-23	SC - 046052 - 7559 CHM	1 x EL94800 light sealed amber rear indicator / 1 x FS19764-element 10 micron fuel filter euro 5 , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel

					clutch and reset GI code,				filter , 1 x LF637 oil filter , 1 x AS2474 air filter , 1 x A3380W1687 filter , 1 x LF3335 fleet guard filter oil , 1 x AF1968M air filter
74741	XS76EE / F	Micka		317319 km	check after treatment fault - found injector to be blocked - replaced as could not clear it / under warranty replaced rail position sensor & replaced fuse for reverse lights	TTT	14-Jul-23	Inv - 291100-00	
74452	XS76EE / F	Micka		309803 km	rewire 7 pin plug , clean out horns on roof , plug truck horn back in , look at reverse beeper - plug in and clear GI code & grease clutch	Luke	16-Jun-23		
74387	XS76EE / F	Micka	A	306485 km	check all fluid levels , grease and brake adjust , check all lights work , top up auto greaser	Luke , Corey	8-Jun-23		
73939	XS76EE / F	Micka	B	280433 km	change engine oil & filters , grease and brake adjust , top up auto greaser , grease clutch and reset GI code	Reece , Josh	21-Apr-23	CHM - 6993	1 x FF5776 fuel filter , 1 x LF14000NN engine oil filter , 1 x FS19764-10 micron fuel filter
74022	XS76EE / F	Micka			replace light	Josh	19-Apr-23	CHM - 6993	1 x 26260CARK amber side light
73687	XS76EE / F	Micka			change out 4 x battery's	Lou Beau repairs / M-Bridge	28-Mar-23		
73719	XS76EE / F	Micka		268052 km	remove and replace 4 x battery	Lou Beau	27-Mar-23	Inv - 6413005040	4 x XN70EX battery

						repairs / M-Bridge			
73546	XS76EE / F	Micka	A	250618 km	check fluid levels , grease and brake adjust , top up auto greaser , hard wire tail light	Josh	23- Feb- 23		
73198	XS76EE / F	Micka			repair light fault - fix plug	Josh	23- Jan- 23		
73142	XS76EE / F	Micka	C	228624 km	change engine oil & filters , change diff oil & filter , change air filters , clear GI code and grease clutch , replace PBR air fittings , clean diff lines	Josh , Reece	13- Jan- 23		
72785	XS76EE / F	Micka	A	208200 km	grease and brake adjust , check all fluid levels , straighten steering wheel , remove rear light bar as need to straighten , replace male 7 pin plug & service ice Pac 1064 hrs , straighten rear light bar	Luke , Corey	30- Nov- 22	SC - 039988	1 x EL82161 plug 7 pin metal
72444	XS76EE / F	Micka		190393 km	replace unloader kit in air dryer	Scott	20- Oct- 22	CHM - 5848	1 x 235 kit unloader air dryer
72346	XS76EE / F	Micka	B	187285 km	change engine oil & filters , grease and brake adjust , check all lights work , top up auto greaser , grease clutch ,	Josh , Corey , Mike	14- Oct- 22	CHM - 5768	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter ,
72392	XS76EE / F	Micka			change out PBR fittings & Suzi coils	Wayne	30- Sep- 22	SC - 038019	2 x AB0149 adaptor 1/2"female , 2 x AB1400 coupling 1/2"female , 1 x AB7810 Suzi coil set red/blue

72135	XS76EE / F	Micka		178329 km	carry out tune up	Josh	21-Sep-22		
71925	XS76EE / F	Micka	A	168319 km	check all fluid levels , grease and brake adjust , top up auto greaser , grease clutch and clear GI code , top up coolant 2 ltr	Luke	24-Aug-22		
71490	XS76EE / F	Micka			check battery's ? , steering column	TTT	26-Jul-22		
71555	XS76EE / F	Micka	B	147822 km	Change engine oil & filter , grease and brake adjust , check all lights work , top up auto greaser	Luke , Josh	20-Jul-22	CHM - 5402	1 x LF1400NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10 micron fuel filter
71533	XS76EE / F	Micka	A	140098 km	check fluid levels , grease and brake adjust , top up auto greaser , clear GI and grease clutch	Sam , Josh	6-Jul-22		
71355	XS76EE / F	Micka	Call Out		truck shut down again ?	CMV / Adelaide	21-Jun-22		
71198	XS76EE / F	Micka	Call Out		selects gears then drops out of gear back to 0	TTT	6-Jun-22		WARRANTY
71241	XS76EE / F	Micka	A	128934 km	auto greaser lines / fittings leaking under steering arm , grease and brake adjust , check fluid levels	Luke , Josh	3-Jun-22		
70981	XS76EE / F	Micka			remove and replace RH rear guard with new , damaged due to trailer & replace 2 mud guard brackets	Sam	10-May-22	SC - 034549	2 x CA5506 bracket mudguard

70901	XS76EE / F T610 / F	Micka / Jeff			2 x 20 ltr demineralised water / 3 x 5 ltr demineralised water	Repco / M- Bridge Repc o / M- Bridge	3- May- 22	Inv - 3870034887 - 3870034886	Inv
70729	XS76EE / F	Micka	C	104109 km	change engine oil & filters , grease and brake adjust , top up auto greaser & repair line , change air filters , change diff oil & filter , check all lights work , grease clutch and reset GI code	Luke , Josh , Mike	8- Apr- 22	CHM - 4756	1 x FF5776 fuel filter , 1 x LF14000NN engine oil filter , 1 x FS19764-10 micron fuel filter , 1 x LF637 oil filter , 1 x A3380W1687 filter , 1 x AS2474 air filter , 1 x LF3335 fleet guard filter oil , 1 x UF110 AdBlue filter , 2 x AFD1968M air filter
70435	XS76EE / F	Micka	B	83893 km	change engine oil & filters , grease and brake adjust , top up auto greaser , grease clutch	Blake , Mike , Josh	2- Mar- 22	CHM - 4562	1 x LF14000NN engine oil filter , 1 x FS19764-10 micron fuel filter
70374	XS76EE / F	Micka			7.5 ltr Demineralised Water	Repco / M- Bridge	22- Feb- 22	Inv - 3870022052	Paid Lou : Trans Credit card
70094	XS76EE / F	Micka			broken airline again going into Melbourne depot	Holmwood Group	28- Jan- 22		
70351	XS76EE / F	Micka			replace air fittings on rear of truck ,	Holmwood Group / Derrimut	28- Jan- 22	Inv - 71594	
70128	XS76EE / F	Micka	A	62238 km	check fluid levels , grease and brake adjust , check all lights work , grease clutch and reset GI code	Blake , Sam	20- Jan- 22		

69962	XS76EE / F	Micka		57902 km	Recall - Steering shaft yoke installation	TTT	12-Jan-22		
69922	XS76EE / F	Micka			1 x 5 litre Demineralised water / hydro unit	Repco / M-Bridge	23-Dec-21	Inv - 3870011314	Paid Lou : Trans Credit Card
69743	XS76EE / F	Micka	B	42377 km	change engine oil & filters , grease and brake adjust , hook up oil pressure sensor for hydro unit - fill with water & turn on (download all info of fuel burn) , grease clutch , used 2 core cable	Luke , Scott , Josh	11-Dec-21	SC - 029838 4112 CHM -	1 x EL1012 cable 2 core 30 mtr roll / 1 x LF1400NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10 micron fuel filter , 1 x 1/4 x 1/8 NT reducing bush , 1 x N072 1/4BSP x M14 , 1 x K301-419-4 pressure switch
69584	XS76EE / F	Micka		? Km	remove and replace both LH & RH rear S/Steel guards	Josh	26-Nov-21	SC - 030304	2 x CA5543 mud guard S/Steel
69578	XS76EE / F	Micka		33456 km	replace LH rear brake booster hose	Josh B	24-Nov-21		
69620	XS76EE / F	Micka	A	31657 km	replace Suzi coils / check fluid levels , grease and brake adjust , top up auto greaser , check all lights work , clear GI code and grease clutch	Sam	22-Nov-21	CHM - 4091	1 x SC3MTSTSET Suzi coil set , 1 x ASA93-23-1/2 female adaptor , 1 x ASA93-32 coupling 1/2"NPT male
69735	XS76EE / F	Micka		27000 km	wire up hydro system	Scotty , Josh	12-Nov-21		
69493	XS76EE / F	Micka		24013 km	fit up new Hydro unit , 8 mtr x 3mm twin core , 6 mtr x 6mm twin core , cable ties	Scott , Josh B	8-Nov-21	CHM - 3972	2 x P14362-040 cushioned 7/8"clamp , 1 x DCT110H1RW-10P double zip ties

69384	XS76EE / F	Micka			1 x frame for Hydro Unit	Ace Engineerin g	1- Nov- 21	Inv - 6222	
69091	XS76EE / F	Mick	B	10427 km	first service	TTT	13- Oct- 21	Inv - 279230-00	
69144	XS76EE / F	Micka		7165 km	cut Suzi coil and re-join with new olive	Josh G	7- Oct- 21		
69136	XS76EE / F	Micka		6290 km	remove and replace broken fitting at soil coils	Kenworth / Derrimut	6- Oct- 21	Inv - 1041544	