

03909880

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection  
Box 45064, Regent Postal Centre  
Winnipeg, MB R2C 5C7  
1-204-955-0970

Manitoba

A902885

Date Inspection Started DAY: 02 MO: 11 YR: 24	Station Number 91541513	Station Name HyLife LTD Labradore	City Labradore
Date Inspection Completed DAY: 02 MO: 11 YR: 24	Mechanic Number A1316161	Mechanic Signature [Signature]	Station Phone Number
Inspection Expiry Date DAY: 30 MO: 11 YR: 25	Vehicle Owner HyLife LTD		
Address 30 Market Blv Steinhilber MB R5E 2X9			
City Steinhilber		Province MB	Postal Code R5E 2X9
Phone 204 424 2300			

  

<input checked="" type="checkbox"/> Pass/Safe Vehicle	Licence Number LK1T12161	Prov. MB	NSC #	Odometer Reading 999965	Odom. Type <input checked="" type="checkbox"/> km <input type="checkbox"/> mi
<input checked="" type="checkbox"/> Fail/Unsafe Vehicle	Vehicle Identification Number 4V14W1C191E1H1X1JW1818191414	Make Volvo	Model VNL	Year 18	Unit # 6075
<input type="checkbox"/> Fail/Hazardous	<input checked="" type="checkbox"/> Confirmed legible Vehicle Identification Number on vehicle				

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ KGB ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) 6-15 reflectors
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X	X	Section 9 - Tire & Wheel: Defects (if any) 9-4 Tire Inflation Pressure
X		Section 10 - Coupling Devices: Defects (if any)

  

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	13	17			100	100		
2	15	5	16	17	100	100		
3	12	9	9	12	100	100		
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -  
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: