



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY03598
Decal Expiry Date: 2025-Oct-31
Inspection Number: 21316754

Inspection Result:

PASS

FACILITY: NORTHERN B.C. TRUCKERS / NS398
INSPECTOR: SCHROEDER, COLIN LESLIE / 109354
INSPECTION TYPE: Complete
INSPECTION CLASS: Class 3 - Trailer and Semi-Trailer
INSPECTION REASON: Semi-annual
INSPECTION START: 2025-Apr-14 04:30 PM MST
INSPECTION COMPLETE: 2025-Apr-14 05:30 PM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 11470J
LICENCED GVW(kg): 0
VEHICLE YEAR: 2020
MAKE: CROSS COUN
MODEL:
REGI: 12955846
UNIT/FLEET#: CPT7
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2C9PBN3M0L1183075
OWNER/LESSEE NAME: 1166211 BC LTD.
ADDRESS: PO BOX 293
Chetwynd, British Columbia
V0C1J0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

BRAKES REPLACE #1 & 2 AXLES

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	31	34	14	13	15	15	
2	Clamp	30	Automatic	32	35	17	17	14	14	
3	Clamp	30	Automatic	37	36	16	16	16	16	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
1	40	40	Lining/Pad	21	21	Rotor/Drum		
2	40	40	Lining (Shoe)	21	21	Drum		
3	54	55	Lining (Shoe)	19	19	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: SCHROEDER, COLIN LESLIE
Road Test Date:
Signature: *Colin Schroeder*
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Apr-17 01:57 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 218 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSD014

4/17/2025 1:57:47 PM MST