



<input checked="" type="checkbox"/> Pass/Safe Vehicle <input type="checkbox"/> Fail/Unsafe Vehicle <input type="checkbox"/> Fail/Hazardous		Licence Number: LHJ51611 Prov.: 015 NSC #: 78956861		Odometer Reading: 125 151 <input checked="" type="checkbox"/> km <input type="checkbox"/> mi	
Date Inspection Started: DAY 09 MO 11 YR 21		Station Number: [] [] [] [] [] [] Station Name: [] [] [] [] [] [] City: [] [] [] [] [] []		Unit #: 6011	
Date Inspection Completed: DAY 12 MO 11 YR 21		Mechanic Number: [] [] [] [] [] [] Mechanic Signature: [] [] [] [] [] [] Station Phone Number: [] [] [] [] [] []		Postal Code: [] [] [] [] [] [] Province: [] [] [] [] [] []	
Inspection Expiry Date: DAY 10 MO 11 YR 21		Vehicle Owner: [] [] [] [] [] [] Address: [] [] [] [] [] [] City: [] [] [] [] [] []		Confirmed legible Vehicle Identification Number on vehicle: <input checked="" type="checkbox"/>	
		Vehicle Identification Number: LXKD119831J317756 Make: KW Model: T800 Year: 20			

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☐ Truck ☒ GVWR ☐ KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus
 List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																
X	X	Section 1 - Power Train: Defects (if any) <u>Top Rail Hose Pipe Line Clamps</u>																																																																																
X		Section 2 Suspension: Defects (if any)																																																																																
X		Section 3 - Brake Systems: <u>3H 3A</u>																																																																																
		Defects (if any)		Circle Brake Type																																																																														
		<div style="display: flex; justify-content: space-between;"> <div> Brake Inspection Type: A (B) C D E <small>Circle appropriate Letter for Internal Brake Component Inspection</small> </div> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>1.65"</td> <td>1.65"</td> <td>16.25"</td> <td>16.25"</td> <td>1.25</td> <td>1.25</td> </tr> <tr> <td>2</td> <td>1.60"</td> <td>1.60"</td> <td>16.25"</td> <td>16.25"</td> <td>1.25</td> <td>1.25</td> </tr> <tr> <td>3</td> <td>1.55"</td> <td>1.55"</td> <td>16.25"</td> <td>16.25"</td> <td>1.25</td> <td>1.25</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table> </div>										Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	1.65"	1.65"	16.25"	16.25"	1.25	1.25	2	1.60"	1.60"	16.25"	16.25"	1.25	1.25	3	1.55"	1.55"	16.25"	16.25"	1.25	1.25	4							5							Final Measurement																						
Axle	Lining		Drum/Rotor		Stroke																																																																													
	L	R	L	R	L	R																																																																												
1	1.65"	1.65"	16.25"	16.25"	1.25	1.25																																																																												
2	1.60"	1.60"	16.25"	16.25"	1.25	1.25																																																																												
3	1.55"	1.55"	16.25"	16.25"	1.25	1.25																																																																												
4																																																																																		
5																																																																																		
Final Measurement																																																																																		
		Section 4 - Steering: Defects (if any)																																																																																
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																
		Section 6 - Lamps: Defects (if any)																																																																																
		Section 7 - Electrical System: Defects (if any)																																																																																
X	X	Section 8 - Body: Defects (if any)		<u>Multi Flip Fender Impact Plate</u>																																																																														
X		Section 9 - Tire & Wheel: Defects (if any)																																																																																
		<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>16</td> <td>10</td> <td></td> <td></td> <td>105</td> <td>105</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>25</td> <td>25</td> <td></td> <td></td> <td>105</td> <td>105</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td>22</td> <td>19</td> <td></td> <td></td> <td>105</td> <td>105</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>										Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	16	10			105	105			2	25	25			105	105			3	22	19			105	105			4									5								
Axle	Tread Depth				Air Pressure																																																																													
	Initial		Corrected		Initial		Corrected																																																																											
	L	R	L	R	L	R	L	R																																																																										
1	16	10			105	105																																																																												
2	25	25			105	105																																																																												
3	22	19			105	105																																																																												
4																																																																																		
5																																																																																		
		Section 10 - Coupling Devices: Defects (if any)																																																																																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature _____

Date: _____