



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	45300 kg	Brake Type:	Air
Owner Name:	Roach Contracting		
Address:	RR1 Site 9 Box 9		
City:	Sexsmith	Province:	AB
		Postal Code:	T0H3C0
Telephone Number:	(780) 897-5975		
Vehicle Identification Number:	1NKDL40X58J936276		
Make:	Kenworth	Model:	Construct
Year:	2008	Unit Number:	
Odometer:	763593 KM	Licence Plate Number:	K09586
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
MVR Mechanical Ltd.	16216
Inspection Technician Name:	Technician Number:
David McNair	B2253
Inspection Technician Signature:	
Inspection Date:	2025/04/11