



Commercial Vehicle Inspection Report

Decal Number: GN45117
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21763321

Y05-1
Inspection Result:
PASS

FACILITY: Royal Truck Repair LTD. / S20445 INSP. TYPE: Complete INSP. START: 2026-May-06 10:15 AM PDT
INSPECTOR: Sahota, Dilraj Singh / 203246 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2026-May-06 12:15 PM PDT
WORK ORDER #: INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 10887752 VIN: 1M1AW07YXDM035593
PLATE #: WW1109 UNIT/FLEET#: OWNER/LESSEE NAME: HAYER DEMOLITION LTD., HAYER DEMOLITION LTD.
LICENCED GVW(kg): 48000 BODY STYLE: Truck Tractor ADDRESS: 6213 126B ST
VEHICLE YEAR: 2013 ODOMETER: 705604 KM Surrey, British Columbia
MAKE: MACK HUB ODOMETER: V3X3N2, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) REPLACED 3 AXLE RIGHT SIDE SHOCK ABSORBER
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED 2 AXLE LEFT SIDE MAXI
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPLACED MARKER LIGHTS AS NEEDED
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	36	36	8			9	✓
2	Clamp	30L	Automatic	34	35	15	11	15	15	
3	Clamp	30L	Automatic	37	37	12	12	12	12	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
1	30	30	Lining/Pad	19	19	Drum		
2	45	45	Lining (Shoe)	16	16	Drum		
3	45	45	Lining (Shoe)	16	16	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Signature: D. Sahota

Road Tester:

This Inspection Report was submitted to CVSE on 2026-May-06 08:52 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE014

5/6/2026 6:52:22 PM PDT