04151840

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C143456

Date Inspection Started	012 DAY	111 MO.	26 YR.	Station Number	C1015916	Station Name: Froese Seed Service	City
Date Inspection Completed	013 DAY	111 MO.	26 YR.	Mechanic Number	M1410613	Mechanic Signature	204 209 1099 Station Phone Number
Inspection Expiry Date	310 DAY	111 MO.	27 YR.				

Vehicle Owner: Froese Seed Service

Address | City | Province | Postal Code | Phone

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: CRF7610 | Prov.: MB | NSC #: MB161137 | Odometer Reading: 1179420 | Odom. Type: ☒ km ☐ mi

Vehicle Identification Number: 1XKPB1DP9JX12FD126615415 | Make: pete | Model: 579 | Year: 15 | Unit #: 102

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck | GVWR 21351817 KGS | X Truck Tractor | ____Trailer | ____Semi-Trailer | ____Bus | ____School Bus | ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X	X	**Section 1 - Power Train:** Defects (if any) 4-E-Hanger bearing loose, 10-A-Alt belt Frayed
X	X	**Section 2 Suspension:** Defects (if any) 5-E-Front R/H bag Fitting Leaking
X	X	
X		**Section 3 - Brake Systems:** 3H (3A)

Defects (if any) / Circle Brake Type
2-G-Air Leak under Hood
13-A-Glad Hard Seals
18-F-Steer parts Chiped/Cracked

Brake Inspection Type: A B (C) D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	New	New	1.52	1.54		
2	.572	.516			1 1/2	1 1/2
3	.501	.442			1 1/2	1 1/2
4						
5						
	Final Measurement					

X		**Section 4 - Steering:** Defects (if any)
X	X	**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any) 7-D-washer nozels
X	X	**Section 6 - Lamps:** Defects (if any) 1-C-R/H tail Light, 1-F-L/H Hood Fender Light 1-K-L/H Reverse Light
X		**Section 7 - Electrical System:** Defects (if any)
X	X	**Section 8 - Body:** Defects (if any) 3-F-Cab Shocks Leaking
X	X	**Section 9 - Tire & Wheel:** Defects (if any) 5-D-Steer Hub Caps corroded

Axle	Tread Depth Initial L	Initial R	Initial R	Corrected L	Corrected R	Air Pressure Initial L	Initial R	Corrected L	Corrected R
1		13	9						
2	12	8	7	9			100 PSI		
3	16	13	13	18					
4									
5									

X	X	**Section 10 - Coupling Devices:** Defects (if any) 7-C-pivot bushings worne

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE