



Commercial Vehicle Inspection Report

Decal Number: PA06272
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21699253

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN / 106407
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual

INSP. START: 2026-Mar-23 08:45 AM MST
INSP. COMPLETE: 2026-Mar-23 09:45 AM MST

VEHICLE JUR: British Columbia
PLATE #: 39912L
LICENCED GVW(kg): 0
VEHICLE YEAR: 2022
MAKE: LANGFAB
MODEL:

REGI: 13867777
UNIT/FLEET#:
BODY STYLE: Pup Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2L9PPA6C0NS014174
OWNER/LESSEE NAME: ALL NORTH TRUCKING LTD. , N/A
ADDRESS: 8356 JAKK RD
Fort St John, British Columbia
V1J8E4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) L1 3 slack sr5 air valves and air lines recent brakes
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxilliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) Marker lights repaired
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	33
2	Clamp	30	Automatic	32	33
3	Clamp	30	Automatic	34	31

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
7	7	8	7	
7	8	9	8	
9	9	8	8	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	24	35
2	39	34
3	20	36

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	20	19
Lining (Shoe)	18	17
Lining (Shoe)	20	18

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		


Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN

Road Test Date:
Signature: 

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Mar-23 11:41 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE014

3/23/2026 11:41:05 AM MST



Commercial Vehicle Inspection Report

Decal Number: PA06299
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21705935

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN / 106407
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Mar-23 07:14 AM MST
INSP. COMPLETE: 2026-Mar-23 08:45 AM MST

VEHICLE JUR: British Columbia
PLATE #: EL7684
LICENCED GVW(kg): 57100
VEHICLE YEAR: 2007
MAKE: KENWORTH
MODEL:

REGI: 00083966
UNIT/FLEET#: 02
BODY STYLE: Dump Truck
ODOMETER: 1059009 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1NKDL40X07R932331
OWNER/LESSEE NAME: All north trucking ltd, .
ADDRESS: 8356 jakk rd
Fort St John, British Columbia
V1j8e4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) Abs r3 pot Recent brake job
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Plate light
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) Exh repair
Section 9A - Tires	Passed Recent tires
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	30	29	16			16	
2	Clamp	30	Automatic	37	35	17	17	17	17	✓
3	Clamp	30	Automatic	36	37	17	17	17	17	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	35	36	Lining (Shoe)	19	19	Drum		
2	40	34	Lining (Shoe)	18.5	19	Drum		
3	36	40	Lining (Shoe)	19	18.5	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN
Road Test Date: _____
Signature: 
Road Tester: _____

This Inspection Report was submitted to CVSE on 2026-Mar-23 11:50 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NS/CVP at the Commercial Vehicle Safety Enforcement



Commercial Vehicle Inspection Report

Decal Number: PY28048
Decal Expiry Date: 2026-Aug-31
Inspection Number: 21654860

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN / 106407
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual

INSP. START: 2026-Feb-08 10:00 AM MST
INSP. COMPLETE: 2026-Feb-08 11:00 AM MST

VEHICLE JUR: British Columbia
PLATE #: 84299K
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2015
MAKE: CANCADE
MODEL: END

REGI: 11208505
UNIT/FLEET#: 08
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2C91333E5F1086667
OWNER/LESSEE NAME: ALL NORTH TRUCKING LTD.,
ADDRESS: 8356 JAKK RD
Fort St John, British Columbia
V1J8E4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) 2 brake Clovis pin
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Lights repaired
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	40	38
2	Clamp	30	Automatic	37	39
3	Clamp	30	Automatic	40	42

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
15	15	7	16	
9	9	12	7	
11	12	13	12	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	40
2	38	36
3	75	80

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	16	16
Lining (Shoe)	13	12

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Feb-08 02:51 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

2/8/2026 2:51:25 PM MST