



Commercial Vehicle Inspection Report

Decal Number: GH21986
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21236693

Y06-1
Inspection Result:
PASS

FACILITY:	NAHANNI TRUCK & TRAILER / S5800	INSP. TYPE:	Complete	INSP. START:	2025-Feb-12 12:30 PM PST
INSPECTOR:	WIDINER, GUY ANTHONY / 112125	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-Feb-12 03:30 PM PST
WORK ORDER #:	80791	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	10263224	VIN:	1DASFC03XBP020432
PLATE #:	91018K	UNIT/FLEET#:		OWNER/LESSEE NAME:	SPECIALIZED TOWING LIMITED, SPECIALIZED TOWING LIMITED
LICENCED GVW(kg):	999999	BODY STYLE:	Flat Deck Trailer	ADDRESS:	PO BOX 64724 RPO SUNWOOD SQAUR, PO BOX 64724 RPO SUNWOOD SQAUR
VEHICLE YEAR:	2011	ODOMETER:			Coquitlam, British Columbia
MAKE:	TRAIL EZE	HUB ODOMETER:			V3B0H1, Canada
MODEL:	TE801	BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxilliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Repaired (same day) repaired abs wiring
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	38	38
2	Clamp	30	Automatic	38	38
3	Clamp	30	Automatic	38	38

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	11.1	11.1	11.9	11.1	
2	6.4	6.4	7.9	7.1	
3	10.3	10.3	8.7	7.9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	37	35
2	32	30
3	42	42

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	20	20
Lining (Shoe)	20	20
Lining (Shoe)	20	20

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: WIDINER, GUY ANTHONY

Signature:

This Inspection Report was submitted to CVSE on 2025-Feb-13 10:26 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

2/13/2025 10:26:15 AM PST