Vehicle History Summary



Fleet #	10036
Registration	XO24VL
Make	ISUZU
Model	FTR900L
VIN / Chassis #	JALFTR34R47000105
Build Date	2005

Date	Reading / Units	Type / Repairer Notes	Repairer
12/10/2026		**Repair Roof Pan** R-7189	Pendergast Northwest freight services
		Measure up roof and order material removed sides and cleaned all silicone and expand foam cut out damaged areas picked up 4 sheets and angle glued and overlapped all sheets and riveted glued and fitted sides and riveted cut new front piece and fitted made new corner endcaps refitted internal roof bracing JAY removed sides and cleaned all silicone and expand foam cut out damaged areas picked up 4 sheets and angle glued and overlapped all sheets and riveted glued and fitted sides and riveted cut new front piece and fitted made new corner endcaps refitted internal roof bracing Cooper	
30/09/2026	708,286 kms	**C** S-2581	
		completed service	
09/09/2026		**CTP** O-2221	GIO
		CTN361803918	
09/09/2026		**Registration** O-2222	SERVICES NSW
		Rego	
03/08/2026	701,743 kms	**B - 30** S-2534	Pendergast Northwest freight services
06/06/2026	662,743 kms	**B - 20k** S-2466	Pendergast Northwest freight services
		window found 2 minor cracks left blinker out new bulb left hand roof light new bulb placed new reflector i missing make up 3 cross beams in back to hold up the roof and stop water leaking in track would not start as air was in fuel line 3 days trying to bleed it out also checked all the fuses ending up spraying brake cleaner in to the filter to qet it running	
01/06/2026		**FUEL SYSTEM** R-6850	Pendergast Northwest freight services
		XO24VL. Got the truck started.	
07/03/2026		**Registration** O-1896	SERVICES NSW
		TRANSFER REGO	
07/12/2025		**RADIATOR** R-6279	Doc's Mobile Mechanical
		XO24VL. Traveled out to moonbi and checked the truck over for getting hot found the radiator was presurising and pushing out the coolant. Removed the thermostates and got the truck back to the yard.	

Signed: _____

Name: _____

Date: _____