Vehicle History Summary



Fleet #	B9032
Registration	TE87JV
Make	Vawdrey
Model	VBS398A
VIN / Chassis #	6HJVAWAUS4SE00823
Build Date	2004

Date	Reading / Units	Type / Repairer Notes	Repairer
12/09/2026		**Registration** O-2235 Rego	SERVICES NSW
25/08/2026	33,255 kms	**B - 20,000Km** S-2579 B Service. Grease all points. Adjust brakes. Replace damaged front Lh marker LED light. Axle 3, Replace missing mud guard and mud flap. Front left corner damaged & missing corner trim- Fabricate & fit new corner cover cap, Sikaflex and rivet into place.	KSY Workshop
12/06/2026		**Registration** O-2065 rego	SERVICES NSW
14/04/2026		**Trailer Tyre** T-1938 2 x 11R22.5 HAULSTAR HA601	Pendergast Northwest freight services
13/03/2026		**Registration** O-1913 REGO	SERVICES NSW
07/01/2026	593,777 kms	**ADJUST BRAKES** R-6377 Adjusted brakes Inspected trailer lights, reflectors, tyres, mudflaps, air bags, air tanks, suspension, plates, NHVR label, trailer connections Had to tighten air fitting from the supply Stopped leaking after Replaced reflectors, broken zip ties Holding air lines in place Aiden	Pendergast Northwest freight services
16/12/2025	1 kms	**B - 20,000Km** S-2308 B Service. Grease all points. Adjust brakes. Repair wiring on 5 clearance lights. Repair rear roller door, Fit missing rollers.. Replace broken Hubb Meter. Axle 3 Rh side brake booster leaking.- Remove and replace as required.	KSY Workshop
13/12/2025		**Registration** O-1681 REGO	SERVICES NSW
11/12/2025		**Registration** O-1670 TRANSFER	SERVICES NSW
10/12/2025		**General Repairs** R-6684	Pendergast Northwest freight services
25/11/2025	7,485 kms	**BREAKDOWN** R-6304 Drove near Murrurundi, clearance light not working Kept blowing fuse, looked at the light plugs and they were fine Looked at the wiring of clearance light on the A trailer and still nothing Looked at the B trailer and ended up coming back to the A trailer. Still nothing, then I checked 34481 clearance light wires were jammed in between the guard bracket and light bracket So I cut the wires and put new fuse in the truck Clearance lights work Ryan	Pendergast Northwest freight services

Signed: _____

Name: _____

Date: _____