Vehicle History Summary



Fleet #	A9032
Registration	YN91ZQ
Make	Vawdrey
Model	VBS398A
VIN / Chassis #	6HJVAWAUS4SE00894
Build Date	2004

Date	Reading / Units	Type / Repairer Notes	Repairer
27/08/2026		**Registration** O-2201	SERVICES NSW
		Registration	
16/06/2026	829,069 kms	**B - 20,000Km** S-2477	KSY Workshop
		B Service. Grease all points. Adjust brakes. Axle 3, Brake shoes low, Lh brake drum cracked- Remove & replace brake shoes, Replace Lh brake drum. Axle 2, Rh side brakes low, Brake drum worn & cracked- Reline Rh side & replace Brake drum. Axle 1, Lh side brakes low- Reline brakes. Clean, Inspect & repack all bearings. Rear marker plate decals faded & torn- Remove & replace decals. Connor. Bill.	
05/06/2026	802,906 kms	**TRUCK TYRE** T-2010	Bridgestone Kempsey
		POS 3,4 TYRATTCN00000 11R22.5 148/145L 16PR ATLAS KTT307 2 FITTR Fitting - Truck Tyre	
25/05/2026		**Missing Mudflap** R-6816	Pendergast Northwest freight services
		Replace Mudflap Weld cracks on Rear bar Jay	
25/05/2026		**Registration** O-2031	SERVICES NSW
		REGO	
13/05/2026		**bent turntable handle** R-6781	Torque N Diesel
		travel to metcash found turntable handle bent bent handle straight on a trailer tested all works ok	
22/04/2026	829,069 kms	**General Lookover** R-6744	Pendergast Northwest freight services
		CHECKED LIGHTS REFLECTORS, SHOCKS, SUSPENTION, LONG VEHICLLE SIGNS , AIR BAGS , AIR TANUS, MUDFLAPS, LANDING LEGS, KING PIN, BRAKES, GREASED ADJUSTED BRAKES. REPLACED 2 X RED REFLECTORS, REPLACED BREAKLIGHTS ON RH SIDE AIDEN	
13/04/2026		**Trailer Tyre** T-1926	Pendergast Northwest freight services
		2 X 11R22.5 HAULSTAR HA601 POS: 15/16	
31/03/2026	8,290,609 kms	**General Repair** R-6633	Pendergast Northwest freight services
		looked over trailer , inspected lights, reflectors replaced 3 x amber 2 x red , 2 x white tires mudflaps shackles suspension truck fittings airbags air tank king pin adjusted brakes greased trailer landing legs long vehicle sign resourced loose air lines going to middle axle L/H booster Aiden Jones	
20/03/2026		**TRUCK TYRE** T-1903	Pendergast Northwest freight services
		2 x 11R22.5 HAULSTAR HA601 POS 21/22	
14/03/2026		**General Repair** R-6629	Pendergast Northwest freight services
02/03/2026		**Registration** O-1866	SERVICES NSW
		REGO	
23/02/2026		**BOOSTER** R-6504	HNL Fleet Newcastle.
		YN91ZQ - Roll back pin won't release. Inspected and found single chamber booster leaking out every port. Removed, measured, replaced & refit new booster. Test, all OK. Secure & tighten air lines. Rolled body back, OK	
14/02/2026		**Trailer Tyre** T-1870	Pendergast Northwest freight services

Date	Reading / Units	Type / Repairer Notes	Repairer
		2 X 11R22.5 DOUBLE STAR HR169 POS: 19/20	
17/01/2026	829,069 kms	**A - 10,000Km** S-2348 A Service Complete Check lights Check over Found axle 1 shock loose Found axle 2 LH brake low Found axle 3 slack adjuster not working Tighten up shock on axle 1 both sides Removed axle 2 LH nuts. Removed old brakes, fitted new brakes and hardware Check s-cam and bushes, all ok Removed pin from slack on axle 3 LH Removed slack adjuster, fitted new slack adjuster Fitted new pin and split pins Adjust all brakes, all ok. Parts - Slack - 10.21103B x1 Truckline $102.78 BSKBC361B9S x1 Truckline $94.41 Luke	
07/01/2026		**ADJUST BRAKES** R-6370 Inspected Trailer Checked lights, reflectors, tyres, mudflaps, air tanks, air bags, trailer connections Adjusted brakes Checked suspension Aiden	Pendergast Northwest freight services
08/12/2025		**Registration** O-1646 REGO	SERVICES NSW
07/12/2025		**EMS Inspection** O-1775 Authorised Inspection Station Number S09329	
29/11/2025		**Registration** O-1642 TRANSFER	SERVICES NSW
25/11/2025	829,069 kms	**BREAKDOWN** R-6303 Drove near Murrurundi, clearance light not working Kept blowing fuse, looked at the light plugs and they were fine Looked at the wiring of clearance light on the A trailer and still nothing Looked at the B trailer and ended up coming back to the A trailer. Still nothing, then I checked 34481 clearance light wires were jammed in between the guard bracket and light bracket So I cut the wires and put new fuse in the truck Clearance lights work Ryan	Pendergast Northwest freight services

Signed: _____

Name: _____

Date: _____