Vehicle History Summary



Fleet #	B9030
Registration	TD49JM
Make	KRUEGER
Model	ST338
VIN / Chassis #	6FH9079DA4M010022
Build Date	2004

Date	Reading / Units	Type / Repairer Notes	Repairer
09/10/2026		**bent legs** R-7144	Pendergast Northwest freight services
		Removed old legs and fit new/second hand found no brackets would fit so measured holes and drilled to suit Jay	
06/10/2026	293,250 kms	**A - 10,000Km** S-2629	Doc's Mobile Mechanical
		TD49JM. Checked over the trailer repaired broken side marker lights greased and adjusted the brakes.	
28/09/2026		**Registration** O-2261	SERVICES NSW
		I-0467213733	
03/08/2026	290,750 kms	**Trailer Tyre** T-2070	Bridgestone Kempsey
		NEW POS 1,2 - POS 1,2 ROTATE TO POS 7,8 - POS 8 ROTATE TO POS 5 TYRATTCN00000 11R22.5 148/145L 16PR ATLAS KTT307 FITTR Fitting - Truck Tyre 98301 TRUCK TYRE ROTATION	
24/07/2026	1 kms	**curtain rail** R-6941	Torque N Diesel
		attend call out travel to AWH yard at Yenorra diagnosed and found L/H/S curtain rail bent shut the hole way of trailer re bent rail test and found ok	
24/06/2026		**Registration** O-2096	SERVICES NSW
		REGO	
28/03/2026		**Registration** O-1939	SERVICES NSW
		REGO	
20/03/2026		**TRUCK TYRE** T-1920	Bridgestone Kempsey
11/03/2026	260,178 kms	**B - 90 days** S-2396	KSY Workshop
		B Service. Grease all points. Adjust brakes. Replaced faulty clearance light, Rh rear. Tighten shock mounts.	
21/01/2026		**Curtain Repair** R-6397	M & G Truck Curtain Repairs
		Repair large holes and tears in Left side Curtain	
10/01/2026	239,252 kms	**Puncture Repair** T-1848	Bridgestone Kempsey
		POS 8 PUNT Puncture Repair - Truck Tyre	
28/12/2025		**Registration** O-1735	SERVICES NSW
		REGO	
22/12/2025		**Registration** O-1728	SERVICES NSW
		TRANSFER REGO	
22/12/2025		**Registration** O-1729	SERVICES NSW
		TRANSFER REGO	

Signed: _____

Name: _____

Date: _____