Vehicle History Summary



Fleet #	12037 rg0012
Registration	CI30KI
Make	Hino
Model	FD1J
VIN / Chassis #	JHDFD1JPPXXX10407
Build Date	2005

Date	Reading / Units	Type / Repairer Notes	Repairer
08/10/2026		**Clutch repair** R-7139	Pendergast Northwest freight services
		found the clutch smoking so I unbolted the tail shaft then started unbolting the gearbox then pulled the clutch out after I then pulled the flywheel off and took it down to retorque to get machined once back fitted new spike bearing and fitted bearing in gearbox then i fitted the clutch then put gearbox back in and fitted the tail shaft Ryan Luke checked	
28/09/2026		**topped up coolant & oil** R-7113	Doc's Mobile Mechanical
		CI30KI. Toped up the coolant and the oil. Pressure cleaned the engine. Helped Shane load the truck.	
17/09/2026	1,134,619 kms	**C - 100k** S-2616	Pendergast Northwest freight services
		completed major service	
20/07/2026		**CTP** O-2129	GIO
		CTN318219793	
20/07/2026		**Registration** O-2130	SERVICES NSW
		I-0463689085	
07/03/2026		**Registration** O-1894	SERVICES NSW
		TRANSFER REGO	

Signed: _____

Name: _____

Date: _____