Vehicle History Summary



Fleet #	FT2002
Registration	Y60497
Make	Terex
Model	20P F/TOP
VIN / Chassis #	AT1323
Build Date	1981

Date	Reading / Units	Type / Repairer Notes	Repairer
09/10/2026		**light check** R-7141	Pendergast Northwest freight services
		Rear parker on tail light LH and side marker LH rear and number plate light was not working rewired from the front of the trailer to the rear on the Left Hand side Cooper	
12/09/2026	104,774 kms	**A - 10,000Km** S-2608	Pendergast Northwest freight services
		Ryan Adjusted 3 sets of brakes axels 80% centre axel 28% axel 50% Replaced NHVR sticker Luke completed A service	
14/08/2026		**Registration** O-2174	SERVICES NSW
		rego	
13/08/2026	94,774 kms	**C - 100,000Km** S-2551	Pendergast Northwest freight services
		repaired cracked chassis RH side on Pivot mount for axle 1 and 2 replace LH side marker light all bushes need replacing kingpin & skid plate worn	
08/08/2026	93,095 kms	**Trailer Tyre** T-2074	Bridgestone Kempsey
		POS 3,4 TYRATTCN00000 11R22.5 148/145L 16PR ATLAS KTT307 FITTR Fitting - Truck Tyre	
12/05/2026		**Registration** O-2011	SERVICES NSW
		REGO	
19/04/2026		**Trailer Annual Inspection Sample** I-68	Pendergast Northwest freight services
		KIN PIN - OK TYRES, BRAKES,LIGHTS, OK SKID BRAKE OK GREASED	
20/03/2026		**Puncture Repair** T-1919	Bridgestone Kempsey
07/03/2026	85,638 kms	**Fit Runout** T-1896	Bridgestone Kempsey
		POS 7,8 FIT RUNOUTS FITTR Fitting - Truck Tyre	
21/02/2026	84,795 kms	**Puncture Repair** T-1882	Bridgestone Kempsey
		POS 9 REPAIR - POS 3,4,10 RUNOUTS PUNT Puncture Repair - Truck Tyre Fitting - Truck Tyre	
16/01/2026		**Registration** O-1788	SERVICES NSW
		TRTANSFER REGO	
17/11/2025		**Registration** O-1582	SERVICES NSW
		REGO	

Signed: _____

Name: _____

Date: _____