


Rebuild Delivery Service Record

Customer Name	BRISBY PLANT HIRE PTY LTD
Mailing Address	PO BOX 98 WAUCHOPE 2446
Dealer Code	T167
Model	815F
Machine Serial Number	1GN01096
Component Serial Number	.
Machine Hours	15,787
Delivery Date	21/01/2025
Rebuild EPP Purchased (If applicable)	36 months / 5,000 Hours Dealer rebuild Transmission + Torque Conv
Rebuild Work order number	NG41881

Acceptance of Delivery

WesTrac Pty Ltd	BRISBY PLANT HIRE PTY LTD
<p>Signed by Jamie Furlong</p> 	<p>Signed by BRISBY PLANT HIRE PTY LTD Customer Representative Karen Cusato Customer Representative Title Director</p> 
<p>Date 27 / 02 / 2025</p>	<p>Date 14 / 03 / 2025</p>

CERTIFICATE *of* SIGNATURE

REF. NUMBER
WQSXG-J4GFQ-IW8GH-4SNM7

DOCUMENT COMPLETED BY ALL PARTIES ON
14 MAR 2025 02:24:54 UTC

SIGNER

JAMIE FURLONG

EMAIL
JAMIE.FURLONG@WESTRAC.COM.AU

TIMESTAMP

SENT
27 FEB 2025 02:38:32 UTC
VIEWED
27 FEB 2025 02:50:11 UTC
SIGNED
27 FEB 2025 02:52:06 UTC

SIGNATURE



IP ADDRESS
110.145.234.54

LOCATION
NEWCASTLE, AUSTRALIA

RECIPIENT VERIFICATION

EMAIL VERIFIED
27 FEB 2025 02:50:11 UTC

BRISBY PLANT HIRE PTY LTD

EMAIL
STEVE@KAZAC.COM.AU

SENT
27 FEB 2025 02:38:32 UTC
VIEWED
14 MAR 2025 02:23:49 UTC
SIGNED
14 MAR 2025 02:24:54 UTC



IP ADDRESS
206.148.31.84

LOCATION
MELBOURNE, AUSTRALIA

RECIPIENT VERIFICATION

EMAIL VERIFIED
14 MAR 2025 02:23:49 UTC

