Vehicle History Report # 74276785
Report Date: November 18, 2026 | 2:51 p.m. EST
Report Status: Complete

2019 INTERNATIONAL LT625

Tractor truck | 6 Cylinders | Diesel
3HCDZTZR5KL473122
Country of Assembly: Mexico
Last Reported Odometer: 698,243 KM



No Accident/Damage Records Found

Last Registered In:
Ontario (Normal)

7 Service Records Found

No U.S. History Found

Unable to check for recall information

Not Actively Declared Stolen

No Import/Export Records Found

Questions? We're here to help.
Visit us at **support.carfax.ca**

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of November 18, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report

Accident/Damage

There are no accidents/damage reported on this vehicle.

Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Sep 12	140,167 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	**Vehicle serviced** • ABS system checked • Airbag system checked • Brakes checked • Cooling system hoses checked • Electrical system checked • Engine checked • Exhaust system checked • Fuel system checked • Glass checked • Emissions or safety inspection performed • Lights checked • Mirror(s) checked • Steering/suspension checked • Tire condition and pressure checked • Tire(s) mounted • Wheel bearings checked • Wipers/washers checked
2020 Sep 9	289,609 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	**Vehicle serviced** • Recommended maintenance performed • ABS system checked • Brakes checked • Doors checked • Engine checked • Fluids checked • Emissions or safety inspection performed • Lights checked • Steering/suspension checked • Tire condition and pressure checked • Wheel bearings checked • Wheel lug nuts torqued
2021 Sep 10		GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	**Vehicle serviced** • ABS system checked • Airbag system checked • Brakes checked • Cooling system hoses checked

	ODOMETER	SOURCE	DETAILS
			• Electrical system checked • Engine checked • Exhaust system checked • Fuel system checked • Glass checked • Emissions or safety inspection performed • Lights checked • Mirror(s) checked • Steering/suspension checked • Tire condition and pressure checked • Tire(s) mounted • Wheel bearings checked • Wipers/washers checked
2022 Sep 6	334,428 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	**Vehicle serviced** • ABS system checked • Airbag system checked • Brakes checked • Cooling system hoses checked • Electrical system checked • Engine checked • Exhaust system checked • Fuel system checked • Glass checked • Emissions or safety inspection performed • Lights checked • Mirror(s) checked • Steering/suspension checked • Tire condition and pressure checked • Tire(s) mounted • Wheel bearings checked • Wipers/washers checked
2023 Sep 21	698,243 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	**Vehicle serviced** • ABS system checked • Brakes checked • Electrical system checked • Engine checked • Exhaust system checked • Fuel system checked • Glass checked • Emissions or safety inspection performed • Lights checked • Mirror(s) checked • Steering/suspension checked • Tire condition and pressure checked • Tire(s) mounted • Wheel bearings checked • Wipers/washers checked
2024 May 22		KROWN VAUDREUIL Vaudreuil-Dorion, Québec, Canada	**Vehicle serviced** • Undercoating/rustproofing applied
2025 Sep 30		GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	**Vehicle serviced** • ABS system checked • Alignment checked • Brakes checked • Tire condition and pressure checked

Open Recalls

⚠ We are unable to check for recall information on this vehicle. Please visit undefined for the most current recall information on this, or any, INTERNATIONAL vehicle.

Stolen Vehicle Check

This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Sep 12	140,167 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Service Record	Vehicle serviced
2020 Sep 9	289,609 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Service Record	Vehicle serviced
2021 Sep 10		GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Service Record	Vehicle serviced
2022 Sep 6	334,428 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Service Record	Vehicle serviced
2023 Sep 21	698,243 KM	GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Service Record	Vehicle serviced
2024 May 22		KROWN VAUDREUIL Vaudreuil-Dorion, Québec, Canada	Service Record	Vehicle serviced
2025 Sep 30		GLENGARRY TRUCK CENTER LTD Alexandria, Ontario, Canada	Service Record	Vehicle serviced
2025 Oct 6		Motor Vehicle Dept. Ontario, Canada	Registration Records	Registered/Renewed



Questions? We're here to help.

Visit us at **support.carfax.ca**

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.
https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use

3HCDZTZR5KL473122

© 2026 CARFAX Canada ULC. All rights reserved.