


TAX INVOICE



Invoice Date
13 Jul 2026

Invoice Number
INV-20106409

Reference
2148

ABN
55 108 103 395

Acacia Ridge Container Park
Pty Ltd
51 Mccotter St
Acacia Ridge QLD 4110
Australia
P: +61 7 3711 7200
E: arcpark@dglgroup.com
W: www.arcpark.com.au
W: www.dglgroup.com

Description	Quantity	Unit Price	GST	Amount AUD
Washout YQ21ZM/YQ23ZM Product - Black Oil Rego# XQ30UU Docket# 44719	1.00	554.63	10%	554.63
Water Surcharge 10%	1.00	55.46	10%	55.46
Environmental Levy 7%	1.00	38.82	10%	38.82
Drainage and disposal of 860L	860.00	2.25	10%	1,935.00
30L Degreaser	30.00	3.20	10%	96.00
40min labour to manually hose	1.00	80.00	10%	80.00
1hr labour to decant	1.00	120.00	10%	120.00
			Subtotal	2,879.91
			TOTAL GST 10%	287.99
			TOTAL AUD	3,167.90

Due Date: 12 Aug 2026

Please note: Effective 13th July 2026, please pay into our new banking details below

Banking Details - National Australia Bank
BSB: 082-001 A/C: 197315873


When paying your invoice, please use invoice number as reference.
Please send remittance to: brandon.gee@dglgroup.com
Thank You.

Credit Card option now available. Credit Card payment will incur a 4% transaction fee.



[View and pay online now](#)

DGL



Acacia
Ridge
Container
Park

44719

51 McCotter Street, Acacia Ridge Qld 4110 P.O Box 469, Archerfield Qld 4108 Ph: 07 3711 7200 Fax: 07 3711 7300 Email: arcpark@dglgroup.com

Client:				Date: 10/7/26				Office Use	
REGO # XQ30UV				Con Note #					
Compartment #	1	2	3	4	5	6	7	8	
Last Product		Black oil							
Cold Wash	✓	✓	✓	✓	✓	✓	✓	✓	
Hot / Det. Wash	✓	✓	✓	✓	✓	✓	✓	✓	
Steam / Hot Det. Wash									
Steam Hours						# 402/2m			
External Wash						# 402/2m			
Hot Air Dry									

Manifolds/Hoses/Pump



Manifolds



Hoses



Pump

Draining	860 Ltrs	
Materials	30 Litres Degreaser	
Cleanliness Certificate	☐ Inhouse	☐ Independent
Leak Check & Safety Survey	☐ 1 Bar	☐ Repairs quoted on E.I.R
Manlid Seal	☐ P.T.F.E	☐ S.W.R
Transport	1 hr Labour Decant	
Handling		
Special Comments	manual hosing labour 60 min	

Date: 10/7/26 Tank has been inspected and found to be visually clean and odour-free.

Operator

Axon/Scott

Drivers Signature

Ed Munroe