


TAX INVOICE



Invoice Date
13 Jul 2026

Invoice Number
INV-20106408

Reference
2150

ABN
55 108 103 395

Acacia Ridge Container Park
Pty Ltd
51 Mccotter St
Acacia Ridge QLD 4110
Australia
P: +61 7 3711 7200
E: arcpark@dglgroup.com
W: www.arcpark.com.au
W: www.dglgroup.com

Description	Quantity	Unit Price	GST	Amount AUD
Washout YQ24ZM Product - Black Oil Rego# XQ30UU Docket# 44716	1.00	348.99	10%	348.99
Water Surcharge 10%	1.00	34.90	10%	34.90
Environmental Levy 7%	1.00	24.43	10%	24.43
Drainage and disposal of 80L	80.00	2.25	10%	180.00
30L Degreaser	30.00	3.20	10%	96.00
30min labour	0.50	120.00	10%	60.00
			Subtotal	744.32
			TOTAL GST 10%	74.43
			TOTAL AUD	818.75

Due Date: 12 Aug 2026

Please note: Effective 13th July 2026, please pay into our new banking details below

Banking Details - National Australia Bank
BSB: 082-001 A/C: 197315873


When paying your invoice, please use invoice number as reference.
Please send remittance to: brandon.gee@dglgroup.com
Thank You.

Credit Card option now available. Credit Card payment will incur a 4% transaction fee.



[View and pay online now](#)

DGL



Acacia
Ridge
Container
Park

44716

51 McCotter Street, Acacia Ridge Qld 4110 P.O. Box 469, Archerfield Qld 4108 Ph: 07 3711 7200 Fax: 07 3711 7300 Email: arcpark@dglgroup.com

Client:					Date: 09/07/26					Office Use	
REGO # <i>X830UU</i>					Con Note # <i>PO# 2150</i>						
Compartment #	<i>1</i>	<i>2</i>	<i>3</i>	<i>4</i>	<i>5</i>						
Last Product			<i>black oil</i>								
Cold Wash	☒	☒	☒	☒	☒						
Hot / Det. Wash	☒	☒	☒	☒	☒						
Steam / Hot Det. Wash											
Steam Hours						<i>#10242M</i>					
External Wash											
Hot Air Dry											

Manifolds/Hoses/Pump

☐

Manifolds

☐

Hoses

☐

Pump

Draining	<i>80 Ltrs</i>		
Materials	<i>30 litres degreaser</i>		
Cleanliness Certificate	☐ Inhouse	☐ Independent	
Leak Check & Safety Survey	☐ 1 Bar	☐ Repairs quoted on E.I.R	
Manlid Seal	☐ P.T.F.E	☐ S.W.R	
Transport			
Handling	<i>30 min Labour.</i>		
Special Comments	<i>manual packaging</i>		

Date: *09/07/26* Tank has been inspected and found to be visually clean and odour-free.

Operator

Drivers Signature