


TAX INVOICE



Invoice Date
27 Jul 2026

Invoice Number
INV-20106660

Reference
2190/2191

ABN
55 108 103 395

Acacia Ridge Container Park
Pty Ltd
51 Mccotter St
Acacia Ridge QLD 4110
Australia
P: +61 7 3711 7200
E: arcpark@dglgroup.com
W: www.arcpark.com.au
W: www.dglgroup.com

Description	Quantity	Unit Price	GST	Amount AUD
Washout YQ31ZM/YQ35ZM Product - Black Oil Rego# XQ30UU Docket# 44796	1.00	554.63	10%	554.63
Water Surcharge 10%	1.00	55.46	10%	55.46
Environmental Levy 7%	1.00	38.82	10%	38.82
Drainage and disposal of 140L	140.00	2.25	10%	315.00
20L Degreaser	20.00	3.20	10%	64.00
1.5hr labour to manually hose and gurni sludge out of compartments	1.50	120.00	10%	180.00
Subtotal				1,207.91
TOTAL GST 10%				120.79
TOTAL AUD				1,328.70

Due Date: 26 Aug 2026

Please note: Effective 13th July 2026, please pay into our new banking details below

Banking Details - National Australia Bank
BSB: 082-001 A/C: 197315873


When paying your invoice, please use invoice number as reference.
Please send remittance to: brandon.gee@dglgroup.com
Thank You.

Credit Card option now available. Credit Card payment will incur a 4% transaction fee.



[View and pay online now](#)

DGL



Acacia
Ridge
Container
Park

44796

51 McCotter Street, Acacia Ridge Qld 4110 PO Box 469, Archerfield Qld 4108 Ph: 07 3711 7200 Fax: 07 3711 7300 Email: arcpark@dglgroup.com

Client:	Date: 24 th JUL 26							Office Use
REGO #	XQ30VV							Con Note # 2196/2191
Compartment #	1	2	3	4	5	6	7	8
Last Product	BLACK OIL							
Cold Wash	✓	✓	✓	✓	✓	✓	✓	✓
Hot / Det. Wash	✓	✓	✓	✓	✓	✓	✓	✓
Steam / Hot Det. Wash								
Steam Hours								
External Wash								# XQ312M
Hot Air Dry								# XQ352M

Manifolds/Hoses/Pump

☐

Manifolds

☐

Hoses

☐

Pump

Draining	40 LHS	
Materials	100 LHS Sludge	
	20 LHS Debris	
Cleanliness Certificate	☐ Inhouse	☐ Independent
Leak Check & Safety Survey	☐ 1 Bar	☐ Repairs quoted on E.I.R
Manlid Seal	☐ P.T.F.E	☐ S.W.R
Transport	30 min Labour Gurney +	
Handling	DECREASE OUTLETS + LIDS!	
Special Comments	1 hr Labour MANUA / HOSE compartments	

Date: 24/7/26 Tank has been inspected and found to be visually clean and odour-free.

Operator

SCOTT M. SCOTT

Drivers Signature

[Signature]