

03919550

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

10/1/14

Vehicle Standards and Ins. Div. 4800 Regent Road St. J. Winnipeg, MB R4T 3L7

Manitoba

Date Inspection Started: 18 02 25
 Date Inspection Completed: 21 02 25
 Inspection Expiry Date: 28 02 26

Station Number: A117276 Trappers Transport Ltd A900995
 Mechanic Number: 22729
 Station Name: Trappers Transport Ltd
 City: [blank] Prov: [blank] Postal Code: [blank] Phone: [blank]
 Vehicle Name: Paccar Financial Services Ltd.
 Address: [blank] City: [blank] Province: [blank] Postal Code: [blank] Phone: [blank]

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

License Number: PEG226
 Prev: MB
 NSO: MB90015
 Odometer Reading: 949280
 Odom Type: [blank]

Vehicle Identification Number: 1XPBDDPP1X24LD676M419
 Make: Paccar Model: 579 Year: 20 Unit: 1030

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck KQB Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark 'X' under 'R' when item Rejected 'XX' under 'R' when item Hazardous 'X' under 'I' when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 - Suspension: Defects (if any) *F-7C Rear Torque Rod worn out F-7C Rear Shocks Leaking*

Section 3 - Brake Systems: *3M* Defects (if any) Brake Brake Test

Axle	Lining		Drum/rotor		Stroke	
	L	R	L	R	L	R
1	5/16	9/16	41.78	42.08		
2	9/16	9/16	41.78	41.80		
3	9/16	9/16	41.52	41.66		
4						
5						

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any) *F-2H Left Hood Marker Light inop*

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any) *F-13C Windshield Cracked*

Section 9 - Tire & Wheel: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	9	13			100	100		
2	19	22	22	22	95	95	95	95
3	21	18	19	19	95	95	95	95
4								
5								

Section 10 - Coupling Devices: Defects (if any) *F-7D Rebuild 5th wheel*

THIS INSPECTION IS NOT A WARRANTY. This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature _____ Date: _____

FV50022-01-(R 08/15)

PRESENT THIS COPY WHEN REGISTERING VEHICLE

Ce document peut être obtenu en français sur demande.