



# Commercial Vehicle Inspection Report

Decal Number: GH13292  
Decal Expiry Date: 2025-Jul-31  
Inspection Number: 21203116

Inspection Result:

**PASS**

FACILITY: BRIGHT QUALITY ENTERPRISES LTD / S15780  
INSPECTOR: JAGPAL, CHANDEEP SINGH / 202483  
WORK ORDER #:

INSP. TYPE: Complete  
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
INSP. REASON: Semi-annual

INSP. START: 2025-Jan-11 12:30 PM PST  
INSP. COMPLETE: 2025-Jan-11 03:00 PM PST

VEHICLE JUR: British Columbia  
PLATE #: SR2497  
LICENCED GVW(kg): 46500  
VEHICLE YEAR: 2001  
MAKE: VOLVO  
MODEL:

REGI: 00567207  
UNIT/FLEET#: 06  
BODY STYLE: Truck Tractor  
ODOMETER: 648900 KM  
HUB ODOMETER:  
BRAKE TYPE: Air  
FUEL TYPE: Diesel

VIN: 4V4NC9GH11N316089  
OWNER/LESSEE NAME: west coast cartage co ltd, .  
ADDRESS: 7489 hume ave  
Delta, British Columbia  
v4g1c3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	20	Automatic	30	30
2	Clamp	30	Automatic	34	32
3	Clamp	30	Automatic	32	32

Comment:

## Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
14			14	✓
19	19	19	19	
19	19	19	19	

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	60
2	38	40
3	34	38

Comment:

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	19	19
Lining (Shoe)	19	19


Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

## Inspection Comments:

Has this Vehicle been road tested? No  
Inspector: JAGPAL, CHANDEEP SINGH  
Road Test Date:  
Signature:   
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jan-12 06:21 PM PST  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

1/12/2025 6:21:12 PM PST