

03963406

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

204-1
LEADVehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-965-0920

Manitoba



A956881

Date Inspection Started DAY: 14 MO: 08 YR: 25	Station Number A6213	Station Name Blair Burdick	City St Adolphe
Date Inspection Completed DAY: 19 MO: 08 YR: 25	Mechanic Number M3971	Mechanic Signature Blair Burdick	Station Phone Number
Inspection Expiry Date DAY: 31 MO: 08 YR: 26	Vehicle Owner By's Transport	Address Box 369	City St Adolphe
	Province MB	Postal Code R5A-1A2	Phone

<input checked="" type="checkbox"/> Pass/Safe Vehicle	Licence Number TA3456	Prov. MB	NSC #	Odometer Reading	Odom. Type km
<input checked="" type="checkbox"/> Fail/Unsafe Vehicle	Vehicle Identification Number 24DHG2B39FA017978	Make Late King	Model Hopper	Year 2004	Unit # B56
<input type="checkbox"/> Fail/Hazardous	<input checked="" type="checkbox"/> Confirmed legible Vehicle Identification Number on vehicle				

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☒ GWR 38000 KGS Truck Tractor Trailer ☒ Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type (15E) Brake Drum Diameter - Worn (15E) Brake Shoe Lining Thickness - Worn (20E) ABS Sensor - Damaged (20E) ABS Wiring - Corrosion
		Section 4 - Steering: Defects (if any)
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) (1i) RF Clearance Lamp - Missing (1j) Identification Lamp - Not Working
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) (5c) R/L Side Frame Rail - Rusted Thru
X		Section 9 - Tire & Wheel: Defects (if any)
		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure				
	Initial		Corrected		Initial		Corrected		
	L	R	L	R	L	R	L	R	
1	8	5	5	6	98	96	107	98	100
2	6	12	7	7	96	94	96	96	100
3	8	5	7	9	98	102	94	98	100
4									
5									

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature

Date: