Alberta Government

CV8587475

80087600008587475

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	**Seating Capacity:**			
GVW:	kg	**Brake Type:**	Air		
Owner Name:	Pineridge Logging Inc				
Address:	3720B 33 street				
City:	Whitecourt	**Province:**	AB	**Postal Code:**	T7S0A2
Telephone Number:	(780) 778-3114				
Vehicle Identification Number:	2K9LB3561GL072020				
Make:	**Gerry's**	**Model:**	**Tridem**		
Year:	**2016**	**Unit Number:**	**LS-02**		
Odometer:	KM	**Licence Plate Number:**	6VH531	**Province:**	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	**Facility Number:**
Woodland County Ventures Ltd.	**16399**
Inspection Technician Name:	**Technician Number:**
David Wall	**C6637**

Inspection Technician Signature:	
Inspection Date:	**2026/07/17**

Version No:1

Alberta Government

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle	Gross Vehicle Weight registered
Trailer	kg

Vehicle Information

VIN	2	K	9	L	B	3	5	6	1	G	L	0	7	2	0	2	0

Unit Number	Year	Make	Model	Odometer
LS-02	2016	Gerry's	Tridem	

Registered Owner's Name	Plate Number
Pineridge Logging Inc	6VH531

Address	Postal Code	Phone Number
3720B 33 street	T7S0A2	(780) 778-3114

Drum Brakes: A-Full Inspection with Drum Removed Disc Brakes:

	LEFT		FRONT	RIGHT		
100 psi / 16 mm	100 psi / 16 mm	419.0	mm Drums/Rotors	419.0	mm	100 psi / 16 mm; 100 psi / 16 mm
		21	mm Linings/Pads	21	mm	
		38	mm Push Rod Travel	38	mm	
100 psi / 16 mm	100 psi / 16 mm	419.0	mm Drums/Rotors	419.0	mm	100 psi / 16 mm; 100 psi / 16 mm
		21	mm Linings/Pads	21	mm	
		38	mm Push Rod Travel	38	mm	
100 psi / 16 mm	100 psi / 16 mm	419.0	mm Drums/Rotors	419.0	mm	100 psi / 16 mm; 100 psi / 16 mm
		21	mm Linings/Pads	21	mm	
		38	mm Push Rod Travel	38	mm	
___ psi / ___ mm	___ psi / ___ mm		mm Drums/Rotors		mm	___ psi / ___ mm; ___ psi / ___ mm
			mm Linings/Pads		mm	
			mm Push Rod Travel		mm	
___ psi / ___ mm	___ psi / ___ mm		mm Drums/Rotors		mm	___ psi / ___ mm; ___ psi / ___ mm
			mm Linings/Pads		mm	
			mm Push Rod Travel		mm	
___ psi / ___ mm	___ psi / ___ mm		mm Drums/Rotors		mm	___ psi / ___ mm; ___ psi / ___ mm
			mm Linings/Pads		mm	
			mm Push Rod Travel		mm	

Park Brake Lining Left N/A mm Right N/A mm Trans N/A mm

Wheel Torque Checked ☑ Inner N/A ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train							
Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"							
Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension							
Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment			✓				

NOTES:
axle one shock absorbers both leaking, installed two new shock absorbers,

Section 3H - Hydraulic Brakes							
Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes							
Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓		
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓		
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance	✓		
3A.15. Drum Brake System Components	✓						

NOTES:
ABS sensor wire broken, replaced ABS wire,
most of the brake shoes are worn down beyond manufacturer specification and drums borne out, installed all new brake shoes and drums at owners request.
Axel 3 the right side brake chamber spring broken, installed new brake chamber.

Section 4 - Steering							
Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements			✓	8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle			✓	8.25. Rear Impact Guard (RIG)	✓		

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts,& Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:
4 tires skidded, installed all new tires at Owner's request.
8 tires uneven worn and stone drilled, install all new tires at owners request.

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 10 - Couplers and Hitches							
Component	P	F	NA	Component	P	F	NA
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #8587475)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/07/17	C6637	16399	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)
2026/07/17

Customer Signature