204-6

P.R.L
PINERIDGE LOGGING INC.

WORK ORDER #

SOLD TO (COMPANY NAME):	DATE: 21 oct 2026
	UNIT #: ST 94
	SERIAL #:
PHONE #:	YEAR/MAKE:
ADDRESS:	ODOMETER: 187887
WORK REQUESTED BY:	WORK COMPLETED BY: Aaron Friesen

WORK PERFORMED: ☐ OIL CHANGE/LUBRICATION/SERVICE ☐ REPAIR

COMMENTS: Service Job Replace Alternator Replace Fan Belt Vmac Belts Fix Colant leak Fix Deck Doors

PARTS /SUPPLIES USED (ATTACH COPIES OF ANY INVOICES)

INVOICE #	DESCRIPTION AND/OR PART #	QUANTITY	UNIT PRICE	AMOUNT
Shop	Oil Filter 7151	X 1		
	Air Filter 9902	X 1		
	Fuel Filter 600737	X 1		
901784944	NAPA		617.43	
901 785151			272.35	

LABOUR

DESCRIPTION	HOURS	RATE	AMOUNT
	8		

TOTAL PARTS	
TOTAL LABOUR	
GST	
GRAND TOTAL	

3720B-33 STREET WHITECOURT ALBERTA, T7S 0A2
PHONE: (780) 778-3114 FAX: (780) 778-3024

K&C Graphics (2008) Inc.

PRL
PINERIDGE LOGGING INC.

WORK ORDER # [ ]

SOLD TO (COMPANY NAME):	DATE: 08 Jan 2026
	UNIT #: ST 24
	SERIAL #:
PHONE #:	YEAR/MAKE:
ADDRESS:	ODOMETER: 187468
WORK REQUESTED BY:	WORK COMPLETED BY: Aaron Friesen

WORK PERFORMED: ☐ OIL CHANGE/LUBRICATION/SERVICE ☐ REPAIR

COMMENTS:

Replace Baterys

PARTS /SUPPLIES USED (ATTACH COPIES OF ANY INVOICES)

INVOICE #	DESCRIPTION AND/OR PART #	QUANTITY	UNIT PRICE	AMOUNT
901-760825	NAPA			

LABOUR

DESCRIPTION	HOURS	RATE	AMOUNT
	1		

TOTAL PARTS	
TOTAL LABOUR	
GST	
GRAND TOTAL	

3720B-33 STREET WHITECOURT ALBERTA, T7S 0A2
PHONE: (780) 778-3114 FAX: (780) 778-3024

K&C Graphics (2008) Inc

PINERIDGE PRL LOGGING

VEHICLE INSPECTION CHECKLIST

INSPECTOR: Johan A Friesen DATE: Oct 2016

UNIT #: ST 24 KM'S: 48,500

ITEM	O.K	REPLACE	REPAIR	COMMENTS
BRAKES				
- FRONT % 100				Took All 4 Wheels
- REAR % 100				
STEERING COMPONENTS				
TIRES				
- FRONT % 80				
- REAR % 75				
FLUID LEVELS				
- TRANSMISSION Good				
-ENGINE Good				
-TRANSFER CASE Good				
-DIFFERENTIAL Good				
ENGINE Good				
-BELTS Good				
-IDLERS Good				
DRIVE SHAFT Good				
U-JOINTS Good				
SERVICE JOB:				
-AIR FILTERS	Replace			
-OIL FILTERS	Replace			
-FUEL FILTERS	Replace			
HOSE & CLAMPS	Replace			
ELECTRICAL COMPONENTS				
-BATTERY Good				
-LIGHTS				
-WIRING Good				
GLASS Good				
SEAT BELTS				
UNIT #/ LOGOS				
RV PLUGS No				
FENDER LINERS Good				
CODES				
-WHAT WAS FIXED				
EXHAUST Good				
-MANIFOLDS Good				
-BROKEN BOLTS No				
-BRACKETS FOR MUFFLER				

Vehicle Inspection Checklist

Inspector: John R Friesen Date: Jun 2015

Unit #: ST24 Km's: _____

ITEM+E38A6:EA6:E113	O.K	REPLACE	REPAIR	COMMENTS
Brakes:				
-Front	✓			Took All Wheels
-Rear		✓		
Steering Components:				
Tires:				
-Front	✓			
-Rear	✓			
Fluid Levels:		Add Lit		
-Transmission	✓			
-Engine	✓			
-Transfer Case	✓			
-Differential	✓			
Engine Belts:	✓			
Drive Shaft:	✓			
U-Joints:	✓			
Service Job:		✓		
-Air Filters		✓		
-Oil Filters		✓		
-Fuel Filters		✓		
Hoses and Clamps:				
Electrical Components:				
-Battery	✓			
-Lights	✓			
-Wiring				
Glass:	✓			
Seat Belts:				
Unit #/Logos				
			Total Hours:	

Comments: _____

_____

Inspector Signature: _____

Management Review Signature: Ruby Lynch

Management Review Date: 6/30/15

CARFAX Vehicle History Report™

CAD $39.99

Vehicle Information:
2011 FORD F550 SUPER DUTY
VIN: 1FDUF5HT8BEC69800
CHASSIS AND CAB
4 WHEEL DRIVE
Standard Equipment | Safety Options

CARFAX Report Provided By:
Ritchie Bros. Aunctioneers Canada Ltd
1500 Sparrow Dr
Nisku, AB T9E8H6
780-955-2486

- No accident / damage reported to CARFAX
- CARFAX 1-Owner vehicle
- Lease vehicle
- Last owned in Alberta
- **6** Detailed records available



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/23/14 at 4:21:52 PM (EDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History

The number of owners is estimated

	Owner 1
Year purchased	2011
Type of owner	Lease
Estimated length of ownership	3 years 4 months
Owned in the following provinces	Alberta
Estimated kilometers driven per year	—
Last reported odometer reading (KM)	—

CARFAX 1 OWNER

CARFAX Registration History

CARFAX guarantees the information in this section

	Owner 1
Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon | Reconstructed | Dismantled	**Guaranteed** No Problem
Not Actual Mileage | Exceeds Mechanical Limits	**Guaranteed** No Problem

BUYBACK CARFAX GUARANTEE

GUARANTEED - None of these major registration problems were reported by a Provincial Ministry. If you find that any of these registration problems were reported by a Provincial Ministry and not included in this report, CARFAX will buy this vehicle back. **Register | View Terms**

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss No total loss reported to CARFAX.	☑ No Issues Reported
Structural Damage No structural damage reported to CARFAX.	☑ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	☑ No Issues Reported
Odometer Check No indication of an odometer rollback.	☑ No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	☑ No Issues Reported
Manufacturer Recall A current list of recalls is available at Ford Motor Company.	☑ No Recalls Reported

CARFAX Detailed History

Glossary

Owner 1

Purchased:	2011
Type:	Lease
Where:	Alberta
Est. length owned:	6/15/11 - present (3 years 4 months)

Date:	Kilometers:	Source:	Comments:
04/28/2011		NICB	Vehicle manufactured and shipped to original dealer
06/15/2011		Alberta Motor Vehicle Dept. Edmonton, AB	Registration issued or renewed First owner reported Registered as lease vehicle Vehicle color noted as White
12/28/2011		Alberta Motor Vehicle Dept. Edmonton, AB	Registration issued or renewed Registered as lease vehicle Vehicle color noted as White
12/04/2012		Alberta Motor Vehicle Dept. Edmonton, AB	Registration issued or renewed Registered as lease vehicle Vehicle color noted as White
07/15/2013		Alberta Motor Vehicle Dept. Edmonton, AB	Registration issued or renewed Registered as lease vehicle Vehicle color noted as White
11/27/2013		Alberta Motor Vehicle Dept. Edmonton, AB	Registration issued or renewed Registered as lease vehicle Vehicle color noted as White

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.ca.

CARFAX Glossary

View Full Glossary

First Owner
When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership or registers a car with a Canadian province.

Ford or Lincoln Mercury Recall
The Ford Motor Company provides CARFAX with recall information regarding safety, compliance and emissions programs announced since 2000 for a specific vehicle. For complete information regarding programs or concerns about this vehicle, please contact a local Ford or Lincoln Mercury Dealer.

Lease
When someone leases a car from a dealer, the dealer actually sells the vehicle to a leasing company. The leasing company then

collects payments for the vehicle from the new owner for 24, 36, 48 or more months. A leasing company can be an independent car dealer or a car manufacturer.

Ownership History
CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title or registration transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Follow Us: facebook.com/CARFAX @CarfaxReports CARFAX on Google+

CARFAX DEPENDS ON THE ACCURACY AND COMPLETENESS OF INFORMATION FROM MULTIPLE THIRD-PARTY SOURCES TO COMPILE THIS REPORT. RELIANCE ON THIS REPORT IS AT YOUR OWN RISK. IN SOME PROVINCES, SUCH AS QUEBEC, YOU MAY HAVE STATUTORY RIGHTS UNDER CONSUMER PROTECTION LEGISLATION. ALSO, CERTAIN PROVINCES MAY PROHIBIT OR RESTRICT THE FOLLOWING DISCLAIMERS OF WARRANTIES AND LIABILITIES. TO THE FULLEST EXTENT PERMITTED BY APPLICABLE LAW, CARFAX DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. IN NO EVENT SHALL CARFAX BE LIABLE FOR ERRORS OR OMISSIONS OF ITS THIRD-PARTY SOURCES. TO THE FULLEST EXTENT PERMITTED BY APPLICABLE LAW, CARFAX SHALL NOT BE RESPONSIBLE FOR ANY DIRECT, INDIRECT, CONSEQUENTIAL, SPECIAL OR EXEMPLARY DAMAGES. NOTWITHSTANDING THE FOREGOING, IF CARFAX IS FOUND TO BE LIABLE FOR ANY DAMAGES, THE TOTAL OF SUCH DAMAGES SHALL NOT EXCEED THE COST OF THIS REPORT.
© 2014 CARFAX, Inc. All rights reserved.
10/23/14 4:21:52 PM (EDT)

J60-36

ALBERTA MOTOR VEHICLE INDUSTRY COUNCIL

MECHANICAL FITNESS ASSESSMENT

As required by Vehicle Inspection Regulation (A/R 211/2006)

Dealer: _____ AMVIC License Number: _____

Address: _____

VEHICLE INFORMATION

Year: 2011 Make: Ford Model: F-550 Previous Province of Registration: _____

Vehicle Identification Number: 1FDUFSHT8BEC69800 Odometer Reading: 26733 [X] (km / mi) [ ]

[✓] Truck [ ] Motorcycle [ ] Bus [ ] Van [ ] Light Truck [ ] Auto [ ] Motorized RV [ ] Other

Please check mark (✓) each item as C = Complies N = Non-Compliant N/A=Not Applicable

Powertrain	C	N
Accelerator	✓	
Fuel System	✓	
Exhaust	✓	
Transmission	✓	
Front/Rear/Spindles Axles	✓	
Clutch	N/A	
Fluid Levels (power steering, brake)	✓	
CV Joints	✓	

Lamps	C	N
Head Lamp Hi Beam	✓	
Head Lamp Lo Beam	✓	
Head Lamp Location	✓	
Daytime Running Lamps	✓	
Tail Lamps	✓	
Brake Lamps	✓	
Turn Signal Lamps	✓	
Hazard Warning Lamps	✓	
Licence Plate Lamp	✓	
Back-up Lamps	✓	

Instruments	C	N
Speedometer/Odometer	✓	
Indicator Lamps	✓	
Horn	✓	
Hi Beam Indicator	✓	

Brakes	C	N
Parking/Emergency Brake	✓	
Hydraulic System	✓	
Vacuum System	N/A	
Drum Brakes	N/A	
Disc Brakes	✓	
Shoes/Pads	✓	
Anti-Lock (if OEM equipped)	✓	

Steering	C	N
Steering Lash	✓	
Steering Linkage	✓	
Rack & Pinion	N/A	
Power Steering System	✓	
King Pin	N/A	
Ball Joints	✓	

Suspension	C	N
Leaf springs	✓	
Struts and Shocks	✓	
Coil spring	✓	
Torsion Bar	✓	
Independent/Multilink Rear	N/A	
Computer Controlled	N/A	

Diagnostic	C	N
Diagnostic Trouble Codes	✓	

Frame & Body	C	N
Hood Latch	✓	
Door Latches & Hinges	✓	
Bumpers	✓	
Windshield Wipers & Washer	✓	
Rear Wiper & Washer	N/A	
Windshield	✓	
Windows	✓	
Defrost/Heaters	✓	
Mirrors	✓	
Seats	✓	
Seat Belts/Airbags	✓	
Mudguards	✓	
Window Glazing	N/A	
Structural Integrity	✓	

Tires & Wheels	C	N
Tread Depth	✓	
Tread Section	✓	
Sidewalls	✓	
Wheels	✓	

Electrical	C	N
Wiring	✓	
Battery	✓	
Switches	✓	
Alternator	✓	

Technician Comments

This is to certify that I have assessed the vehicle described above in accordance with the *Traffic Safety Act*, Vehicle Equipment Regulation (A/R 122/2009). By signing this assessment, I verify the contents of this document are true and correct.

Signature of Certified Journeyman Technician: —

Technician Name (Print): _____

Technician Trade Certificate Number: —

Date: _____

I, the buyer of this vehicle, acknowledge receipt of this assessment.

Signature of Buyer

Buyer (Print)

Signature of Salesperson

Salesperson (Print)

Date

N/A Auction.

RECORD OF INSPECTION

TRANSPORTATION

(ase Print)

istered Owner's Name _____

ne _____ Fax _____

icle Make Ford Vehicle Model F-550 Year 2011

meter 26733 Unit # _____ License Plate No. _____ GVWR or Bus Cap 19500lb

icle Identification number 1FDUF5HT8BEC69800

RECORD MEASUREMENTS

	LEFT	FRONT	RIGHT
	1.530"	DRUMS/ROTORS	1.530"
m.m. 12	.340"	LININGS/PADS	.335" 12 m.m.
PSI		PUSH ROD TRAVEL	PSI
		CAM ROTATION	
	1.536"	DRUMS/ROTORS	1.536"
m.m. 10 14	.456"	LININGS/PADS	.450" 10 10 m.m.
PSI		PUSH ROD TRAVEL	PSI
		CAM ROTATION	
		DRUMS/ROTORS	
m.m.		LININGS/PADS	m.m.
PSI		PUSH ROD TRAVEL	PSI
		CAM ROTATION	
		DRUMS/ROTORS	
m.m.		LININGS/PADS	m.m.
PSI		PUSH ROD TRAVEL	PSI
		CAM ROTATION	

WHEELS TORQUE CHECKED ☑ 150ft-lb { Identify by location if Wheels Removed at time of Inspection }

echanic's Comments

11A pacific service body, Steering tight, E-brake works, Vmac underhood compressor

YY MM DY

_____ | 2014 | 09 | | 11.00 | CV5178673 | ☐ Yes ☑ No

Inspection Station Number | Inspection Date | Time AM/PM | CVIP Certificate (if) Issued

_____ _____ _____

Name of Inspection Mechanic (Print) | Signature of Inspection Mechanic | Mechanic Number

ehicle received without Repairs

o Rejected Items YES _____ _____ _____

Signature of Vehicle Owner or Representative | Title

VEHICLE INSPECTION CHECKLIST

INSPECTOR: Johan R Friesen DATE: May 2017

UNIT #: ST 24 KM'S: 54,870

ITEM	O.K	REPLACE	REPAIR	COMMENTS
BRAKES				Replace Back Left Caliper
- FRONT % 100				
- REAR % 100				
STEERING COMPONENTS				Serves Transmission Fluid
TIRES				
- FRONT % 40				Torque All 4 Wheels at 150
- REAR % 75				
FLUID LEVELS				
- TRANSMISSION				
-ENGINE Good				VM2C Serves 5.6
-TRANSFER CASE Good				
-DIFFERENTIAL Good				Delete DEF
ENGINE				
-BELTS Good				
-IDLERS OK				
DRIVE SHAFT Good				
U-JOINTS Good				
SERVICE JOB:	Replace			
-AIR FILTERS	Replace			
-OIL FILTERS	Replace			
-FUEL FILTERS	Replace			
HOSE & CLAMPS				
ELECTRICAL COMPONENTS				
-BATTERY Good				
-LIGHTS Good				
-WIRING				
GLASS Good				
SEAT BELTS				
UNIT #/ LOGOS				
RV PLUGS No				
FENDER LINERS Good				
CODES				
-WHAT WAS FIXED				
EXHAUST Good				
-MANIFOLDS Good				
-BROKEN BOLTS No				
-BRACKETS FOR MUFFLER				

VEHICLE INSPECTION CHECKLIST

INSPECTOR: Johan Rfrig DATE: May 2018

UNIT #: 5724 KM'S: 80,643

ITEM	O.K	REPLACE	REPAIR	COMMENTS
BRAKES				Tork 2T 150. All 4 Wheels.
- FRONT % 100				
- REAR % 100				
STEERING COMPONENTS				
TIRES				Replace front Drive Shaft on Aug 2018.
- FRONT % 90				
- REAR % 95				
FLUID LEVELS				
- TRANSMISSION Good				
-ENGINE Good				
-TRANSFER CASE Good				
-DIFFERENTIAL Good				
ENGINE				
-BELTS Good				
-IDLERS OK				
DRIVE SHAFT Good				
U-JOINTS Good				
SERVICE JOB:		Replace		
-AIR FILTERS		Replace		
-OIL FILTERS		Replace		
-FUEL FILTERS		Replace		
HOSE & CLAMPS				
ELECTRICAL COMPONENTS				
-BATTERY Good				
-LIGHTS Good				
-WIRING				
GLASS Needs		New		Glass
SEAT BELTS				
UNIT #/ LOGOS				
RV PLUGS No				
FENDER LINERS Good				
CODES				
-WHAT WAS FIXED				
EXHAUST Good				
-MANIFOLDS Good				
-BROKEN BOLTS				
-BRACKETS FOR MUFFLER				