



# Commercial Vehicle Inspection Report

Decal Number: GL32728  
Decal Expiry Date: 2027-Jan-31  
Inspection Number: 21641536

Inspection Result:  
**PASS**

**FACILITY:** STARLIGHT TRUCK REPAIR / S12430      **INSP. TYPE:** Complete      **INSP. START:** 2026-Jan-14 06:00 AM -07  
**INSPECTOR:** Walter, Reuben Jason / 200998      **INSP. CLASS:** Class 1 - Light Vehicle with LGVV 5500 kg or less      **INSP. COMPLETE:** 2026-Jan-14 08:00 AM -07  
**WORK ORDER #:**      **INSP. REASON:** Annual

**VEHICLE JUR:** Alberta      **REGI:**      **VIN:** k14mmesl6pb056933  
**PLATE #:**      **UNIT/FLEET#:** N/A      **OWNER/LESSEE NAME:** [REDACTED]  
**LICENCED GVW(kg):** 0      **BODY STYLE:** 4-Door Vehicle      **ADDRESS:** [REDACTED]  
**VEHICLE YEAR:** 2023      **ODOMETER:** 23746 KM  
**MAKE:** Buick      **HUB ODOMETER:**      **BRAKE TYPE:** Hydraulic  
**MODEL:** Encore      **FUEL TYPE:** Gasoline

<b>Vehicle Identification (VIN)</b>	Passed
<b>Section 1 - Power Train</b>	Passed
<b>Section 2 - Suspension</b>	Passed
<b>Section 3 - Brake System</b>	Passed
<b>Section 3H - Hydraulic Brakes</b>	Passed
<b>Section 4 - Steering</b>	Passed
<b>Section 5 - Instruments and Auxiliary Equipment</b>	Passed
<b>Section 6 - Lamps</b>	Passed
<b>Section 7 - Electrical System</b>	Passed
<b>Section 8 - Frame and Body</b>	Passed
<b>Section 9A - Tires</b>	Repaired (same day) Winter tires
<b>Section 9B - Wheels</b>	Passed
<b>Section 10 - Coupling Devices</b>	Passed
<b>Section 11 - Other Vehicle Components</b>	Not Applicable

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	11			11	✓	Pad	12	12	Drum	24.00	24.00
2	11			11		Pad	12	12	Drum	15.00	15.00
<b>Comment:</b>						<b>Comment:</b>			<b>Comment:</b>		

**Inspection Comments:**  
**Has this Vehicle been road tested?** Yes      **Road Test Date:** Before Inspection      **Road Tester:** Reuben  
**Inspector:** Walter, Reuben Jason      **Signature:** 

This Inspection Report was submitted to CVSE on 2026-Jan-24 06:44 PM -07  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.