



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71238

Station Name: Magnum Industries Ltd

Technician #: 86639

Technician Name: Justin Lacelle

Signing Officer #: 88591

Signing Officer Name: Stefanie Reardon

Customer Details:

Name: Bucks Construction

Address: Box 45, Shaunavon, Saskatchewan, S0N 2M0

Vehicle Details:

VIN: 2PLH01812LBK54530

Hubometer Reading:

Year: 1990

Vehicle Make/Model: TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
		x		Retro Reflective Markings (6)	Needs reflective tape on the rear
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
		x		Trailer Power Cord (7)	Trailer cord and hoses in bad shape.

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 24/32 in • Brake Drum/Rotor: 16.5 in • Brake Stroke: 1 in

Wheel3-Off : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 22/32 in • Brake Drum/Rotor: 16.55 in • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A305011

Inspection Completed Date: 28Mar2025

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.