

## Work Order Service History

Asset Code :	R78	XB99FE 2011 Hino Rigid Truck				Operation No :		
Registration :	XB99FE	HIN						
<b>Work Order</b>	<b>00020075</b>	Work Order Date :		06/09/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
Service Code:	GEN	General Repair			Meter Reading :	474,616		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	
CHECK OVER & FIT NUMBER PLATES								
								<b>Total for Service</b> 0.00
								<b>Total for Work Order</b> 0.00
<b>Work Order</b>	<b>00020076</b>	Work Order Date :		09/09/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
Service Code:	GEN	General Repair			Meter Reading :	474,863		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	
GATE MISSING FOOT - REPLACED 1 x GATE FOOT								
LUBED CURTAINS & RATCHETS								
FITTED NEW HANGERS TO 4 x GATES								
								<b>Total for Service</b> 0.00
								<b>Total for Work Order</b> 0.00
<b>Work Order</b>	<b>00020196</b>	Work Order Date :		11/09/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
Service Code:	GEN	General Repair			Meter Reading :	475,020		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	
BVR - JUMP STARTED TRUCK AT KINGSFORD SMITH DRIVE, MAY NEED 2 x BATTERIES								
								<b>Total for Service</b> 0.00
								<b>Total for Work Order</b> 0.00
<b>Work Order</b>	<b>00020136</b>	Work Order Date :		14/09/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
Service Code:	GEN	General Repair			Meter Reading :	475,827		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	
R&R BATTERIES AS REQUIRED								
								<b>Total for Service</b> 0.00
								<b>Total for Work Order</b> 0.00
<b>Work Order</b>	<b>00020766</b>	Work Order Date :		30/09/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
Service Code:	GEN	General Repair			Meter Reading :	0		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	
NEW SIGNAGE								
								<b>Total for Service</b> 0.00
								<b>Total for Work Order</b> 0.00
<b>Work Order</b>	<b>00020862</b>	Work Order Date :		04/10/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair
Service Code:	GEN	General Repair			Meter Reading :	481,016		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	
FITTED GPS AS REQUIRED & LOGGED								
								<b>Total for Service</b> 0.00
								<b>Total for Work Order</b> 0.00
<b>Work Order</b>	<b>00021794</b>	Work Order Date :		31/10/2019	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance
Service Code:	TYRES	Tyres Service - Trailer			Meter Reading :	486,574		
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	

## Work Order Service History

R&amp;R TYRES 8

											Total for Service	0.00				
											Total for Work Order	0.00				
Work Order	00022498		Work Order Date : 20/11/2019			Repair Location :	EX0103	Yatala Workshop	Exodas	General Repair						
Service Code:	GEN	General Repair			Meter Reading :			0				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details						Extension			
NHVAS MAINTENANCE STICKER FITTED 20/11/2019 BY BENJAMIN BODYCOTE.											Total for Service	0.00				
											Total for Work Order	0.00				
Work Order	00022500		Work Order Date : 20/11/2019			Repair Location :	EX0103	Yatala Workshop	Exodas	General Repair						
Service Code:	GEN	General Repair			Meter Reading :			0				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details						Extension			
BLEW OUT RADIATOR											Total for Service	0.00				
											Total for Work Order	0.00				
Work Order	00022850		Work Order Date : 02/12/2019			Repair Location :	EX0103	Yatala Workshop	Exodas	General Repair/Maintenance						
Service Code:	GEN	General Repair			Meter Reading :			493,376				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details						Extension			
HINO LABOUR TO RESET ALL DPR FLAG AND RESET PM DEPOSIT VALUE											Total for Service	0.00				
PERFORM DPR FORCED REGENERATION AND MONITOR DATA											Total for Work Order	0.00				
COULD NOT FAULT																
Work Order	00023192		Work Order Date : 18/12/2019			Repair Location :	EX0103	Yatala Workshop	Exodas	General Repair/Maintenance						
Service Code:	GEN	General Repair			Meter Reading :			495,390				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details						Extension			

## Work Order Service History

COMPLETED BY SCI-FLEET HINO 18.12.19  
INVOICE # RJ045410

HINO LABOUR TO SCAN TEST WITH HINO DX TO FIND FAULT CODE FOR THROTTLE ACTUATOR DC MOTOR.  
PERFORM ACTUATE TEST OF THROTTLE BODY AND NO RESPONSE.  
REMOVE P/S INTERCOOLER HOSE TO CHECK THROTTLE PLEATE AND FOUND TO BE STUCK FULLY OPEN. UN JAM THROTTLE PLATE AND RETEST, STILL NO ACTUATION.  
CHECK WIRING AND CONNECTION TO DC MOTOR PERFORM SOFTWARE UPGRADE OF ECU AND INITLIZE THROTTLE MOTOR, NOW FUNCTION OKAY CLEAR FAULT CODE AND ROAD TEST OKAY.  
RECOMMEND:  
REPLACING THROTTLE ASSEMBLY  
REMOVE AND CLEAN INTAKE MANIFOLD OF EXCESSIVE CARBON  
REMOVE EGR PIPE TO INSPECT EGR COOLER AND VALVE

DX SCAN TOOL FEE

HINO LABOUR TO REMOVE INTAKE PIPE AND INSPEC EGR VALVE AND COOLER.  
INSPEC EGR COOLER FOR CARBON - OKAY  
HOT WASH INLET PIPE AS REQUIRED AS EXCESSIVLY CARBONED.  
STRIP AND CLEAN EGR VALVE AS REQUIRED.  
REMOVE AND REPLACE THROTTLE BODY ASSEMBLY AND GASKETS.  
TEST OKAY

PAID VIA CREDIT CARD.

Work Order	00023731	Work Order Date :	09/01/2020	Repair Location :	EX0103	Yatala Workshop Exodas	Drive Tyre Rotatioin	Total for Service	0.00	
Service Code:	ROTDRI	Drive Tyre Rotatioin			Meter Reading :	499,305		Total for Work Order	0.00	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
DRIVE TYRE ROTATION COMPLETED.										

COMPLETED BY BRIDGESTONE - DAVE 09.01.2020

Work Order	00023790	Work Order Date :	09/01/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance	Total for Service	0.00	
Service Code:	GEN	General Repair			Meter Reading :	0		Total for Work Order	0.00	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
COMPLETED BY BRIDGESTONE 09.01.2020 INVOICE # 97886609										

Work Order	00026622	Work Order Date :	27/04/2020	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance	Total for Service	0.00	
Service Code:	GEN	General Repair			Meter Reading :	0		Total for Work Order	0.00	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Units	Rate	Extension
COMPLETED BY U-RIPPA TAUTLINER REPAIRS 27.04.2020 INVOICE # 00031781										

1 x PATCHING REPAIR TO LEFT CURTAIN DOUBLE LAYER

## Work Order Service History

										Total for Service	0.00	
										Total for Work Order	0.00	
Work Order	00027742		Work Order Date : 03/06/2020			Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	GEN	General Repair				Meter Reading :		0				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details		Units	Rate	Extension
COMPLETED BY CORRECT AUTO ELECTRICAL 03.06.2020												
INVOICE # 00017511												
PROCEED TO SITE CHECK INTERIOR FAN, COMES ON WITH PARK LIGHTS TEST SWITCHES, WILL NEED TO STRIP DASH AND FOLLOW CABLES REMOVED PHONE KIT AND REDUCER STUCK BEHIND RADIO INFORMED MICK - NEED TO CHECK WITH HINO												
										Total for Service	0.00	
										Total for Work Order	0.00	
Work Order	00027534		Work Order Date : 04/06/2020			Repair Location :	EX0103	Yatala Workshop Exodas	Steer Tyre Rotatioin			
Service Code:	STEROT	Steer Tyre Rotation				Meter Reading :		521,327				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details		Units	Rate	Extension
STEER TYRE ROTATION COMPLETED.												
COMPLETED BY BRIDGESTONE - JOHNNY 04.06.2020										Total for Service	0.00	
										Total for Work Order	0.00	
Work Order	00029699		Work Order Date : 30/07/2020			Repair Location :	EX0103	Yatala Workshop Exodas	General Repair/Maintenance			
Service Code:	GEN	General Repair				Meter Reading :		533,462				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details		Units	Rate	Extension
INVOICE RZCSR51985												
INVESTIGATE INDICATOES SOMETIMES FLASHING FAST AND SOMETIMES NOT WORKING AT ALL INVESTIGATE A/C BLOWER MOTOR COMING ON WHEN HEADLIGHTS TURNED ON INSPECTION & TESTING HAS FOULD MULIPLE CONCERNS WITH LIGHTING AND ALSO WIRE AROUND BODY AUTO EXEC REQUIRED TO FURTHER INSPECT REPAIRIES CARRIED OUT TO THE FOLLOWING FOUND SAM MODULE TO BE FULL OF WHAT SEEMS TO BE WD40 HAS BEEN CLEANED BROKEN WIRING TO LH TAIL LAMP ASSEMPLY REPAIRED L/H BRAKE LIGHT WAS COMING ON WITH PARK LIGHTS FOUND PARK LIGHT GROUND WIRE CONNECTED TO BRAKE LIGHT FEKK FOUND CAN BUS SYSTEM FAULT PRESENT DUE INCORRECT LOAD ON BRAKE LIGHT CIRCUIT MODIFIED WIRING TO INCREASE LOAD ALL OK CARRIED OUT MULTIPLE TESTS ON HEADLIGHTS AND BLOWER MOTOR AND HAVE BEEN UNABLE TO FAULT												
										Total for Service	0.00	
										Total for Work Order	0.00	
Work Order	00032655		Work Order Date : 23/11/2020			Repair Location :	EX0103	Yatala Workshop Exodas	General Repair			
Service Code:	GEN	General Repair				Meter Reading :		557,961				
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details		Units	Rate	Extension

## Work Order Service History

REPAIR COMPLETED BY KEIRAN/BEN/MICK

REAR BRAKES WERE STAYING ON, REMOVED HUBS  
RELINED SHOES ON LH AND RH SIDE, CLEANED SCAMS AND SLACK ADJUSTERS  
CLEANED AND INSPECTED BEARINGS, REPACKED WITH BPW GREASE  
REPLACED GREASE SEALS  
REFITTED BRAKES AND HUBS  
STILL HAD TROUBLE RELEASING BRAKES  
HILL START BUTTON WAS ACTIVE

MAINTENANCE WORK ORDER										Total for Service 0.00		
										Total for Work Order 0.00		
Work Order	00035071		Work Order Date : 25/02/2021		Repair Location : EX0103		Yatala Workshop Exodas		Rigid C Service			
Service Code:	DEFECT	Defect Repair			Meter Reading : 0						Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension	
DEFECT CLEARED.										Total for Service 0.00		
Service Code:	EXOINS	Exodas Annual Roadworthy NHVAS			Meter Reading : 0						Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension	
VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION.												
ATTEMPT # 1												
INSPECTION COMPLETED BY SEAN AND KEIRAN										Total for Service 0.00		
Service Code:	RIGIDA	Rigid A Service			Meter Reading : 0						Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension	
SERVICE COMPLETED.										Total for Service 0.00		
Service Code:	RIGIDB	Rigid B Service			Meter Reading : 0						Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension	
SERVICE COMPLETED BY KEIRAN AND BEN												
FITTED FIRE EXTINGUISHER AND DG KIT												
REPLACED WIPER BLADES												
MONITOR OIL AROUND OIL FILTER												
BOTH CORNERS AROUND REAR POLES ARE CRACKING										Total for Service 0.00		
Service Code:	RIGIDC	Rigid C Service			Meter Reading : 0						Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension	
SERVICE COMPLETED BY KEIRAN AND BEN												
TOPPED UP 3L OF COOLANT										Total for Service 0.00		
										Total for Work Order 0.00		
Work Order	00043409		Work Order Date : 03/07/2021		Repair Location : EX0103		Yatala Workshop Exodas		Rigid A Service			
Service Code:	RIGIDA	Rigid A Service			Meter Reading : 0						Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension	

## Work Order Service History

SERVICE COMPLETED BY SEAN

									Total for Service	0.00	
									Total for Work Order	0.00	
Work Order	00043465	Work Order Date : 05/11/2021			Repair Location : EX0103	Yatala Workshop Exodas	General Repair				
Service Code:	GEN	General Repair		Meter Reading : 624,122					Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				
REPAIR COMPLETED.											

												Total for Service	0.00	
												Total for Work Order	0.00	
Work Order	00043999	Work Order Date : 03/12/2021			Repair Location : EX0103	Yatala Workshop Exodas	General Repair							
Service Code:	GEN	General Repair		Meter Reading : 628,701					Units	Rate	Extension			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details							
REPAIR COMPLETED BY KEIRAN														

REMOVED AND REPLACED AC FAN

												Total for Service	0.00	
												Total for Work Order	0.00	
Work Order	00044455	Work Order Date : 23/12/2021			Repair Location : EX0103	Yatala Workshop Exodas	General Repair							
Service Code:	GEN	General Repair		Meter Reading : 631,857					Units	Rate	Extension			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details							
REPAIR COMPLETED BY KEIRAN														

REPLACED CABIN FILTER AND SCREEN

												Total for Service	0.00	
												Total for Work Order	0.00	
Work Order	00044958	Work Order Date : 28/01/2022			Repair Location : EX0103	Yatala Workshop Exodas	Rigid B Service							
Service Code:	RIGIDA	Rigid A Service		Meter Reading : 636,840					Units	Rate	Extension			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details							
SERVICE COMPLETED.														

Service Code:	RIGIDB	Rigid B Service		Meter Reading : 636,840					Units	Rate	Extension			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details							

SERVICE COMPLETED BY KEIRAN, IAN AND BEN

COMPLTED B SERVICE

\*ROCKER COVER GASKET LEAKING

\*SPRING SHACKLES DON'T ACCEPT GREASE

\*GEARBOX LEAK/OUTPUT NUT/SINCRO IN 4TH, CLUTCH SLIPPING

RADIATOR BLOW OUT

TRUCK CURRENTLY GROUNDED

												Total for Service	0.00	
												Total for Work Order	0.00	
Work Order	00046840	Work Order Date : 12/04/2022			Repair Location : EX0103	Yatala Workshop Exodas	Rigid C Service							
Service Code:	GEN	General Repair		Meter Reading : 636,840					Units	Rate	Extension			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details							
REPAIR COMPLETED.														

## Work Order Service History

Service Code:	EXOINS	Exodas Annual Roadworthy NHVAS					Meter Reading :	0	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				

VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION.

ATTEMPT # 1

INSPECTION COMPLETED BY KEIRAN

Service Code:	RIGIDA	Rigid A Service					Meter Reading :	643,998	Total for Service	0.00	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension

SERVICE COMPLETED.

Service Code:	RIGIDC	Rigid C Service					Meter Reading :	643,998	Total for Service	0.00	
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		Units	Rate	Extension

SERVICE COMPLETED BY KEIRAN, IAN AND TYLER

ADJUSTED A/C BELT

COMPLETED FULL CHECK

\*BODY NEEDS TO GO BACK FOR WARRANTY ( DEFECT IN N DRAWER )

Work Order	00047145	Work Order Date : 23/04/2022					Repair Location : EX0103	Yatala Workshop Exodas	General Repair	Total for Service	0.00
Service Code:	GEN	General Repair					Meter Reading :	646,083	Units	Rate	Extension

REPAIR COMPLETED BY KEIRAN

FITTED 24-12V CONVERTER TO CIG PLUG, FITTED UHF

Work Order	00047241	Work Order Date : 28/04/2022					Repair Location : EX0103	Yatala Workshop Exodas	General Repair	Total for Service	0.00
Service Code:	GEN	General Repair					Meter Reading :	646,563	Units	Rate	Extension

REPAIR COMPLETED BY KEIRAN

ADJUSTED CLUTCH

TOPPED UP COOLANT (500ML)

REFER DEFECT 7487 - BROWN & HURLEY COMPLETED BRAKE TEST COULD NOT FAULT BRAKE SYSTEM

Work Order	00047677	Work Order Date : 18/05/2022					Repair Location : EX0103	Yatala Workshop Exodas	A Service Cummins E5	Total for Service	0.00
Service Code:	CUMAE5	A Service Cummins E5					Meter Reading :	650,139	Units	Rate	Extension

SERVICE COMPLETED BY KEIRAN AND BRENDAN

TIGHTENED LEAKING BANDO BOLT ON RH SIDE OF MOTOR AND TOPPED UP COOLANT 2L

LUBED CURTAINS AND TRACKS

Work Order	00047677	Work Order Date : 18/05/2022					Repair Location : EX0103	Yatala Workshop Exodas	A Service Cummins E5	Total for Service	0.00
Service Code:	CUMAE5	A Service Cummins E5					Meter Reading :	650,139	Units	Rate	Extension

## Work Order Service History

											Total for Work Order			0.00
Work Order	00050052		Work Order Date : 22/08/2022			Repair Location : EX0103		Yatala Workshop Exodas		General Repair/Maintenance				
Service Code:	GEN	General Repair				Meter Reading :		0						
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details			Units	Rate	Extension	
REPAIR COMPLETED BY KIM MARTIN TRAILERS INV# 73137														
PLEASE REFER TO ATTACHED INVOICE														Total for Service 0.00
														Total for Work Order 0.00
Work Order	00051548		Work Order Date : 22/10/2022			Repair Location : EX0103		Yatala Workshop Exodas		Rigid B Service				
Service Code:	RIGIDA	Rigid A Service				Meter Reading :		656,105						
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details			Units	Rate	Extension	
SERVICE COMPLETED.														Total for Service 0.00
Service Code:	RIGIDB	Rigid B Service				Meter Reading :		656,105						
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details			Units	Rate	Extension	
SERVICE COMPLETED BY MICK, TYLER AND FLYNN														
REPLACED BATTERIES														Total for Service 0.00
														Total for Work Order 0.00
Work Order	00052122		Work Order Date : 16/11/2022			Repair Location : EX0103		Yatala Workshop Exodas		General Repair				
Service Code:	GEN	General Repair				Meter Reading :		0						
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details			Units	Rate	Extension	
FITTED FUEL CAP														
REPAIR COMPLETED BY KEIRAN														Total for Service 0.00
														Total for Work Order 0.00
Work Order	00052765		Work Order Date : 12/12/2022			Repair Location : EX0103		Yatala Workshop Exodas		General Repair/Maintenance				
Service Code:	TYRES	Tyres Service - Trailer				Meter Reading :		664,407						
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details			Units	Rate	Extension	
CARRIED OUT BY BRIDGESTONE														
REFER INVOICE: 88863953														Total for Service 0.00
														Total for Work Order 0.00
Work Order	00054059		Work Order Date : 06/02/2023			Repair Location : EX0103		Yatala Workshop Exodas		General Repair/Maintenance				
Service Code:	GEN	General Repair				Meter Reading :		0						
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice		Details			Units	Rate	Extension	
Hino 500 Series JHDGH8JSMXXX10011														Total for Service 0.00
Check over and provide COI and HVRAS for registration														Total for Work Order 0.00

## Work Order Service History

Work Order	00054043	Work Order Date :	10/02/2023	Repair Location :	EX0103	Yatala Workshop Exodas	General Repair	
Service Code:	DEFECT	Defect Repair			Meter Reading :	673,904	Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Extension

DEFECT CLEARED.

Reported Defect :-

Defect Code : 00008012

Defect Reference : 10356

Date : 31/08/2022

Description of Defect :

DOES NOT HOLD AIR PRESSURE WHEN TURNED OFF FOR A FEW MINUTES

Reported Defect :-

Defect Code : 00008011

Defect Reference : 10357

Date : 31/08/2022

Description of Defect :

WICKED BODY ROLL SUSPENSION ISSUE

Total for Service 0.00

Service Code:	GEN	General Repair		Meter Reading :	673,904		Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details		

REPAIR COMPLETED.

REPLACED MASTER & SLAVE CYLINDER

FIXED QUICK RELEASE FITTING LEAKING AIR

MASTER CYLINDER FROM HINO NERANG

Total for Service 0.00

Total for Work Order 0.00

Work Order	00054729	Work Order Date :	10/03/2023	Repair Location :	EX0103	Yatala Workshop Exodas	Rigid A Service	
Service Code:	RIGIDA	Rigid A Service			Meter Reading :	678,714	Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Extension

SERVICE COMPLETED.

FITTED SCREEN SUPPLIED BY VIEWTRACK

Total for Service 0.00

Total for Work Order 0.00

Work Order	00055740	Work Order Date :	20/04/2023	Repair Location :	EX0103	Yatala Workshop Exodas	Rigid B Service	
Service Code:	DEFECT	Defect Repair			Meter Reading :	685,379	Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Extension

DEFECT CLEARED.

Total for Service 0.00

Service Code:	RIGIDA	Rigid A Service		Meter Reading :	685,379		Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Extension

SERVICE COMPLETED.

Total for Service 0.00

Service Code:	RIGIDB	Rigid B Service		Meter Reading :	685,379		Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details	Extension

## Work Order Service History

SERVICE COMPLETED.  
NEED PASSENGER ENGINE MOUNT  
SUMP GASKET

											Total for Service	0.00			
											Total for Work Order	0.00			
Work Order	00058804		Work Order Date : 11/08/2023			Repair Location :	EX0103	Yatala Workshop	Exodas	Rigid B Service					
Service Code:	DEFECT	Defect Repair				Meter Reading :	708,775				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension				
DEFECT CLEARED.											Total for Service	0.00			
Service Code:	RIGIDA	Rigid A Service				Meter Reading :	708,775				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension				
SERVICE COMPLETED.											Total for Service	0.00			
Service Code:	RIGIDB	Rigid B Service				Meter Reading :	708,775				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension				
SERVICE COMPLETED BY MATT & FLYNN ON 09/08/2023..											Total for Service	0.00			
											Total for Work Order	0.00			
Work Order	00058805		Work Order Date : 11/08/2023			Repair Location :	EX0103	Yatala Workshop	Exodas	Rigid C Service					
Service Code:	DEFECT	Defect Repair				Meter Reading :	708,775				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension				
DEFECT CLEARED.											Total for Service	0.00			
Service Code:	RIGIDA	Rigid A Service				Meter Reading :	708,775				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension				
SERVICE COMPLETED.											Total for Service	0.00			
Service Code:	RIGIDC	Rigid C Service				Meter Reading :	708,775				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension				
SERVICE COMPLETED.											Total for Service	0.00			
											Total for Work Order	0.00			
Work Order	00058824		Work Order Date : 14/08/2023			Repair Location :	EX0103	Yatala Workshop	Exodas	Exodas Annual Roadworthy NHVAS					
Service Code:	DEFECT	Defect Repair				Meter Reading :	708,775				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension				
DEFECT CLEARED.											Total for Service	0.00			
Service Code:	EXOINS	Exodas Annual Roadworthy NHVAS				Meter Reading :	708,775				Units	Rate			
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details				Extension				

## Work Order Service History

VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION.  
ATTEMPT # 1

INSPECTION COMPLETED BY MATT & FLYNN ON 09/08/2023.

										Total for Service	0.00	
										Total for Work Order	0.00	
Work Order	00063898		Work Order Date :		26/01/2024		Repair Location :	EX0103	Yatala Workshop Exodas	Rigid B Service		
Service Code:	DEFECT	Defect Repair					Meter Reading :	740,731			Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			Extension		
DEFECT CLEARED.												
										Total for Service	0.00	
Service Code:	RIGIDA	Rigid A Service					Meter Reading :	740,731			Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			Extension		
SERVICE COMPLETED.												
										Total for Service	0.00	
Service Code:	RIGIDB	Rigid B Service					Meter Reading :	740,731			Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			Extension		
SERVICE COMPLETED BY NICK & JOE ON 26/01/2024.												
NOTED: * REPLACE BELT NEXT SERVICE. DEFECT NO. 00010760 CREATED												
										Total for Service	0.00	
										Total for Work Order	0.00	
Work Order	00068718		Work Order Date :		29/06/2024		Repair Location :	EX0103	Yatala Workshop Exodas	Rigid B Service		
Service Code:	DEFECT	Defect Repair					Meter Reading :	769,377			Units	Rate
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			Extension		
DEFECT CLEARED.												
Reported Defect :- Defect Code : 00008789 Defect Reference : 10358 Date : 14/02/2023 Description of Defect : AIRCON GOING FROM COOL TO WARM												
DEFECT CLEARED ON 29/06/2024 Reported Defect :- Defect Code : 00009660 Defect Reference : 00058805 Date : 09/08/2023 Description of Defect : HI LOW SELECTOR LEAKING AIR ON BACK OF GEAR BOX												
DEFECT CLEARED ON 29/06/2024												
										Total for Service	0.00	

## Work Order Service History

Service Code: RIGIDA Rigid A Service						Meter Reading :	769,377	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
SERVICE COMPLETED.										<b>Total for Service</b> 0.00
Service Code: RIGIDB Rigid B Service						Meter Reading :	769,377	Units	Rate	Extension
Task Code	Employee	Product Code	Warehouse	Category	Supplier	Invoice	Details			
'B' SERVICE COMPLETED BY WORKSHOP (BEN, COREY & JOSEPH) ON 29/06/2024.										<b>Total for Service</b> 0.00
HI/LOW GEAR REPAIRED AIRCON FINE DOOR JAM FINE RE-NUTTED FRONT RHS CURTAIN POLE.										<b>Total for Service</b> 0.00
										<b>Total for Work Order</b> 0.00
										<b>Total for Asset</b> 0.00
										<b>Total for Report</b> 0.00

no