

Commercial Vehicle Inspection Report

Decal Number: GN77064
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21889685

212-7
2020253
Inspection Result: **PASS**

FACILITY: VALLEY TRUCK AND TRAILER LTD. / S12251
INSPECTOR: MCKENNA, SCOTT RON / 202485
WORK ORDER #: 7359
VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2015
MAKE: CROSS COUN
MODEL:
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-Aug-13 08:30 AM PDT
INSP. COMPLETE: 2026-Aug-13 10:30 AM PDT
REGI: 13098598
UNIT/FLEET#: SD03
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2C9SST353FM183010
OWNER/LESSEE NAME: ROCK SOLID INDUSTRIES,
ADDRESS: PO BOX 176
Merritt, British Columbia
V1K 1B8, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	36	40
2	Clamp	30	Automatic	38	40
3	Clamp	30	Automatic	36	30

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	6	8	9	9	
	6	7	7	10	
	15	15	14	15	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	45
2	60	65
3	75	65

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
	Lining (Shoe)	17	17
	Lining (Shoe)	16	16
	Lining (Shoe)	15	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
	Drum		
	Drum		
	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: MCKENNA, SCOTT RON
Road Test Date:
Signature:
Road Tester:
This Inspection Report was submitted to CISE on 2026-Aug-30 12:59 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

