

2018 NISSAN SENTRA S

Sedan | 4 Cylinders | Gas
3N1AB7AP4JY258096
Country of Assembly: Mexico
Last Reported Odometer: 94,423 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



12 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of May 12, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2020 Dec 7	Ontario, Canada	
	Police Reported Accident: Accident reported: severe damage Involving front or side impact with another motor vehicle Damage to front Claim: Collision	\$14,161.00
2024 Dec 18	Ontario, Canada	
	Claim: Collision	\$19,047.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2022 Jun 14	Eastern Canada	
	Auction Announcement: AUCTION ANNOUNCED AS ACCIDENT REPAIR	
2025 Jan 23	n/a	
	Damage Event: Damage reported: minor damage Damage to front	



Registration

✓ This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **Québec** with **Normal** branding.
- In the province of **Ontario** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Apr 30	47,360 KM	Active Green & Ross London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed
2019 May 30	48,187 KM	Accurate Auto Repair Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Safety inspection performed
2019 Nov 22	49,428 KM	Maple Nissan Maple, Ontario, Canada	Vehicle serviced
2019 Dec 13	50,015 KM	Maple Nissan Maple, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Charcoal/vapor canister replaced • Drivability/performance checked
2020 Jun 30	54,792 KM	Woodbine Nissan Etobicoke, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Air filter replaced • Brakes checked • Brake fluid flushed/changed • Front brakes serviced • Oil and filter changed • Rear brakes serviced/adjusted
2020 Oct 14	58,521 KM	Maple Nissan Maple, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Brakes checked • Brake rotor(s) replaced • Front brake pads replaced • Front brake rotor(s) replaced • Oil and filter changed
2021 Apr 12	65,595 KM	Maple Nissan Maple, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Brake fluid flushed/changed • Oil and filter changed
2021 Aug 17	67,459 KM	Maple Nissan Maple, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed
2021 Dec 29	72,591 KM	Maple Nissan Maple, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Air filter checked • Battery serviced • Oil and filter changed
2022 May 25	83,182 KM	Maple Nissan Maple, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed
2022 Sep 26	92,063 KM	Maple Nissan Maple, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Air filter checked • Oil and filter changed

	ODOMETER	SOURCE	DETAILS
2022 Nov 9	94,423 KM	Maple Toyota Maple, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Air filter replaced • Battery replaced • Battery serviced • Brakes serviced • Cabin air filter replaced/cleaned • Front brake rotor(s) resurfaced • Oil and filter changed • Safety inspection performed • Wiper(s) replaced • Vehicle washed/detailed



Open Recalls

✔ No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact NISSAN or visit [Nissan's website](https://www.nissanusa.com/recalls-vin.html). (https://www.nissanusa.com/recalls-vin.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Feb 16		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial
2019 Apr 3		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2019 Apr 30	47,360 KM	Active Green & Ross London, Ontario, Canada	Service Record	Vehicle serviced
2019 May 30	48,187 KM	Accurate Auto Repair Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2019 Oct 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as white
2019 Nov 22	49,428 KM	Maple Nissan Maple, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Dec 13	50,015 KM	Maple Nissan Maple, Ontario, Canada	Service Record	Vehicle serviced
2020 Jun 30	54,792 KM	Woodbine Nissan Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2020 Oct 14	58,521 KM	Maple Nissan Maple, Ontario, Canada	Service Record	Vehicle serviced
2020 Dec 7		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • severe damage • Involving front or side impact • with another motor vehicle • Damage to front
2020 Dec 7		Insurance Records Ontario, Canada		
2021 Feb 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2021 Apr 12	65,595 KM	Maple Nissan Maple, Ontario, Canada	Service Record	Vehicle serviced
2021 Aug 17	67,459 KM	Maple Nissan Maple, Ontario, Canada	Service Record	Vehicle serviced
2021 Dec 29	72,591 KM	Maple Nissan Maple, Ontario, Canada	Service Record	Vehicle serviced
2022 May 25	83,182 KM	Maple Nissan Maple, Ontario, Canada	Service Record	Vehicle serviced
2022 Jun 14	84,098 KM	Auto Auction Eastern Canada	Auction Announcement	AUCTION ANNOUNCED AS ACCIDENT REPAIR
2022 Sep 26	92,063 KM	Maple Nissan Maple, Ontario, Canada	Service Record	Vehicle serviced
2022 Oct 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white
2022 Nov 9	94,423 KM	Maple Toyota Maple, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as white
2024 Aug 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2024 Dec 18		Ontario, Canada	Collision	
2025 Jan 23			Damage Event	Damage reported: minor damage Damage to front

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2025 Mar 27	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white
2025 Apr 24	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.

